



DAILY FIELD REPORT

Project	Bedford Beverly Brownfield Site	Report No.	52
BCP Site	BCP Site No. C224384	Date	12/19/2023
Location	2359 and 2360 Bedford Avenue, Brooklyn, NY	File No.	0205432
Client	Bedford Beverly Acquisitions LLC, Maman Contracting (Maman), International Concrete	Temperature	31-42 °F
Contractor	Haley & Aldrich	Wind Direction	W to E, 11 mph
Weather	Partly Cloudy	Personnel on Site	A. Stewart, E. Nunez, & D. Djombalic
Humidity	74%	Time on Site	6:30 am to 3:30 pm

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich currently under review by NYSDEC and the NYSDEC-approved Change of Use dated 17 August 2023 to begin support of excavation work. Site observations are summarized below.

Daily Observations:

- Contractor (International Concrete) continued support of excavation (SOE) installation along the perimeter of Lots 14 and 53.
- Contractor (International Concrete) continued loading soil for transport and disposal off-site.

Waste Disposal/Backfill Import Tracking:

Material Export:

- Thirty-three (33) loads of non-hazardous fill material from grids WC-15 (5-10') and WC-15 (0-5')
- Soil/Fill disposal is summarized below:

	<i>Facility: Bayshore Soil Management, Keasbey, NJ (Non-Haz Soil)</i>		<i>Facility: P Park NJ LLC, Prospect Park, NJ (Non-Haz Soil)</i>		<i>Facility: Keystone Trade Center, Fairless Hills, PA (Non-Haz Soil)</i>		<i>Facility: Posillico Materials Permitted Wash Plant, LLC, Farmingdale, NY (Non-Haz Soil)</i>		<i>Totals:</i>	
<i>Today:</i>	0 Loads	0 CY	0 Loads	0 CY	33 Loads	660 CY	0 Loads	0 CY	33 Loads	660 CY
<i>Total:</i>	<u>186 Loads</u>	<u>3,720 CY</u>	<u>643 Loads</u>	<u>12,860 CY</u>	<u>262 Loads</u>	<u>5,240 CY</u>	<u>97 Loads</u>	<u>1,940 CY</u>	<u>1,188 Loads</u>	<u>23,760 CY</u>

*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

- Asphalt disposal is summarized below:

	<i>Facility: Flushing Asphalt Recycling, Flushing NY (Asphalt)</i>		<i>Facility: Mount Materials, Fairless Hills, PA (Asphalt)</i>		<i>Totals:</i>	
<i>Today:</i>	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY
<i>Total:</i>	<u>117 Loads</u>	<u>2,340 CY</u>	<u>9 Loads</u>	<u>180 CY</u>	<u>126 Loads</u>	<u>2,520 CY</u>

*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Date : 2023-12-19

Personnel : D. Djombalic, E. Nunez & A. Stewart
 Weather : Partly Cloudy
 Humidity : 74%
 Wind Direction : W to E, 11 mph

Particulate Background (ug/m3) : 6.226
 PID Background (ppm) : 0.0

Action Levels : Downwind perimeter of work area above background levels
 PID (ppm) : > 5 ppm for the 15-min average
 Dust (ug/m3) : > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
06:45		6.226		4.684		0.0		0.0		
07:00		5.153		6.455		0.0		0.0		
07:15		4.688		30.368		0.0		0.0		
07:30		4.694		5.848		0.0		0.0		
07:45		4.182		7.759		0.0		0.0		
08:00	13.946	5.253		7.347		0.0		0.0		
08:15	9.719	5.104	3.876	9.106	0.0	0.0	0.0	0.0		
08:30	7.795	5.179	2.565	4.103	0.0	0.0	0.0	0.0		
08:45	7.284	6.433	2.739	4.564	0.0	0.0	0.0	0.0		
09:00	7.032	6.881	2.477	3.768	0.0	0.0	0.0	0.0		
09:15	5.759	3.289	2.297	2.740	0.0	0.0	0.0	0.0		
09:30	5.978	5.000	2.328	2.921	0.0	0.0	0.0	0.0		
09:45	5.638	4.729	2.569	3.275	0.0	0.0	0.0	0.0		
10:00	6.605	4.336	2.611	3.112	0.0	0.0	0.0	0.0		
10:15	5.262	4.150	2.359	2.491	0.0	0.0	0.0	0.0		
10:30	4.252	3.420	1.609	1.902	0.0	0.0	0.0	0.0		
10:45	3.587	4.553	1.411	1.414	0.0	0.0	0.0	0.0		

2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00	2.991	2.973	1.029	1.7	0.0	0.0	0.0	0.0		
11:15	3.969	1.464	1.239	0.9	0.0	0.0	0.0	0.0		
11:30	2.907	2.418	0.687	0.8	0.0	0.0	0.0	0.0		
11:45	2.649	1.616	0.806	0.7	0.0	0.0	0.0	0.0		
12:00	1.988	1.345	0.537	0.9	0.0	0.0	0.0	0.0		
12:15	1.767	1.222	0.702	0.7	0.0	0.0	0.0	0.0		
12:30	1.626	1.392	0.817	0.9	0.0	0.0	0.0	0.0		
12:45	2.694	2.253	0.890	1.3	0.0	0.0	0.0	0.0		
13:00	2.316	2.952	1.007	1.3	0.0	0.0	0.0	0.0		
13:15	2.037	3.535	0.900	1.2	0.0	0.0	0.0	0.0		
13:30	2.137	3.714	0.870	1.7	0.0	0.0	0.0	0.0		
13:45	2.256	2.199	0.840	1.1	0.0	0.0	0.0	0.0		
14:00	2.346	3.879	0.957	1.5	0.0	0.0	0.0	0.0		
14:15		1.729		2.5		0.0		0.0		
14:30		2.181		1.1		0.0		0.0		
14:45		1.859		1.8		0.0		0.0		
15:00		1.165		1.9		0.0		0.0		
15:15		2.077		2.0		0.0		0.0		

- C&D disposal is summarized below:

	<i>Facility: Mount Materials, Fairless Hills, PA (Non-Haz Concrete)</i>		<i>Totals:</i>	
<i>Today:</i>	0 Loads	0 CY	0 Loads	0 CY
<i>Total:</i>	<u>61 Loads</u>	<u>1,220 CY</u>	<u>61 Loads</u>	<u>1,220 CY</u>

*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

Material Import:

- Material import is summarized below:

	<i>Facility: Mount Hope Quarry, Wharton, NJ (ASTM #57)</i>		<i>Facility: Mount Hope Quarry, Wharton, NJ (ASTM #3)</i>		<i>Totals:</i>	
<i>Today:</i>	0 Loads	0 CY	0 load	0 CY	0 Load	0 CY
<i>Total:</i>	<u>5 Loads</u>	<u>100 CY</u>	<u>12 loads</u>	<u>240 CY</u>	<u>17 Loads</u>	<u>340 CY</u>

*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

Samples Collected:

- No samples were collected.

CAMP Activities:

- Air monitoring during ground-intrusive activities was performed at four locations during ground intrusive work from 6:45 am to 3:15 pm. No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.

Activities Planned for Coming Week:

- Contractor (International Concrete) will continue stockpiling soil on the perimeter of Lot 14 for disposal.
- Contractor (International Concrete) will begin stockpiling soil on the perimeter of Lot 53 for disposal.
- Contractor (International Concrete) will continue installing H piles as part of SOE installation on the perimeter of the site.
- Contractor (International Concrete) will continue transportation and disposal of soil/fill to an approved facility.

Site Photographs:



Photo 1: View of contractor loading soil for off-site disposal on Lot 14, facing southwest.



Photo 2: View of contractor installing piles in Lot 53, facing north-northwest.

