

DAILY FIELD REPORT

Project	817-819 Bedford Avenue Development	Report No.	006
NYSDEC Site ID	C224399	Date	Thursday, 09/19/2024
Location	819 Bedford Avenue, Brooklyn, New York	File No.	0207044
Client	819 Mazel Mit Brucha LLC	Temperature	66°F
Contractor	Coastal Environmental Solutions, Inc. (driller)	Wind Direction	2mph North
Weather	Sunny	Personnel on Site	O. Hennigan
Humidity	65%	Time on Site	7:00am – 4:15pm

Scope of Work: H&A of New York Engineering and Geology, LLP (Haley & Aldrich of New York) performed Remedial Investigation (RI) activities as per the Remedial Investigation Work Plan (RIWP) approved on 26 July 2024.

Daily Activities:

- Haley & Aldrich of New York on-site to conduct the remedial investigation in accordance with the approved RIWP.
- Haley & Aldrich completed groundwater sampling at monitoring wells MW-03 and MW-04.

Samples Collected:

- Haley & Aldrich of New York collected the following samples as part of the RI:
 - HA-MW-03, HA-MW-04, and DUP01-20240919;

CAMP Activities:

- CAMP was not deployed since no ground intrusive activities were conducted.

Activities Planned for Coming Week:

- Continue to collect groundwater samples from existing wells and newly installed wells.

Site Photographs:

Photo 1: View of groundwater sample collection.



Photo 2: Alternate view of groundwater sample collection.

Site Map:



LEGEND:

- Site Boundary
- Approximate Extent of Work Area
- Appx. Location of Partial Cellar
- Existing Permanent Groundwater Monitoring Well
- Proposed Soil Boring/Groundwater Monitoring Well Location
- Proposed Soil Boring Location
- Limited Phase II Soil Boring and Soil Sample Location
- Proposed Soil Vapor Point Location