

DAILY FIELD REPORT

Project	817-819 Bedford Avenue Development	Report No.	007
NYSDEC Site ID	C224399	Date	Friday, 09/20/2024
Location	819 Bedford Avenue, Brooklyn, New York	File No.	0207044
Client	819 Mazel Mit Brucha LLC	Temperature	63°F
Contractor	DPK Consulting	Wind Direction	3mph North
Weather	Sunny	Personnel on Site	O. Hennigan
Humidity	65%	Time on Site	7:00am – 4:15pm

Scope of Work: H&A of New York Engineering and Geology, LLP (Haley & Aldrich of New York) performed Remedial Investigation (RI) activities as per the Remedial Investigation Work Plan (RIWP) approved on 26 July 2024.

Daily Activities:

- Haley & Aldrich of New York on-site to conduct the remedial investigation in accordance with the approved RIWP.
- Haley & Aldrich completed groundwater sampling at monitoring wells MW-01, MW-02, MW-05, and MW-06.
- DPK Consulting completed a monitoring well survey.

Samples Collected:

- Haley & Aldrich of New York collected the following samples as part of the RI:
 - HA-MW-01, HA-MW-02, HA-MW-05, and HA-MW-06;

CAMP Activities:

- CAMP was not deployed since no ground intrusive activities were conducted.

Activities Planned for Coming Week:

- Complete the remedial investigation report.

Site Photographs:

Photo 1: View of groundwater sample collection.











Photo 2: View of monitoring well survey being performed.

Site Map:



LEGEND:

-  Site Boundary
-  Approximate Extent of Work Area
-  Appx. Location of Partial Cellar
-  Existing Permanent Groundwater Monitoring Well
-  Proposed Soil Boring/Groundwater Monitoring Well Location
-  Proposed Soil Boring Location
-  Limited Phase II Soil Boring and Soil Sample Location
-  Proposed Soil Vapor Point Location