DAILY FIELD REPORT

Project	291 Wallabout Street Site	**Report No.**	48
BCP Site	NYSDEC BCP SITE C224416	**Date**	08/24/2026
Location	291 Wallabout St	**File No.**	0211139
Client	291 Wallabout Realty LLC	**Temperature**	L: 66 H: 81
Contractor	Concrete Raptor Construction American Dewatering Grouting	**Wind Direction**	SW to NE up to 19 mph
Weather	Partly Cloudy	**Personnel on Site**	J. Moen
Humidity	60%	**Time on Site**	7:00am – 6:30pm

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the NYSDEC-Approved Remedial Action Work Plan (RAWP) and Decision Document dated November 2025. Site observations are summarized below.

Daily Observations:

- Continued work on foundation elements.
- Pouring of concrete underpinning.

Waste Disposal/Material Import Tracking:

Material Export:

Soil/Fill Material is summarized below

Disposal Facility	*Bayshore Soil Management, LLC* *Keasbey, New Jersey*		*Conestoga Landfill* *Morgantown, Pennsylvania*		*Posillico Materials, LLC* *Farmingdale, New York*		*Republic Environmental Systems (PA), LLC* *Hatfield, Pennsylvania*		*P Park NJ* *Prospect Park, New Jersey*		*Total*	
	Loads	Tons	Loads	Tons	Loads	Tons	Loads	Tons	Loads	Tons	Loads	Tons
Today:	0	0	0	0	0	0	0	0	0	0	0	0
Total:	34	680	5	100	3	60	1	20	28	560	71	1420

C&D export is summarized below

	Facility: Morrisville Materials, Morrisville, PA (C&D disposal)	
Today:	0 Loads	0 CY
Total:	19 Loads	380 CY

Material Import:

Facility	*Mt. Hope Quarry Wharton, New Jersey (3/4" ASTM #57 Stone)*		*Totals*	
Today	0 Load	0 CY	0 Load	0 CY
Total	3 Load	60 CY	3 Load	60 CY

HALEY ALDRICH

DAILY FIELD REPORT

Samples Collected:

- None.

CAMP Activities:

- Air monitoring was performed at one upwind and one downwind location during ground intrusive activities. Two 15-minute average concentration of volatiles organic compounds (VOCs) or 15-minute average concentration of particulate matter smaller than 10 microns in diameter (PM10) exceeded the action levels.
    - No exceedance today.
    - PM10 and VOC data were not recorded at the downwind monitoring station at 15:00pm due to a battery outage. No ground intrusive work was performed during this time, and no odors or dust was observed. The battery was replaced, and data collection at the upwind station resumed at 15:15pm.

Activities Planned for Coming Week:

- Contractor will continue work on building foundation.

Site Photographs:





Photo 1. Excavation and rebar for concrete underpinning, facing east.



Photo 2: Pouring concrete for underpinnings, facing north.

Site Plan:



LEGEND:

- Upwind CAMP Station
- Downwind CAMP Station
- Stabilized Truck Entrance and Truck Wash Area
- Ingress
- Egress
- Approximate Work Area

291 Wallabout St Brooklyn

Air Monitoring Log

Date : 2026-08-24

Personnel : _____
Weather : _____
Humidity : _____
Wind Direction : _____

Particulate Background (ug/m3) : _____
PID Background (ppm) : _____

Action Levels : Downwind perimeter of work area above background levels
PID (ppm) : > 5 ppm for the 15-min average
Dust (ug/m3) : > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. VOC(Station1)	Avg. VOC(Station2)	Odors	Notes Activities/Additional Monitoring
07:15	14.651	8.878	0.8	0.1		
07:30	8.002	7.854	0.3	0.1		
07:45	8.307	5.924	0.2	0.0		
08:00	8.181	5.648	0.1	0.0		
08:15	8.601	5.735	0.1	0.0		
08:30	9.808	7.541	0.1	0.0		
08:45	11.224	8.733	0.1	0.0		
09:00	11.958	13.017	0.1	0.0		
09:15	16.861	13.518	0.1	0.0		
09:30	14.214	11.449	0.0	0.0		
09:45	14.087	11.992	0.1	0.0		
10:00	13.301	10.777	0.1	0.0		
10:15	12.412	10.071	0.0	0.0		
10:30	14.168	11.300	0.0	0.0		
10:45	17.285	11.528	0.1	0.1		

291 Wallabout St Brooklyn

Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. VOC(Station1)	Avg. VOC(Station2)	Odors	Notes Activities/Additional Monitoring
11:00	16.824	10.675	0.1	0.0		
11:15	11.936	11.249	0.0	0.0		
11:30	11.510	11.923	0.0	0.1		
11:45	11.495	12.282	0.1	0.1		
12:00	13.311	12.574	0.1	0.1		
12:15	14.520	11.735	0.1	0.1		
12:30	14.412	12.128	0.1	0.1		
12:45	14.345	11.149	0.1	0.1		
13:00	12.652	10.406	0.0	0.1		
13:15	11.213	9.816	0.0	0.1		
13:30	12.358	9.551	0.0	0.0		
13:45	10.691	9.089	0.1	0.0		
14:00	8.912	7.891	0.1	0.0		
14:15	8.557	6.987	0.0	0.0		
14:30	9.942	7.169	0.1	0.0		
14:45	11.220	6.788	0.0	0.0		
15:00	9.886		0.1			
15:15	6.919	6.698	0.0	0.0		
15:30	6.082	6.222	0.0	0.0		
15:45	5.942	5.775	0.1	0.0		
16:00	6.227	6.147	0.0	0.0		
16:15	6.985	6.554	0.0	0.0		
16:30	7.137	7.026	0.0	0.0		
16:45	7.636	6.935	0.0	0.1		
17:00	8.136	7.355	0.0	0.0		
17:15	8.940	7.416	0.0	0.0		
17:30	8.300	7.829	0.0	0.0		
17:45	8.767	8.240	0.0	0.0		
18:00	10.085	8.773	0.1	0.0		

tblAllData (postgres)

Site Name	Station Na..	Serial Number	DateStart	DateEnd
H&A-291 Wallabout St Brooklyn	Station1	DS 01062022-2056	8/24/2026 ..	8/24/2026 6:09:00 ..
	Station2	DS 01062022-2057	8/24/2026 ..	8/24/2026 6:10:00 ..