### 2023-2024 PERIODIC REVIEW REPORT

for

## 44-30 PURVES STREET Long Island City, New York NYSDEC BCP Site No. C241162

Prepared For:

Gotham Organization, Inc. 432 Park Avenue South, 2<sup>nd</sup> Floor New York, New York 10016

Prepared By:

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. 368 Ninth Avenue, 8<sup>th</sup> Floor New York, New York 10001

> December 20, 2024 170282502



368 Ninth Avenue, 8th Floor

New York, NY 10001

T: 212.479.5400

F: 212.479.5444

www.langan.com

#### **TABLE OF CONTENTS**

1.0		INTRODUCTION	_
	1.1	General	3
	1.2	Site Description	3
	1.3	Site Background and Environmental History	3
	1.4		
	1.5	,	
	1.6		
	1.7	·	
2.0		IC/EC PLAN COMPLIANCE REPORT	
_	2.1		
	2.2	·	
	2.3		
3.0		MONITORING PLAN COMPLIANCE REPORT	
		Monitoring Plan Components	
	3.2	· · · · · · · · · · · · · · · · · · ·	
	·-	3.2.1 Composite Cover System Inspection	
		3.2.2 SMD System Inspection	
		3.2.3 Annual Site-wide Inspection	
	3.3	Conclusions and Recommendations	
4.0		OPERATION & MAINTENANCE (O&M) PLAN COMPLIANCE REPORT	
	4.1		
	4.2	<b>'</b>	
		4.2.1 Evaluation of SMD System	
	4.3	,	
	4.4		
5.0		OVERALL CONCLUSIONS AND RECOMMENDATIONS	
	5.1		
	5.2	·	
		5.2.1 Composite Cover System	
		5.2.2 SMD System	
		5.2.3 IC Components	
	5.3	,	
6.0		DER-31 GREEN REMEDIATION EVALUATION	
		Waste Generation1	
	6.2		
	6.3	67 6	
	6.4		
	6.5		
	6.6	,	
7.0	5.0	CERTIFICATION OF IC/ECS	
	7.1	IC/EC Certification Form	
	7.1		1 – 1 <u>/</u> 1

#### **FIGURES**

Figure 1 Site Location Map

Figure 2 SMD and Vapor Barrier Layout Plan

Figure 3 Composite Cover System Plan

#### **APPENDICES**

Appendix A	Environmental Easement
Appendix B	Site Inspection Photographs

Appendix C Composite Cover System Inspection Form

Appendix D SMD System Inspection Forms
Appendix E Annual Site-Wide Inspection Form

Appendix F Institutional and Engineering Controls Certification Form

#### 1.0 INTRODUCTION

#### 1.1 General

This Periodic Review Report (PRR) was prepared in accordance with the New York State Department of Environmental Conservation (NYSDEC)-approved October 21, 2015 Site Management Plan (SMP) and Section 6.3 of NYSDEC Division of Environmental Remediation (DER)-10 Technical Guidance for Site Investigation and Remediation. The certification period for this PRR is September 30, 2023 through September 30, 2024. A periodic review of all institutional and engineering controls (IC/ECs) and a site evaluation are required for fulfillment of the remedial action at 44-30 Purves Street (the site) under the Brownfield Cleanup Program (BCP), which is administered by the NYSDEC. The site was accepted into the BCP (Site No. C241162) and a Brownfield Cleanup Agreement (BCA), Index No. C241162-06-14, was executed on June 12, 2014. Site remediation was performed in accordance with the December 7, 2014 Remedial Action Work Plan (RAWP). NYSDEC issued a Certificate of Completion for the site on December 21, 2015.

#### 1.2 Site Description

The site is located at 44-30 Purves Street in the Long Island City neighborhood of Queens, New York and is identified as Block 268, Lot 1 on the New York City Tax Map. The irregularly-shaped, 0.62-acre site is bound by Purves Street to the east, a 10-story residential building to the southeast (Lot 31), Thomson Avenue to the southwest, 44<sup>th</sup> Drive to the west, and a 27-story residential building to the north (Lot 4). A site location map is included as Figure 1.

The site is improved with a 35-story residential building with frontage along Purves Street, a two-story building with residences, residential amenity space and retail along Thomson Avenue and 44<sup>th</sup> Drive, and an open, partially-paved and partially-landscaped courtyard. A ventilated parking garage spans an area of about 11,000 square feet in the lowest level of the building along Thomson Avenue and 44<sup>th</sup> Drive.

#### 1.3 Site Background and Environmental History

The site is within a historically industrial area of Long Island City, Queens and was used for manufacturing purposes as early as the 1940s, including a chemical laboratory, automobile repair, private garage, controller and fine chemicals manufacturing, and welding and repair services. Several environmental investigations and reports were completed between April 2006 and September 2014: April 2006 Phase I Environmental Site Assessment (ESA), November 2006 Phase II Environmental Site Investigation (ESI), December 2011 Phase I ESA, and September 2014 Remedial Investigation Report (RIR).

A summary of investigation findings for each report is provided in the 2014 RIR. The conclusions of the investigation reports are summarized as follows:

- Two underground storage tanks (USTs) are shown on the 1947 and 1950 Sanborn maps. Petroleum impacts identified in soil were attributed to the suspected USTs.
- A variable site-wide historic fill layer was present up to 11 feet thick and contained semivolatile organic compound (SVOC), pesticide, polychlorinated biphenyl (PCB), and metal concentrations that exceeded RURR SCOs<sup>1</sup>.
- Tetrachloroethene (PCE) and trichloroethene (TCE) were detected in groundwater at concentrations exceeding NYSDEC SGVs<sup>2</sup>.
- PCE and TCE were detected in soil vapor throughout the site.
- On-site PCE and TCE impacts to soil vapor and groundwater were attributed to an off-site source.

#### 1.4 Summary of Remedial Action

A Track 4 remediation was implemented in accordance with the NYSDEC-approved November 7, 2014 RAWP between March 16 and October 30, 2015. A detailed account of the remedy is provided in the November 13, 2015 Final Engineering Report (FER), and is summarized as follows:

- Excavation and off-site disposal of hazardous lead-impacted historic fill, petroleum-impacted material, and contaminated nonhazardous historic fill material exceeding the Track 4 Site-Specific SCOs to depths of 4.5 to 7 feet below grade surface (bgs) throughout the site and to about 8 feet bgs for elevator pits and one UST excavation
- Decommissioning, closure, and removal of four USTs (including two previously unknown USTs) and collection and analysis of endpoint soil samples for each UST location
- Collection and analysis of documentation soil samples from the base of the excavation and the perimeter sidewalls, in accordance with NYSDEC DER-10
- Backfilling excavations to development grade with recycled concrete aggregate (RCA) and 3/4-inch virgin crushed stone

<sup>&</sup>lt;sup>1</sup> RURR SCOs = Title 6 of the Official Compilation of New York Codes, Rules, and Regulations (6 NYCRR) NYSDEC Part 375 Restricted Use Restricted-Residential (RURR) Soil Cleanup Objectives (SCOs).

NYSDEC SGVs = NYSDEC Technical and Operational Guidance Series (TOGS) 1.1.1 Ambient Water Quality Standards and Guidance Values (SGVs).

For contaminated soil remaining after remediation, the following controls were implemented:

#### Engineering Controls (ECs)

- Composite cover system, consisting of: (1) 10-inch-thick reinforced concrete building slabs above a vapor barrier/waterproofing membrane, (2) concrete pavement, and (3) two feet of clean stone above a demarcation barrier in landscaped areas
- Installation and operation of a sub-membrane depressurization (SMD) system, under portions of the site building that are not used as a mechanically-ventilated parking garage, to mitigate potential volatile organic compound (VOC) vapor intrusion into the building

#### Institutional Controls (ICs)

- Execution of an Environmental Easement
- Implement, maintain and monitor the ECs
- Prevent exposure to residual soil contaminants by controlling any disturbance below the composite cover through an SMP
- Limit the use and development of the site to restricted-residential, commercial and industrial uses only

With the exception of installation of the above-slab portions of the SMD system, remedial activities were completed as of October 30, 2015. Above-slab portions of the SMD system were completed during the balance of building construction. The building is complete and has a NYC-issued certificate of occupancy.

#### 1.5 Effectiveness of the Remedial Program

The remedial program was designed to eliminate or mitigate environmental and human health exposure to adverse environmental conditions still present in soil, groundwater, and soil vapor. The ICs and ECs for the certification period meet the remedial objectives for the site.

#### 1.6 Compliance

All ICs and ECs remain fully in place at the site for the certification period and continue to be effective.

#### 1.7 Recommendations

No changes to the SMP are recommended at this time.

#### 2.0 IC/EC PLAN COMPLIANCE REPORT

IC/ECs are required to protect human health and the environment because residual contaminated soil, groundwater, and soil vapor exists in the site subsurface. The IC/EC Plan included in the SMP describes the procedures for the implementation and management of the IC/ECs.

#### 2.1 IC/EC Components

The following summarizes IC/ECs implemented at the site:

- Operation and maintenance of the SMD system, installed under portions of the site building that are not used as a mechanically-ventilated parking garage, to mitigate potential VOC vapor intrusion into the building. The parking garage is ventilated in accordance with the New York City Mechanical Code. The SMD layout plan is shown on Figure 2.
- Maintenance of a composite cover system to prevent human exposure to residual contaminated soils remaining under site structures. The location and components of the composite cover are shown on Figure 3.
- The site may be used for restricted-residential use as described in 6 NYCRR Part 375-1.8(g)(2)(iii), commercial use as described in 6 NYCRR Part 375-1.8(g)(2)(iii) and industrial use as described in 6 NYCRR Part 375-1.8(g)(2)(iv).
- All ECs must be operated, maintained, and inspected as specified in the SMP.
- The use of groundwater underlying the property is prohibited without necessary water quality treatment as determined by the New York State Department of Health (NYSDOH) or the New York City Department of Health and Mental Hygiene to render it safe for use as drinking water or for industrial purposes, and the user must first notify and obtain written approval to do so from the NYSDEC.
- All future activities on the property that will disturb residual contaminated material must be conducted in accordance with the SMP.
- Monitoring to assess the performance and effectiveness of the remedy must be performed as defined in the SMP.
- Operation, maintenance, monitoring, inspection, and reporting of any mechanical or physical components of the remedy shall be performed as defined in the SMP.
- Access to the site must be provided to agents, employees or other representatives of the State of New York with reasonable prior notice to the property owner to ensure compliance with the restrictions identified by the Environmental Easement (included as Appendix A).

• The site shall not be used for unrestricted or residential uses as defined in 6 NYCRR 375-1.8(g)(2)(i), and the above-stated engineering controls may not be discontinued without an amendment or extinguishment of the Environmental Easement.

#### 2.2 Goal Status and Corrective Measures

The annual SMD system inspection was performed on May 28, 2024. The north SMD system blower was observed to not be operational during the inspection. No other deficiencies were observed. The NYSDEC Project Manager was notified of the deficiency via email on May 30, 2024. An additional SMD system inspection was performed on August 28, 2024. The SMD system was observed to be operational, and no deficiencies were noted during the inspection.

#### 2.3 Conclusions and Recommendations

No additional modifications to the IC/ECs are proposed at this time.

#### 3.0 MONITORING PLAN COMPLIANCE REPORT

#### 3.1 Monitoring Plan Components

The components of the Monitoring Plan are as follows:

- 1. Annual inspection of the composite cover system;
- 2. Annual inspection of the SMD system and parking garage ventilation system; and
- 3. Annual site-wide inspection.

A comprehensive inspection was conducted on May 28, 2024 that included the three above-listed monitoring plan components. Site inspection photographs are provided in Appendix B. A summary of each inspection is presented in the following sections and the inspection forms detailing findings are provided in Appendices C, D, and E.

#### 3.2 Summary of Monitoring Completed

#### 3.2.1 Composite Cover System Inspection

The annual composite cover system was inspected on May 28, 2024, including a visual assessment for integrity of the site building slabs, pavers and stone in landscaped areas, and the sidewalk pavement along Purves Street. Damages and/or breaches to the composite cover system were not identified during the annual inspection events for the certification period. A composite cover system inspection form is included as Appendix C.

#### 3.2.2 SMD System Inspection

Inspection of the SMD system was conducted on May 28, 2024. The SMD system was inspected to determine whether the system installation and function is satisfactory and consistent with the manufacturer's specifications and the design criteria. The north SMD system blower was observed to not be operational during the inspection. No other deficiencies were observed. The NYSDEC Project Manager was notified of the deficiency via email on May 30, 2024. An electrician performed maintenance on the north SMD system blower on August 22, 2024. An additional SMD system inspection was performed on August 28, 2024. The SMD system was observed to be operational, and no deficiencies were noted during the inspection. Based on the inspections, the SMD system is operational and consistent with the design criteria. The SMD inspection forms are included in Appendix D.

#### 3.2.3 Annual Site-wide Inspection

The annual site-wide inspection was completed on May 28, 2024. This consisted of spot inspections of all ECs and verification of ICs. All IC/EC components inspected were in compliance with the SMP. Deviations or discrepancies were not observed. The completed site-wide inspection form is included as Appendix E.

#### 3.3 Conclusions and Recommendations

No changes to the SMP are recommended at this time.

#### 4.0 OPERATION & MAINTENANCE (O&M) PLAN COMPLIANCE REPORT

#### 4.1 **O&M Plan Purpose**

The components of the O&M Plan are as follows:

Continuous operation and maintenance, as necessary, of the SMD system

#### 4.2 SMD O&M Activities

SMD system inspections were performed following initial startup and testing, which was completed on March 6, 2018. Inspections consisted of documenting the accessible, above-grade components of the SMD system, recording flow readings, testing the system alarm, and documenting the vacuum gauge readings. The north SMD system blower was observed to not be operational during the May 28, 2024 inspection. An electrician performed maintenance on the north SMD system blower on August 22, 2024. The north SMD system blower was observed to be operational during the inspection conducted on August 28, 2024.

#### 4.2.1 Evaluation of SMD System

The SMD system primary objective is to create a negative pressure under the floor slab and draw soil vapor to the two vacuum blowers located on the roof of the building, where the vapor is discharged to and diluted with the atmosphere. Based on the inspections, the SMD system is operational and functioning within the design criteria.

#### 4.3 O&M Deficiencies

The north SMD system blower deficiency observed during the May 28, 2024 inspection was resolved as documented during the August 28, 2024 inspection. No deficiencies were identified during the August 28, 2024 site inspection. A paper copy of the O&M plan was not available at the site but the plan was accessible electronically.

#### 4.4 Conclusions and Recommendations

No changes to the SMP are recommended at this time.

#### 5.0 OVERALL CONCLUSIONS AND RECOMMENDATIONS

#### 5.1 SMP Compliance

Each component of the SMP, including the IC/EC Plan, Monitoring Plan, and O&M Plan, was in compliance for the certification period.

#### 5.2 Remedy Performance Evaluation

#### 5.2.1 Composite Cover System

Conditions of the site building slabs and landscaped areas were inspected for quality and integrity. The site-wide composite cover system was observed to be intact and continues to protect public health and the environment.

#### 5.2.2 SMD System

The north SMD system blower was observed to not be operational during the May 28, 2024 inspection. An electrician performed maintenance on the north SMD system blower on August 22, 2024. The north SMD system blower was observed to be operational during the inspection conducted on August 28, 2024. The SMD system is operating as designed and is mitigating the potential exposure to soil vapor contaminants.

#### 5.2.3 IC Components

All ICs were maintained during the certification period, and the Environmental Easement on the site remains in place.

#### 5.3 Future Submittals

Annual inspections of the SMD system and site-wide composite cover system will continue to be conducted as specified in the NYSDEC-approved SMP Reporting Plan. Forms and other information generated during regular monitoring events and inspections will be submitted at the time of the annual PRR.

#### 6.0 DER-31 GREEN REMEDIATION EVALUATION

The NYSDEC DER-31 Green Remediation Policy requires that green remediation concepts and techniques be considered during all stages of the remedial program (including site management), with the goal of improving the sustainability of the cleanup and summarizing the net environmental benefit of any implemented green technology. This section provides a discussion and evaluation of environmental impacts associated with site management activities for the site during the 2023 to 2024 reporting period, and a summary of green remediation goals for the 2024 to 2025 reporting period.

Green remediation principles and techniques were implemented to the extent feasible in the site management phase of the remedy as per DER-31. The green remediation components evaluated were as follows:

- Waste Generation
- Energy Usage
- Emissions
- Water Usage
- Land and/or Ecosystems

#### 6.1 Waste Generation

Waste generation considers the management of waste associated with site management activities and any waste reduction projects including, but not limited to, material reuse and recycling. For the annual inspections, minimal to no waste was generated and electronic means of data collection (i.e., tablets) were used to reduce paper consumption.

#### 6.2 Energy Usage

Energy usage considers the electrical usage for operation of SMD system and site lighting needed for OM&M activities. The SMD system is powered using the municipal grid, and therefore are subject to local energy supply means. Annual energy usage is summarized in Table 6.5.

#### 6.3 Emissions

Emissions tracking considers fuel usage for transportation to and from the site for inspections. Fuel usage is required for transportation of personnel to and from the site, and transportation associated with screening/sampling equipment. During the 2023 to 2024 reporting period, personnel used public transportation to and from the site and in-house equipment was used so a courier was not needed. Annual emissions are summarized in Table 6.5.

#### 6.4 Water Usage

Water usage considers sources of water for tasks such as decontamination, irrigation, etc. No water was used during the annual site inspections.

#### 6.5 Land and/or Ecosystems

Land and/or ecosystems considers any disturbances and restoration of land and/or ecosystems as part of the implementation/operation of the remedy. No disturbances or restoration of land and/or ecosystems are required as part of site management activities.

**Table 6.1: Annual Environmental Analysis** 

Item	Estimated Power Usage (kWh)	Estimated Carbon Footprint (metric tons CO2e)	Comment
SMD System Blowers	12,000	2.61	2 x Airtech 3b1400 Regenerative Blowers
Equipment	125	0.03	PID, Velocicalc
Transit to/from site Inspection	N/A	N/A	Public Transit
Computer Usage	0.5	0.016	Field Preparation, Reporting

#### 6.6 Goals for Site Management Activities in 2025

While future development associated with the site's remedial program is not anticipated, goals for the project to incorporate green remediation principles and techniques include:

- Off-set energy consumption with energy collected from sustainable technology (i.e. solar panels, wind turbines, etc.)
- Personnel will continue to utilize public transportation to and from the site when possible during annual site-wide inspections to reduce emissions;
- Langan equipment will be used when possible to eliminate the need for an equipment courier; and
- Tracking of detailed green remediation components to generate an environmental footprint analysis for the 2024 to 2025 reporting period.

Langan will continue to evaluate green remediation concepts and techniques for inclusion in site management, with the goal of improving the sustainability of the cleanup and site management activities.

#### 7.0 CERTIFICATION OF IC/ECS

#### 7.1 IC/EC Certification Form

The completed IC/EC Certification Form is provided as Appendix F.

#### 7.2 IC/EC Certification

I, Jason Hayes, P.E., of Langan, have been authorized and designated by the site owner to sign this certification for the site.

For each IC/EC identified for the site, I certify that to the best my knowledge all of the following statements are true:

- The inspection of the site to confirm the effectiveness of the IC/ECs required by the remedial program was performed under my direction;
- The IC/ECs employed at this site are unchanged from the date the control was put in place, or last approved by the Department;
- Nothing has occurred that would impair the ability of the control to protect the public health and environment;
- Nothing has occurred that would constitute a violation or failure to comply with any site management plan for this control;
- Access to the site will continue to be provided to the Department to evaluate the remedy, including access to evaluate the continued maintenance of this control;
- Use of the site is compliant with the environmental easement;
- The engineering control systems are performing as designed and are effective;
- To the best of my knowledge and belief, the work and conclusions described in this
  certification are in accordance with the requirements of the Site remedial program and
  generally accepted engineering practices; and
- The information presented in this report is accurate and complete.

I certify that all information and statements in this certification are true. I understand that a false statement made herein is punishable as Class "A" misdemeanor, pursuant to section to be the Penal Law.

089491


New York State Professional Engineer #


<u>| Z /36 /2024</u> Date


ieriature<sub>08949</sub>


It is a violation of Article 145 of New York State Education Law for any person to alter this document in any way without the express written verification of adoption by any New York State licensed engineer in accordance with Section 7209(2), Article 145, New York State Education

Law.










# APPENDIX A Environmental Easement



## **DEED DESCRIPTION OF BLOCK 268, LOT 1**

BEGINNING at a point on the westerly side of Purves Street distant 101 feet northerly from the corner formed by the intersection of the westerly side of Purves Street with the northeasterly side of Thomson Avenue;

RUNNING THENCE northerly olong the westerly side of Purves Street o distance

THENCE westerly ond ot right ongles to the westerly side of Purves Street o

THENCE southerly and porollel with the westerly side of Purves Street a distance of 50 feet to o point;

THENCE westerly on a course forming an interior angle of 89 degrees 38 minutes 20 seconds with the easterly side of 44th Drive a distance of 88.54 feet (deed), 88.47 feet (survey) to a point on the eosterly side of 44th Drive; THENCE southerly along the easterly side of 44th Drive a distance of 59.94

feet to the corner formed by the intersection of the easterly side of 44th Drive with the northeasterly side of Thomson Avenue;

THENCE southeosterly olong the northeosterly side of Thomson Avenue a distance of 148.32 feet to a point;

THENCE northeasterly and at right angles to the northeasterly side of Thomson Avenue a distance of 45.21 feet to a point;

THENCE eosterly ond ot right ongles to the westerly side of Purves Street a distance of 45.21 feet to the westerly side of Purves Street and the point or place of BEGINNING

Encompassing on area of 27,092 square feet or 0.622 acres.

## WRITTEN DESCRIPTION FOR BLOCK 268, LOT 1 **ENVIRONMENTAL EASEMENT**

BEGINNING at a point on the westerly sideline of Purves Street, shown 60 feet wide on the Long Island City Atloses, where the same is intersected by the division line between londs hereindescribed and londs now or formerly of Jewel Liton LLC, described in CRFN 2013000255742, said point distant 101.00 feet measured northerly along said sideline from its intersection with the northeasterly sideline of Thomson Avenue, shown 100 feet wide on soid Long Island City Atlases, and runs, thence:

- Along londs of Jewel Liton LLC, South 64'40'47" West, o distance of 45.21
- feet, to o point; thence 2. Continuing olong lands of Jewel Liton LLC, South 16'26'57" West, o distance of 45.21 feet, to a point on the northeosterly sideline of
- Thomson Avenue; thence 3. Along the northeosterly sideline of Thomson Avenue, North 73°33'03" West, o distonce of 148.32 feet, to its intersection with the eosterly sideline of 44th Drive, formerly Nott Avenue, shown 100 feet wide on soid Long Island City Atlases; thence
- 4. Along the eosterly sideline of 44th Drive, North 27\*43'03" West, o distonce of 59.97 feet, to a point where the same is intersected by the division line between lands hereindescribed and lands now or formerly of Purves Development LLC, described in CRFN 2014000077940; thence 5. Along Purves Development LLC, North 64°40'47" Eost, o distonce of 88.47
- feet to a point; thence 6. Continuing olong Purves Development LLC, North 25'19'13" West, o distance of 50.00 feet, to o point; thence
- 7. Continuing along Purves Development LLC, North 64\*40'47" East, a distance of 100.00 feet, to a point in the westerly sideline of Purves
- 8. Along the westerly sideline of Purves Street, South 25'19'13" East, a distance of 175.00 feet, to the Point of Beginning.

Encompassing an areo of 27,092 squore feet or 0.622 acre.

# I FCFND ...

CONCRETE

CONC

LEGEND	(NOT SHOWN TO SCALE)		
	HYDRANT STREET LIGHT AREA LIGHT SIGNAL POLE POLE GUY WIRE MANHOLE (TYPE AS LABELED) WATER VALVE GAS VALVE SHRUB		STORM DRAIN SANITARY LINE GAS LINE WATER LINE ELECTRIC LINE TELEPHONE LINE OVERHEAD WIRE GUIDE RAIL (TYPE AS NOTED) CHAIN LINK FENCE TREE LINE EASEMENT LINE
	CATCH BASIN SPOT ELEVATION CLEAN OUT TREE	322	PROPERTY LINE RIGHT-OF-WAY LINE CONTOUR LINE
● ○→ BWS SYS CC	SIGN BOLLARD TRAFFIC SIGNAL BROKEN WHITE STRIPE SINGLE YELLOW STRIPE CONCRETE CURB	DYS DOUBLE YELLOW SWS SINGLE WHITE ST RCP REINFORCED CON EP EDGE OF PAVEM CMP CORRUGATED ME LSA LANDSCAPED AR DC DROP CURB	TRIPE ICRETE PIPE ENT TAL PIPE

## NOTES


- 1. THIS SURVEY IS BASED UPON EXISTING PHYSICAL CONDITIONS FOUND AT THE SUBJECT SITE, AND THE FOLLOWING REFERENCES:
- PREPARED BY: OLD REPUBLIC NATIONAL TITLE INSURANCE COMPANY TITLE NUMBER: 901153 EFFECTIVE DATE: 6/20/2013
- B. TITLE PRO FORMA: PREPARED BY OLD REPUBLIC NATIONAL TITLE INSURANCE COMPANY TITLE NUMBER: 905099 EFFECTIVE DATE: 10/17/2014
- C. MAP ENTITLED "TOPOGRAPHIC & BOUNDARY SURVEY, BLOCK 268, LOT AS SHOWN, SECTION 2, COUNTY OF QUEENS" PREPARED BY APPLE SURVEYING AND DATED
- MAP ENTITLED "SURVEY OF PROPERTIES SITUATED IN: 44-18/38 PURVES STREET, BOROUGH OF QUEENS, COUNTY OF QUEENS, CITY OF NEW YORK, STATE OF NEW YORK, TOPO SURVEY, SIDEWALK AND STREET ELEVATIONS, BLOCK 268, LOT 1, 4, 22, 23, 24, 25, 26" PREPARED BY FEHRINGER SURVEYING, P.C. AND DATED
- E. MAP ENTITLED "LONG ISLAND CITY ATLAS MAPS, SHEET 14"
- F. SURVEY OF BLOCK 268, LOT 4 IN THE BOROUGH OF QUEENS, CITY OF NEW YORK, QUEENS COUNTY, NY PREPARED BY GERALD T. O'BUCKLEY, DATED MAY 7, 2013.
- G. MAP ENTITLED "TITLE SURVEY, TITLE NO. QUE 235739, BLOCK 268, LOT 1,24,25,26, SECTION 2, COUNTY OF QUEENS" PREPARED BY BIG APPLE LAND SURVEYORS, P.C. DATED JANUARY 04, 2005 AND LAST REVISED SEPTEMBER 30,
- H. SURVEY OF BLOCK 268, LOTS 1,22.23,24,25 & 26, SECTION 2, COUNTY OF QUEENS" PREPARED BY AAA GROUP LAND SURVEYORS SERVICES DATED JANUARY
- 2. THE SURVEYED PROPERTY IS SUBJECT BUT NOT LIMITED TO THE FOLLOWING FACTS AS REVEALED BY THE HEREON REFERENCED INFORMATION. THE INFORMATION SHOWN HEREON DOES NOT CONSTITUTE A TITLE SEARCH BY THE SURVEYOR. ALL INFORMATION THAT MAY AFFECT THE QUALITY OF TITLE TO BOTH THE SUBJECT AND ADJOINING PARCELS SHOULD BE VERIFIED BY AN ACCURATE AND CURRENT TITLE
- 3. THE MERIDIAN OF THIS SURVEY IS REFERENCED TO NYS-LI NAD83 (2011) AS ESTABLISHED USING GPS METHODS.
- 4. STREET NAMES AND R.O.W. WIDTHS, BLOCK AND LOT NUMBERS AS PER MAPS

REFERENCED IN NOTES 1C, 1D & 1E.

- 5. PLANIMETRIC INFORMATION SHOWN HEREON HAS BEEN OBTAINED FROM GROUND SURVEYS BY LANGAN ENGINEERING, ENVIRONMENTAL, SURVEYING AND LANDSCAPE ARCHITECTURE, D.P.C. DURING MAY 2015.
- 6. AS PER THE "NEW YORK CITY PRELIMINARY FIRM DATA COMMUNITY PANEL NUMBER 3604970202G." PANEL NOT PRINTED THE ENTIRE THE SUBJECT PROPERTY LIES WITHIN ZONE X SHADED, AN AREA OF 0.2% ANNUAL CHANCE FLOOD HAZARD.
- 7. OFFSETS (IF SHOWN) ARE FOR SURVEY REFERENCES ONLY AND ARE NOT TO BE USED IN CONSTRUCTION OF ANY TYPE.
- 8. WETLANDS, ENVIRONMENTAL AND/OR HAZARDOUS MATERIALS LOCATION, IF ANY, NOT COVERED UNDER THIS CONTRACT.
- 9. UNLESS SPECIFICALLY NOTED HEREON, STORM AND SANITARY SEWER INFORMATION (INCLUDING PIPE INVERT, PIPE MATERIAL, AND PIPE SIZE) WAS OBSERVED AND MEASURED AT FIELD LOCATED STRUCTURES (MANHOLES/CATCH BASINS, ETC ). CONDITIONS CAN VARY FROM THOSE ENCOUNTERED AT THE TIMES WHEN AND THE LOCATIONS WHERE DATA WAS OBTAINED, DESPITE MEETING THE REQUIRED STANDARD OF CARE THE SURVEYOR CANNOT AND DOES NOT WARRANT THAT PIPE MATERIAL AND/OR PIPE SIZE THROUGHOUT THE PIPE RUN ARE THE SAME AS THOSE OBSERVED AT EACH STRUCTURE, OR THAT THE PIPE RUN IS STRAIGHT BETWEEN THE LOCATED STRUCTURES.
- ADDITIONAL UTILITY (WATER, GAS, ELECTRIC ETC ... ) DATA MAY BE SHOWN FROM FIELD LOCATED SURFACE MARKINGS (BY OTHERS), EXISTING STRUCTURES, AND/OR FROM EXISTING DRAWINGS.
- UNLESS SPECIFICALLY NOTED HEREON THE SURVEYOR HAS NOT EXCAVATED TO PHYSICALLY LOCATE THE UNDERGROUND UTILITIES. THE SURVEYOR MAKES NO GUARANTEES THAT THE SHOWN UNDERGROUND UTILITIES ARE EITHER IN SERVICE. ABANDONED OR SUITABLE FOR USE, NOR ARE IN THE EXACT LOCATION OR CONFIGURATION INDICATED HEREON.
- PRIOR TO ANY DESIGN OR CONSTRUCTION THE PROPER UTILITY AGENCIES MUST BE CONTACTED FOR VERIFICATION OF UTILITY TYPE AND FOR FIELD LOCATIONS
- UNLESS NOTED BELOW SUPPLEMENTAL DOCUMENTS WERE NOT USED TO COMPILE THE SUBSURFACE UTILITY INFORMATION SHOWN HEREON 10. THIS IS TO CERTIFY THAT THERE ARE NO STREAMS NOR NATURAL WATERCOURSES
- ON THE PROPERTY AS SHOWN ON THIS SURVEY. 11. UNAUTHORIZED ALTERATION OR ADDITION TO A SURVEY MAP BEARING A LICENSED LAND SURVEYOR'S SEAL IS A VIOLATION OF SECTION 7209, SUB-DIVISION 2, OF
- THE NEW YORK STATE EDUCATION LAW. 12. THIS PLAN NOT VALID UNLESS EMBOSSED OR BLUE INK STAMPED WITH THE SEAL
- 13. THE PROPERTY IS SUBJECT TO A DECLARATION OF COMMON SEWER AND SITE CONNECTION RECORDED IN CRFN 2015000011044.

OF THE PROFESSIONAL.

THIS PROPERTY IS SUBJECT TO AN ENVIRONMENTAL EASEMENT HELD BY THE NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION PURSUANT TO TITLE 36 OF ARTICLE 71 OF THE NEW YORK ENVIRONMENTAL CONSERVATION LAW. THE ENGINEERING AND INSTITUTIONAL CONTROLS FOR THIS EASEMENT ARE SET FORTH IN MORE DETAIL IN THE SITE MANAGEMENT PLAN (SMP). A COPY OF THE SMP MUST BE OBTAINED BY ANY PARTY WITH AN INTEREST IN THE PROPERTY. THE SMP CAN BE OBTAINED FROM NYS DEPARTMENT OF ENVIRONMENTAL CONSERVATION, DIVISION OF ENVIRONMENTAL REMEDIATION, SITE CONTROL SECTION, 625 BROADWAY, ALBANY, NY 12233 OR AT DERWEB@DEC.NY.GOV.



PROJECT LOCATION MAP

SCALE: NO SCALE

Date Description REVISIONS

T: 212.479.5400 F: 212.479.5444 www.langan.com

050784-1

PROFESSIONAL LAND SURVEY

NEW JERSEY NEW YORK CONNECTICUT PENNSYLVANIA OHIO WASHINGTON, DC FLORIDA TEXAS NORTH DAKOTA CALIFORNIA ABU DHABI ATHENS DOHA DUBAI ISTANBUL PANAMA Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. S.A. Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. Langan Engineering and Environmental Services, Inc. Langan CT, Inc.

Project

# 44-30 PURVES STREET

BLOCK No. 268, LOT No.1 **BOROUGH OF QUEENS** CITY OF NEW YORK

QUEENS COUNTY

STATE OF NEW YORK

# **BOUNDARY SURVEY**

Drawing No. 170282501 21 MAY 2015 VB-101 cale 1"=20" Checked By rawn By PDF ubmission Date

21 MAY 2015 Filename: U:\data5\170282501\Cadd Data - 170282501\SheetFiles\SURVEY\170282501-VB101-0101.dwg Date: 5/28/2015 Time: 16:47 User: gperiu Style Table: Langan.stb Layout: ARCHD-SL

## NYC DEPARTMENT OF FINANCE OFFICE OF THE CITY REGISTER

This page is part of the instrument. The City Register will rely on the information provided by you on this page for purposes of indexing this instrument. The information on this page will control for indexing purposes in the event of any conflict with the rest of the document.

**QUEENS** 



2015081800555001003E1EFD

#### RECORDING AND ENDORSEMENT COVER PAGE PAGE 1 OF 10 Preparation Date: 08-18-2015 Document Date: 07-31-2015 Document ID: 2015081800555001 Document Type: EASEMENT Document Page Count: 9 RETURN TO: PRESENTER: ROYAL REGISTERED PROPERTY REPORTS INC ROYAL REGISTERED PROPERTY REPORTS INC 180853 180853 **500 5TH AVENUE** 500 5TH AVENUE **SUITE 1540 SUITE 1540** NEW YORK, NY 10110 NEW YORK, NY 10110 212-376-0900 212-376-0900 PROPERTY DATA Borough Block Lot Unit Address

268 1 Entire Lot 44-30 PURVES STREET

Property Type: NON-RESIDENTIAL VACANT LAND Easement

	CROS	S REFEREN	CE DATA			
CRFNor DocumentID	or	Ycar	Rcel	Pagc	or File Number	
GRANTOR/SELLER: PURVES STREET OWNERS LLC 52 VANDERBILT AVENUE NEW YORK, NY 10017		PEO CON OF I BRO	ANTEE/BU PLE OF ST MMISSION	FATE OF N IER. DEPT MENTAL (	IEW YORK BY CONSERVATION , 625	

	FEES AN	D TAXES
Mortgage :		Filing Fcc:
Mortgage Amount:	\$ 0.00	\$
Taxable Mortgage Amount:	\$ 0.00	NYC Real Property Transfer Tax:
Exemption:		\$
TAXES: County (Basic):	\$ 0.00	NYS Real Estate Transfer Tax:
City (Additional):	\$ 0.00	\$
Spec (Additional):	\$ 0.00	RECORDED OR F
TASF:	\$ 0.00	OF THE CITY F
MTA:	\$ 0.00	CITY OF
NYCTA:	\$ 0.00	Recorded/Fil
Additional MRT:	\$ 0.00	City Registe
TOTAL:	\$ 0.00	
Recording Fee:	\$ 82.00	
Affidavit Fee:	\$ 0.00	(Inauta

RECORDED OR FILED IN THE OFFICE
OF THE CITY REGISTER OF THE

CITY OF NEW YORK

Recorded/Filed 08-26-2015 12:11 City Register File No.(CRFN):

250.00

0.00

0.00

2015000296906

Grante M. Sill

City Register Official Signature

# ENVIRONMENTAL EASEMENT GRANTED PURSUANT TO ARTICLE 71, TITLE 36 OF THE NEW YORK STATE ENVIRONMENTAL CONSERVATION LAW

WHEREAS, the Legislature of the State of New York has declared that it is in the public interest to encourage the remediation of abandoned and likely contaminated properties ("sites") that threaten the health and vitality of the communities they burden while at the same time ensuring the protection of public health and the environment; and

WHEREAS, the Legislature of the State of New York has declared that it is in the public interest to establish within the Department a statutory environmental remediation program that includes the use of Environmental Easements as an enforceable means of ensuring the performance of operation, maintenance, and/or monitoring requirements and the restriction of future uses of the land, when an environmental remediation project leaves residual contamination at levels that have been determined to be safe for a specific use, but not all uses, or which includes engineered structures that must be maintained or protected against damage to perform properly and be effective, or which requires groundwater use or soil management restrictions; and

WHEREAS, the Legislature of the State of New York has declared that Environmental Easement shall mean an interest in real property, created under and subject to the provisions of Article 71, Title 36 of the New York State Environmental Conservation Law ("ECL") which contains a use restriction and/or a prohibition on the use of land in a manner inconsistent with engineering controls which are intended to ensure the long term effectiveness of a site remedial program or eliminate potential exposure pathways to hazardous waste or petroleum; and

WHEREAS, Grantor, is the owner of real property located at the address of 44-30 Purves Street in the City of New York, County of Queens and State of New York, known and designated on the tax map of the New York City Department of Finance as tax map parcel number: Block 268 Lot 1, being the same as that property conveyed to Grantor by deeds dated June 19, 2014 and October 17, 2014 and recorded in the City Register of the City of New York in CFRN #'s 2014000225213 and 2014000372295, respectively. The property subject to this Environmental Easement (the "Controlled Property") comprises approximately .622 +/- acres, and is hereinafter more fully described in the Land Title Survey dated May 21, 2015 prepared by Paul D. Fisher, L.S., which will be attached to the Site Management Plan. The Controlled Property description is set forth in and attached hereto as Schedule A; and

WHEREAS, the Department accepts this Environmental Easement in order to ensure the protection of public health and the environment and to achieve the requirements for remediation

established for the Controlled Property until such time as this Environmental Easement is extinguished pursuant to ECL Article 71, Title 36; and

NOW THEREFORE, in consideration of the mutual covenants contained herein and the terms and conditions of Brownfield Cleanup Agreement Index Number: C241162-06-14 as amended by Amendment #1 dated January 22, 2015, Grantor conveys to Grantee a permanent Environmental Easement pursuant to ECL Article 71, Title 36 in, on, over, under, and upon the Controlled Property as more fully described herein ("Environmental Easement")

- 1. <u>Purposes</u>. Grantor and Grantee acknowledge that the Purposes of this Environmental Easement are: to convey to Grantee real property rights and interests that will run with the land in perpetuity in order to provide an effective and enforceable means of encouraging the reuse and redevelopment of this Controlled Property at a level that has been determined to be safe for a specific use while ensuring the performance of operation, maintenance, and/or monitoring requirements; and to ensure the restriction of future uses of the land that are inconsistent with the above-stated purpose.
- 2. <u>Institutional and Engineering Controls</u>. The controls and requirements listed in the Department approved Site Management Plan ("SMP") including any and all Department approved amendments to the SMP are incorporated into and made part of this Environmental Easement. These controls and requirements apply to the use of the Controlled Property, run with the land, are binding on the Grantor and the Grantor's successors and assigns, and are enforceable in law or equity against any owner of the Controlled Property, any lessees and any person using the Controlled Property.
  - A. (1) The Controlled Property may be used for:

Restricted Residential as described in 6 NYCRR Part 375-1.8(g)(2)(ii), Commercial as described in 6 NYCRR Part 375-1.8(g)(2)(iii) and Industrial as described in 6 NYCRR Part 375-1.8(g)(2)(iv)

- (2) All Engineering Controls must be operated and maintained as specified in the Site Management Plan (SMP);
- (3) All Engineering Controls must be inspected at a frequency and in a manner defined in the SMP;
- (4) The use of groundwater underlying the property is prohibited without necessary water quality treatment\_as determined by the NYSDOH or the New York City Department of Health and Mental Hygiene to render it safe for use as drinking water or for industrial purposes, and the user must first notify and obtain written approval to do so from the Department;
- (5) Groundwater and other environmental or public health monitoring must be performed as defined in the SMP;
  - (6) Data and information pertinent to Site Management of the Controlled

Property must be reported at the frequency and in a manner defined in the SMP;

- (7) All future activities on the property that will disturb remaining contaminated material must be conducted in accordance with the SMP;
- (8) Monitoring to assess the performance and effectiveness of the remedy must be performed as defined in the SMP;
- (9) Operation, maintenance, monitoring, inspection, and reporting of any mechanical or physical components of the remedy shall be performed as defined in the SMP;
- (10) Access to the site must be provided to agents, employees or other representatives of the State of New York with reasonable prior notice to the property owner to assure compliance with the restrictions identified by this Environmental Easement.
- B. The Controlled Property shall not be used for Residential purposes as defined in 6NYCRR 375-1.8(g)(2)(i), and the above-stated engineering controls may not be discontinued without an amendment or extinguishment of this Environmental Easement.
- C. The SMP describes obligations that the Grantor assumes on behalf of Grantor, its successors and assigns. The Grantor's assumption of the obligations contained in the SMP which may include sampling, monitoring, and/or operating a treatment system, and providing certified reports to the NYSDEC, is and remains a fundamental element of the Department's determination that the Controlled Property is safe for a specific use, but not all uses. The SMP may be modified in accordance with the Department's statutory and regulatory authority. The Grantor and all successors and assigns, assume the burden of complying with the SMP and obtaining an up-to-date version of the SMP from:

Site Control Section
Division of Environmental Remediation
NYSDEC
625 Broadway
Albany, New York 12233
Phone: (518) 402-9553

- D. Grantor must provide all persons who acquire any interest in the Controlled Property a true and complete copy of the SMP that the Department approves for the Controlled Property and all Department-approved amendments to that SMP.
- E. Grantor covenants and agrees that until such time as the Environmental Easement is extinguished in accordance with the requirements of ECL Article 71, Title 36 of the ECL, the property deed and all subsequent instruments of conveyance relating to the Controlled Property shall state in at least fifteen-point bold-faced type:

#### This property is subject to an Environmental Easement held

# by the New York State Department of Environmental Conservation pursuant to Title 36 of Article 71 of the Environmental Conservation Law.

- F. Grantor covenants and agrees that this Environmental Easement shall be incorporated in full or by reference in any leases, licenses, or other instruments granting a right to use the Controlled Property.
- G. Grantor covenants and agrees that it shall, at such time as NYSDEC may require, submit to NYSDEC a written statement by an expert the NYSDEC may find acceptable certifying under penalty of perjury, in such form and manner as the Department may require, that:
- (1) the inspection of the site to confirm the effectiveness of the institutional and engineering controls required by the remedial program was performed under the direction of the individual set forth at 6 NYCRR Part 375-1.8(h)(3).
  - (2) the institutional controls and/or engineering controls employed at such site:
    - (i) are in-place;
- (ii) are unchanged from the previous certification, or that any identified changes to the controls employed were approved b the NYSDEC and that all controls are in the Department-approved format; and
- (iii) that nothing has occurred that would impair the ability of such control to protect the public health and environment;
- (3) the owner will continue to allow access to such real property to evaluate the continued maintenance of such controls;
- (4) nothing has occurred that would constitute a violation or failure to comply with any site management plan for such controls;
- (5) the report and all attachments were prepared under the direction of, and reviewed by, the party making the certification;
- (6) to the best of his/her knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted engineering practices; and
  - (7) the information presented is accurate and complete.
- 3. <u>Right to Enter and Inspect</u>. Grantee, its agents, employees, or other representatives of the State may enter and inspect the Controlled Property in a reasonable manner and at reasonable times to assure compliance with the above-stated restrictions.
- 4. <u>Reserved Grantor's Rights</u>. Grantor reserves for itself, its assigns, representatives, and successors in interest with respect to the Property, all rights as fee owner of the Property, including:
- A. Use of the Controlled Property for all purposes not inconsistent with, or limited by the terms of this Environmental Easement;
- B. The right to give, sell, assign, or otherwise transfer part or all of the underlying fee interest to the Controlled Property, subject and subordinate to this Environmental Easement;

#### 5. Enforcement

A. This Environmental Easement is enforceable in law or equity in perpetuity by Grantor, Grantee, or any affected local government, as defined in ECL Section 71-3603, against the owner of the Property, any lessees, and any person using the land. Enforcement shall not be defeated because of any subsequent adverse possession, laches, estoppel, or waiver. It is not a defense in any action to enforce this Environmental Easement that: it is not appurtenant to an interest in real property; it is not of a character that has been recognized traditionally at common law; it imposes a negative burden; it imposes affirmative obligations upon the owner of any interest in the burdened property; the benefit does not touch or concern real property; there is no privity of estate or of contract; or it imposes an unreasonable restraint on alienation.

- B. If any person violates this Environmental Easement, the Grantee may revoke the Certificate of Completion with respect to the Controlled Property.
- C. Grantee shall notify Grantor of a breach or suspected breach of any of the terms of this Environmental Easement. Such notice shall set forth how Grantor can cure such breach or suspected breach and give Grantor a reasonable amount of time from the date of receipt of notice in which to cure. At the expiration of such period of time to cure, or any extensions granted by Grantee, the Grantee shall notify Grantor of any failure to adequately cure the breach or suspected breach, and Grantee may take any other appropriate action reasonably necessary to remedy any breach of this Environmental Easement, including the commencement of any proceedings in accordance with applicable law.
- D. The failure of Grantee to enforce any of the terms contained herein shall not be deemed a waiver of any such term nor bar any enforcement rights.
- 6. <u>Notice</u>. Whenever notice to the Grantee (other than the annual certification) or approval from the Grantee is required, the Party providing such notice or seeking such approval shall identify the Controlled Property by referencing the following information:

County, NYSDEC Site Number, NYSDEC Brownfield Cleanup Agreement, State Assistance Contract or Order Number, and the County tax map number or the Liber and Page or computerized system identification number.

Parties shall address correspondence to:

Site Number: C241162 Office of General Counsel

NYSDEC 625 Broadway

Albany New York 12233-5500

With a copy to:

Site Control Section

Division of Environmental Remediation

NYSDEC 625 Broadway Albany, NY 12233

All notices and correspondence shall be delivered by hand, by registered mail or by Certified mail and return receipt requested. The Parties may provide for other means of receiving and communicating notices and responses to requests for approval.

- 7. <u>Recordation</u>. Grantor shall record this instrument, within thirty (30) days of execution of this instrument by the Commissioner or her/his authorized representative in the office of the recording officer for the county or counties where the Property is situated in the manner prescribed by Article 9 of the Real Property Law.
- 8. <u>Amendment</u>. Any amendment to this Environmental Easement may only be executed by the Commissioner of the New York State Department of Environmental Conservation or the Commissioner's Designee, and filed with the office of the recording officer for the county or counties where the Property is situated in the manner prescribed by Article 9 of the Real Property Law.
- 9. <u>Extinguishment.</u> This Environmental Easement may be extinguished only by a release by the Commissioner of the New York State Department of Environmental Conservation, or the Commissioner's Designee, and filed with the office of the recording officer for the county or counties where the Property is situated in the manner prescribed by Article 9 of the Real Property Law.
- 10. <u>Joint Obligation</u>. If there are two or more parties identified as Grantor herein, the obligations imposed by this instrument upon them shall be joint and several.

Remainder of Page Intentionally Left Blank

IN WITNESS WHEREOF, Grantor has caused this instrument to be signed in its name.

Purves Street Owners, LLC:
By:
Print Name: Parid Bawe
Title: Authorized Signatury Date: 7/1/5

Grantor's Acknowledgment

STATE OF NEW YORK )
COUNTY OF NEWYEK )
On the
Notary Public - State of New York

WENDY GALARZA
PUBLIC-STATE OF NEW YORK
No. 01GA6200632
Qualified in Bronx County
My Commission Expires February 09, 2017

THIS ENVIRONMENTAL EASEMENT IS HEREBY ACCEPTED BY THE **PEOPLE OF THE STATE OF NEW YORK**, Acting By and Through the Department of Environmental Conservation as Designee of the Commissioner, By: Robert W. Schick, Director Division of Environmental Remediation Grantee's Acknowledgment STATE OF NEW YORK ) ss: COUNTY OF ALBANY On the 31% day of 3%, in the year 20%, before me, the undersigned, personally appeared Robert W. Schick, personally known to me or proved to me on the basis of satisfactory evidence to be the individual(s) whose name is (are) subscribed to the within instrument and acknowledged to me that he/she/ executed the same in his/her/ capacity as Designee of the Commissioner of the State of New York Department of Environmental Conservation, and that by his/her/ signature on the instrument, the individual, or the person upon behalf of which the individual acted executed the instrument. Notary Public - State of New York

David J. Chiusano
Notary Public, State of New York
No. 01CH5032146
Qualified in Schenectady County
Commission Expires August 22, 20

#### **SCHEDULE "A" PROPERTY DESCRIPTION**


ALL THAT CERTAIN plot, piece or parcel of land, with the buildings and improvements thereon erected, situate, lying and being in the Borough and County of Queens, City and State of New York, bounded and described as follows:

BEGINNING at a point on the westerly sideline of Purves Street, shown 60 feet wide on the Long Island City Atlases, where the same is intersected by the division line between lands herein described and lands now or formerly of Jewel Liton LLC, described in CRFN 2013000255742, said point distant 101.00 feet measured northerly along said sideline from its intersection with the northeasterly sideline of Thomson Avenue, shown 100 feet wide on said Long Island City Atlases, and runs, thence:

- 1. Along lands of Jewel Liton LLC, South 64'40'47" West, a distance of 45.21 feet, to a point; thence
- 2. Continuing along lands of Jewel Liton LLC, South 16'26'57" West, a distance of 45.21 feet, to a point on the northeasterly sideline of Thomson Avenue; thence
- 3. Along the northeasterly sideline of Thomson Avenue, North 73·33'03" West, a distance of 148.32 feet, to its intersection with the easterly sideline of 44th Drive, formerly Nott Avenue, shown 100 feet wide on said Long Island City Atlases; thence
- 4. Along the easterly sideline of 44th Drive, North 27·43'03" West, a distance of 59.97 feet, to a point where the same is intersected by the division line between lands herein described and lands now or formerly of Purves Development LLC, described in CRFN 2014000077940; thence
- 5. Along Purves Development LLC, North 64'40'47" East, a distance of 88.47 feet to a point: thence
- 6. Continuing along Purves Development LLC, North 25'19'13" West, a distance of 50.00 feet, to a paint; thence
- 7. Continuing along Purves Development LLC, North 64"40'47" East, a distance of 100.00 feet, to a point in the westerly sideline of Purves Street; thence
- 8. Along the westerly sideline of Purves Street, South 25"19'13" East, a distance of 175.00 feet, to the Point of Beginning.
- 9. Encompassing an area of 27,092 square feet or 0.622 acres.



Photo 1, 05/28/2024: View of main lobby and composite cover (facing north).



**Photo 2, 05/28/2024:** View of submembrane depressurization (SMD) system riser pipe penetration through the cellar slab (facing west).



Photo 3, 05/28/2024: View of blower units on roof (facing northwest).




Photo 4, 05/28/2024: View of vacuum gauge connected to roof blower (facing east).



Photo 5, 05/28/2024: View of filter attached to south SMD blower (facing south).




Photo 6, 05/28/2024: View of flow readings collected from the south blower (facing northwest).




**Photo 7, 05/28/2024:** View of photoionization detector (PID) readings collected from the south blower (facing northwest).



Photo 8, 05/28/2024: View within the filter segment of the south blower.



**Photo 9, 05/28/2024:** View of concrete building slab composite cover in ventilated parking garage (facing east).



**Photo 10, 05/28/2024:** View of concrete building slab composite cover in gas meter room (facing northeast).



Photo 11, 05/28/2024: View of composite cover in laundry room (facing southwest).




Photo 12, 05/28/2024: View of composite cover in bicycle storage room (facing west).




Photo 13, 05/28/2024: View of composite cover in resident storage room (facing west).



Photo 14, 05/28/2024: View of composite cover in compactor room (facing southeast).




Photo 15, 05/28/2024: View of labeled SMD piping in storage room (facing northeast).



Photo 16, 05/28/2024: View of composite cover in pool storage room (facing south).




Photo 17, 05/28/2024: View of composite cover in supply room (facing south).




Photo 18, 05/28/2024: View of composite cover in the janitorial closet (facing north).




Photo 19, 05/28/2024: View of composite cover in the building storage room (facing south).



Photo 20, 05/28/2024: View of composite cover in the water meter room (facing southeast).



Photo 21, 05/28/2024: View of SMD riser behind maintenance hallway wall panel.



Photo 22, 05/28/2024: View of landscaping and composite cover in courtyard (facing northwest).




Photo 23, 05/28/2024: View of composite cover in maintenance hallway (facing east).



Photo 24, 05/28/2024: View of SMD system breaker and alarm panels (facing west).



**Photo 25, 05/28/2024:** View of the clean out valve installed to remove water from the SMD system (facing south).

# APPENDIX C Composite Cover System Inspection Form

### **COMPOSITE COVER SYSTEM INSPECTION CHECKLIST**

Site Name: 44-30 Purves Street Location: Lo			ong Isl	land (	City, N	IY Project I	Number:	170282502			
Inspector Name: Olivia O'Donnell Date: 5/28			28/20:	24	Wea	ther Conditions:	Su	ınny, 74 F			
Re	Reason for Inspection (i.e., routine, severe condition, etc.):				Annual Inspection						
							ne following: N/A: Not Applica	able)			
				Υ	N	N/A	Is the Situation Normal?		Remarks		
	General										
1	What are the curren	it site conditions?				✓	Y	Build	ling is complete and	d occupied.	
	Impermeable Cap										
2	Are there any indica the time of this insp	tions of a breach in the ca pection?	apping system at		<b>✓</b>		Y				
3	construction activity any tenant improver	ction activity, or indication within the past certificati ments), that included the l site at the time of this ins	on year (including breaching of the		<b>✓</b>		Y				
4		is there documentation the HASP, and CAMP for the				<b>√</b>	Υ				
**		y of the above question able, documentation atta s:								e provided	
Mi	Minimum Inspection Schedule:										

- Site-wide inspections will be conducted annually, per certification year, at a minimum.
- Additional inspections will also be conducted at times of severe weather condition events.
- All inspection events will use this checklist.



# APPENDIX D SMD System Inspection Forms

#### **SMD SYSTEM INSPECTION CHECKLIST**

Site	Name: 44-30 Purves Street Location: Long Island City, N	۱Y	-		Project Number:	170282502			
Insp	Inspector Name: Olivia O'Donnell Date: 5/28/2024 Weather Conditions: Sunny 74								
Rea	Reason for Inspection (i.e., routine, severe condition, etc.):  Annual Inspection								
		Che	ck on	e of the	e following:				
		(Y: Y	es l	N: No 1	N/A: Not Applicable)				
		Υ	N	N/A	Is the Situation Normal?	Remarks			
	Records								
1	Is the Operations & Maintenance Plan readily available on-site?	<b>√</b>			Y	Records available in Langan digital archives.			
2	Based on site records, when was the last inspection, maintenance, or repair event?			<b>✓</b>	Y	5/17/2023			
3	Based on site records, was the system inoperational for any amount of time since the last inspection, maintenance, or repair event? For how long? Provide details.	<b>√</b>			N	North blower not operating at time of inspection			
	Alarm System								
4	Do the alarm lights indicate that the system is operational?	✓			Υ				
	General System								
5	Is there any construction activity, or indication of any construction activity within the past certification year (including any tenant improvements), that included the breaching of the floor slab, on-site at the time of this inspection?		✓		Y				
6	If YES to number 5, is there documentation that the Soil Management Plan, HASP, and CAMP for the site was/is being followed?			<b>✓</b>	N/A				
7	If YES to number 5, is there documentation that all breaches in the floor slab have been sealed?			<b>✓</b>	N/A				
8	Does all visible SSD piping appear intact and undamaged?	<b>√</b>			Y				
9	Have any intake points been constructed at the roof near (less than 10 feet) the SMD blower discharge point?		<b>√</b>		Y				
	SSD Blower Unit								
10	Is the SSD blower operational at the time of the inspection?		~		N	North blower not operating at time of inspection			
11	What is the VelociCalc Meter reading?	<b>√</b>			Y	South Blower: 115 CFM North Blower: NA			
12	Is the SSD blower expelling air at the discharge point?		<b>~</b>		N	North blower not operating at time of inspection			
***	If the answer to any of the above questions indicates the SMD system is no	n-on	eratio	onal or	malfunctioning or that this FC is in	non-compliance additional remarks must be			

Additional remarks:

PID Reading at South Blower: 0.0 ppm, Vacuum Gauge at South Blower: 45 \* H2O

PID Reading at North Blower: NA, Vacuum Gauge at North Blower: NA

The first floor riser pipe connected to the north blower is drained of accumulated condensation once every three months



provided and, where applicable, documentation attached to this checklist detailing additional inspection and repair activities\*\*\*

#### **SMD SYSTEM INSPECTION CHECKLIST**

Site	e Name: 44-30 Purves Street Location:Long Island City, N	ΙΥ	-		Project Number:	170282502						
Ins	Inspector Name: Olivia O'Donnell Date: 8/28/2024				Weather Conditions:	Sunny 80						
Rea	ason for Inspection (i.e., routine, severe condition, etc.):			Ann	ual Inspection - Follow-up							
					Check one of the following:							
					N/A: Not Applicable)							
	Ta	Y	N	N/A	Is the Situation Normal?	Remarks						
	Records											
1	Is the Operations & Maintenance Plan readily available on-site?	~			Y	Records available in Langan digital archives.						
2	Based on site records, when was the last inspection, maintenance, or repair event?			<b>√</b>	Y	5/28/2024						
3	Based on site records, was the system inoperational for any amount of time since the last inspection, maintenance, or repair event? For how long? Provide details.	<b>✓</b>			N	North blower observed to be operating as normal.						
	Alarm System	ı										
4	Do the alarm lights indicate that the system is operational?	✓			Y							
	General System											
5	Is there any construction activity, or indication of any construction activity within the past certification year (including any tenant improvements), that included the breaching of the floor slab, on-site at the time of this inspection?		<b>✓</b>		Y							
6	If YES to number 5, is there documentation that the Soil Management Plan, HASP, and CAMP for the site was/is being followed?			<b>✓</b>	N/A							
7	If YES to number 5, is there documentation that all breaches in the floor slab have been sealed?			✓	N/A							
8	Does all visible SSD piping appear intact and undamaged?	1			Y							
9	Have any intake points been constructed at the roof near (less than 10 feet) the SMD blower discharge point?		<b>✓</b>		Y							
	SSD Blower Unit											
10	Is the SSD blower operational at the time of the inspection?	<b>√</b>			Y							
11	What is the VelociCalc Meter reading?	1			Y	South Blower: 151.05 CFM North Blower: 161.28 CFM						
12	Is the SSD blower expelling air at the discharge point?	1			Y							
	1											

Additional remarks:

PID Reading at South Blower: 0.0 ppm, Vacuum Gauge at South Blower: 45 \* H2O

PID Reading at North Blower: 0.0, Vacuum Gauge at North Blower: 63 \* H2O

The first floor riser pipe connected to the north blower is drained of accumulated condensation once every three months



<sup>\*\*\*</sup>If the answer to any of the above questions indicates the SMD system is non-operational or malfunctioning, or that this EC is in non-compliance, additional remarks must be provided and, where applicable, documentation attached to this checklist detailing additional inspection and repair activities\*\*\*

# APPENDIX E Annual Site-Wide Inspection Form

### SITE INSPECTION CHECKLIST

Sit	Site Name: 44-30 Purves Street Location: Long Island City, NY Project Number: 170282502									
Ins	Inspector Name: Olivia O'Donnell Date: 5/28/2024			Weather Conditions: Sunny 74 F						
Re	Reason for Inspection (i.e., routine, severe condition, etc.):			Annual Inspection						
					ne following: N/A: Not App	olicable)				
		Υ		N/A	Is the	Remarks				
	General				Normal?					
	General									
1	What are the current site conditions?			✓	Y	Building is complete and occupied.				
	Are all applicable site records (e.g., documentation of construction									
2	activity, SMD system maintenance and repair, most current easement, etc.) complete and up to date?	✓			Y					
	ote., complete and up to date:									
	Environmental Easement									
3	Has site use (restricted residential) remained the same?	✓			Y					
4	Does it appear that all environmental easement restrictions have been followed?	✓			Y					
	Impermeable Cap									
5	Are there any indications of a breach in the capping system at the time of this inspection?		<b>~</b>		Y	Capping system intact at the time of the inspection. No active construction.				
6	Are there any cracks in the building slabs?		✓		Y					
7	Are there any cracks in the building walls?		<b>√</b>		Y					
8	Is there any construction activity, or indication of any construction activity within the past certification year (including any tenant improvements), that included the breaching of the capping system, on-site at the time of		✓		Y					
9	this inspection?  If YES to number 7, is there documentation that the Soil Management Plan, HASP, and CAMP for the site was/is being followed?			<b>✓</b>	Y					
	If the answer to any of the above questions indicate non-compliance with any IC/ECs for the site, additional remarks  * must be provided and, where applicable, documentation attached to this checklist detailing additional inspection and repair activities.  Additional remarks:  Minimum Inspection Schedule:									
	<ul> <li>Site-wide inspections will be conducted annually, per certification year, at a minimum.</li> <li>Additional inspections will also be conducted at times of severe weather condition events.</li> </ul>									
• /	All inspection events will use this checklist.									

## LANGAN

### **APPENDIX F**

## INSTITUTIONAL AND ENGINEERING CONTROLS CERTIFICATION FORM

#### NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

**Division of Environmental Remediation** 

625 Broadway, 11<sup>th</sup> Floor, Albany, NY 12233-7020 P: (518)402-9543 | F: (518)402-9547 www.dec.ny.gov

8/13/2024

David Brause Member Purves Street Owners LLC 52 Vanderbilt Avenue c/o Brause Realty Inc. New York, NY 10017 DAB@BrauseRealty.com

Re: Reminder Notice: Site Management Periodic Review Report and IC/EC Certification Submittal

**Site Name:** 44-30 Purves Street

Site No.: C241162

**Site Address:** 44-30 Purves Street

Long Island City, NY 11101

#### Dear David Brause:

This letter serves as a reminder that sites in active Site Management (SM) require the submittal of a periodic progress report. This report, referred to as the Periodic Review Report (PRR), must document the implementation of, and compliance with, site-specific SM requirements. Section 6.3(b) of DER-10 *Technical Guidance for Site Investigation and Remediation* (available online at http://www.dec.ny.gov/regulations/67386.html) provides guidance regarding the information that must be included in the PRR. Further, if the site is comprised of multiple parcels, then you as the Certifying Party must arrange to submit one PRR for all parcels that comprise the site. The PRR must be received by the Department no later than **October 30, 2024**. Guidance on the content of a PRR is enclosed.

Site Management is defined in regulation (6 NYCRR 375-1.2(at)) and in Chapter 6 of DER-10. Depending on when the remedial program for your site was completed, SM may be governed by multiple documents (e.g., Operation, Maintenance, and Monitoring Plan; Soil Management Plan) or one comprehensive Site Management Plan.

A Site Management Plan (SMP) may contain one or all of the following elements, as applicable to the site: a plan to maintain institutional controls and/or engineering controls ("IC/EC Plan"); a plan for monitoring the performance and effectiveness of the selected remedy ("Monitoring Plan"); and/or a plan for the operation and maintenance of the selected remedy ("O&M Plan"). Additionally, the technical requirements for SM are stated in the decision document (e.g., Record of Decision) and, in some cases, the legal agreement directing the remediation of the site (e.g., order on consent, voluntary agreement, etc.).

When you submit the PRR (by the due date above), include the enclosed forms documenting that all SM requirements are being met. The Institutional Controls (ICs) portion of the form (Box 6) must be signed by you or your designated representative. The Engineering Controls (ECs) portion of the form (Box 7) must be signed by a Professional Engineer (PE). If you cannot certify that all SM requirements are being met, you must submit a Corrective Measures Work Plan that identifies the actions to be taken to restore compliance. The work plan must include a schedule to be approved by the Department. The Periodic Review process will not be considered complete until all necessary corrective measures are completed and all required controls are certified. Instructions for completing the certifications are enclosed.



All site-related documents and data, including the PRR, must be submitted in electronic format to the Department of Environmental Conservation. The required format for documents is an Adobe PDF file with optical character recognition and no password protection. Data must be submitted as an electronic data deliverable (EDD) according to the instructions on the following webpage:

#### https://www.dec.ny.gov/chemical/62440.html

Documents may be submitted to the project manager either through electronic mail or by using the Department's file transfer service at the following webpage:

#### https://fts.dec.state.ny.us/fts/

The Department will not approve the PRR unless all documents and data generated in support of the PRR have been submitted using the required formats and protocols.

You may contact Manfred Magloire, the Project Manager, at 718-482-4078 or manfred.magloire@dec.ny.gov with any questions or concerns about the site. Please notify the project manager before conducting inspections or field work. You may also write to the project manager at the following address:

New York State Department of Environmental Conservation One Hunters Point Plaza 47-40 21st Street Long Island City, NY 11101

#### **Enclosures**

PRR General Guidance Certification Form Instructions Certification Forms

ec: w/ enclosures

ec: w/ enclosures

Manfred Magloire, Project Manager
Cris-Sandra Maycock, Chief, Region 2 - Remediation Section A
Jane O'Connell, Hazardous Waste Remediation Supervisor, Region 2
Langan Engineering - Jason Hayes - jahayes@langan.com

The following parcel owner did not receive an ec:

Purves Street Owners Llc - Parcel Owner

#### **Enclosure 1**

#### **Certification Instructions**

#### **I. Verification of Site Details** (Box 1 and Box 2):

Answer the three questions in the Verification of Site Details Section. The Owner and/or Qualified Environmental Professional (QEP) may include handwritten changes and/or other supporting documentation, as necessary.

#### II. Certification of Institutional Controls/ Engineering Controls (IC/ECs)(Boxes 3, 4, and 5)

- 1.1.1. Review the listed IC/ECs, confirming that all existing controls are listed, and that all existing controls are still applicable. If there is a control that is no longer applicable the Owner / Remedial Party should petition the Department separately to request approval to remove the control.
- 2. In Box 5, complete certifications for all Plan components, as applicable, by checking the corresponding checkbox.
- 3. If you <u>cannot</u> certify "YES" for each Control listed in Box 3 & Box 4, sign and date the form in Box 5. Attach supporting documentation that explains why the **Certification** cannot be rendered, as well as a plan of proposed corrective measures, and an associated schedule for completing the corrective measures. Note that this **Certification** form must be submitted even if an IC or EC cannot be certified; however, the certification process will not be considered complete until corrective action is completed.

If the Department concurs with the explanation, the proposed corrective measures, and the proposed schedule, a letter authorizing the implementation of those corrective measures will be issued by the Department's Project Manager. Once the corrective measures are complete, a new Periodic Review Report (with IC/EC Certification) must be submitted within 45 days to the Department. If the Department has any questions or concerns regarding the PRR and/or completion of the IC/EC Certification, the Project Manager will contact you.

#### **III. IC/EC Certification by Signature** (Box 6 and Box 7):

If you certified "YES" for each Control, please complete and sign the IC/EC Certifications page as follows:

- For the Institutional Controls on the use of the property, the certification statement in Box 6 shall be completed and may be made by the property owner or designated representative.
- For the Engineering Controls, the certification statement in Box 7 must be completed by a Professional Engineer or Qualified Environmental Professional, as noted on the form.



# Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



Sit	Site Details Site No. C241162						
Sit	e Name 44-30 Purve	s Street					
Cit <sub>y</sub>	e Address: 44-30 Pun y/Town: Long Island ( unty: Queens e Acreage: 0.622		Zip Code: 11101				
Re	porting Period: Septe	mber 30, 2023 t	o September 30, 2024				
					YES	NO	
1.	Is the information abo	ove correct?			✓		
	If NO, include handw	ritten above or o	on a separate sheet.				
2.	Has some or all of the tax map amendment		oeen sold, subdivided, m orting Period?	nerged, or undergone a		$\checkmark$	
3.	Has there been any of (see 6NYCRR 375-1	•	t the site during this Rep	porting Period		<b>√</b>	
4.	Have any federal, sta for or at the property		permits (e.g., building, conting Period?	discharge) been issued		<b>√</b>	
			2 thru 4, include docu				
5.	Is the site currently u	ndergoing deve	lopment?				
					Box 2		
					YES	NO	
6.	Is the current site use Restricted-Residentia		n the use(s) listed below and Industrial	?	$ \checkmark $		
7.	Are all ICs in place a	nd functioning a	s designed?	$\mathbf{Z}'$			
IF THE ANSWER TO EITHER QUESTION 6 OR 7 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.							
AC	Corrective Measures V	Vork Plan must	be submitted along with	n this form to address th	nese issı	ues.	
Cia	nature of Owner Pome	edial Party or De	signated Representative	. ————————————————————————————————————			

		Box 2	A
•		YES	NO
8.	Has any new information revealed that assumptions made in the Qualitative Exposure Assessment regarding offsite contamination are no longer valid?		$\checkmark$
	If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form.		
9.	Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years)	✓	
	If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions.		

SITE NO. C241162 Box 3

#### **Description of Institutional Controls**

<u>Parcel</u> <u>Owner</u> <u>Institutional Control</u>

268-1 Purves Street Owners LLC

Ground Water Use Restriction Landuse Restriction Monitoring Plan Site Management Plan

O&M Plan

Soil Management Plan IC/EC Plan

Intuitional controls mandate operation, maintenance, monitoring and reporting measures for all Engineering controls. They provide restriction on site usage and prevent future exposure to remaining contamination by controlling subsurface disturbances.

The site may be used for restricted residential as described in 6 NYCRR part 375-1.8(g)(2)(ii), commercial as described in 6 NYCRR part 375-1.8(g)(2)(iii) and industrial as described in 6 NYCRR part 375-1.8(g)(2) (iV). All engineering Controls (ECs) must be operated and maintained as specified in the site management plan(SMP). All ECs must be inspected at a frequency and in a manner defined in the SMP. The use of groundwater underlying the property is prohibited without necessary water quality treatment as determined by the NYSDOH or the New York City Department of Health and Mental Hygiene to render it safe for use as drinking water or for industrial purposes, and the user first notify and obtain written approval to do so from the Department. Groundwater and other environmental or public health monitoring must be performed as defined in the SMP. Data and information pertinent to Site Management of the Controlled property must be reported at the frequency and in a manner defined in the SMP. All future activities on the property that will disturb remaining contaminated material must be conducted in accordance with the SMP. Monitoring to assess the performance and effectiveness of the remedy must be performed as defined in the SMP. Operation, maintenance, monitoring, inspection, and reporting of any mechanical or physical components of the remedy shall be performed as defined in the SMP. Access to the site must be provided to agents, employees or other representatives of the State of New York with reasonable prior notice to the property owner to assure compliance with the restriction identified by this environmental easement.

Box 4

#### **Description of Engineering Controls**

<u>Parcel</u> <u>Engineering Control</u>

268-1

Vapor Mitigation Cover System

Engineering controls include a composite cover system to prevent future exposure to the residual contamination remaining in place and a submembrane depressurization system to mitigate soil vapor intrusion.

Box	5
-----	---

	Periodic Review Report (PRR) Certification Statements
1.	I certify by checking "YES" below that:
	a) the Periodic Review report and all attachments were prepared under the direction of, and reviewed by, the party making the Engineering Control certification;
	b) to the best of my knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted engineering practices; and the information presented is accurate and compete.
	YES NO
	$\mathbf{Z}$
2.	For each Engineering control listed in Box 4, I certify by checking "YES" below that all of the following statements are true:
	(a) The Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;
	(b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment;
	(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;
	(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and
	(e) if a financial assurance mechanism is required by the oversight document for the site, the mechanism remains valid and sufficient for its intended purpose established in the document.
	YES NO
	$\mathbf{Z}'$
	IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.
	A Corrective Measures Work Plan must be submitted along with this form to address these issues.
	Signature of Owner, Remedial Party or Designated Representative Date

#### IC CERTIFICATIONS SITE NO. C241162

Box 6

#### SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal

David Brause	at 52 Vanderbilt Ave, NY, NY 10017
print name	print business address
am certifying asOwner	(Owner or Remedial Party)
for the Site named in the Site Detail  Digitally signed by Div. cn-David A. Bra ou, email-dable brack Date: 2024.12.30 14:  Signature of Owner, Remedial Part Rendering Certification	David A. Brause use, o=Brause Realty, serealty.com, c=US 40:05-05'00'  12/30/24

#### **EC CERTIFICATIONS**

Box 7

### **Professional Engineer Signature**

I certify that all information in Boxes 4 and 5 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

I JASON HAYES at 368 print name	Ninth Aur , 8TH FL , NEW York , NY print business address
am certifying as a Professional Engineer for the	(Owner or Remedial Party)
Signature of Professional Engineer, for the Owner a Remedial Party, Rendering Certification	Dagage Date (Required for PE)

## Enclosure 3 Periodic Review Report (PRR) General Guidance

#### I. Executive Summary: (1/2-page or less)

- A. Provide a brief summary of site, nature and extent of contamination, and remedial history.
- B. Effectiveness of the Remedial Program Provide overall conclusions regarding;
  - 1. progress made during the reporting period toward meeting the remedial objectives for the site
  - 2. the ultimate ability of the remedial program to achieve the remedial objectives for the site.

#### C. Compliance

- 1. Identify any areas of non-compliance regarding the major elements of the Site Management Plan (SMP, i.e., the Institutional/Engineering Control (IC/EC) Plan, the Monitoring Plan, and the Operation & Maintenance (O&M) Plan).
- 2. Propose steps to be taken and a schedule to correct any areas of non-compliance.

#### D. Recommendations

- 1. recommend whether any changes to the SMP are needed
- 2. recommend any changes to the frequency for submittal of PRRs (increase, decrease)
- 3. recommend whether the requirements for discontinuing site management have been met.

#### II. Site Overview (one page or less)

- A. Describe the site location, boundaries (figure), significant features, surrounding area, and the nature extent of contamination prior to site remediation.
  - B. Describe the chronology of the main features of the remedial program for the site, the components of the selected remedy, cleanup goals, site closure criteria, and any significant changes to the selected remedy that have been made since remedy selection.

#### III. Evaluate Remedy Performance, Effectiveness, and Protectiveness

Using tables, graphs, charts and bulleted text to the extent practicable, describe the effectiveness of the remedy in achieving the remedial goals for the site. Base findings, recommendations, and conclusions on objective data. Evaluations and should be presented simply and concisely.

#### IV. IC/EC Plan Compliance Report (if applicable)

- A. IC/EC Requirements and Compliance
  - 1. Describe each control, its objective, and how performance of the control is evaluated.
  - 2. Summarize the status of each goal (whether it is fully in place and its effectiveness).
  - 3. Corrective Measures: describe steps proposed to address any deficiencies in ICECs.
  - 4. Conclusions and recommendations for changes.

#### B. IC/EC Certification

1. The certification must be complete (even if there are IC/EC deficiencies), and certified by the appropriate party as set forth in a Department-approved certification form(s).

#### V. Monitoring Plan Compliance Report (if applicable)

- A. Components of the Monitoring Plan (tabular presentations preferred) Describe the requirements of the monitoring plan by media (i.e., soil, groundwater, sediment, etc.) and by any remedial technologies being used at the site.
- B. Summary of Monitoring Completed During Reporting Period Describe the monitoring tasks actually completed during this PRR reporting period. Tables and/or figures should be used to show all data.
- C. Comparisons with Remedial Objectives Compare the results of all monitoring with the remedial objectives for the site. Include trend analyses where possible.
- D. Monitoring Deficiencies Describe any ways in which monitoring did not fully comply with the monitoring plan.
- E. Conclusions and Recommendations for Changes Provide overall conclusions regarding the monitoring completed and the resulting evaluations regarding remedial effectiveness.

#### VI. Operation & Maintenance (O&M) Plan Compliance Report (if applicable)

- A. Components of O&M Plan Describe the requirements of the O&M plan including required activities, frequencies, recordkeeping, etc.
- B. Summary of O&M Completed During Reporting Period Describe the O&M tasks actually completed during this PRR reporting period.
- C. Evaluation of Remedial Systems Based upon the results of the O&M activities completed, evaluated

- the ability of each component of the remedy subject to O&M requirements to perform as designed/expected.
- D. O&M Deficiencies Identify any deficiencies in complying with the O&M plan during this PRR reporting period.
- E. Conclusions and Recommendations for Improvements Provide an overall conclusion regarding O&M for the site and identify any suggested improvements requiring changes in the O&M Plan.

#### VII. Overall PRR Conclusions and Recommendations

- A. Compliance with SMP For each component of the SMP (i.e., IC/EC, monitoring, O&M), summarize;
  - 1. whether all requirements of each plan were met during the reporting period
  - 2. any requirements not met
  - 3. proposed plans and a schedule for coming into full compliance.
- B. Performance and Effectiveness of the Remedy Based upon your evaluation of the components of the SMP, form conclusions about the performance of each component and the ability of the remedy to achieve the remedial objectives for the site.

#### C. Future PRR Submittals

- 1. Recommend, with supporting justification, whether the frequency of the submittal of PRRs should be changed (either increased or decreased).
- 2. If the requirements for site closure have been achieved, contact the Departments Project Manager for the site to determine what, if any, additional documentation is needed to support a decision to discontinue site management.

#### VIII. Additional Guidance

Additional guidance regarding the preparation and submittal of an acceptable PRR can be obtained from the Departments Project Manager for the site.