



Monthly Progress Report HIP Cleaners 169-47 137<sup>th</sup> Avenue – Queens, NY **BCP Site #C241166** August 2017

## **Activities Completed during the Reporting Period**

Coordinate pressure field extension test with Participant.

Gauged groundwater well locations to confirm groundwater direction/elevation. The IRM WE was accepted by NYSDEC on August 17, 2017 and subsequently sent to the repository.
Modifications to Work Plan and/or Schedule
None.
Issues Encountered
None.
Data Collected/Received during the Reporting Period
None.
Activities Undertaken in Support of Citizen Participation Plan
None.
Activities Planned for Next Reporting Period: