

**Monthly Progress Report**  
**HIP Rochdale Cleaners**  
**169-47 137th Avenue – Queens, NY**  
**BCP Site #C241166**  
**December 2017**

**Activities Completed during the Reporting Period**

Site visit to map out pressure field locations in coordination with Rochdale Village administrators. Communication with NYSDEC regarding the need for installation of a downgradient well.

**Modifications to Work Plan and/or Schedule**

None.

**Issues Encountered**

None.

**Data Collected/Received during the Reporting Period**

None.

**Activities Undertaken in Support of Citizen Participation Plan**

None.

**Activities Planned for Next Reporting Period:**

Coordinate pressure field extension test.