DAILY INSPECTION REPORT

Report No. BKQM Multi Site: Former Kenneth Trading Corp (Site No. C241215A)

Division of Environmental Remediation STATE OF OPPORTUNITY Environ				Departm Environn Conserva	nental	NYSDEC Contract No. Superintendent:				
Site Location: Astor						NYSDEC PM:	Jolene Lo	zews	ski	
Site Location: Astoria, New York					Consultant PM: Jessica Beattie					
<u> </u>		r Condition	S			514	Consultant Site	e Inspecto	rs:	
General Description	Sunny 70 dograd	s AM	0	Sunny 0 degree		PM PM				
Temperature Wind	79 degree 7 MPH SV			MPH SV		PM	Hannah Lofgren			
Health & Safety										
If any box below is checked "Yes", provide explanation under "Health & Safety Comments".										
				N/	A					
Were there any exceeds	ances of the pe	rimeter air mo	nitorina	reported	on this d	ate?	*Yes	No x	N/	A
Were there any nuisano							*Yes	No x	N/	Α
Health & Safety Con	-						1	,	1	
- Wore proper PPE and		is safativ bat i	wooth or/	hiah hum	idity one	l biologi	aal (maaguita) s	20000100		
- wore proper PPE and	discussed trail	ic salety, not	weamer/	nign nun	iluity, and	ı biologi	cai (mosquito) (concerns.		
Summary of Work Performed Arrived at site: 07:00 De			De	eparted Site: 14:00						
Summary of Work P	enonnea	Anivedat	Sile.	07.00		De	sparted Site.	14.00		
 CDM Smith sampled existing wells MW-4, MW-5, and MW-13I. CDM Smith created the chain of custody (COC) and demobilized the site at the end of the day. Investigation derived waste was picked up by IRT at 13:45. 4 coolers of samples were picked up by the Pace Laboratories Courier at 13:10. 										
Equipment/Material If any box below is o	checked "Yes						Tracking Con	nments"		
Were there any vehicles which did not display proper D.O.T numbers and placards? Yes No NA x										
•	Were there any vehicles which were not tarped?			Yes	No NA x					
Were there any vehicles	which were no	ot decontamin	ated pric	or to exitin	ng the wo	rk site?	Yes	No	N/	A x
Personnel and Equip	pment				•					
Individual		Co	mpany			Tra	ade	Tota	al Hou	urs
Julie Duffy			M Smith			Scie	entist		7	
Hannah Lofgre	en		M Smith				ineer		7	
Maggie Tan	_		M Smith M Smith				ineer entist		7	
Kevin Griffith		CD				3016				
Equipment Descr	Imported/D	.	Conti	ractor/Ver	naor		Quantity	<u> </u>	Jsed	Daily
Material Description	elivered to Site			aste Profi Applicab			rce or Disposal ty (If Applicable)	Dail Load	s	Weigh t (tons)*
Visitors to Site: None										
Name Representing Entered Exc				clusion/	clusion/CRZ Zone					
		Yes No								
Site Representatives							•	•		



Proposed Sampling Locations

Former Kenneth Trading Corp. 11-35 31st Dr., Astoria, New York

NYSDEC Site No. C241215A

Report No. BKQM Multi Site: Former Kenneth Trading Corp (Site No. C241215A)

Date: 07/01/2025

Hannah Lofgren **CDM Smith Project Schedule Comments** Sampling completed at Former Kenneth Trading Corp. Field team plans to mobilize to Former Sterling Transformer Corp on 7/2/2025. **Issues Pending** Interaction with Public, Property Owners, Media, etc. None. Work Area roposed Sub Slab and Indoor Air Sample 11-15 31st Drive Astoria, NY 11106 11-21 31st Drive Astoria, NY 11106 11-38 31st Drive Astoria, NY 11106 11-44 31st Drive Astoria, NY 11106 31-01 Vernon Boulevard Long Island City, NY 11106 31-23 Vernon Boulevard Astoria, NY 11106 Astoria, NY 11106 31-29 Vernon Boulevard Astoria, NY 11106 31-43 VERNON BOULEVARD, Astoria, NY, USA 31-59 Vernon Blvd, Long Island City, NY 11106 31-14 12th Street Long Island City, NY 11106 31-18 12th Street Astoria, NY 11106 31-20 12th Street Astoria, NY 11106 31-22 12th Street Astoria, NY 11106 11-38 31st A 31-26 12th Street Astoria, NY 11106 11-42 31st Avenu 31-28 12th Street Astoria, NY 11106 31-30 12th Street Astoria, NY 11106 Astoria, NY 11100 31-32 12th Street Astoria, NY 11106 31-34 12th Street Astoria, NY 11106 31-17 12th St, Long Island City, NY 11106 31-29 12th St, Long Island City, NY 11106 31-31 12th St, Astoria, NY 11106 31-33 12th St, Astoria, NY 11106 If the proposed sub-slab and indoor air sampling locations receive poor response from canvassing seven additional backup locations have been ide and are marked on the figure. 11-15 Broadway Astoria, NY 11106

Proposed Sub Slab and Indoor Air Sample

Existing Monitoring Wells to be Sampled

Back-up Sub Slab and Indoor Air Sample

0 30 60 120 180 240

New York Tax Parce I- Propo

Proposed Soil Gas Sample Location

■ New York Tax Parcels

CDM Smith




Photo 1: PFAS, VOC, SVOC, Pesticides, Metals, PCB and 1,4-Dioxane Analysis COC for 7/01/2025.



Photo 2: Low-Flow Groundwater Sampling at Monitoring Well MW-5.

Comments	
N/A	
Site Inspector(s): Hannah Lofgren	Date: 07/01/2025

Date: 07/01/2025

DAILY HEALTH CHECKLIST

Is social distancing being practiced?	Yes ⊠	No □
Is the tail gate safety meeting held outdoors?	Yes ⊠	No □
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes ⊠	No □
Were personal protective gloves, masks, and eye protection being used?	Yes ⊠	No □
Are sanitizing wipes, wash stations or spray available?	Yes ⊠	No □
Have any workers/visitors been excluded based on close contact with individuals diagnosed with COVID-19, have recently traveled to restricted areas or countries, or are symptomatic (fever, chills, cough/shortness of breath)?	Yes □	No ⊠
Comments:		

REMEDIAL ACTIVITIES AT PROPERTIES

 Have anyone at this location been tested and confirme COVID-19? 	ed to have	No ⊠
2. Is anyone at this location isolated or quarantined for C	OVID-19? Yes □	No ⊠
Has anyone at this location had contact with anyone k COVID-19 in the past 14 days?	nown to have Yes □	No ⊠
 Does anyone at this location have any symptoms of a infection (e.g., cough, sore throat, fever, or shortness of 		No ⊠
5. Does the Department and its contractors have your pe the property at this time?	rmission to enter Yes □	No ⊠
 If Yes to <u>any</u> of 1-4 above: If it is <u>not</u> critical that service/entry be carried out immed be postponed until the risk of COVID-19 is lower, or call accomplished remotely/without entry, postpone or conwithout entry. If it <u>is</u> critical that service/entry be carried out immediate occupants that as a precaution and for our own protection personnel will be donning appropriate PPE* (including protection) - and do so prior to entry. 	n be duct service Yes □ tely, advise tion, project	No 🗆

Date: 07/01/2025

Comments:			
NUISANCE CHECKLIST			
Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No ⊠	N/A□
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM 🗆	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No ⊠	N/A□
Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is the site supplied with green power and is it properly installed and/or maintained?	Yes □	No □	N/A⊠
Is the site employing 2007 or newer or retrofitted diesel trucks?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is equipment properly maintained and operated by trained personnel?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points?	ам □	РМ 🗆	N/A⊠
Are products and materials appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠



DAILY INSPECTION REPORT

Page **7** of **7**

Report No. BKQM Multi Site: Former Kenneth Trading Corp (Site No. C241215A)

Are resiliency features included in the design or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Are appropriate metrics documented for inclusion on Form A, Summary of Green Remediation Metrics, by the CONTRACTOR?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
<u>Comments:</u>			