



## **Daily Report for October 1, 2019**

**Far Rockaway Project  
20-02 Mott Avenue  
Far Rockaway, NY  
BCP #C241224**

**1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.**

- Pouring concrete footings in Building C—grids A1 and B1 and 2.
- Iron work within Buildings B and C.

**2. Locations of work and quantities of material imported and exported from the Site.**

- No materials were exported or imported from the site today.

**3. A summary of any and all complaints with relevant details (names, phone numbers).**

No complaints.

**4. A summary of CAMP findings (air and dust readings).**

No elevated PID or dust readings were identified.

**5. An explanation of notable Site conditions.**

Today's work was overseen by Jason Cooper of CA RICH. No conditions of note were observed.

**6. Planned Activities**

- Continue formwork and waterproofing for Building B and C footings.

## Photo Log

Photo 1-  
View of  
Building B  
excavation  
area. View is  
looking  
towards the  
north.



Photo 2-  
View of  
Building B  
excavation  
area. View is  
looking  
towards the  
north.





Photo 3-  
View of  
Building B  
excavation  
area. View is  
looking  
towards  
northwest.



Photo 4 –  
View of  
Building C  
excavation  
near the  
southern  
portion of the  
building.  
View is  
looking west.





Photo 5 –  
View of the  
excavation in  
Building C.  
View is  
looking  
northwest.



Photo 6 –  
View of  
Building B.  
The view is  
looking  
towards the  
southeast.





Photo 7 –  
View of  
southeast  
corner of  
excavation of  
Building B.  
Note  
excavation at  
former bank.



Photo 8 –  
View of  
Building C  
excavation.  
View is  
looking  
south.

