

Progress Report No. 68
Kissena Center Site
Queens, New York 11355
Brownfield Cleanup Program Site No. C241231
Reporting Period: June 2025

1. Introduction

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) is submitting this monthly progress report on behalf of Kimco Kissena Center, LLC (the Participant), in accordance with the June 25, 2019 Brownfield Cleanup Agreement. This monthly progress report summarizes work performed at the Kissena Center Site (the site) for the month of June 2025.

The site is located at 46-15 to 46-31 Kissena Boulevard in the Flushing neighborhood of Queens, New York and is identified as Tax Block 5208, Lot 45 on the Queens Borough Tax Map. The site encompasses an area of about 68,200 square feet (1.57 acres) and is occupied by an approximately 22,520-square-foot one-story shopping center and an asphalt-paved parking lot. Commercial tenants include Gold City Supermarket, Star Laundromat and Cleaners, Ming Xing Gift Shop, and Fay Da Bakery. The site is bordered by residential homes followed by Union Street and Holly Avenue to the north, an asphalt-paved parking lot and residential homes followed by Laburnum Avenue and Union Street to the east, a two-story restaurant followed by Kissena Boulevard to the south, and a two-story commercial building occupied by multiple restaurants followed by Holly Avenue and Kissena Boulevard to the west. A Site Location Map is attached as Figure 1.

2. Remedial Actions Relative to the Site during this Reporting Period

Langan evaluated groundwater, soil vapor, sub-slab soil vapor and co-located indoor air sample analytical data from the supplemental investigation. Langan started preparing the draft Supplemental Investigation Report.

3. Actions Relative to the Site Anticipated for the Next Reporting Period

Langan will submit groundwater, soil vapor, sub-slab soil vapor and co-located indoor air sampling data tables, figures, and laboratory analytical reports to the New York State Department of Environmental Conservation (NYSDEC) and the New York State Department of Health (NYSDOH). We will schedule a meeting with NYSDEC to discuss the sampling results and proposed next steps. Langan will continue preparing the Supplemental Investigation Report and subsequent revised Remedial Action Work Plan.

4. Approved Activity Modifications (changes of work scope and/or schedule)

None.

5. Results of Sampling, Testing, and Other Relevant Data

Groundwater, soil vapor, sub-slab soil vapor, and co-located indoor air sampling data was received and data validation was completed. Langan submitted electronic data deliverables (EDD) to NYSDEC's EQUIS™ database on June 11, 2025.

6. Deliverables Submitted During This Reporting Period

None.

7. Information Regarding Percentage of Completion

The BCP project is approximately 10% complete.

8. Unresolved Delays Encountered or Anticipated That May Affect the Schedule and Mitigation Efforts

None.

9. Citizen Participation Plan Activities during This Reporting Period


None.

10. Activities Anticipated in Support of the CPP for the Next Reporting Period


None.

11. Miscellaneous Information

None.



A
B
C
D



LEGEND

 APPROXIMATE SITE BOUNDARY

NOTE

1. BASEMAP IS REFERENCED FROM UNITED STATES GEOLOGICAL SURVEY 7.5-MINUTE SERIES FLUSHING AND JAMAICA QUADRANGLE MAPS, DATED AUGUST 2016.

LANGAN
Langan Engineering, Environmental, Surveying,
Landscape Architecture and Geology, D.P.C.
21 Penn Plaza, 360 West 31st Street, 8th Floor
New York, NY 10001
T: 212.479.5400 F: 212.479.5444 www.langan.com

Project
**46-15 TO 46-31
KISSENA BOULEVARD**
BLOCK No. 5208, LOT No. 45
QUEENS NEW YORK

Figure Title
**SITE LOCATION
MAP**

Project No.
170564601
Date
12/28/2018
Drawn By
NEK
Checked By
ELS

Figure No.
1
Sheet 1 of 1