

ATTACHMENT A
SECTION I: PROPERTY INFORMATION

ATTACHMENT A

SECTION I: PROPERTY INFORMATION

Item 2: Property Maps

Figure A-1 is the required United States Geological Survey (USGS) 7.5-minute quadrangle map showing the location of the site.

Figure A-2 provides a site base map with scale, north arrow orientation, date, and location of the site with respect to adjacent streets and roadways.

Figure A-3 provides a site base map that shows i) proposed brownfield site boundary line, with adjacent property owners clearly identified; and ii) surrounding land uses.

Figure A-4 provides the Queens Borough Tax Map.

Figure E-5 provides a site survey with lands under water depicted.

Item 8: Prior Remediation

Six closed and one active New York State Department of Environmental Conservation (NYSDEC) spills are associated with the site and summarized in the table below.

Parcel/Tax Block + Lot	Spill No.	Spill Date	Closure Date	Material	Notes
57-00 Block 2601, Lot 6	94-11004	11/17/1994	11/17/1994	Gasoline	Release of unknown amount of gasoline. NYSDEC records do not indicated whether remedial work occurred.
57-00 Block 2601, Lot 6	97-09690	11/20/1997	1/8/1998	Diesel Fuel	Release of unknown amount of diesel fuel. NYSDEC records do not indicated whether remedial work occurred.
57-57 Block 2602, Lot 68	98-12248	1/4/1999	7/12/2006	Petroleum	Petroleum impacted soil identified once underground storage tank (UST) removed. Impacted soil removed.
57-00 Block 2601, Lot 6	07-09978	12/18/2007	12/28/2007	Petroleum	UST failed tank tightness test. UST repaired and re-tested. UST subsequently passed tightness test.
57-00 Block 2601, Lot 6	08-08170	10/21/2008	10/27/2012	Petroleum	Illegal petroleum storage and refueling operations. Impacted soil identified. Remediation occurred.
57-00 Block 2601, Lot 6	13-06438	9/19/2013	2/12/2014	Diesel	Impacted soil and pea gravel encountered in a tank vault following removal of a 4,000-gallon diesel UST. Spill reportedly remediated.
57-05 Block 2602, Lot 72	211-0517	3/17/2022	–	Diesel	Analytical results from post UST removal soil samples indicated a potential petroleum release.

- NYSDEC Spill No. 94-11004 was reported November 17, 1994 due to the release of an unknown volume of gasoline on the 57-00 parcel (Block 2601, Lot 6). The spill was administratively closed on November 17, 1994.
- NYSDEC Spill No. 97-09690 was reported November 20, 1997 after the release of an unknown volume of diesel fuel on soil on the 57-00 parcel (Block 2601, Lot 6). No further information regarding the spill was provided. The spill was administratively closed on January 8, 1998.
- NYSDEC Spill No. 98-12248 was reported on January 4, 1999 after petroleum impacted soil was identified during the removal of a UST on the 57-57 parcel (Block 2602, Lot 68) while under the Boro Lumber Company occupancy. Petroleum impacted soil was removed and endpoint samples were collected. The spill was remediated and was administratively closed on July 12, 2006.
- NYSDEC Spill No. 07-09978 was reported after a UST failed a tank tightness test on December 18, 2007 on the 57-00 parcel (Block 2601, Lot 6). The tank lines were re-tested and it was determined that the vent line failed due to a loose fitting. According to a NYSDEC report, evidence of petroleum impacts to the subsurface were not identified by Larry E. Tyree Co., Inc. (the contracted environmental services provider of the site occupant). The spill was administratively closed on December 28, 2007 following report submission by Larry E. Tyree Co.

- NYSDEC Spill No. 08-08170 was reported October 21, 2008 after the report of an active release of petroleum substances and illegal storage and refueling of vehicles on the 57-00 parcel (Block 2601, Lot 6). A limited subsurface investigation was reportedly completed in 2009 that identified petroleum impacts in soils from surface grade to about eight feet below grade surface. About 381.04 tons of petroleum impacted soil was reportedly excavated and disposed of in 2010. Documentation of soil and groundwater samples were collected post remediation and the spill was administratively closed on October 27, 2012.
- NYSDEC Spill No. 13-06438 was reported on September 19, 2013 after diesel impacted soil and pea gravel was identified in a tank vault during the removal of a 4,000-gallon UST on the 57-00 parcel (Block 2601, Lot 6). A closure report summarizing the remedial work and analytical data was completed by Preferred Environmental Services. The spill was administratively closed February 12, 2014.
- NYSDEC Spill No. 211-0517 was reported on March 17, 2022 after the receipt of laboratory analytical results which indicated a diesel release on the 57-05 parcel (Block 2602, Lot 72). Soil samples were collected during the removal of one 3,500-gallon diesel UST. This spill remains open with NYSDEC.

Item 9: Lands under Water

A small section of land is beneath water on the southwestern end of the 57-00 parcel (Block 2601, Lot 6). A map depicting the section of lands under water is included as **Figure E-5**.

Item 12: Easements

The NYC Digital Tax Map did not identify easements on the subject property. However, a NYSDEC Order on Consent (OOC) exists for Tax Block 2601, Lots 1 and 6 (parcels 57-00 and 58-20). The OOC was established in relation to a required tidal wetlands management area on the western side of the Tax Lots. Impacted soil may be located within this OOC area. Applicant will consult with NYSDEC on particular investigation and remediation protocols required within the tidal wetlands management area.

Item 14: Property Description and Environmental Assessment Narrative

Location

The site is located at 57-00 (Block 2601, Lot 6), 58-20 (Block 2601, Lot 1), and 57-05 (Block 2602, Lot 72) 47th Street, Maspeth, Borough of Queens, New York. The Site is bisected by 47th Street, the 57-00 and 58-20 parcels are located on the western side of 47th Street and the 57-05 parcel is located on the eastern side of 47th Street. The site is bound to the north by 58th Road, followed by the NYC Department of Sanitation Queens West 5 Garage; to the east by a moving and storage facility and also a delivery company; to the south by the NYC Department of Environmental Protection Newtown Creek aeration facility and 57-57 47th Street (former eatery and retail store); to the west by Newtown Creek (a National Priorities List [NPL] site). Surrounding properties include single- and multi-story buildings occupied by industrial and commercial occupants.

Site Features

The site is a combined 3.74 acres and is fully vacant. Improvements at the site include buildings associated with a former concrete recycling facility including offices and a concrete testing laboratory and vehicle maintenance garage on parcel 57-00 (Block 2601, Lot 6). A garage building with office space is located on the 57-05 parcel (Block 2602, Lot 72). Permanent features are not located on the 58-20 parcel (Block 2601, Lot 1).

Current Zoning and Land Use

According to the New York City (NYC) Planning Commission Zoning Map 13b, the site is located in an M3-1 manufacturing zoning district. M3 districts are designated as areas with heavy industries that generate noise, traffic or pollutants. Typical uses include power plants, solid waste transfer facilities and recycling plants, and fuel supply depots.

Past Use of the Site

57-00 (Block 2601, Lot 6) and 58-20 (Block 2601, Lot 1)

These two tax lots were first developed as a fertilizer works circa 1897, followed by an oil depot circa 1914-1936. The building currently located on the 57-00 parcel (Block 2601, Lot 6) was constructed in mid-1960s and was used for truck parking. Truck repair occurred on the 57-00 parcel (Block 2601, Lot 6) from approximately 1982 until operations ceased in 2021. Concrete recycling began on the 57-00 parcel (Block 2601, Lot 6) circa 2004 and continued simultaneously with truck repair operations until 2021.

Probable and Confirmed Contaminants Associated with Former Operations

Metals: Heavy metals including mercury, arsenic, lead, and nickel were identified within soil and groundwater samples collected on Block 2601, Lot 1 and/or Lot 6. The presence of these heavy metals in soil and groundwater may be associated with historical fertilizer works operations conducted on the site from circa 1902 to 1914.

Semi-Volatile Organic Compounds (SVOCs): SVOCs were identified in surficial soils and in groundwater across this portion of the site. Their presence in soil and groundwater at the site may be related to former truck repair operations and oil depot operations on both tax lots (Block 2601; Lot 6 & Block 2601; Lot 1) and former concrete recycling operations on the northern end of Lot 6 and the entirety of Lot 1. Former truck repair occurred from circa 1976 through 2021 and Valvoline Oil Co. operated circa 1914 to 1936.

Volatile Organic Compounds (VOCs): Chlorinated solvents and petroleum-related (ethylbenzene in groundwater) contamination was identified in soil vapor and/or groundwater on this portion of the site. The presence of these compounds in soil vapor and/or groundwater may be attributed to former vehicle maintenance/repair operations which occurred on Block 2601; Lot 6 circa 1976 through 2001. Chlorinated solvent-based degreasers may have been utilized in association with these operations.

NYSDEC Programs:

- Petroleum Bulk Storage Program
- Solid Waste Disposal Facility
- Closed Spill Cases
- Order of Consent

57-05 (Block 2602, Lot 72)

The 57-05 parcel also historically operated as a fertilizer works (circa 1897) and oil depot (circa 1914-1936) along with the 57-00 parcel (Block 2601, Lot 6). A motor freight station operated on this parcel circa 1963 and 1982 to 2006. From 2006 to 2021 the parcel was utilized to store materials, maintain vehicles, and stage equipment/trucks.

One 4,500-gallon diesel UST was removed in December 1998. A 550-gallon waste oil UST and a 3,500-gallon diesel UST were removed from the parcel February 21, 2022.

Probable and Confirmed Contaminants Associated with Former Operations

Metals: Heavy metals were not identified within soils on this portion of the site. However, iron, manganese, and sodium were identified in site groundwater. These metals are likely naturally occurring on the site.

SVOCs: SVOCs were not identified within soil or groundwater on this portion of the site.

VOCs: Soil and groundwater within this portion of the site contain petroleum-related VOC contamination. These impacts are potentially attributed to former underground storage tanks and/or the former oil depot on this portion of the property. Sub-slab vapors were not identified. VOC impacts may be associated with the historical motor freight station or vehicle maintenance operations that occurred on this portion of the site

NYSDEC programs:

- Petroleum Bulk Storage Program
- Closed and Open Spill Database Cases

Site Geology and Hydrogeology

The United States Department of Agriculture indicates the surficial geology of the site consists of predominantly Urban Land, with a till substratum and also Urban land, tidal marsh. According to Bakersville's Bedrock and Engineering Maps of New York County and Parts of Kings and Queen Counties, New York, and Parts of Bergen and Hudson Counties, New Jersey", dated 1994, indicates the bedrock underlying the site is part of the Hartland Formation. The Hartland Formation is comprised of micaschist and quartz-feldspar granulite, with localized intrusions of granite and pegmatite. Geological surface features (i.e. outcroppings) were not identified.

Soil borings completed as part of a Phase II Environmental Site Investigation (ESI) performed by Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) in July 2021 indicated the site is underlain by fill material consisting of fine-grained sand with varying amounts of fine gravel, silt, brick, wood, and concrete was identified from below surface grade to depths ranging from about 4 to 16 feet bgs. Native soil, typically consisting of fine-grained sand and silt with varying amounts of medium sand, peat and fine gravel was identified beneath the fill layer to the

boring termination depths, ranging from 5 to 20 feet bgs. Peat was detected in some boring locations at a depth of approximately 11.5 feet bgs.

Groundwater was encountered at depths of approximately 7 to 10.5 feet below grade during Langan's Phase II ESI. Groundwater flow is suspected to be westerly towards Newtown Creek; groundwater flow direction was not evaluated as part of Langan's Phase II ESI.

Environmental Assessment

Based on the findings of previous subsurface investigations, the primary contaminants of concern on the site are volatile organic compound (VOC), semi-volatile organic compound (SVOC), and metals in soil, groundwater and/or soil vapor on all three Tax Block/Lots that comprise the site. The primary contaminants of concern for the site have been detected in soil, groundwater and/or soil vapor at concentrations exceeding the applicable regulatory criteria for the intended future use of the site, below are further details regarding contaminants of concern and impacted media. Reports detailing the findings below are included in **Attachment B**.


A findings summation is below:

- Field Evidence of Petroleum Impacts:
 - Odors, staining, and elevated photoionization detector (PID) readings were identified in soil borings installed on the southeastern end of parcel 57-00 (Block 2601, Lot 6) and the northeastern end of parcel 57-05 (Block 2602, Lot 72). The soil boring installed within the southeastern end of the 57-00 parcel (Block 2601, Lot 1) was installed within a former UST grave (SB01). Soil boring SB02 located within the 57-00 parcel (Block 2601, Lot 6) building (SB02). The soil boring installed within the northeastern end of the 57-05 parcel was located near a UST which was removed in March 2022 (SB04). These soil borings are depicted on **Figure E-1** located in **Attachment E**.
 - Following the removal of a 3,500-gallon diesel UST from the 57-05 parcel, staining, odors, and PID readings of up to 52 parts per million were identified within the excavation.
- Soil:
 - VOCs, SVOCs, and metals were detected in soil on the 57-00, 58-20, and 57-05 parcels at concentrations above the New York State Department of Environmental Conservation (NYSDEC) Title 6 Part 375 Protection of

Groundwater Soil Cleanup Objectives (SCOs), Restricted Commercial Use SCOs (Commercial Use SCOs), and/or Restricted Industrial Use SCOs (Industrial SCOs).

- VOCs which were greater than their respective Protection of Groundwater SCOs include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, acetone, ethylbenzene, n-butylbenzene, n-propylbenzene, total xylenes, and methyl ethyl ketone.
- One SVOC (chrysene) was detected above the Protection of Groundwater SCO but no other criteria. SVOCs were detected in soil throughout the 57-00 and 58-20 parcels at concentrations greater than Commercial Use SCOs and/or Industrial Use SCOs. SVOCs which were greater than their respective Commercial Use SCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, chrysene, dibenz(a,h)anthracene, and ideno(1,2,3-cd)pyrene. SVOCs which were identified greater than their respective Industrial Use SCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, dibenzo(a,h)anthracene, and ideno(1,2,3-cd)pyrene. SVOCs detected several times greater than the Industrial Use SCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, dibenzo(a,h)anthracene, and ideno(1,2,3-cd)pyrene.
- One metal (selenium) was detected at a concentration above the Protection of Groundwater SCO. Metals in four soil samples were detected several times greater than the Industrial Use SCO. These four samples were collected as per Langan's November 2021 Phase II ESI and are identified as samples SB10_3-4, SB07_8-9, LB-10 (6.5-7.0), and USTB-4; **Figure E-1** depicts these locations and sample concentrations. The metals identified at unusually high concentrations include arsenic, lead and mercury.
- Groundwater:
 - Groundwater sample locations are depicted in **Figure E-2**. Groundwater sample MW02 was collected from the 57-00 parcel and contained the VOCs 1,2-dichloropropane, isopropylbenzene, ethylbenzene, and n-propylbenzene at concentrations greater than their respective NYSDEC Technical Operational Guidance Series 1.1.1 Ambient Water Quality Standards and Guidance Values (SGVs). Two groundwater samples collected from the 57-05 parcel contained the VOCs methyl tert-butyl ether and toluene at concentrations greater than the SGVs.

- The Underground Injection Control (UIC) structure on the 57-05 parcel was sampled; liquids within this structure contained toluene, which was also detected in groundwater above its SGV in a nearby temporary well point TW-8. The UIC structure is likely the source of toluene in nearby groundwater.
- Various metals were identified in unfiltered groundwater at concentrations greater than their respective SGVs on all three parcels. Filtered metals (antimony, iron, manganese, sodium, and arsenic) were detected at concentrations greater than their respective SGVs
- Soil Vapor:
 - Sub-slab soil vapor (SSV) and co-located indoor air samples were collected on May 12, 2022 from structures on parcels 57-00 (Block 2601, Lot 6) and 57-05 (Block 2602, Lot 72). Sample locations and concentrations are included in **Figure E-3**. Laboratory results from the SSV and IA data for samples SSV03/IA03 were compared to the appropriate NYSDOH Soil Vapor/Indoor Air Matrices for vinyl chloride, the resulting recommendation is to mitigate. The SSV03/IA03 sample was collected on the 57-00 parcel (Block 2601, Lot 6).
 - Due to the vinyl chloride concentration in the SSV03 sample, the reporting limits for compounds 1,1-dichloroethene, cis1,2-dichloroethene, and trichloroethene exceeded the minimum concentrations for SSV for which mitigation is recommended regardless of indoor air concentration for their respective matrices.



Legend

Approximate Site Boundary



NOTES:
1. BASEMAP ADAPTED FROM UNITED STATES GEOLOGICAL SURVEY (USGS) 7.5-MINUTE SERIES TOPOGRAPHICAL MAPS, BROOKLYN, NEW YORK, QUADRANGLE.

LANGAN

21 Penn Plaza, 360 West 31st Street, 8th Floor
New York, NY 10001-2727
T: 212.479.5400 F: 212.479.5444 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying,
Landscape Architecture and Geology, D.P.C.
Langan International LLC

Collectively known as Langan

Project

**57-00, 57-05
and 58-20 47th Street**

BLOCK Nos. 2601; 2602
LOT Nos. 1 and 6; 72

QUEENS

NEW YORK

Figure Title

**SITE LOCATION
MAP**

Project No.

100965501

Date

3/21/2022

Scale

1"=2,000'

Drawn By

MG

Submission Date

Figure No.

A-1



Legend
Approximate Site Boundary

NOTES:
1. WORLD AERIAL IMAGERY BASEMAP IS PROVIDED THROUGH LANGAN'S
ESRI AND ARCGIS SOFTWARE LICENSING AND ARCGIS ONLINE.

LANGAN
Langan Engineering, Environmental, Surveying,
Landscape Architecture and Geology, D.P.C.
21 Penn Plaza, 360 West 31st Street, 8th Floor
New York, NY 10001
T: 212.479.5400 F: 212.479.5444 www.langan.com

Project
**57-00, 57-05
and 58-20 47th Street**
BLOCK Nos. 2601; 2602
LOT Nos. 1 and 6; 72
QUEENS
NEW YORK

Figure Title		Figure No.	
SITE PLAN		Project No.	100965501
		Date	3/21/2022
		Scale	1"=100'
		Drawn By	MG


WARNING: It is a violation of the NYS Education Law Article 145 for any person, unless acting under the direction of a licensed professional engineer, land surveyor or geologist, to alter this item in any way.






LANGAN

Langan Engineering, Environmental, Surveying,
Landscape Architecture and Geology, D.P.C.
21 Penn Plaza, 360 West 31st Street, 8th Floor
New York, NY 10001
T: 212.479.5400 F: 212.479.5444 www.langan.com



WARNING: IT IS A VIOLATION OF THE NYS
EDUCATION LAW ARTICLE 145 FOR ANY PERSON,
UNLESS HE IS ACTING UNDER THE DIRECTION OF A
LICENSED PROFESSIONAL ENGINEER, TO ALTER THIS
ITEM IN ANY WAY.



ATTACHMENT B
HISTORICAL REPORTS

(Previously Submitted, not included with this submission)

ATTACHMENT C
SECTION II: PROJECT DESCRIPTION

ATTACHMENT C

SECTION II: PROJECT DESCRIPTION

Item 4: Project Description

The purpose of this project is to investigate and remediate this contaminated brownfield site by implementing remedial measures that are protective of human health and the environment. The remedial program will start with the preparation of a Remedial Investigation Work Plan (RIWP) that is being submitted concurrently with this Brownfield Cleanup Program (BCP) Application. Site investigation will commence in 2022 once this application is determined to be suitable and approved. If the site is accepted into the BCP and the Brownfield Cleanup Agreement is fully executed by October 15 2022, the remedial investigation will begin on or around November 1, 2022. A remediation will promptly follow. It is anticipated that a certificate of completion will be obtained by the end of 2023 (i.e., December 31, 2023). After remediation, the two existing buildings on the site will be improved and leased and the areas outside of the buildings (with the exception of the wetland and buffer areas, to the extent improvements are restricted by the existing Order on Consent) will be improved for vehicle parking.

ATTACHMENT D
SECTION III: LAND USE FACTORS

ATTACHMENT D

SECTION III: LAND USE FACTORS

Item 1: Current Zoning

According to the New York City (NYC) Planning Commission Zoning Map 13b, the site is located in an M3-1 manufacturing zoning district. M3 districts are designated for areas with heavy industries that generate noise, traffic or pollutants. Typical uses include power plants, solid waste transfer facilities, recycling plants, and fuel supply depots.

Item 3: Current Use

The entirety of the site is currently vacant.

Item 4: Current Site Uses – Possible Contaminant Source Areas

The site is currently vacant. It became vacant in spring/summer 2021 when concrete aggregate recycling operations ceased. Past uses which likely impacted the Site include:

- **Petroleum Bulk Storage** historically occurred at the site. Circa 1914 to 1936, Valvoline Oil Company occupied the 58-20 parcel (Block 2601 Lot 1) and 57-05 parcels (Block 2602 Lot 72) with some auxiliary operations on the 57-00 parcel (Block 2601 Lot 6). Operations included the storage of oil in large capacity oil tanks and barrels. Soil staining and elevated photoionization detector (PID) readings were identified within the 58-20 parcel (Block 2601, Lot 1) in areas identified to have this former operation. Semi-volatile organic compounds (SVOCs) and total and dissolved metals were identified in groundwater and soil above their respective NYSDEC Ambient Water Quality Standards and Guidance Values (SGVs) and Commercial and Industrial Restricted Use Soil Cleanup Objectives (SCOs) within the former petroleum storage area. These SVOC and metal concentrations in soil and groundwater are greater than the intended future use criteria.
- **Historical Site Operations** included the use of the property as a fertilizer works circa 1897 to 1914. Following fertilizer works usage, the property was utilized as an oil depot for petroleum bulk storage (this use is described above). Following this use, parcels associated with the site were utilized for vehicle repair within several commercial garage bays within each building. The 57-00 and 58-20 parcels (Block 2601, Lot 6 and Block 2601, Lot 1) were concurrently utilized as a concrete aggregate recycling facility from circa 2003 until spring 2021.

Stormwater runoff from the parking area associated with the 57-00 parcel (Block 2601, Lot 6) has been flowing into a storm water vault located on the southwestern end of the

parcel. In addition to stormwater runoff, material collected in interior trench drains and an oil/water separator have historically been tied to the structure. Two underground injection control (UIC) units are located on the 57-05 parcel (Block 2602, Lot 72). Groundwater samples were collected near the northern UIC structure, these samples contained volatile organic compound (VOCs) greater than their respective SGVs.

A utility survey was completed in March 2022 to further evaluate these UIC units. The northern UIC structure was identified to be connected to the interior trench drains. Currently, no operations are not being conducted on-site and water is not being conveyed to the UIC structure from the interior trench drains. Sludge and liquids within the UIC structures located on the 57-05 parcel (Block 2602, Lot 72) is planned for removal in July 2022. Cleaning and sealing of the on-site trench drains located at the 57-00 and 57-05 parcels (Block 2601, Lot 6 and Block 2602, Lot 72) and oil/water separator located at the 57-00 parcel (Block 2601, Lot 6) will also be completed at this time.

Soil borings installed within the 57-00 and 58-20 parcels (Block 2601, Lot 6 and Block 2601, Lot 1) contained staining, odors, and PID readings. Soil samples collected from this parcel contained SVOCs and metals at concentrations greater than Commercial and Industrial Restricted Use SCOs. Groundwater within the 57-00 and 58-20 (Block 2601, Lot 6 and Block 2601, Lot 1) portions of the property exhibited VOCs, SVOCs, and metals at concentrations greater than their respective SGVs.

Soil on the 57-05 parcel (Block 2602, Lot 72) contained SVOCs greater than Commercial and Industrial Restricted Use SCOs. Groundwater on this parcel contained VOCs, SVOCs, and metals greater than their respective NYSDEC SGVs. Soil and groundwater impacts are both greater than intended future use cleanup objectives.

Item 5: Intended Use Post-Remediation

After remediation, the two buildings on the site will be improved and leased and the areas outside of the buildings (with the exception of the wetland associated buffer area, to the extent that improvements are not permitted per the Order on Consent) will be improved for vehicle parking. The post-remediation use will comply with the current M3-1 zoning.

Item 8: Current and/or Recent Development Patterns

The proposed post-remediation uses include industrial uses, which are consistent with the current zoning and with industrial development patterns in the area.

Item 9: Consistency with Applicable Zoning Laws/Maps

The current site use is consistent with current zoning laws/maps. The current zoning is M3-1, which supports the proposed industrial use of the site. A figure showing the existing zoning map is included in this attachment.

Item 10: Consistency with Comprehensive Community Master Plans

The site is within the Maspeth Industrial Business Zone (IBZ) – one of 21 IBZs within NYC where expanded business services are available for industrial and manufacturing businesses. The extents of the Maspeth Industrial Business Zone are depicted in a figure included in this attachment. The planned post-remediation use of the site is consistent with the Maspeth IBZ.

ZONING MAP

THE NEW YORK CITY PLANNING COMMISSION

Major Zoning Classifications:
The number(s) and/or letter(s) that follows on R, C or M District designation indicates use, bulk and other controls as described in the text of the Zoning Resolution.

- R – RESIDENTIAL DISTRICT
- C – COMMERCIAL DISTRICT
- M – MANUFACTURING DISTRICT

SPECIAL PURPOSE DISTRICT
An area designated for a special purpose district as described in the text of the Zoning Resolution.

AREA(S) REZONED

Effective Date(s) of Rezoning:
06-02-2022 C 210299 ZMK

Special Requirements:

For a list of lots subject to CEQR environmental requirements, see APPENDIX C.

For a list of lots subject to "D" restrictive declarations, see APPENDIX D.

For Inclusionary Housing designated areas and Mandatory Inclusionary Housing areas on this map, see APPENDIX F.

ZONING MAP 13a




MAP KEY

8d	9b	9d
12c	13a	13c
12d	13b	13d

© Copyrighted by the City of New York


NOTE: Zoning information as shown on this map is subject to change. For the most current zoning information, visit the Zoning action of the Department of City Planning website: www.nyc.gov/planning or contact the Zoning Information Desk at (212) 720-3291.



Maspeth IBZ

Maspeth IBZ Boundary

 All items



ATTACHMENT E
SECTION IV: PROPERTY'S ENVIRONMENTAL HISTORY

ATTACHMENT E

SECTION IV: PROPERTY'S ENVIRONMENTAL HISTORY

Item 1: Environmental Reports and Investigations

Environmental reports prepared for the site are summarized below and include the following:

- Tank Tightness Test Reporting, dated December 28, 2007, prepared by The Tyree Organization, Ltd. (Tyree)
- Investigation Summary Report, dated November 2010, prepared by Environmental Management Solutions, Inc. (EMSI)
- Sample Collection Summary Letter, dated August 20, 2012, prepared by Taylord Environment (Taylord)
- Diesel Fuel Spill Remediation- Spill No. 13-06438, dated December 5, 2013, prepared by Preferred Environmental Services (PES)
- Phase I Environmental Site Assessment, dated July 21, 2021, prepared by Langan
- Phase II Environmental Site Investigation, dated July 26, 2021, prepared by Langan
- Phase I Environmental Site Assessment, dated December 20, 2021, prepared by Langan
- Phase II Environmental Site Investigation, dated December 22, 2021, prepared by Langan
- Underground Storage Tank UST Removal and Underground Injection Control Unit Sampling Letter, dated June 13, 2022, prepared by Langan
- Vapor Intrusion Summary Letter, dated June 13, 2022, prepared by Langan

The previously listed environmental reports are appended to this attachment as separate pdf electronic copies.

Tank Tightness Testing Report, dated December 28, 2007, prepared by Tyree

A tank tightness test was completed on a 4,000-gallon diesel underground storage tank (UST) located on the southeastern portion of the 57-00 parcel (Block 2601 Lot 6) on December 18, 2007. The UST did not pass the tank tightness test. A spill was reported to the New York State Department of Environmental Conservation (NYSDEC) and Spill No. 07-09978 was assigned to this incident. Subsequent faxes to NYSDEC indicate that the failure was due to a cross over line that had not been removed from the tank top. The line was removed and the tank passed a subsequent tank tightness test on December 21, 2007. The spill was administratively closed according to the NYSDEC Spill Report Form on December 28, 2007.

Investigation Summary Report, dated November 2010, prepared by EMSI

This report summarizes remedial efforts associated with NYSDEC Spill No. 08-08170 on 57-00 parcel (Block 2601, Lot 6). This spill was reported by NYSDEC for petroleum releases in association with illegally storing and dispensing petroleum. This report prompted the remedial activities summarized below.

- A total of 351.04 tons of petroleum impacted soil was excavated and disposed of off-site from the western side of the building north of the former oil storage room. In addition, a concrete pad with a floor drain (without connected piping) was removed from this area.
- Seven post excavation soil samples were collected from the sidewalls and center base of the excavation. Samples were analyzed for volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs).
- Laboratory analytical results indicated polycyclic aromatic hydrocarbons (PAHs) benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, benzo(a)pyrene, and dibenzo(a,h)anthracene exceeded the 2010 NYSDEC Residential Restricted Use Soil Cleanup Objectives (SCOs).
- As per an NYSDEC letter dated April 16, 2012, a groundwater monitoring well was required to be installed within the soil excavation to evaluate groundwater quality.

According to a NYSDEC Spill Report Form, this spill was closed October 27, 2012.

Sample Collection Summary Letter, dated August 20, 2012, prepared by Taylord

A soil boring and a temporary well point were installed on the site to further evaluate the remedial excavation which occurred as described above in 2010. A soil and groundwater sample were collected from the soil boring/temporary well point location and analyzed for the CP-51 guidance listed VOCs and SVOCs.

Soil results were compared to the NYSDEC CP-51 standards. All analyzed compounds were below their respective CP-51 SCOs. This sample was also compared to the 2022 6 NYCRR Part 375 Protection of Groundwater SCOs, all analyzed compounds were below all applicable SCOs.

Diesel Fuel Spill Remediation- Spill No. 13-06438, dated December 5, 2013, prepared by PES

This report summarizes remedial actions taken to remedy NYSDEC Spill No. 13-06438. This spill was reported in association with the removal of a 4,000-gallon diesel UST from the 57-00 property. Below is a summation of pertinent parts of this report.

- One out-of-service 4,000-gallon diesel UST was removed on September 19, 2013. During the removal, staining and petroleum impacted pea gravel was identified within the underground tank vault.
- Two soil borings were collected from below the concrete base of the UST vault. Fill material was identified and sampled from within these locations.
- Laboratory analytical results from these soil borings indicated three SVOCs were greater than their respective NYSDEC CP-51 SCOs. These compounds were benzo(a)anthracene at 1,100 ppb, chrysene at 1,100 ppb, and indeo(1,2,3-c,d)pyrene at 570 ppb. These detected concentrations are less than Commercial and Restricted Industrial Use (Industrial) SCOs.

According to NYSDEC data, the 13-06438 case was closed with the NYSDEC on February 11, 2014.

Phase I Environmental Site Assessment, dated July 21, 2021, prepared by Langan

Langan completed a Phase I Environmental Site Assessment (ESA) on behalf of Bay Crane Service of New York in July 2021. The ESA identified the following two recognized environmental conditions (RECs):

- Historical Use of Subject Property: Historically, the 57-00 and 58-20 parcels (Block 2601, Lot 6 and Block 2601, Lot 1) were utilized to accept/recycle concrete from construction and demolition. In addition, historical records indicate the site was utilized for various industrial operations since circa 1902.
- Western-Adjoining Superfund Site: The adjoining Newtown Creek is listed as a USEPA Superfund Site on the National Priority List.

Phase II Environmental Site Investigation, dated July 26, 2021, prepared by Langan

Langan completed a Phase II Environmental Site Investigation (ESI) on behalf of Bay Crane Service of New York in July 2021. The ESI was completed to investigate the two RECs identified in the Phase I ESA. A geophysical was completed on all three parcels prior to ground intrusive activities. A total of eleven soil borings and four temporary well points were installed, as depicted in **Figures E-1 and E-2** located in **Attachment B**.

Three soil borings exhibited petroleum-like odor and staining (SB-01, SB-02, and SB-04). Two of these soil borings were installed on the 57-00 parcel (Block 2601, Lot 6) and one of these soil borings was on the 57-05 parcel (Block 2602 Lot 72). Soil samples were compared to the NYSDEC Part 375 Protection of Groundwater, Commercial, and Industrial SCOs. Soil analytical results indicated VOCs, SVOCs, and metals were greater than their respective Protection of

Groundwater SCOs. SVOCs and metals were greater than their respective Commercial and Industrial SCOs. Within collected groundwater samples, several metals and VOCs were identified at concentrations greater than their respective NYSDEC Title 6 Technical and Operational Guidance Series (TOGS) Class GA Groundwater Standards and Guidance Values (SGVs).

- Soil analytical results indicated the 57-00 parcel (Block 2601, Lot 6) contained benzo(a)pyrene and arsenic at concentrations greater than their respective Commercial and Industrial SCOs. Dibenzo(a,h)anthracene, mercury, and lead were identified at concentrations greater than their respective Commercial SCOs. Methyl ethyl ketone, benzo(k)fluoranthene, acetone, benzo(b)fluoranthene, and chrysene was identified at concentrations greater than their respective Protection of Groundwater SCOs.
- Soil analytical results indicated the 58-20 parcel (Block 2601, Lot 1) contained benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, dibenzo(a,h)anthracene, and ideno(1,2,3-cd)pyrene at concentrations greater than their respective Commercial and Industrial SCOs. Chrysene and mercury were identified at concentrations greater than the Commercial SCO.
- Soil analytical results indicated the 57-05 parcel (Block 2602, Lot 72) contained methyl ethyl ketone at a concentrations greater than its Protection of Groundwater SCO. No compounds were detected above Commercial or Industrial SCOs.

Groundwater

- Petroleum related VOCs and SVOCs were also identified in groundwater on parcel 57-00 (Block 2601, Lot 6). Several metals (dissolved and undissolved) were also identified at concentrations greater than their respective SGVs.
- Metals which exceeded their respective groundwater SGVs on the 57-00 parcel (Block 2601, Lot 6) include antimony, arsenic, iron, lead, magnesium, manganese, and sodium in unfiltered (total) samples. Filtered (dissolved) samples contained iron, magnesium, manganese, and sodium greater than their respective SGVs.
- Groundwater analytical results indicated a sample collected on the 57-05 parcel (Block 2602, Lot 72) contained the VOC methyl tert-butyl ether (MTBE) and total dissolved metals at concentrations greater than their respective SGVs.
- Total dissolved metals which exceeded their respective SGVs on the 57-05 parcel (Block 2602, Lot 72) include iron, manganese, and sodium.

Phase I Environmental Site Assessment, dated December 20, 2021, prepared by Langan

Langan completed a Phase I ESA on behalf of Prologis, L.P. dated December 2021. The ESA identified the following four RECs:

- Historical Site Use: Commercial/industrial use of the site dates back to the 1800s. Most recently the 57-00 and 58-20 parcels (Block 2601, Lot 6 and Block 2601, Lot 1) operated as a concrete recycling facility.
- Newtown Creek Superfund: The adjoining Newtown Creek is listed as a USEPA Superfund Site on the National Priority List.
- On-site Storm Water Vault & Oil/Water Separator: A potential oil/water separator (OWS) was identified within a former vehicle maintenance garage. The OWS is connected to an on-site storm water vault.
- Methyl Tert-Butyl Ether (MTBE) in Groundwater: MTBE was identified within groundwater during July 2021 Phase II ESI activities on the 57-05 parcel (Block 2602, Lot 72).

Phase II Environmental Site Investigation, dated December 22, 2021, prepared by Langan

Langan completed a Phase II ESI on behalf of Prologis, L.P. in December 2021 to investigate the four RECs identified in the Phase I ESA. A geophysical was completed on all three parcels prior to ground intrusive activities. A total of ten soil borings and nine temporary well points were installed, as depicted in **Figures E-1 and E-2** located in **Attachment E**.

Geophysical activities identified two anomalies consistent with potential USTs on the 57-05 parcel (Block 2602, Lot 72). One of the anomalies was located north of a building addition along 47th Street and the other anomaly was identified within the northeastern end of the parcel.

Soil analytical results indicated SVOCs benzo(a)pyrene, benzo(b)fluoranthene, and dibenzo(a,h)anthracene were detected at concentrations greater than their respective Commercial and/or Industrial SCOs on the 57-00 parcel (Block 2601, Lot 6). Specifically, benzo(a)pyrene was identified greater than the Commercial and Industrial SCOs, benzo(b)fluoranthene was identified greater than the Commercial SCO, and dibenzo(a,h)anthracene was identified greater than the Commercial SCO. Select metals were also detected at concentrations greater than their respective Commercial and/or Industrial SCOs on the 57-00 parcel (Block 2601, Lot 6). Specifically, arsenic, barium, copper, cyanide, lead and mercury were identified at concentrations greater than their respective Commercial SCOs. Arsenic and mercury were identified greater than their respective Industrial SCOs.

On the 57-00 parcel (Block 2601, Lot 6), VOCs 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, acetone, ethylbenzene, n-butylbenzene, n-propylbenzene, and total xylenes were identified at concentrations greater than their respective Protection of Groundwater SCOs. The SVOC

chrysene and the metal selenium were identified in exceedance of their respective Protection of Groundwater SCOs.

Acetone and ethylbenzene were detected at concentrations greater than their respective Protection of Groundwater SCOs at the 57-05 parcel (Block 2602, Lot 72).

An ethylbenzene SGV exceedance was identified on the 57-00 parcel (Block 2601, Lot 6). Isopropylbenzene and toluene SGV exceedances were identified on the 57-05 parcel (Block 2602, Lot 72). Select SVOC SGV exceedances were identified on the 57-00 parcel (Block 2601, Lot 6).

Underground Storage Tank UST Removal and Underground Injection Control Unit Sampling Summary Letter, dated June 13, 2022, prepared by Langan

Two USTs were removed from the 57-05 parcel (Block 2602, Lot 72) on February 21, 2022. The USTs consisted of one 550-gallon waste oil tank (UST 002) and one 3,500-gallon diesel tank (UST 003). Once uncovered, it was determined that the tanks had previously been abandoned through observation of cut holes in the top of the tanks. The 3,500-gallon diesel tank contained soil and approximately 2,550-gallons of liquid (apparent rain water mixed with some product). The 550-gallon waste oil UST contained approximately 550-gallons of liquid (apparent rain water mixed with some product) and tank bottoms (sludge). Once the tanks were removed, samples were collected from the sides and center base of the excavations. Laboratory results are summarized below:

- Five soil samples were collected from within the 3,500-gallon diesel UST grave. Soil samples were analyzed for Commissioner Policy 51 (CP51) Fuel Oil and CP51 Polycyclic Aromatic Hydrocarbons (PAHs).
 - Analytical results indicated a detectable amount of xylenes within sample USTB-3. Xylene (m/p and total) concentrations were below the Commercial and Industrial SCOs but greater than CP-51 standards.
 - Three of the five samples had detectable levels of SVOCs. Sample USTB-4 contained benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, dibenzo(a,h)anthracene, and ideno(1,2,3-cd)pyrene at concentrations greater than Commercial and Industrial SCOs.
 - Sample USTB-4 contained benzo(k)fluoranthene, chrysene, and phenanthrene greater than the CP-51 NYSDEC/Protection of Groundwater standards. These compounds did not exceed their respective Commercial and Industrial SCOs.

- Staining, elevated PID readings, and the laboratory analytical results identified during removal of the 3,500-gallon diesel UST are indicative of a petroleum release. NYSDEC was notified of the release and Spill No. 211-05-17 was assigned to the matter.
 - Additional soils were not excavated from the UST grave; the grave was backfilled with imported clean fill material.
- Five soil samples were collected from within the 550-gallon waste oil UST grave and one sample was collected from stained soil atop the UST. Soil samples were analyzed for VOCs, SVOCs, metals, and PCBs.
 - Analytical results indicate that the post UST removal soil samples and stained soil atop the UST did not contain concentrations of VOCs, SVOCs, PCBs, or metals at concentrations greater than the CP51, Commercial SCOs, or the Industrial SCOs. All samples contained detectable concentrations of metals and SVOCs.
- During Phase II ESI activities in July and November 2021, groundwater samples were collected near the UIC structure. Laboratory results indicated methyl tert-butyl ether (MTBE) and toluene were detected at concentrations greater than their respective SGVs. UIC contents included both liquid and solid waste. Samples were collected of both media and toluene was detected in liquid within the structure. Because toluene was detected both in the UIC contents and in groundwater near the UIC structure, it appears toluene may be emanating from contents within the UIC structure.

Vapor Intrusion Summary Letter, dated June 13, 2022, prepared by Langan

On May 12, 2022, Langan completed indoor air and sub-slab vapor (SSV) within the 57-00 building (Block 2601 Lot 6) and 57-05 building (Block 2602 Lot 72). SSV samples were co-located with indoor air samples. An ambient air sample was also collected upwind of the 57-00 building. **Figure E-3** depicts the SSV, indoor air, and ambient air sample locations, **Table 3** includes laboratory analytical information.

- SSV samples SSV01 through SSV03 and indoor air samples IA01 through IA03 were located on the 57-00 property (Block 2601, Lot 6). SSV samples SSV04 and SSV05 and indoor air samples IA04 and IA05 samples were located on the 57-05 parcel (Block 2602, Lot 72). Indoor air and sub-slab vapor (SSV) laboratory results were compared to the appropriate New York State Department of Health (NYSDOH) Soil Vapor/Indoor Air Matrices (NYSDOH Matrices) and NYSDOH Air Guideline Values (AGVs). All indoor air values were well below the AGVs. A results summary is included below.
- Laboratory results from the ambient air and indoor air samples were input into the NYSDOH Matrices. Carbon tetrachloride was identified in all indoor air and the ambient

air samples at a concentration recommending “no further action”. Carbon tetrachloride appears to be a background impact and not site specific.

- 57-00 (Block 2601, Lot 6) Building:
 - Chlorinated solvent and petroleum related VOCs were identified in SSV beneath the building. Locations SSV01 and SSV02 contained VOCs at concentrations less than NYSDOH Matrices, further action is not recommended for these locations.
 - Sample results from location SSV03 was input into the NYSDOH Matrices which recommended “mitigation” for this location. Concentrations of vinyl chloride within the SSV03 sample were identified at a concentration which was identified at a concentration which recommended “mitigation” regardless of indoor air concentrations.
 - Due to the vinyl chloride concentration in the SSV03 sample, the reporting limits for compounds 1,1-dichloroethene, cis1,2-dichloroethene, and trichloroethene exceeded the minimum concentrations for SSV for which mitigation is recommended regardless of indoor air concentration for their respective matrices.
- 57-05 (Block 2602, Lot 72) Building:
 - When evaluated using the NYSDOH Matrices, each of the co-located soil vapor and indoor air samples yielded a recommendation for “no further action”. The only VOC included in the NYSDOH Soil Vapor/Indoor Air Matrices detected in indoor air was carbon tetrachloride. As discussed above, carbon tetra chloride is considered a background contaminant and not related to VI within the building.

Item 2 - Sampling Data

Sample analytical results from the July 2021 Langan Phase II ESI and December 2021 Langan Phase II ESI are presented in **Figures E-1** and **E-2**. Sub-slab sample results are included in **Figure E-3**. Sample results are compared to the following criteria:

- Soil sample results are compared to 6 NYCRR Part 375 Restricted Use Commercial and Industrial SCOs and Protection of Groundwater SCOs.
- Groundwater sample results are compared to NYSDEC TOGS SGVs.
- Sub-slab vapor and indoor air results were evaluated using the NYSDOH Soil Vapor/Indoor Air Matrices A, B, and C. Indoor air results were compared to the NYSDOH Air Guideline Values (AGVs).

Tables summarizing the detected concentrations of each contaminant by media type from the 2021 Phase II ESIs are included as **Tables 1A, 1B, 2A** and **2B** in this attachment. Soil vapor sample data is included as **Tables 3A** and **3B**.

Soil

Analytes detected at concentrations above Protection of Groundwater SCOs, Commercial Use SCOs, and Industrial Use SCOs are presented below. Exceedances of Protection of Groundwater SCOs are in normal font, exceedances of Commercial Use SCOs are in italic font, and exceedances of Industrial Use SCOs in bold.

VOCs

- Acetone: SB08, SB11, LB-2, LB-3, LB-4, LB-9B-2N, LB-10; maximum concentration of 33 mg/kg in LB-10.
- 1,2,4-Trimethylbenzene at a concentration of 33 mg/kg in LB-10
- 1,3,5-Trimethylbenzene at a concentration of 21 mg/kg in LB-10
- Ethylbenzene: LB-9B-2N and LB-10; maximum concentration of 35 mg/kg in LB-10
- Methyl ethyl ketone: SB04 and SB11; maximum concentration 0.78 mg/kg in SB11
- N-butylbenzene at a concentration of 13 mg/kg in LB-10
- N-propylbenzene at a concentration of 11 mg/kg in LB-10
- Total xylenes at a concentration of 87 mg/kg in LB-10

SVOCs

- Benzo(a)anthracene: SB03, **SB07**, SB11, LB-1, LB-2, and LB-3; maximum concentration of 64.8 mg/kg in SB07
- Benzo(a)pyrene: *SB03*, **SB07**, and **SB11**; maximum of 47.1 mg/kg in SB07
- Benzo(b)fluoranthene: **SB07**, SB11, LB-2, LB-3, and **USTB-4**; maximum of 39.2 mg/kg in SB07
- Chrysene: SB11, LB-1, LB-2, LB-3, LB-10, and *SB07* at a concentration of 65.2 mg/kg
- Dibenzo(a,h)anthracene: **SB07**, *SB11*, *LB-1*, *LB-3*, LB-10, and *USTB-4*; maximum of 9.53 mg/kg
- Ideno(1,2,3-cd)pyrene: **SB07** and **USTB-4**; maximum concentration of 26.7 mg/kg.

Metals

- Arsenic: **SB10**, **LB-3**, and **LB-10**; maximum concentration of 1,900 mg/kg in LB-10
- Barium: *LB-2* at a concentration of 1,400 mg/kg
- Copper: *LB-2* at a concentration of 580 mg/kg
- Cyanide: *LB-10* at a concentration of 140 mg/kg

- Lead: **SB10**, **LB-2**, LB-3, and **LB-10**; maximum concentration of 1,800 mg/kg in SB10
- Mercury: SB07, SB10, SB11, LB-1, LB-2, LB-3, and **LB-10**; maximum concentration of 6.5 mg/kg in LB-10
- Selenium: LB-2, LB-3, and LB-10; maximum concentration of 67 mg/kg in LB-10

Groundwater

Analytes detected above the NYSDEC SGVs are presented below.

VOCs

- 1,2-Dichloropropane: MW02 at a concentration of 7 ug/L
- Ethylbenzene: TW-1 at a concentration of 8.6 ug/L
- Isopropylbenzene: MW02 and TW-8 at a maximum of 24 ug/L in TW-8
- Toluene: TW-8 and UIC at a maximum of 60 ug/L in TW-8
- N-propylbenzene: MW02 at a concentration of 6 ug/L
- Methyl-tert butyl ether: MW04 at a concentration of 73 ug/L

SVOCs

- Acenaphthalene: TW-1 at a concentration of 53 ug/L
- Anthracene: TW-1 at a concentration of 73 ug/L
- Benzo(a) anthracene: MW03, TW-1, and TW-2; maximum of 63 ug/L in TW-1
- Benzo(a)pyrene: MW03, TW-1, and TW-2; maximum of 43 ug/L in TW-1
- Benzo(b)fluoranthene: MW03, TW-1, TW-2, and UIC; maximum of 44 ug/L in TW-1
- Benzo(k)fluoranthene: MW03, TW-1, and TW-2; maximum of 10 ug/L in TW-1
- Chrysene: MW03, TW-1, TW-2, and UIC; maximum concentration of 60 ug/L in TW-1
- Fluoranthene: TW-1 at a concentration of 110 ug/L
- Fluorene: TW-1 at a concentration of 55 ug/L
- Ideno(1,2,3-cd)pyrene: MW03, TW-1, TW-2, and UIC; maximum concentration of 15 ug/L in TW-1
- Naphthalene: TW-1 at a concentration of 17 ug/L
- Phenanthrene: TW-1 at a concentration of 220 ug/L
- Pyrene: TW-1 at a concentration of 170 ug/L

Metals (Unfiltered)

- Antimony: MW03, TW-1, TW-2, TW-3, TW-4, and TW-6; maximum concentration of 22 ug/L in TW-3 (unfiltered)
- Arsenic: MW03, TW-1, TW-2, TW-3, TW-4, and TW-6; maximum concentration of 340 ug/L in TW-3 (unfiltered)
- Barium: TW-3 at a concentration of 2,300 ug/L (unfiltered)
- Beryllium: TW-2 and TW-6; maximum concentration of 5.1 ug/L in TW-6 (unfiltered)
- Cadmium: TW-2 at a concentration of 10 ug/L
- Total chromium: TW-1, TW-2, TW-3, TW-4, TW-6; maximum concentration of 320 ug/L in TW-6 (unfiltered)
- Copper: TW-1, TW-2, TW-3, TW-4; maximum concentration of 1,300 ug/L in TW-3 (unfiltered)
- Iron: MW01, MW02, MW03, MW04, TW-1, TW-2, TW-3, TW-4, TW-6; maximum concentration of 210,000 ug/L in TW-6 (unfiltered)
- Lead: TW-1, TW-2, TW-3, TW-4, and TW-6; maximum concentration of 6,600 ug/L in TW-3 (unfiltered)
- Magnesium: MW01, TW-2, TW-3, and TW-4; maximum concentration of 63,000 ug/L in TW-2 (unfiltered)
- Manganese: MW01, MW02, MW04, TW-1, TW-2, TW-3, TW-4, and TW-6; maximum concentration of 4,300 ug/L in TW-6 (unfiltered)
- Mercury: TW-1, TW-2, TW-3, and TW-4; maximum concentration of 320 ug/L in TW-2 (unfiltered)
- Nickel: TW-2, and TW-6; maximum concentration of 150 ug/L in TW-2 (unfiltered)
- Selenium: TW-2, TW-3, and TW-6; maximum concentration of 28 ug/L in TW-3 (unfiltered)
- Sodium: MW01, MW02, MW03, MW04, TW-1, TW-2, TW-3, TW-4, and TW-6; maximum concentration of 320,000 ug/L in TW-4 (unfiltered)
- Zinc: TW-2 (unfiltered) at a concentration of 4,900 ug/L

Metals (Filtered)

- Antimony: MW03, TW-1, TW-2, TW-3, TW-4, and TW-6; maximum concentration of 8.3 ug/L in TW-6
- Arsenic: TW-3 at a concentration of 45 ug/L

- Iron: MW01, MW02, MW03, MW04, and TW-2; maximum concentration of 11,100 ug/L in MW01
- Magnesium: MW01 at a concentration of 38,800 ug/L
- Manganese: MW01, MW02, MW04, and TW-2; maximum concentration of 3,090 ug/L in MW02
- Sodium: MW01, MW02, MW03, MW04, TW-1, TW-2, TW-3, TW-4, and TW-6; maximum concentration of 310,000 ug/L in TW-4

Indoor Air/Soil Vapor

Co-located SSV and IA samples were evaluated using applicable NYSDOH Matrices A, B, and C. In addition, indoor air data was compared to NYSDOH AGVs. The results of these analysis are below.

VOCs

- All indoor air sample VOCs were below their respective AGVs.
- Trichloroethene: SSV02 and SSV03; maximum concentration of 83.8 ug/m³ in SSV03.
 - The resulting NYSDOH Matrix recommendation for SSV03 is “mitigate”.
- Cis 1,2-dichloroethene: SSV03 at a concentration of 83.8 ug/m³.
 - The resulting NYSDOH Matrix recommendation for SSV03 is “mitigate”.
- 1,1-dichloroethene: SSV03 at a concentration of 61.9 ug/m³.
 - The resulting NYSDOH Matrix recommendation for SSV03 is “mitigate”.
- Carbon tetrachloride: AA01, IA01, IA02, IA03, IA04, and IA05; maximum concentration of 0.61 ug/m³.
 - The resulting NYSDOH Matrix recommendation for these samples is “no further action”.
- Tetrachloroethene: SSV02 and SSV03; maximum concentration of 485 ug/m³ in SSV02.
 - The resulting NYSDOH Matrix recommendation for these samples is “no further action”.
- Methylene chloride: SSV03 at a concentration of 135 ug/m³.
 - The resulting NYSDOH Matrix recommendation for SSV03 is “mitigate”.
- Vinyl chloride: SSV03 at a concentration of 501 ug/m³.
 - The resulting NYSDOH Matrix recommendation for SSV03 is “mitigate”.

The detection of compounds in soil above applicable future use SCOs, in groundwater above SGVs, and in soil vapor and co-located indoor air at concentrations that yield a recommendation of “mitigate” when evaluated using NYSDOH matrices present a risk to human health and the environment and require remediation.

Item 3 – Attachments

- Figure E-1 – Historical Soil Sample Locations and Results
- Figure E-2 – Historical Groundwater Sample Locations and Results
- Figure E-3 – Historical Indoor Air, Sub-Slab Soil Vapor, and Ambient Air Sample Locations and Results
- Table 1 – Soil Sample Analytical Results Summary
- Table 2 – Groundwater Sample Analytical Results Summary
- Table 3 – Indoor Air, Sub-Slab Soil Vapor, and Ambient Air Results Summary


Item 4 – Past and Current Land Uses

57-00 (Block 2601 Lot 6) & 58-20 (Block 2601 Lot 1)

- NYC Concrete Materials AKA Pebble Lane Associates, LLC (2003-Spring 2021)
- Queen’s Truck Auto Center [repair shop] and Sky [concrete] Materials (2013-2017), Rizzo Environmental Services office (2013-2015)
- Alfredo Lamanna Trucking Inc., Brookville Enterprises, Inc., Island Transport [parking], Almar [construction] Supplies, Inc. (2000-2005)
- United Leasing Corp. (1991)
- Fruehauf Trailer Corporation (1976)

57-05 (Block 2602 Lot 72)

- Marshark Craft NYC [mobile catering] (2020-May 2021)
- Almar [construction] Supplies, Inc. (2011-2017)
- Sagana Industries (2005)
- Office Depot Stlt (2000)
- Arflo Trucking Inc. and Queens Motor Transportation (1983)
- Tayaton HW Co. Inc. (1967-1970)



LANGAN
300 RIVER DRIVE, SUITE 200
NEW JERSEY, NEW YORK, VIRGINIA, CALIFORNIA
NEW HAMPSHIRE, ILLINOIS, INDIANA, OHIO
NEW MEXICO, NEBRASKA, NORTH CAROLINA
PENNSYLVANIA, RHODE ISLAND, SOUTH CAROLINA
Tennessee, Texas, Utah, Vermont, Washington
Wisconsin, Wyoming, and all other states

Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72

Drawing Title
HISTORICAL SOIL
SAMPLE LOCATIONS
AND RESULTS

Project No.
100965501

Date
10/6/2022

Scale
1" = 80'

Drawn By
ATR

Figure
E-1

Project No.
100965501

Drawing Title
HISTORICAL SOIL
SAMPLE LOCATIONS
AND RESULTS

Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72

Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72

Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72


Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72

Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72

Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72

Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72

Project
57-00, 57-05, &
58-20 47th STREET
BLOCK NOS. 2601, 2602
LOT NOS. 1 & 6, 72






Table 1A
Soil Sample Analytical Results

Block 2601, Lots 57.05, 57.06, and 58.20 47th Street
Block 2601, Lots 57.05, 57.06, and 58.20 47th Street
Maple, Quebec, Canada
Langan Project No.: 100865501

Analyte	CAS Number	NYSDEC Part 375 Protection of Groundwater	NYSDEC Part 375 Restricted Use Commercial SCOs	NYSDEC Part 375 Restricted Use Industrial SCOs	Location	USTB-1		USTB-2		USTB-3		USTB-4		USTB-5		WASTE CLASSIFICATION	WASTE CLASSIFICATION		
						Sample Name	Sample Depth	USTB-1		USTB-2		USTB-3		USTB-4				USTB-5	
								Result	Unit	Result	Unit	Result	Unit	Result	Unit			Result	Unit
Pesticides																			
4,4'-DDD	72-54-8	14	92	180	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
4,4'-DDE	72-54-9	17	62	120	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
4,4'-DDT	50-29-3	136	47	94	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Aldrin	309-00-2	0.19	0.68	1.4	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Alpha BHC (Alpha Hexachlorocyclohexane)	319-84-6	0.02	3.4	6.8	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Beta BHC (Beta Hexachlorocyclohexane)	319-85-7	0.09	2.0	4.0	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Beta Endosulfan	33213-65-9	102	200	920	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Chlordane (alpha and gamma)	57-74-9	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Chlordane (beta)	57-74-9	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
DDT	50-29-3	0.1	1.4	2.8	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Endosulfan Sulfate	1031-07-8	1000	200	920	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Endrin Alderlyde	72-20-8	0.06	89	410	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Endrin Ketone	52484-70-5	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Gamma BHC (Lindane)	58-89-9	0.1	9.2	23	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Heptachlor	76-44-8	0.38	15	29	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Heptachlor Epoxide	1024-67-3	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Methoxychlor	72-43-5	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Toxaphene	8001-35-2	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Polychlorinated Biphenyl																			
PCB-1016 (Anclor 1016)	12674-11-2	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	<0.038 U	<0.038 U		
PCB-1221 (Anclor 1221)	11104-28-2	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
PCB-1232 (Anclor 1232)	11141-16-5	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
PCB-1242 (Anclor 1242)	53469-21-9	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
PCB-1248 (Anclor 1248)	12672-29-6	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
PCB-1254 (Anclor 1254)	11897-69-1	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
PCB-1260 (Anclor 1260)	11096-62-5	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.0209 J		
PCB-1262 (Anclor 1262)	37324-29-5	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	<0.038 U		
PCB-1268 (Anclor 1268)	11100-14-4	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	<0.038 U		
Total PCBs	1336-36-3	3.2	1	25	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.0209 J		
Metals																			
Aluminum	7429-90-5	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Antimony	7440-38-0	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Barium	7440-39-3	820	16	10000	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	4.85		
Beryllium	7440-41-7	47	590	2700	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Bismuth	7440-43-9	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Cadmium	7440-70-2	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Chromium, Hexavalent	18540-29-9	19	400	800	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	16.1		
Chromium, Total	7440-47-3	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Cobalt	7440-48-4	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Copper	7440-50-8	1720	270	10000	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Cyanide	57-12-5	40	27	10000	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Iron	7439-92-1	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Lead	7439-92-1	469	1000	3000	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	88.5		
Magnesium	7439-95-4	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Manganese	7439-96-5	2000	10000	10000	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.425		
Mercury	7439-97-6	0.73	218	1000	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	<1.81 U		
Molybdenum	7440-09-7	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	<0.904 U		
Potassium	7440-09-7	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Selenium	7782-49-2	4	1500	6800	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Silver	7440-22-4	8.3	1500	6800	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Sulfur	7704-34-9	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Thallium	7440-28-0	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Vanadium	7440-66-2	NS	NS	NS	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
Zinc	7440-66-6	2480	10000	10000	mg/kg	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA		
General Chemistry																			
SOLIDS, Percent																			
Percent																			

Table 1A
Soil Sample Analytical Results

Page 1 of 1

57-00, 57-05, and 58-20 47th Street
Maspeth, Queens, New York
Langan Project No.: 100965501

Notes:

CAS - Chemical Abstract Service

NS - No standard

mg/kg - milligram per kilogram

NA - Not analyzed

RL - Reporting limit

<RL - Not detected

Soil sample analytical results are compared to the New York State Department of Environmental Conservation (NYSDEC) Title 6 of the Official Compilation of New York Codes, Rules, and Regulations (NYCRR) Part 375 Unrestricted Use, Protection of Groundwater, and Restricted Use Restricted-Residential Soil Cleanup Objectives (SCO).

Criterion comparisons for 3- & 4-methylphenol (m&p cresol) are provided for reference. Promulgated SCOs are for 3-methylphenol (m-cresol) and 4-methylphenol (p-cresol).

Qualifiers:

D - The concentration reported is a result of a diluted sample.

E - The result is estimated and cannot be accurately reported due to levels encountered or interferences.

J - The analyte was detected above the method detection limit (MDL), but below the RL; therefore, the result is an estimated concentration.

U - The analyte was analyzed for, but was not detected at a level greater than or equal to the RL; the value

J - The analyte was positively identified and the associated numerical value is the approximate concentration of the analyte in the sample.

UJ - The analyte was not detected at a level greater than or equal to the RL; however, the reported RL is

U - The analyte was analyzed for, but was not detected at a level greater than or equal to the level of the RL or

Exceedance Summary:

10 - Result exceeds Protection of Groundwater SCOs

10 - Result exceeds Restricted Use Commercial SCOs

10 - Result exceeds Restricted Use Industrial SCOs

Table 1B
Soil Sample Analytical Results- BCP Application Summary

57-00, 57-05, and 58-20 47th Street
Block 2601, Lot 6, Block 2601, Lot 1, and Block 2602, Lot 72
Maspeth, Queens, New York
Langan Project No.: 100965501

Analytes > SCOs	Detections > Protection of Groundwater	Detections > Restricted Residential SCOs	Detections > Restricted Industrial SCOs	Maximum Detection (ppm)	Protection of Groundwater (ppm)	Restricted Residential SCOs (ppm)	Restricted Industrial SCOs (ppm)	Sample Depth of Highest Concentration (feet)
Benzol(a)anthracene	7	2	2	64.8	1	5.6	11	8.0-9.0
Benzol(a)pyrene	1	7	6	47.1	22	1	1.1	8.0-9.0
Benzob(b)fluoranthene	6	3	2	39.2	1.7	5.6	11	8.0-9.0
Chrysene	6	1	0	65.2	1	56	110	8.0-9.0
Dibenz(a,h)anthracene	0	5	2	9.53	1000	0.56	1.1	8.0-9.0
Indeno(1,2,3-cd)pyrene	2	2	2	26.7	8.2	5.6	11	8.0-9.0
Arsenic	3	3	3	1,900	16	16	16	6.5-7.0
Barium	1	1	0	1,400	820	400	10000	10.5-11.0
Copper	0	1	0	580	1720	270	10000	10.5-11.0
Cyanide	1	1	0	140	40	27	10000	6.5-7.0
Lead	4	3	0	1,840	450	1000	3900	3.0-4.0
Mercury	8	5	1	6.5	0.73	2.8	5.7	6.5-7.0

Soil sample analytical results are compared to the New York State Department of Environmental Conservation (NYSDEC) Title 6 of the Official Compilation of New York Codes, Rules, and Regulations (NYCRR) Part 375 Unrestricted Use, Protection of Groundwater, and Restricted Use Restricted-Residential Soil Cleanup Objectives (SCO).
ppm= parts per million

Table 2A

57-00, 57-05, and 58-20 47th Street
Block 2601, Lot 6, Block 2601, Lot 1, and Block 2602, Lot 72
Maspeth, Queens, New York

[illegible]

Table 2A
Phase II Environmental Site Investigation
Groundwater Sample Analytical Results

Page 1 of 1

57-00, 57-05, and 58-20 47th Street
Maspeth, Queens, New York
Langan Project No.: 100965501

Notes:

CAS - Chemical Abstract Service

NS - No standard

ug/l - microgram per liter

NA - Not analyzed

RL - Reporting limit

<RL - Not detected

Groundwater sample analytical results are compared to the New York State Department of Environmental Conservation (NYSDEC) Title 6 of the Official Compilation of New York Codes, Rules, and Regulations (NYCRR) Part 703.5 and the NYSDEC Technical and Operational Guidance Series (TOGS) 1.1.1 Ambient Water Quality Standards and Guidance Values for Class GA Water (herein collectively referenced as "NYSDEC SGVs").

The criteria comparison for total metals (Chromium, Total) is provided for reference. The promulgated SGV shown is for hexavalent chromium.

Qualifiers

D - The concentration reported is a result of a diluted sample.

J - The analyte was detected above the method detection limit (MDL), but below the RL; therefore, the result is an estimated concentration.

U - The analyte was analyzed for, but was not detected at a level greater than or equal to the RL; the value shown in the table is the RL.

J - The analyte was positively identified and the associated numerical value is the approximate concentration of the analyte in the sample.

UJ - The analyte was not detected at a level greater than or equal to the RL; however, the reported RL is approximate and may be inaccurate or imprecise.

U - The analyte was analyzed for, but was not detected at a level greater than or equal to the level of the RL or the sample concentration for results impacted by blank contamination.

Exceedance Summary:

10 - Result exceeds NYSDEC SGVs

Table 2B
Groundwater Sample Analytical Results

57-00, 57-05, and 58-20 47th Street
Block 2601, Lot 6, Block 2601, Lot 1, and Block 2602, Lot 72
Maspeth, Queens, New York
Langan Project No.: 100965501

Analyte > AWQS	Detections > AWQS	Maximum Detection (ppb)	AWQS (ppb)
1,2-Dichloropropane	1	7	1
Ethylbenzene	1	8.6	5
Isopropylbenzene (Cumene)	2	24	5
n-Propylbenzene	1	6	5
Tert-Butyl Methyl Ether	1	73	10
Toluene	2	60	5
Acenaphthene	1	53	20
Anthracene	1	73	50
Benzo(a)anthracene	3	63	0.02
Benzo(a)pyrene	3	43	0
Benzo(b)fluoranthene	4	44	0.002
Benzo(k)fluoranthene	3	10	0.002
Chrysene	4	60	0.002
Fluoranthene	1	110	50
Fluorene	1	55	50
Indeno(1,2,3-cd)pyrene	4	15	0.002
Naphthalene	1	17	10
Phenanthrene	1	280	50
Pyrene	1	170	50
Antimony	6	22	3
Arsenic	6	340	25
Barium	1	2,300	1000
Beryllium	2	5.1	3
Cadmium	1	10	5
Chromium, Total	5	320	50
Copper	4	1,300	200
Iron	9	310,000	300
Lead	6	6,600	25
Magnesium	4	63,000	35,000
Manganese	8	3,090	300
Mercury	4	320	0.7
Nickel	2	150	100
Selenium	3	28	10
Sodium	9	310,000	20,000
Zinc	1	4,900	2,000

Groundwater sample analytical results are compared to the New York State Department of Environmental Conservation (NYSDEC) Title 6 of the Official Compilation of New York Codes, Rules, and Regulations (NYCRR) Part 703.5 and the NYSDEC Technical and Operational Guidance Series (TOGS) 1.1.1 Ambient Water Quality Standards and Guidance Values for Class GA Water (herein collectively referenced as "NYSDEC SGVs").

ppb= parts per billion

Table 2A
Vapor Sample Analytical Results- RCP Application Summary
57-00, 57-05, and 58-20 47th Street
Block 2601, Lot 6, Block 2601, Lot 1, and Block 2602, Lot 72
Manhattan, Queens, New York
Lungm Project No.: 1095551

SAMPLE ID: LAB ID:	NYSDOH Decision Matrix (A)	Units	Custodian	NYSDOH Decision Matrix (B)(1)		SSV01		IM01		SSV02		IM02		SSV03		IM03		SSV04		IM04		SSV05		IM05		AA01			
				Volatile Organics in Air		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS		SOX, VAPORS	
				Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q	Conc	Q
Trichloroethene	0.2	1	6	60	ND	0.107	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.079	ND	0.079	
Gas 1,2-Dichloroethene	0.2	1	6	60	ND	0.079	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.079	ND	0.079	
1,1-Dichloroethene	0.2	1	6	60	ND	0.079	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.079	ND	0.079	
Carbon tetrachloride	0.2	1	6	60	ND	0.079	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.079	ND	0.079	
Trichloroethylene	0.2	1	6	60	ND	0.079	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.793	ND	0.079	ND	0.079	ND	0.079	
1,1,1-Trichloroethane	3	10	100	1000	ND	0.109	ND	0.109	ND	1.09	ND	0.109	ND	1.09	ND	0.109	ND	1.09	ND	0.109	ND	1.09	ND	0.109	ND	0.109	ND	0.109	
Methylene Chloride	3	10	100	1000	ND	1.74	ND	1.74	ND	1.74	ND	1.74	ND	1.74	ND	1.74	ND	1.74	ND	1.74	ND	1.74	ND	1.74	ND	1.74	ND	1.74	
Vinyl Chloride	0	0.2	6	60	ND	0.051	ND	0.051	ND	0.511	ND	0.051	ND	0.511	ND	0.051	ND	0.511	ND	0.051	ND	0.511	ND	0.051	ND	0.051	ND	0.051	

Notes:
D - Indicates result is from an analysis that required a dilution
Bdd - Indicates concentration above NYSDOH soil vapor/indoor air guidance concentrations
Indicated Indoor Air Results

Table 3B
Vapor Sample Analytical Results- BCP Application Summary

57-00, 57-05, and 58-20 47th Street
Block 2601, Lot 6, Block 2601, Lot 1, and Block 2602, Lot 72
Maspeth, Queens, New York
Langan Project No.: 100965501

Analytes	Total Detections	Maximum Detection (ug/m3)	Sample Type
cis-1,2-Dichloroethylene	1	61.9	Soil Vapor
1,1-Dichloroethylene	1	61.9	Soil Vapor
Carbon tetrachloride	6	0.61	Indoor Air Ambient Air
Tetrachloroethene	11	485	Soil Vapor
Methylene chloride	1	135	Soil Vapor
Vinyl Chloride	1	501	Soil Vapor

* Reporting Limit exceedances also included
 ug/m3= Micrograms per cubic meter

ATTACHMENT F
SECTION V: REQUESTOR INFORMATION

ATTACHMENT F

SECTION V: REQUESTOR INFORMATION

Item 2 – Limited Liability Corporation Members/Owners

A copy of the entity information for 47th Street & 58th Road LLC (the Requestor) from the New York State Department of State Division of Corporations is included with this attachment. The Requestor is a foreign limited liability company, authorized to conduct business in New York State. 47th Street & 58th Road LLC is 100% owned by Prologis, L.P., a Delaware limited partnership (whose general partner is Prologis, Inc., a publicly traded real estate investment trust listed on the New York Stock Exchange under the ticker symbol: PLD). 47th Street & 58th Road LLC and Prologis, L.P. are a foreign limited liability company and a foreign limited partnership, respectively.

Department of State

Division of Corporations

Entity Information

[Return to Results](#)[Return to Search](#)

Entity Details

ENTITY NAME: 47TH STREET & 58TH ROAD LLC	DOS ID: 6320527
FOREIGN LEGAL NAME: 47TH STREET & 58TH ROAD LLC	FICTITIOUS NAME:
ENTITY TYPE: FOREIGN LIMITED LIABILITY COMPANY	DURATION DATE/LATEST DATE OF DISSOLUTION:
SECTION OF LAW: LIMITED LIABILITY COMPANY - 802 LIMITED LIABILITY COMPANY LAW - LIMITED LIABILITY COMPANY LAW	ENTITY STATUS: ACTIVE
DATE OF INITIAL DOS FILING: 11/04/2021	REASON FOR STATUS:
EFFECTIVE DATE INITIAL FILING: 11/04/2021	INACTIVE DATE:
FOREIGN FORMATION DATE: 10/27/2021	STATEMENT STATUS: CURRENT
COUNTY: ALBANY	NEXT STATEMENT DUE DATE: 11/30/2023
JURISDICTION: DELAWARE, UNITED STATES	NFP CATEGORY:

[ENTITY DISPLAY](#)[NAME HISTORY](#)[FILING HISTORY](#)[MERGER HISTORY](#)[ASSUMED NAME HISTORY](#)

Service of Process Name and Address

Name: C/O CORPORATION SERVICE COMPANY

Address: 80 STATE STREET, ALBANY, NY, UNITED STATES, 12207 - 2543

Chief Executive Officer's Name and Address

Name:

Address:

Principal Executive Office Address

Address:

Registered Agent Name and Address

Name:

Address:

Entity Primary Location Name and Address

Name:

Address:

Farmcorpflag

ATTACHMENT G
SECTION VI: REQUESTOR ELIGIBILITY

ATTACHMENT G

SECTION VI: REQUESTOR ELIGIBILITY

Item 13: BCP Volunteer Statement

The Requestor is seeking to enter the New York State Department of Environmental Conservation (NYSDEC) Brownfields Cleanup Program (BCP) as a Volunteer. Based on the following information, the Requestor qualifies as a Volunteer. Prior to purchasing the property, the Requestor performed Phase I Environmental Site Assessment (ESA) using the guidelines and limitations of the following: 1) ASTM International's (ASTM) E1527-13 (Standard Practice for ESAs: Phase I ESA Process (and subsequent amendments thereto)), and 2) the United States Environmental Protection Agency's (USEPA) 2006 standards for All Appropriate Inquiry (AAI) Rule (40 CFR Part 312). Also prior to purchasing the property, the Requestor performed a Phase II Environmental Site Investigation (ESI) to supplement existing subsurface data generated by others and summarized in the Phase I ESA. The Phase II ESI identified potential sources of contamination at the property that have been further evaluated and/or addressed by the Requestor post-closing.

The Requestor meets the requirements of a Volunteer as defined by New York Consolidated Laws, Environmental Conservation Law- ENV 27-1405 1 (b). The Requestor has the following relationship to the site in that (ii) all disposals/releases of hazardous substances occurred prior to the time of ownership and (iii) the Requestor does not have affiliation with potentially responsible parties. The Requestor's liability would arise solely as a result of ownership or involvement with the redevelopment of the site.

Since title was transferred to 47th Street & 58th Road LLC on December 30, 2022, it has exercised appropriate care by vacating the site of prior operators, maintaining the Order of Consent wetland area and buffer zone and investigating and removing two underground storage tanks (USTs). Geophysical and utility subsurface investigations were completed on-site to evaluate the location of underground utility lines and other structures including underground injection control (UIC) units. Two UIC structures were identified on the 57-05 parcel (Block 2602, Lot 72). The northern UIC structure was identified to be connected to the interior trench drains. Currently, no operations are conducted on-site and water is not being conveyed to the UIC structure from the interior trench drains. Sludge and liquids within the UIC structures located on the 57-05 parcel (Block 2602, Lot 72) is planned for removal in July 2022. Cleaning and sealing of the on-site trench drains located at the 57-00 and 57-05 parcels (Block 2601, Lot 6 and Block 2602, Lot 72) and oil/water separator located at the 57-00 parcel (Block 2601, Lot 6) will also be completed at this time. The Site is currently unoccupied, previous operations ceased approximately June 29, 2021.

Following acceptance of the property to the BCP program, the Requestor will continue to exercise appropriate care by implementing the requirements of the BCP. As such, the Requestor qualifies as a Volunteer.

Former Site Owners:

The following table is based on review of records obtained from the New York City Department of Finance Automated City Register Information System (ACRIS).

Date	Owner	Relationship to Requestor
<u>57-00 and 58-20 Parcels (Block 2601; Lots 6 & 1)</u>		
4/30/1988	Island Transportation Corporation 570 Gardner Avenue Brooklyn, NY 11222	None
4/30/1988-11/13/2020	57-00 Maspeth Avenue, LLC 248-22 Brookville Boulevard Rosedale, NY 11422	None
11/13/2020-11/17/2020	RL Family Property Owner, LLC EL Family Property Owner, LLC SLMJL Family Property Owner, LLC 248-22 Brookville Boulevard Rosedale, NY 11422	None
11/17/2020-12/30/2021	RL Family Property Owner, LLC 248-22 Brookville Boulevard Rosedale, NY 11422	None
12/30/2021-Present	47 th Street & 58 th Road LLC Pier 1, Bay 1 San Francisco, CA 9411 415.733.9574	Requestor
<u>57-05 Parcel (Block 2602; Lot 72)</u>		
1/4/1973	LECO Distributors, Inc. 57-05 47 th Street Maspeth, NY 11378	None

Date	Owner	Relationship to Requestor
<i>57-05 Parcel (Block 2602; Lot 72)</i>		
1/4/1973-11/9/1983	Laurent Associates, Inc. Andrew Libasci Here Realty, Inc. Edward N. Slade <i>42-08 Bell Boulevard Bayside, NY 11361</i>	None
11/9/1983-5/31/2006	Alfredo Lamanna <i>3 Devine Street Lynbrook, NY 11563</i>	None
5/31/2006-11/13/2020	FUMO, LLC <i>57-00 47th Street Maspeth, NY 11378</i>	None
11/13/2020-11/13/2020	RL Family Property Owner, LLC <i>248-22 Brookville Boulevard Rosedale, NY 11422</i>	None
11/13/2020-12/30/2021	RL Family Property Owner, LLC EL Family Property Owner, LLC SLMJL Family Property Owner, LLC <i>248-22 Brookville Boulevard Rosedale, NY 11422</i>	None
12/30/2021-Present	47 th Street & 58 th Road LLC <i>Pier 1, Bay 1 San Francisco, CA 9411 415.733.9574</i>	Requestor

Former Site Occupants:

The table below is based on review of City Directory; Sanborn Maps; Google Street View imagery; NY Department of State Division of Corporations, Securities and Exchange Commission filings; site interviews; recoded deeds and leases; and a title search along with standard internet searches. In addition, other sources which were utilized but produced duplicative information include ACRIS, OASIS (Department of Buildings, Department of Finance, and Zoning and Land Use). All sources utilized with the exception of Sanborn Maps were unable to identify historical owners/operators prior to the 1970s.

Reference Item	Operational Years	Occupant	Contact Information	Relationship to Requestor
<u>57-00 and 58-20 Parcels (Block 2601; Lots 6& 1)</u>				
1	December 2021-Present	Not Applicable- Vacant	47th Street & 58th Road LLC Pier 1, Bay 1 San Francisco, CA 9411 415.733.9574	Requestor
2	June 2021-December 2021	Not Applicable- Vacant	248-22 Brookville Boulevard Rosedale, NY 11422 516.361.8838	None
3	2003-June 2021	NYC Concrete Materials AKA Pebble Lane Associates, LLC	475 Market Street, Suite 300 Elmwood Park, NJ 07407 713.499.6200	None
4	2013-2017	Queen's Truck Auto Center (Repair shop)	No Return	None
5		Sky Materials	PO Box 302 Calverton, NY 11933 718.456.8090	None
6	2013-2015	Rizzo Environmental Services	1605 Lakeview Drive Hewett, NY 11557	None
7	1995-2012	Island Transportation	299 Edison Avenue Farmingdale, NY 11735 631.694.4490	None
8	2000-2005	Alfredo Lamanna Trucking Inc.	248-22 Brookville Boulevard Rosedale NY 11422 718.456.8636	None
9		Brookville Enterprises, Inc.	No longer in business	None
10		Almar Supplies, Inc.	248-22 Brookville Boulevard Rosedale NY 11422 718.456.8636	None
11	1991	United Leasing Corp.	247-32 Jericho Turnpike Bellerose Village, NY, 11001	None
12	1976	Fruehauf Trailer Corporation	No longer in business	None
13	1914-1936	Valvoline Oil Co.	3499 Dabney Drive Lexington, KY 40509	None
14	1902-1914	Moller and Co's. Fertilizer and Rendering Works	No longer in business	None
<u>57-05 Parcel (Block 2602; Lot 72)</u>				
15	December 2021-Present	Not applicable- Vacant	47th Street & 58th Road LLC Pier 1, Bay 1 San Francisco, CA 9411 415.733.9574	Requestor
16	Spring 2021-December 2021	Not applicable- Vacant	248-22 Brookville Boulevard Rosedale, NY 11422 516.361.8838	None
17	2020-May 2021	Marshark Craft NYC	1950 Steinway Street New York, NY 11105 646.705.2656	None
18	2011-2017	Almar Supplies, Inc.	248-22 Brookville Boulevard Rosedale NY 11422 718.456.8636	None
19	2005	Sagana Industries	No longer in business	None
20	2000	Office Depot Stlt	No Return	None
21	1983	Arflo Trucking Inc.	No longer in business	None
22		Queens Motor Transportation	No Return	None
23	1967-1970	Taynton HW Co. Inc. (Freight systems)	No longer in business	None
24	1914-1936	Valvoline Oil Co.	3499 Dabney Drive Lexington, KY 40509	None

Reference Items:

Below is a list of sources which were utilized to determine information in the table above:

1. Recorded deed
2. Site visit and interview with Site contact
3. Recoded lease
4. Google Street View photograph from this time period
5. Google Street View photograph from this time period and internet search verification
6. Google Street View photograph from this time period and internet search verification
7. Recoded deed and lease
8. City Directory
9. City Directory
10. City Directory
11. City Directory
12. City Directory
13. Sanborn Maps
14. Sanborn Maps
15. Recorded deed
16. Site visit and interview with Site contact
17. Google Street View photograph from this time period and internet search verification
18. Google Street View photograph from this time period and internet search verification
19. City Directory
20. City Directory
21. City Directory
22. City Directory
23. City Directory
24. Sanborn Maps

CONSULT YOUR LAWYER BEFORE SIGNING THIS INSTRUMENT--THIS INSTRUMENT SHOULD BE USED BY LAWYERS ONLY.

THIS INDENTURE, made as of this 30 day of December, 2021,

BETWEEN

RL FAMILY PROPERTY OWNER LLC, a New York limited liability company, **EL FAMILY PROPERTY OWNER LLC**, a New York limited liability company, and **SLMJL FAMILY PROPERTY OWNER LLC**, a New York limited liability company, each having an address at 248-22 Brookville Boulevard, Rosedale, New York 11422, collectively, party of the first part, and

47TH STREET & 58TH ROAD LLC, a Delaware limited liability company, having an address at c/o Prologis, Inc., 1800 Wazee Street, Suite 500, Denver, Colorado, 80202,

party of the second part.

WITNESSETH, that the party of the first part, in consideration of ten dollars and other valuable consideration paid by the party of the second part does hereby grant and release unto the party of the second part, the heirs or successors and assigns of the party of the second part forever,

Tax Map
Designation:

ALL, that certain plot, piece or parcel of land and all buildings and improvements thereon erected situated, lying and being more particularly described in Schedule "A" annexed hereto and forming a part hereof.

Block: 2601
Lot(s): 6
Queens County
Section: 14

TOGETHER with all right, title and interest, if any, of the party of the first part in and to any streets and highways abutting the above described premises to the center lines thereof; **TOGETHER** with the appurtenances and all the estate and rights of the party of the first part in and to said premises; **TO HAVE AND TO HOLD** the premises herein granted unto the party of the second part, the heirs or successors and assigns of the party of the second part forever;

Address:
57-00 47th St.,
Maspeth, NY

AND the party of the first part, in compliance with Section 13 of the Lien Law, covenants that the party of the first part will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of the improvement and will apply the same first to the payment of the cost of the improvement before using any part of the total of the same for any other purpose.

The word "party" shall be construed as if it read "parties" whenever the sense of this indenture so requires.

The Premises herein described are the same and are intended to be the same as those conveyed to the party of the first part by deed dated November 12, 2020 and recorded November 20, 2020 in the Office of the City Register of the City of New York at CRFN 2020000326467.

[End of Text; Signature Page to Follow]

CONSULT YOUR LAWYER BEFORE SIGNING THIS INSTRUMENT--THIS INSTRUMENT SHOULD BE USED BY LAWYERS ONLY.

THIS INDENTURE, made as of this 30 day of December, 2021, ~ -

BETWEEN

EL FAMILY PROPERTY OWNER LLC, a New York limited liability company, and **SLMJL FAMILY PROPERTY OWNER LLC**, a New York limited liability company, each having an address at 248-22 Brookville Boulevard, Rosedale, New York 11422,

collectively, party of the first part, and

47TH STREET & 58TH ROAD LLC, a Delaware limited liability company, having an address at c/o Prologis, Inc., 1800 Wazee Street, Suite 500, Denver, Colorado, 80202,

party of the second part.

Tax Map
Designation:

Block: 2601
Lot(s): 1
Queens County
Section: 14

Address:
58-20 47th St.,
Maspeth, NY

WITNESSETH, that the party of the first part, in consideration of ten dollars and other valuable consideration paid by the party of the second part does hereby grant and release unto the party of the second part, the heirs or successors and assigns of the party of the second part forever,

ALL of their rights, title and interest in that certain plot, piece or parcel of land and all buildings and improvements thereon erected situated, lying and being more particularly described in Schedule "A" annexed hereto and forming a part hereof.

TOGETHER with all right, title and interest, if any, of the party of the first part in and to any streets and highways abutting the above described premises to the center lines thereof; **TOGETHER** with the appurtenances and all the estate and rights of the party of the first part in and to said premises; **TO HAVE AND TO HOLD** the premises herein granted unto the party of the second part, the heirs or successors and assigns of the party of the second part forever;

AND the party of the first part, in compliance with Section 13 of the Lien Law, covenants that the party of the first part will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of the improvement and will apply the same first to the payment of the cost of the improvement before using any part of the total of the same for any other purpose.

The word "party" shall be construed as if it read "parties" whenever the sense of this indenture so requires.

The Premises herein described are the same and are intended to be the same as those conveyed to the party of the first part by deed dated November 13, 2020 and recorded November 20, 2020 in the Office of the City Register of the City of New York at CRFN 2020000326471

[End of Text; Signature Page to Follow]

CONSULT YOUR LAWYER BEFORE SIGNING THIS INSTRUMENT--THIS INSTRUMENT SHOULD BE USED BY LAWYERS ONLY.

THIS INDENTURE, made as of this 13th day of November, 2020,

BETWEEN

FUMO, LLC, a New York limited liability company, having an address at 248-22 Brookville Boulevard, Rosedale, New York 11422,

party of the first part, and

RL FAMILY PROPERTY OWNER LLC, a New York limited liability company, as to a one-third (1/3rd) undivided interest, **EL FAMILY PROPERTY OWNER LLC**, a New York limited liability company, as to a one-third (1/3rd) undivided interest, and **SLMJL FAMILY PROPERTY OWNER LLC**, a New York limited liability company, as to a one-third (1/3rd) undivided interest, each having an address at 248-22 Brookville Boulevard, Rosedale, New York 11422, with the three (3) grantees hold title as tenants-in-common,

party of the second part.

Tax Map
Designation:

Block: 2602
Lot(s): 72
Queens County
Section: 14

Address:
57-05 47th St.,
Flushing, NY

WITNESSETH, that the party of the first part, in consideration of ten dollars and other valuable consideration paid by the party of the second part does hereby grant and release unto the party of the second part, the heirs or successors and assigns of the party of the second part forever,

ALL, that certain plot, piece or parcel of land and all buildings and improvements thereon erected situated, lying and being more particularly described in Schedule "A" annexed hereto and forming a part hereof.

TOGETHER with all right, title and interest, if any, of the party of the first part in and to any streets and highways abutting the above described premises to the center lines thereof; **TOGETHER** with the appurtenances and all the estate and rights of the party of the first part in and to said premises; **TO HAVE AND TO HOLD** the premises herein granted unto the party of the second part, the heirs or successors and assigns of the party of the second part forever;

AND the party of the first part, in compliance with Section 13 of the Lien Law, covenants that the party of the first part will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of the improvement and will apply the same first to the payment of the cost of the improvement before using any part of the total of the same for any other purpose.

The word "party" shall be construed as if it read "parties" whenever the sense of this indenture so requires.

The Premises herein described are the same and are intended to be the same as those conveyed to the party of the first part by deed dated May 31, 2006 and recorded September 26, 2006 in the Office of the City Register of the City of New York at CRFN 2006000542059.

[End of Text; Signature Page to Follow]

ATTACHMENT H
SECTION XI: CONTACT LIST INFORMATION

ATTACHMENT H

SECTION XI: CONTACT LIST INFORMATION

Chief Executive Officer

Mayor Eric Adams
City Hall
260 Broadway
New York, NY 10007

New York City Planning Commission

Allen P. Cappelli, Esq., Commissioner
Department of City Planning
120 Broadway, 31st Floor
New York, NY 10271

Borough of Queens, Borough President

Donovan Richards, Jr.
120-55 Queens Boulevard
Queens, NY 11424

Residents, owners, and occupants of the site and properties adjacent to the site:

Site Owner:

47th Street & 58th Road LLC
c/o Prologis, Inc.
Pier 1 Bay 1
San Francisco, CA 94111
415.733.9574

Adjacent Property Owners and Tenants:

NYC Department of Sanitation Queens West 5 Garage
47-01 48th Street
Queens, NY 11377
718.326.9803
Owner: NYC Department of Sanitation
125 Worth Street
New York, NY 10013

Mixed Tenant Warehouse Space
57-47 47th Street
Queens, NY 11377
LaserShip: 804.414.2590
Owner: 57-47 47th Street Associates, LLC

Former Delicatessen
57-57 47th Street
Queens, NY 11377
No telephone number
Owner: 47th Street & 58th Road LLC

Newtown Creek Aeration Facility
58-26 47th Street
Queens, NY 11377
718.595.7000
Owner: NYC Department of Environmental Protection

Local news media from which the community typically obtains information

The Queens Ledger
45-23 47th Street
Woodside, NY 11377
718.639.7000

Public Water Supply

The responsibility for supplying water in New York City (NYC) is shared between the NYC Department of Environmental Protection (NYCDEP), the NYC Municipal Water Finance Authority, and the NYC Water Board:

NYCDEP
Vincent Sapienza, Commissioner
59-17 Junction Boulevard, 13th Floor
Flushing, NY 11373

NYC Municipal Water Finance Authority
255 Greenwich Street, 6th Floor
New York, NY 10007

NYC Water Board
Department of Environmental Protection
59-17 Junction Boulevard, 8th Floor
Flushing, NY 11373

Any person who has requested to be placed on the contact list:

We are unaware of any requests for inclusion on the contact list at this time.

Schools and Day Care Facilities

There are no schools or day care facilities located on the site or within ½-mile of the site.

Document Repositories:

Vincent Arcuri, Jr.
Chairperson
Queens Community Board 5
61-23 Myrtle Avenue
Queens, NY 11385
Phone: (718) 366-1834
qn05@cb.nyc.gov

Usha Pinto
Branch Manager
Queens Public Library – Maspeth Branch
69-70 Grand Avenue
Queens, NY 11378
(718) 639-5228
Usha.pinto@queenslibrary.org

Letters received from the repositories acknowledging that they agree to act as document repositories for the BCP project are included in this attachment.

31 March 2022

Usha Pinto
Branch Manager
Queens Public Library- Maspeth Branch
69-70 Grand Avenue
Queens, NY 11378

**Re: Brownfield Cleanup Program Application
57-00, 57-05, and 58-20 47th Street (the "site")
Block 2601, Lots 6 and 1; Block 2602, Lot 72
Maspeth, Queens, NY 11378**

Dear Ms. Pinto,

We represent 47th Street & 58th Road LLC in their anticipated New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program (BCP) application for the above-referenced 3.74-acre site that is comprised of Queens Borough (Queens County) Tax Block 2601, Lots 6 and 1; Block 2602, Lot 72. The Site is located in the Maspeth neighborhood of Queens. It is a NYSDEC requirement that we supply them a letter certifying that the Queens Public Library Maspeth Branch is willing and able to serve as a public repository for all documents pertaining to the cleanup of this property. Following NYSDEC review of each document, Langan will provide the Queens Public Library Maspeth Branch with a link or CD containing the files, which it will make available to the public for the duration of the site's involvement with the BCP. Please sign below if you are able to certify that your library would be willing and able to act as the temporary public repository for this BCP project.

Sincerely,
**Langan Engineering, Environmental, Surveying,
Landscape Architecture and Geology, D.P.C.**



Rebekah Diehl
Senior Staff Scientist

Yes, the Queens Public Library Maspeth Branch is willing and able to act as a public repository on behalf of 47th Street & 58th Road LLC in their cleanup of the site under the NYSDEC BCP.

USHA PINTO
(Name)

COMMUNITY LIBRARY MANAGER
(Title)

4/22/22
(Date)

31 March 2022

Vincent Arcuri, Jr.
Queens Community Board 5
61-23 Myrtle Avenue
Queens, NY 11385

**Re: Brownfield Cleanup Program Application
57-00, 57-05, and 58-20 47th Street (the "site")
Block 2601, Lots 6 and 1; Block 2602, Lot 72
Maspeth, Queens, NY 11378**

Dear Mr. Arcuri,

We represent 47th Street & 58th Road LLC in their anticipated New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program (BCP) application for the above-referenced 3.74-acre site that is comprised of Queens Borough (Queens County) Tax Block 2601, Lots 6 and 1; Block 2602, Lot 72. The Site is located in the Maspeth neighborhood of Queens. It is a NYSDEC requirement that we supply them a letter certifying that the local community board is willing and able to serve as a public repository for all documents pertaining to the cleanup of this property. Following NYSDEC review of each document, Langan will provide the local community board with a link or CD containing the files, which it will make available to the public for the duration of the site's involvement with the BCP. Please sign below if you are able to certify that your community board would be willing and able to act as the temporary public repository for this BCP project.

Sincerely,

**Langan Engineering, Environmental, Surveying,
Landscape Architecture and Geology, D.P.C.**



Rebekah Diehl
Senior Staff Scientist

Yes, the Queens Community Board 5 is willing and able to act as a public repository on behalf of 47th Street & 58th Road LLC in their cleanup of the site under the NYSDEC BCP.

Gary Giordano Gary Giordano
(Name)

4/22/2021
(Date)

District Manager
(Title)