



MONTHLY STATUS REPORT

Prepared By: Trevor Treglia

WEATHER	Snow		Rain		Overcast		Partly Cloudy	x	Bright Sun	
TEMP.	< 32		32-50		50-70		70-85	x	>85	

BCP No.:	C546047	PVE Project No.:	561231	Date:	5/26/2021
Project Name:	42 Gates Avenue, Village of Victory, Saratoga County, NY				

Consultant: PVE	Consultant On-Site: Trevor Treglia
General Contractor: N/A	General Contractor Contact: N/A

Work Activities Performed:
 PVE was retained by Victory Mills LLC (the Volunteer) for the ongoing investigation and remediation activities in accordance with the NYSDEC BCP requirements.

- Site Activities:
- No excavation activities were undertaken during the month of May.
 - No field activities were undertaken during the month of May.
 - On site structures continue to deteriorate within the BCP boundary.

- Waste Disposal:
- No waste disposal was undertaken during site activities.

Problems Encountered:

- Moderate deterioration of on-site structures.

Planned Activities for Next Month:

- Next BCP inspection scheduled for June 2021.



BCP Boundary Map



Photo Log

Photo 1 –

Overview of BCP Site.



Photo 2 –

View of northwestern side of main structure.



Photo 3 –

Interior of main structure.



Photo 4 –

View of northern side of main structure.



Photo 5 –

View of northern wooded area.



Photo 6 –

View of eastern side of main structure.



Photo 7 –

Typical view of adjoining stream along eastern side of BCP Area.



Photo 8 –

View of southern side of main structure.



Photo 9 –

Typical view of southern grassed area.



Photo 10 –

Typical interior view of main structure.



Photo 11 –

Typical basement view of main structure.

