Monthly Field Report 42 Gates Avenue, Village of Victory, Saratoga County, NY NYSDEC Site #C546047 PVE File #561231 Page 1 of 8



## **MONTHLY STATUS REPORT**

Partly Bright WEATHER Snow Rain Overcast X Cloudy Sun Prepared By: Trevor Treglia TEMP. < 32 32-50 50-70 70-85 x >85

BCP No.:	C546047	PVE Project No.:	561231	Date:	6/26/2021
Project Name:	42 Gates Avenue, Village of Victory, Saratoga County, NY				

Consultant:	Consultant On-Site:
PVE	Conor Tarbell
General Contractor:	General Contractor Contact:
N/A	N/A

## Work Activities Performed:

PVE was retained by Victory Mills LLC (the Volunteer) for the ongoing investigation and remediation activities in accordance with the NYSDEC BCP requirements.

# Site Activities:

- No excavation activities were undertaken during the month of June.
- No field activities were undertaken during the month of June.
- On site structures continue to deteriorate within the BCP boundary.

#### Waste Disposal:

No waste disposal was undertaken during site activities.

### Problems Encountered:

Moderate deterioration of on-site structures.

#### Planned Activities for Next Month:

Next BCP inspection scheduled for July 2021.

Monthly Field Report 3532 North Road, Dutchess County, Poughkeepsie, New York NYSDEC Site #C314121 PVE File #560909 Page 2 of 8



# **BCP Boundary Map**



Monthly Field Report 3532 North Road, Dutchess County, Poughkeepsie, New York NYSDEC Site #C314121 PVE File #560909 Page 3 of 8



# Photo Log

Photo 1 –

View of northwestern side of main structure.



Photo 2 –

Interior of main structure.



Monthly Field Report 3532 North Road, Dutchess County, Poughkeepsie, New York NYSDEC Site #C314121 PVE File #560909



Page 4 of 8 Photo 3 –

View of northern side of main structure.



Photo 4 –

View of northern wooded area.



Monthly Field Report 3532 North Road, Dutchess County, Poughkeepsie, New York NYSDEC Site #C314121 PVE File #560909 Page 5 of 8



Photo 5 –

View of eastern side of main structure.



Photo 6 -

Typical view of adjoining stream along eastern side of BCP Area.



Monthly Field Report 3532 North Road, Dutchess County, Poughkeepsie, New York NYSDEC Site #C314121 PVE File #560909



Page 6 of 8 Photo 7 –

View of southern side of main structure.



Photo 8 –

Typical view of southern grassed area.



Monthly Field Report 3532 North Road, Dutchess County, Poughkeepsie, New York NYSDEC Site #C314121 PVE File #560909



Page 7 of 8 Photo 9 –

Typical interior view of main structure.



Photo 10 -

Typical basement view of main structure.

