C&S Companies

499 Colonel Eileen Collins Blvd Syracuse, NY 13212 p: (315) 455-2000 www.cscos.com

REMEDIAL INVESTIGATION

MONTHLY PROGRESS REPORT

FOR
SOUTH SALINA STREET PARCELS
1081 SOUTH SALINA STREET
CITY OF SYRACUSE, ONONDAGA COUNTY, NEW YORK

NYSDEC SITE No. C734140

PROGRESS REPORT #20
REPORTING PERIOD: JULY 2022

Introduction

This progress report has been prepared to inform the NYS Department of Environmental Conservation ("NYSDEC") on the progress of the investigation of the South Salina Street Parcels Site in Syracuse, New York. The Site is in the Brownfield Cleanup Program.

Deliverables Completed and Submitted:

No work plans, reports, or other deliverables were completed during this reporting period.

Work to be Completed Next Reporting Period:

Construction began on June 6, 2022. Security fencing was installed and a large portion of the stumps were removed. Additional work is delayed while geotechnical information is being generated. Work resumed in early August. Currently, work is mainly focused on topsoil stripping and landfill disposal.

C&S will continue to provide full time construction observation and air monitoring.

Percentage Complete and Delays Encountered / Anticipated:

The Remedial Investigation is complete.

Sincerely,

C&S ENGINEERS, INC.

Matthew L. Walker

Senior Project Environmental Scientist

cc: file