



**C&S Companies**  
499 Colonel Eileen Collins Blvd  
Syracuse, NY 13212  
p: (315) 455-2000  
www.cscos.com

**REMEDIAL INVESTIGATION**

**MONTHLY PROGRESS REPORT**

FOR

SOUTH SALINA STREET PARCELS

1081 SOUTH SALINA STREET

CITY OF SYRACUSE, ONONDAGA COUNTY, NEW YORK

**NYSDEC SITE NO. C734140**

PROGRESS REPORT #27

*REPORTING PERIOD: APRIL / MAY 2023*

---

**Introduction**

This progress report has been prepared to inform the NYS Department of Environmental Conservation ("NYSDEC") on the progress of the investigation of the South Salina Street Parcels Site in Syracuse, New York. The Site is in the Brownfield Cleanup Program.

**Deliverables Completed and Submitted:**

None during the reporting period.

**Work Completed During Reporting Period:**

- None.

**Work to be Completed Next Reporting Period:**

Volunteer will continue to maintain security fence and erosion controls.

**Percentage Complete and Delays Encountered / Anticipated:**

The Remedial Investigation is complete.

Sincerely,

**C&S ENGINEERS, INC.**

A handwritten signature in black ink, appearing to read 'Matt L. Walker'.

Matthew L. Walker

Senior Project Environmental Scientist

cc: file