NYSDEC SPILL REPORT FORM

DEC REGION: 7 **SPILL NUMBER:** 2201762

SPILL NAME: GRASS **DEC LEAD:** AYRUSSO

CALLER NAME: ROBERT NOTARO **NOTIFIER'S NAME:** ROBERT NOTARO

CLR'S AGENCY: SUN ENVIROMENTAL **NOTIFIER'S AGENCY:** SUN ENVIROMENTAL

CALLER'S PHONE: (315) 956-0213 **NOTIFIER'S PHONE:** (315) 956-0213

SPILL DATE: 05/26/2022 **SPILL TIME:** 11:00 am **DISPATCHER:**

CALL RECEIVED DATE: 05/26/2022 **RECEIVED TIME:** 11:56 am AAABDELR

SPILL LOCATION

PLACE: GRASS **COUNTY:** Onondaga

STREET: CORNER OF LOUCKS RD AND CANADA DRV **TOWN/CITY:** Dewitt

COMMUNITY: DEWITT

CONTACT: ROBERT NOTARO **CONTACT PHONE:** (315) 956-0213

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Other

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

Hydraulic line blew that caused spill. Area is cleaned.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
hydraulic oil	Petroleum	2.00 G		

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
SUN ENVIROMENTAL	CORNER OF LOUKES RD AND CANADA DRV DEWI	ROBERT NOTARO (315) 956-0213

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

5/26/2022 DEC Anthony Russo spoke with Sun Environmental who is the RP. Said the hydraulic line blew on one of their excavators when it got snagged on a tree root. About 2 gallons spilled to grass. Waste to be drummed and disposed of as potential PCB waste because of the nature of the site. Two drums of waste genereated. Clean up already complete.

PIN **T & A** **COST CENTER**

CLASS: D4 **CLOSE DATE:** 05/27/2022 **MEETS STANDARDS:** True