



July 10, 2009

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

June 2009 Progress Report
Index # B8-0735-07-01
Site #C828142

Dear Mr. Caffoe:

Pursuant to the Brownfield Site Cleanup Agreement for the 666 Driving Park Site, this progress report has been prepared to summarize project activities performed during June 2009.

There were no RI field activities in June. The second round groundwater and metals delineation analytical results were received in June. These results will be provided with the revised RI report.

Weekly site inspections began on June 2, 2008. Site inspections, as requested by NYSDEC, will be completed throughout and following the RI to assess the integrity of the site fence and make repairs as needed. Site inspection reports corresponding to the period from April 6th to June 22, 2009 are attached. With the cessation of RI fieldwork, site inspections are now conducted every other week.

If you have any questions regarding this schedule please contact me at (716) 278-5496.


Regards,
DuPont Corporate Remediation Group

A handwritten signature in black ink, appearing to read "Paul Mazierski".

Paul Mazierski
Project Director

S:\URS\RDP\Monthly Reports\June 09\RDP 06_09 Monthly Report.doc
PM/dms/mac

cc: Bart Putzig, Lisa LoMaestro Silvestri, Maura Desmond, NYSDEC
Katherine Comerford, NYSDOH
Joseph Biondillo, Mark Gregor, City of Rochester; Jeff Danzinger, Day Environmental
Joseph Albert, Monroe County Health Dept.
Steve Rahaim, Maura C. Desmond, Steve Sterenchock, Maryann Nicholson, DuPont
Daniel M. Sheldon, URSD Corporation
CRG Projects Database/Project No. 507463



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 4/6/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496


Maintenance Performed (Check)

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: all are secure and check good
 - b)
 - c) **Breaches –** Remarks: none to report at this time
 - d) **Slatted Fencing Condition:** Remarks: N/A
 - e) **Vegetative Overgrowth–** Remarks: none
- X 2) **Site Status**
- a) **Debris –** none
 - b) **Surface Staining –** Remarks: N/A
 - c) **Storm Drains –** Remarks: semi clear and functioning
 - d) **Monitoring Wells –** Remarks: check good
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: Good
- X 3) **Other –** Remarks:

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 4/13/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496


**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: good -everything locked
 - b)
 - c) **Breaches -** Remarks: none
 - d) **Slatted Fencing Condition:** Remarks: none
 - e) **Vegetative Overgrowth-** Remarks: no vegetative overgrowth
- X 2) **Site Status**
- a) **Debris -** no debris at this time
 - b) **Surface Staining -** Remarks: no surface staining
 - c) **Storm Drains -** Remarks: check good, functioning
 - d) **Monitoring Wells -** Remarks: N/A
 - e) **Light Poles -** Remarks: N/A
 - f) **Pavement Condition -** Remarks: pavement is good
- X 3) **Other -** Remarks:

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 4/20/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: all are locked and secure at this time
- b)
- c) **Breaches –** Remarks: no breaches to report
- d) **Slatted Fencing Condition:** Remarks: good condition
- e) **Vegetative Overgrowth–** Remarks: none


X 2) **Site Status**

- a) **Debris –** no debris noted at this time
- b) **Surface Staining –** Remarks: none
- c) **Storm Drains –** Remarks: functioning
- d) **Monitoring Wells –** Remarks: none
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: good condition right now

X 3) **Other –** Remarks: _____

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 4/27/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

X 1)

Fence

- a) **Locks/Gate-** Remarks: locked and secure at this time
- b) **Breaches –** Remarks: no breaches to report
- c) **Slatted Fencing Condition:** Remarks: good condition
- d) **Vegetative Overgrowth–** Remarks: none

X 2)

Site Status


- a) **Debris –** no debris noted at this time
- b) **Surface Staining –** Remarks: none
- c) **Storm Drains –** Remarks: functioning
- d) **Monitoring Wells –** Remarks: none
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: good condition right now

X

3) **Other –** Remarks:

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 5/4/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496


Maintenance Performed (Check)

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: all are locked and secure
 - b) **Breaches –** Remarks: no breaches to report
 - c) **Slatted Fencing Condition:** Remarks: good condition
 - d) **Vegetative Overgrowth–** Remarks: none
- X 2) **Site Status**
- a) **Debris –** no debris
 - b) **Surface Staining –** Remarks: none
 - c) **Storm Drains –** Remarks: OK
 - d) **Monitoring Wells –** Remarks: none
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: good
- X 3) **Other –** Remarks:

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 5/11/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: all secure
- b) **Breaches –** Remarks: no breaches
- c) **Slatted Fencing Condition:** Remarks: NA
- d) **Vegetative Overgrowth–** Remarks: none


X 2) **Site Status**

- a) **Debris –** no debris
- b) **Surface Staining –** Remarks: no surface staining
- c) **Storm Drains –** Remarks: OK
- d) **Monitoring Wells –** Remarks: none
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: good condition

X 3) **Other –** Remarks:

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 5/18/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496


**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: all are secured
 - b) **Breaches –** Remarks: no breaches at this time
 - c) **Slatted Fencing Condition:** Remarks: NA
 - d) **Vegetative Overgrowth–** Remarks: no vegetative overgrowth
- X 2) **Site Status**
- a) **Debris –** no debris
 - b) **Surface Staining –** Remarks: no surface staining
 - c) **Storm Drains –** Remarks: semi clear and functioning
 - d) **Monitoring Wells –** Remarks: locked and secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: good
- X 3) **Other –** Remarks:

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 5/26/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: locks/gates are all secure
- b) **Breaches –** Remarks: no breaches
- c) **Slatted Fencing Condition:** Remarks: NA
- d) **Vegetative Overgrowth–** Remarks: None

X 2) **Site Status**

- a) **Debris –** N/A
- b) **Surface Staining –** Remarks: no surface staining at this time
- c) **Storm Drains –** Remarks: semi clear and functioning
- d) **Monitoring Wells –** Remarks: locked and secure
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: good condition

X 3) **Other –** Remarks:

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 6/8/09 EMERGENCY CONTACT:
INSPECTOR: Cliff Simon PAUL MAZIERSKI
WITNESSES: 716-278-5496


Maintenance Performed (Check)

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: Locks and gates secure
 - b)
 - c) **Breaches –** Remarks: no breaches at this time
 - d) **Slatted Fencing Condition:** Remarks: Standing & Secure
 - e) **Vegetative Overgrowth–** Remarks: needs mowing
- X 2) **Site Status**
- a) **Debris –** no debris
 - b) **Surface Staining –** Remarks: None at this time
 - c) **Storm Drains –** Remarks: semi clear and functioning
 - d) **Monitoring Wells –** Remarks: all check good and secured
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: Good
- X 3) **Other –** Remarks: _____

REQUIRED MAINTENANCE ACTIVITIES:

none



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 6/22/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: locks/gates check good and secure
 - b) **Breaches –** Remarks: found large section approximately 27” of chain link fence missing –SW section near driving park by R&R
 - c) **Slatted Fencing Condition:** Remarks: check good
 - d) **Vegetative Overgrowth–** Remarks: all cut down
- X 2) **Site Status**
- a) **Debris –** No debris at this time
 - b) **Surface Staining –** Remarks: no surface staining at this time
 - c) **Storm Drains –** Remarks: semi -clear and functioning
 - d) **Monitoring Wells –** Remarks: check locked and secured
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: check good to fair at this time
- X 3) **Other –** Remarks:

REQUIRED MAINTENANCE ACTIVITIES:

none