



DuPont Corporate Remediation Group  
Buffalo Avenue & 26<sup>th</sup> Street  
Building 35  
Niagara Falls, NY 14302  
(716) 278-5100

August 17, 2009

Todd M. Caffoe, P.E.  
Environmental Engineer 2  
New York State Department of Environmental Conservation – Region 8  
6274 East Avon-Lima Road  
Avon, New York 14414

**July 2009 Progress Report**  
**Index # B8-0735-07-01**  
**Site #C828142**

Dear Mr. Caffoe:

Pursuant to the Brownfield Site Cleanup Agreement for the 666 Driving Park Site, this progress report has been prepared to summarize project activities performed during July 2009.

There were no RI field activities in June. The revised RI report, which will include the second round groundwater and metals delineation soil results, will be submitted to the Agency in September.

Weekly site inspections began on June 2, 2008. Site inspections, as requested by NYSDEC, will be completed throughout and following the RI to assess the integrity of the site fence and make repairs as needed. Site inspection reports from inspections completed in July are attached.


If you have any questions regarding this schedule please contact me at (716) 278-5496.

Regards,  
**DuPont Corporate Remediation Group**

Paul Mazierski  
Project Director

S:\URS\RDP\Monthly Reports\June 09\RDP 07\_09 Monthly Report.doc  
PM/dms/mac

cc: Bart Putzig, Lisa LoMaestro Silvestri, Maura Desmond, NYSDEC  
Katherine Comerford, NYSDOH  
Joseph Biondillo, Mark Gregor, City of Rochester; Jeff Danzinger, Day Environmental  
Joseph Albert, Monroe County Health Dept.  
Steve Rahaim, Maura C. Desmond, Steve Sterenchock, Maryann Nicholson, DuPont  
Daniel M. Sheldon, URSD Corporation  
CRG Projects Database/Project No. 507463



# S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

## 666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 7/7/09  
INSPECTOR: Cliff Simon  
WITNESSES:

EMERGENCY CONTACT:  
PAUL MAZIERSKI  
716-278-5496

**Maintenance  
Performed  
(Check)**

**Item**

X 1) **Fence**

- a) **Locks/Gate-** Remarks: locks and gates check secure
- b) **Breaches –** Remarks: 27" of chain link fence still missing –
- c) **Slatted Fencing Condition:** Remarks: 1 small section off and on ground covered with tree branch
- d) **Vegetative Overgrowth–** Remarks: check good

X 2) **Site Status**

- a) **Debris –** No debris at this time
- b) **Surface Staining –** Remarks: none found at this time
- c) **Storm Drains –** Remarks: semi -clear and functioning
- d) **Monitoring Wells –** Remarks: check secure and good condition
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: check good at this time

X 3) **Other –** Remarks: \_\_\_\_\_

**REQUIRED MAINTENANCE ACTIVITIES:** awaiting fence contractor to assess and cost of repair



# S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

## 666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 7/27/09  
INSPECTOR: Cliff Simon  
WITNESSES:

EMERGENCY CONTACT:  
PAUL MAZIERSKI  
716-278-5496

### **Maintenance Performed (Check)**

### **Item**

X 1) **Fence**

- a) **Locks/Gate-** Remarks: locks and gates check secured
- b) **Breaches –** Remarks: 27" of chain link fence still missing –have quote, approved by Stu, awaiting schedule
- c) **Slatted Fencing Condition:** Remarks: 1 small section off and on ground covered with tree branch
- d) **Vegetative Overgrowth–** Remarks: check good

X 2) **Site Status**

- a) **Debris –** No debris at this time
- b) **Surface Staining –** Remarks: none found at this time
- c) **Storm Drains –** Remarks: semi -clear and functioning
- d) **Monitoring Wells –** Remarks: check secure and good condition
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: check good at this time

X 3) **Other –** Remarks: \_\_\_\_\_

**REQUIRED MAINTENANCE ACTIVITIES:** scheduling fence repair by  
NYS Fence