

October 10, 2009

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **September 2009 Progress Report**
Index # B8-0735-07-01
Site #C828142

Dear Mr. Caffoe:

On behalf of DuPont CRG, Parsons is pleased to provide this monthly progress report summarizing the project activities performed during September 2009 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site.

There were no Remedial Investigation (RI) field activities in September. The revised RI report, which will include the second round groundwater and metals delineation soil results, will be submitted to the New York State Department of Environmental Conservation (NYSDEC) in November 2009.

Weekly site inspections began on June 2, 2008. Site inspections, as requested by NYSDEC, will be completed throughout and following the RI to assess the integrity of the site fence and make repairs as needed. Site inspection reports from inspections completed in September are attached.

Please contact me at (716) 432-7685 if you have any questions

Sincerely,


PARSONS



Jeffrey S. Poulsen
Project Manager

Attachment: Site Inspection Forms

cc: Bart Putzig, Lisa LoMaestro Silvestri, Maura Desmond, NYSDEC
Katherine Comerford, NYSDOH
Joseph Biondillo, Mark Gregor, City of Rochester; Jeff Danzinger, Day Environmental
Joseph Albert, Monroe County Health Dept.
Steve Rahaim, Steve Sterenchock, Maryann Nicholson, DuPont
Paul F Mazierski, DuPont CRG
Carole Luttrell, CRG Projects Database/Project No. 507463
Parsons File: 445424 – correspondence sent



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 9/14/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: Lock and gates check secured
- b) **Breaches –** Remarks: No Breaches at this time
- c) **Slatted Fencing Condition:** Remarks: standing with small section down
- d) **Vegetative Overgrowth–** Remarks: Interior fence line w. side tree overgrowth. North corner sumac over growth

X 2) **Site Status**

- a) **Debris –** no debris at this time
- b) **Surface Staining –** Remarks: no surface staining at this time
- c) **Storm Drains –** Remarks: semi clear and functioning
- d) **Monitoring Wells –** Remarks: wells check secured
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: Fair condition at this time

X 3) **Other –** _____

REQUIRED MAINTENANCE ACTIVITIES:



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 9/21/09
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: Lock and gates check secured
- b) **Breaches –** Remarks: No Breaches at this time
- c) **Slatted Fencing Condition:** Remarks: standing with 1 piece down
- d) **Vegetative Overgrowth–** Remarks: Field is clear cut and clean

X 2) **Site Status**

- a) **Debris –** no debris at this time
- b) **Surface Staining –** Remarks: no surface staining at this time
- c) **Storm Drains –** Remarks: semi clear and functioning
- d) **Monitoring Wells –** Remarks: Locks and caps check secured
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: Fair condition at this time

X 3) **Other –** _____

REQUIRED MAINTENANCE ACTIVITIES: Fence line west side will require trimming or removal of vines and trees