

February 5, 2010

Todd M. Caffoe, P.E.  
Environmental Engineer 2  
New York State Department of Environmental Conservation – Region 8  
6274 East Avon-Lima Road  
Avon, New York 14414

RE: **January 2010 Progress Report**  
**Index # B8-0735-07-01**  
**Site #C828142**

Dear Mr. Caffoe:

On behalf of DuPont CRG, Parsons is pleased to provide this monthly progress report summarizing the project activities performed during January 2010 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site.

There were no Remedial Investigation (RI) field activities in December. The revised RI Addendum, which will include the second round groundwater and metals delineation soil results, is scheduled to be submitted to the New York State Department of Environmental Conservation (NYSDEC) in early 2010.

Weekly site inspections began on June 2, 2008. Site inspections, as requested by NYSDEC, will be completed throughout and following the RI to assess the integrity of the site fence and make repairs as needed. Site inspection reports from inspections completed in January are attached.

Please contact me at (716) 432-7685 if you have any questions

Sincerely,

**PARSONS**



Jeffrey S. Poulsen  
Project Manager

Attachment: Site Inspection Forms (2)

cc: Bart Putzig, Lisa LoMaestro Silvestri, Maura Desmond, NYSDEC  
Katherine Comerford, NYSDOH  
Joseph Biondillo, Mark Gregor, City of Rochester; Jeff Danzinger, Day Environmental  
Joseph Albert, Monroe County Health Dept.  
Steve Rahaim, Steve Sterenchock, Maryann Nicholson, DuPont  
Paul F Mazierski, DuPont CRG  
Carol Luttrell, CRG Projects Database/Project No. 507463  
Parsons File: 445424 – correspondence sent



# S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

## 666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 1/13/2010  
INSPECTOR: Cliff Simon  
WITNESSES:

EMERGENCY CONTACT:  
PAUL MAZIERSKI  
716-278-5496

### **Maintenance Performed (Check)**

### **Item**

X 1) **Fence**

- a) **Locks/Gate-** Remarks: Lock and gates check secured
- b) **Breaches –** Remarks: no breaches at this time
- c) **Slatted Fencing Condition:** Remarks: checks good
- d) **Vegetative Overgrowth–** Remarks: snow covered 1.5 feet

X 2) **Site Status**


- a) **Debris –** snow covered
- b) **Surface Staining –** Remarks: snow covered
- c) **Storm Drains –** Remarks: snow covered
- d) **Monitoring Wells –** Remarks: check secured
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: snow covered

X 3) **Other –** \_\_\_\_\_ All gates blocked by snow banks

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

### **REQUIRED MAINTENANCE ACTIVITIES:**

\_\_\_\_\_  
\_\_\_\_\_



# S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

## 666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 1/29/2010  
INSPECTOR: Cliff Simon  
WITNESSES:

EMERGENCY CONTACT:  
PAUL MAZIERSKI  
716-278-5496

### **Maintenance Performed (Check)**

### **Item**

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: Lock and gates check secured
  - b) **Breaches –** Remarks: no breaches at this time
  - c) **Slatted Fencing Condition:** Remarks: checks good
  - d) **Vegetative Overgrowth–** Remarks: no overgrowth at this time
- X 2) **Site Status**
- a) **Debris –** No debris
  - b) **Surface Staining –** Remarks: checks good
  - c) **Storm Drains –** Remarks: functioning
  - d) **Monitoring Wells –** Remarks: check secured
  - e) **Light Poles –** Remarks: N/A
  - f) **Pavement Condition –** Remarks: checks good
- X 3) **Other –** N/A
- 
- 
- 

### **REQUIRED MAINTENANCE ACTIVITIES:**

---

---