

March 9, 2010

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **February 2010 Progress Report**
Index # B8-0735-07-01
Site #C828142

Dear Mr. Caffoe:

On behalf of DuPont CRG, Parsons is pleased to provide this monthly progress report summarizing the project activities performed during February 2010 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site.

There were no Remedial Investigation (RI) field activities in December. The revised RI Addendum, which will include the second round groundwater and metals delineation soil results, is scheduled to be submitted to the New York State Department of Environmental Conservation (NYSDEC) in April 2010.

Weekly site inspections began on June 2, 2008. Site inspections, as requested by NYSDEC, will be completed throughout and following the RI to assess the integrity of the site fence and make repairs as needed. The site inspection report from the inspection completed in February is attached.

Please contact me at (716) 432-7685 if you have any questions

Sincerely,


PARSONS



Jeffrey S. Poulsen
Project Manager

Attachment: Site Inspection Forms (1)

cc: Bart Putzig, Lisa LoMaestro Silvestri, Maura Desmond, NYSDEC
Katherine Comerford, NYSDOH
Joseph Biondillo, Mark Gregor, City of Rochester; Jeff Danzinger, Day Environmental
Joseph Albert, Monroe County Health Dept.
Steve Rahaim, Steve Sterenchock, Maryann Nicholson, DuPont
Paul F Mazierski, DuPont CRG
Carol Luttrell, CRG Projects Database/Project No. 507463
Parsons File: 445424 – correspondence sent



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 2/19/10
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: Lock and gates check secured
 - b) **Breaches –** Remarks: no breaches at this time
 - c) **Slatted Fencing Condition:** Remarks: slatted fence secured
 - d) **Vegetative Overgrowth–** Remarks: no overgrowth – snow covered
- X 2) **Site Status**
- a) **Debris –** Remarks: No debris at this time – snow covered
 - b) **Surface Staining –** Remarks: snow covered
 - c) **Storm Drains –** Remarks: snow covered
 - d) **Monitoring Wells –** Remarks: check secured
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: snow covered
- X 3) **Other –** Main gate blocked by snow plow remains
- _____
- _____
- _____

REQUIRED MAINTENANCE ACTIVITIES:
