

June 3, 2010

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **May 2010 Progress Report**
Index # B8-0735-07-01
Site #C828142

Dear Mr. Caffoe:

On behalf of DuPont CRG, Parsons is pleased to provide this monthly progress report summarizing the project activities performed during May 2010 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site.

There were no Remedial Investigation (RI) field activities in May.

Weekly site inspections began on June 2, 2008. Site inspections, as requested by NYSDEC, will continue to be made to assess the integrity of the site fence and make repairs as needed. The reports from the two inspections completed in May are attached.

Please contact me at (716) 432-7685 if you have any questions

Sincerely,

PARSONS



Jeffrey S. Poulsen
Project Manager

Attachment: Site Inspection Forms (2)

cc: Bart Putzig, Lisa LoMaestro Silvestri, Maura Desmond, NYSDEC
Katherine Comerford, NYSDOH
Joseph Biondillo, Mark Gregor, City of Rochester; Jeff Danzinger, Day Environmental
Joseph Albert, Monroe County Health Dept.
Steve Rahaim, Steve Sterenchock, Maryann Nicholson, DuPont
Paul F Mazierski, DuPont CRG
Carol Luttrell, CRG Projects Database/Project No. 507463
Parsons File: 445424 – correspondence sent

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 5-11-2010
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: Lock and gates check secured
 - b) **Breaches –** Remarks: no breaches at this time
 - c) **Slatted Fencing Condition:** Remarks: slatted fence check standing/secured
 - d) **Vegetative Overgrowth–** Remarks: Mild growth at this time
- X 2) **Site Status**
- a) **Debris –** Remarks: Fair debris –little to none
 - b) **Surface Staining –** Remarks: No surface staining at this time
 - c) **Storm Drains –** Remarks: semi-clear & functional
 - d) **Monitoring Wells –** Remarks: check secured and locked at this time
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: Pavement in fair condition at this time
- X 3) **Other –** _____

REQUIRED MAINTENANCE ACTIVITIES:



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 5-24-2010
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: Lock and gates check secured
- b) **Breaches –** Remarks: no breaches at this time
- c) **Slatted Fencing Condition:** Remarks: slatted fence check standing/secured
- d) **Vegetative Overgrowth–** Remarks: will require mowing

X 2) **Site Status**

- a) **Debris –** Remarks: piles of tree debris along slatted fence
- b) **Surface Staining –** Remarks: No staining at this time
- c) **Storm Drains –** Remarks: semi-obstructed & functional
- d) **Monitoring Wells –** Remarks: check secured
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: Pavement in fair condition

X 3) **Other –** N/A at this time

REQUIRED MAINTENANCE ACTIVITIES: