

January 6, 2011

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **December 2010 Progress Report**
Index # B8-0735-07-01
Site #C828142

Dear Mr. Caffoe:

On behalf of DuPont CRG, Parsons is pleased to provide this monthly progress report summarizing the project activities performed during December 2010 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site.

Inspections began on June 2, 2008. Site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), will continue to be made to assess the integrity of the site fence and make repairs as needed. The reports from the three inspections completed in December are attached.

DuPont has completed the Remedial Alternative Analysis Report (RAAR) in accordance with the December 31, 2010 submittal schedule agreed to by the NYSDEC. Copies of the Report were submitted to the agencies on December 30, 2010.

Please contact me at (716) 432-7685 if you have any questions

Sincerely,

PARSONS



Jeffrey S. Poulsen, Project Manager

Attachment: Site Inspection Forms (3)

cc: Bart Putzig, Lisa LoMaestro Silvestri, Maura Desmond, NYSDEC
Katherine Fish (Comerford), NYSDOH
Joseph Biondillo, Mark Gregor, City of Rochester
Jeff Danzinger, Day Environmental
Joseph Albert, Monroe County Health Dept.
Steve Rahaim, Steve Sterenchock, Maryann Nicholson, DuPont
Paul F Mazierski, DuPont CRG
Carol Luttrell, CRG Projects Database/Project No. 507463
Parsons File: 446306 – correspondence sent



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 12/3/2010
INSPECTOR: Ty Hookway
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: Lock and gates check secured
 - b) **Breaches –** Remarks: No Breaches at this time
 - c) **Slatted Fencing Condition:** Remarks: slatted fencing standing/secured
 - d) **Vegetative Overgrowth–** Remarks: No overgrowth
- X 2) **Site Status**
- a) **Debris –** Remarks: No debris at this time
 - b) **Surface Staining –** Remarks: No surface staining at this time
 - c) **Storm Drains –** Remarks: storm drains clear and functioning
 - d) **Monitoring Wells –** Remarks: check secured
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: Pavement in fair condition –
- X 3) **Other** Note: none

REQUIRED MAINTENANCE ACTIVITIES:



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 12/20/2010
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: Lock and gates check secured
- b) **Breaches –** Remarks: No Breaches at this time
- c) **Slatted Fencing Condition:** Remarks: slatted fencing standing/secured
- d) **Vegetative Overgrowth–** Remarks: snow covered

X 2) **Site Status**

- a) **Debris –** Remarks: only snow
- b) **Surface Staining –** Remarks: snow covered
- c) **Storm Drains –** Remarks: storm drains open and functioning
- d) **Monitoring Wells –** Remarks: check secured
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: snow covered –

X 3) **Other** Note: none

REQUIRED MAINTENANCE ACTIVITIES:



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 12/28/2010
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: Lock and gates check secured
 - b) **Breaches –** Remarks: No Breaches at this time
 - c) **Slatted Fencing Condition:** Remarks: slatted fencing standing/secured
 - d) **Vegetative Overgrowth–** Remarks: still snow covered
- X 2) **Site Status**
- a) **Debris –** Remarks: snow
 - b) **Surface Staining –** Remarks: snow covered
 - c) **Storm Drains –** Remarks: storm drains open and functioning
 - d) **Monitoring Wells –** Remarks: check secured
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: snow covered –
- X 3) **Other** Note: none

REQUIRED MAINTENANCE ACTIVITIES:
