

July 5, 2011

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **June 2011 Progress Report**
Index # B8-0735-07-01
Site #C828142

Dear Mr. Caffoe:

On behalf of DuPont CRG, Parsons is pleased to provide this monthly progress report summarizing the project activities performed during June 2011 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Inspections at this site began on June 2, 2008. Site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), will continue to be made weekly to assess the integrity of the site fence and make repairs as needed. Reports from the four inspections completed during June are attached.

DuPont received on June 16, 2011 the Department's comments on the Remedial Alternatives Analysis Report which DuPont submitted to the Department during the first week of January. DuPont will respond to the Department's comments within 30 days of receipt.

Feel free to contact me in Syracuse at (315) 552-9674 if you have any questions.

Sincerely,

PARSONS



David B. Babcock, P.E.
Project Manager

Attachment: Site Inspection Forms (4)

cc: Bart Putzig, Maura Desmond, NYSDEC
Katherine Fish (Comerford), NYSDOH
Joseph Biondolillo, Mark Gregor, City of Rochester
Jeff Danzinger, Day Environmental
Joseph Albert, Monroe County Health Dept.
Steve Rahaim, Steve Sterenchock, Maryann Nicholson, DuPont
Paul F Mazierski, DuPont CRG
Carol Luttrell, CRG Projects Database/Project No. 507463
Parsons File: 446306 – correspondence sent



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 6/6/2011
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

- X 1) Fence
- a) Locks/Gate- Remarks: main gate lock cut, other locks check good
 - b) Breaches – Remarks: No Breaches
 - c) Slatted Fencing Condition: Remarks: Slatted fencing check secure and standing
 - d) Vegetative Overgrowth– Remarks: Stonewood and Waters will be here this week to cut overgrowth
- X 2) Site Status
- a) Debris – Remarks: no major debris at this time
 - b) Surface Staining – Remarks: no surface staining at this time
 - c) Storm Drains – Remarks: clear and functioning
 - d) Monitoring Wells – Remarks: monitoring wells check secure
 - e) Light Poles – Remarks: N/A
 - f) Pavement Condition – Remarks: fair
- X 3) Other Note: _____

REQUIRED MAINTENANCE ACTIVITIES:



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 6/13/2011
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: main gate lock cut, other locks check good
- b) **Breaches –** Remarks: No Breaches at this time
- c) **Slatted Fencing Condition:** Remarks: Slatted fencing check secure and standing
- d) **Vegetative Overgrowth–** Remarks: All grass and weeds cut down

X 2) **Site Status**

- a) **Debris –** Remarks: no major debris at this time
- b) **Surface Staining –** Remarks: no surface staining
- c) **Storm Drains –** Remarks: clear and functioning
- d) **Monitoring Wells –** Remarks: monitoring wells check secure
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: fair

X 3) **Other** Note: Installed Combination lock #3006 to open. On main entrance gate

REQUIRED MAINTENANCE ACTIVITIES:



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 6/20/2011
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

Maintenance Performed (Check)

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: Locks and gates check secure!
 - b) **Breaches –** Remarks: No Breaches found at this time
 - c) **Slatted Fencing Condition:** Remarks: Slatted fencing check secure and standing
 - d) **Vegetative Overgrowth–** Remarks: no vegetative overgrowth
- X 2) **Site Status**
- a) **Debris –** Remarks: no major debris at this time
 - b) **Surface Staining –** Remarks: no surface staining
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: monitoring wells check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair
- X 3) **Other** Note: _____

REQUIRED MAINTENANCE ACTIVITIES:



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE: 6/27/2011
INSPECTOR: Cliff Simon
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: Locks and gates check secure!
- b) **Breaches –** Remarks: No Breaches found at this time
- c) **Slatted Fencing Condition:** Remarks: Slatted fencing check secure and standing
- d) **Vegetative Overgrowth–** Remarks: no vegetative overgrowth

X 2) **Site Status**

- a) **Debris –** Remarks: no debris at this time
- b) **Surface Staining –** Remarks: no surface staining
- c) **Storm Drains –** Remarks: clear and functioning
- d) **Monitoring Wells –** Remarks: monitoring wells check secure
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: fair

X 3) **Other** Note: N/A

REQUIRED MAINTENANCE ACTIVITIES:
