

April 1, 2014

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **January through March 2014 Quarterly Progress Report**
Index # B8-0735-07-01
DuPont Rochester Driving Park Site (#C828142)

Dear Mr. Caffoe:

On behalf of DuPont's Corporate Remediation Group (CRG), Parsons is pleased to provide this quarterly progress report summarizing project activities for January through March 2014 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), began on June 2, 2008 and continue to be conducted weekly on behalf of DuPont to assess site conditions and maintain the site as needed. Reports from the 12 weekly inspections completed during January, February and March 2014 are attached. The most recent weekly report dated March 25 indicates spring cleanup is needed referring to litter along the fence line that will be picked up.

Please approve the Completion Report that DuPont submitted to NYSDEC for the remedial action DuPont completed at this site in late 2012. NYSDEC on January 15, 2014 submitted comments to DuPont on the draft Completion Report. DuPont submitted the final report to NYSDEC on February 28, 2014.

Contact me at (315) 552-9674 or Jacob Tambe of DuPont at (302) 999-2518 with any questions.

Sincerely,

PARSONS



David B. Babcock, P.E.
Project Manager

Attachment: Site Inspection Reports (12)

cc: Bart Putzig, Maura Desmond, NYSDEC
Julia Kenney, NYSDOH
Joseph Biondolillo, Mark Gregor, City of Rochester
Jeff Danzinger, Day Environmental
John Frazer, Monroe County Health Dept.
Steve Rahaim, Bert Heilman, Maryann Nicholson, DuPont
Jacob Tambe, DuPont CRG
Mary Cedeno, CRG Projects Database/Project No. 507463
Parsons File: 446896 – correspondence sent



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 01/07/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
 - a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none

- X 2) **Site Status**
 - a) **Debris –** Remarks: snow covered
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair

- X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 01/14/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

X 1)

Fence

- a) **Locks/Gate-** Remarks: locks and gates check secure
- b) **Breaches** – Remarks: none
- c) **Slatted Fencing Condition:** Remarks: check secure
- d) **Vegetative Overgrowth**– Remarks : none

X 2)

Site Status

- a) **Debris** – Remarks: none
- b) **Surface Staining** – Remarks –no surface staining –
- c) **Storm Drains** – Remarks: clear and functioning
- d) **Monitoring Wells** – Remarks: check secure
- e) **Light Poles** – Remarks: N/A
- f) **Pavement Condition** – Remarks: fair

X

3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 01/21/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth-** Remarks : none

- X 2) **Site Status**
- a) **Debris –** Remarks: none
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair

X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 01/28/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
 - a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none

- X 2) **Site Status**
 - a) **Debris –** Remarks: none
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair

X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 02/04/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none

- X 2) **Site Status**
- a) **Debris –** Remarks: none
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair

X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 02/11/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none

- X 2) **Site Status**
- a) **Debris –** Remarks: none
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair

X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 02/18/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

X 1) **Fence**

- a) **Locks/Gate-** Remarks: locks and gates check secure
- b) **Breaches –** Remarks: none
- c) **Slatted Fencing Condition:** Remarks: check secure
- d) **Vegetative Overgrowth–** Remarks : none

X 2) **Site Status**

- a) **Debris –** Remarks: none
- b) **Surface Staining –** Remarks –no surface staining –
- c) **Storm Drains –** Remarks: clear and functioning
- d) **Monitoring Wells –** Remarks: check secure
- e) **Light Poles –** Remarks: N/A
- f) **Pavement Condition –** Remarks: fair

X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 02/25/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none

- X 2) **Site Status**
- a) **Debris –** Remarks: snow covered
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair

X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 03/04/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
 - a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none

- X 2) **Site Status**
 - a) **Debris –** Remarks: snow covered
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair

X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 03/11/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none

- X 2) **Site Status**
- a) **Debris –** Remarks: snow covered
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair

X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 03/18/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none
- X 2) **Site Status**
- a) **Debris –** Remarks: snow covered
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair
- X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____



S.E. BAKER & COMPANY

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

DATE 03/25/14
INSPECTOR: W. Shattuck
WITNESSES:

EMERGENCY CONTACT:
PAUL MAZIERSKI
716-278-5496

**Maintenance
Performed
(Check)**

Item

- X 1) **Fence**
- a) **Locks/Gate-** Remarks: locks and gates check secure
 - b) **Breaches –** Remarks: none
 - c) **Slatted Fencing Condition:** Remarks: check secure
 - d) **Vegetative Overgrowth–** Remarks : none
- X 2) **Site Status**
- a) **Debris –** Remarks: will need spring cleanup
 - b) **Surface Staining –** Remarks –no surface staining –
 - c) **Storm Drains –** Remarks: clear and functioning
 - d) **Monitoring Wells –** Remarks: check secure
 - e) **Light Poles –** Remarks: N/A
 - f) **Pavement Condition –** Remarks: fair
-
-
- X 3) **Other** _____

REQUIRED MAINTENANCE ACTIVITIES: _____