

40 La Riviere Drive, Suite 350 • Buffalo, New York 14202 • (716) 541-0730 • Fax: (716) 541-0760

January 11, 2016

Todd M. Caffoe, P.E. Environmental Engineer 2 New York State Department of Environmental Conservation – Region 8 6274 East Avon-Lima Road Avon, New York 14414

RE: October through December 2015 Quarterly Progress Report Index # B8-0735-07-01

DuPont Rochester Driving Park Site (#C828142)

Dear Mr. Caffoe:

On behalf of DuPont's Corporate Remediation Group (CRG), Parsons is pleased to provide this quarterly progress report summarizing project activities for October through December 2015 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), began on June 2, 2008 and continue to be conducted weekly on behalf of DuPont to assess site conditions and maintain the site as needed. Reports from the 13 weekly inspections completed during October, November and December2015 are attached. There are currently no issues or action items to report during this quarter.

Contact me at (315) 552-9721 or Jacob Larsen of DuPont at (302) 999-3866 with any questions.

Sincerely,

PARSONS

Heather Milling

Heather Philip. Project Manager

Attachment: Site Inspection Reports (12) cc: Bernette Schilling, NYSDEC

Julia Kenney, NYSDOH

Joseph Biondolillo, Mark Gregor, City of Rochester

Jeff Danzinger, Day Environmental John Frazer, Monroe County Health Dept. Steve Rahaim, Doug Fletcher, DuPont

Jacob Larsen, DuPont CRG

Mary Cedeno, CRG Projects Database/Project No. 507463 Wade Silkworth, Monroe County Department of Public Health

Parsons File: 446896 – correspondence sent



Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

Maintenance Performed (Check all th	
_ 1. Fei a.	Locks/Gate: CHECKED SECURE
ь.	Breaches: NO BREACHES AT THIS TIME
c.	Slatted Fencing Condition:
d.	Vegetative Overgrowth:
_ 2. Sit	a. Debris: CK b. Surface Staining: HIA c. Storm Drains: CLEAR d. Monitoring Wells: ALL CHECKED SECLIRE e. Light Poles: HIA f. Pavement Condition: FAIR.
3. Of	her:



666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

INSPECT	OR: BILL SHATTUCK	DATE: _	10/12/2015
Maintenance Performed (Check all th			
1. Fe	nce Locks/Gate: All checked secure		
b.	Breaches: No breaches at this time	· •	
c.	Slatted Fencing Condition: OK		
d.	Vegetative Overgrowth: Browning and no lo	onger actively growing	due to time of year.
2. Sit	te Status a. Debris: <u>OK</u>		
	b. Surface Staining: N/A		
	c. Storm Drains: Clear		
	d. Monitoring Wells: Checked OK and	secure	
	e. Light Poles: N/A		
	f. Pavement Condition: Fair		
3. Ot		encing was cut dow	n on 10/08/2015
Required M	Saintenance Activities:		



Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114 302-999-3860

INSPECT	OR: BILL SHATTUCK	DATE: 10/23/2015	
Maintenance Performed (Check all th			
1. Fe	nce Locks/Gate: All checked secure		
b.	Breaches: No breaches at this time		
c.	Slatted Fencing Condition: No Change	e	
d.	Vegetative Overgrowth: Grass and wee	eds have gone dormant	
2. Sit	 b. Surface Staining: N/A c. Storm Drains: No Change d. Monitoring Wells: All checked OK 	Cand secure at this time	
3. Ot	her:		
Required M			



Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114

302-999-3860

INSPECTOR: BILL SHATTUCK DATE: 10/30/2015

Maintenance

1.	Fence a. Locks/Gate: All checked secure
	b. Breaches: No breaches at this time
	c. Slatted Fencing Condition: No Change
2.	Vegetative Overgrowth: Not active at this time
3.	Site Status
	a. Debris: No Change
	b. Surface Staining: N/A
	c. Storm Drains: No Change
	d. Monitoring Wells: All checked OK and secure
	e. Light Poles: N/A
	f. Pavement Condition: No Change
4.	Other:



Maintenance Performed

(Check all that apply)

S.E. Baker & Company

Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114 302-999-3860

INSPECTOR: BILL SHATTUCK

DATE: 11/02/2015

	b. Bre	eaches: No breaches at this time
	c. Sla	tted Fencing Condition: No Change
2.	Vegetat	tive Overgrowth: No Change
3.	Site Sta	itus
	a.	Debris: No Change
	b.	Surface Staining: N/A
	c.	Storm Drains: No Change
	d.	Monitoring Wells: All checked OK and secure
	e.	Light Poles: N/A
	f.	Pavement Condition: No Change
4.	Other:	



666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114 302-999-3860

INSPECTOR: BILL SHATTUCK

Maintenance Performed DATE: 11/09/2015

1.	Fence a. Locks/Gate: All checked secure at this time
	b. Breaches: No breaches at this time
	c. Slatted Fencing Condition: No Change
2.	Vegetative Overgrowth: No Change
3.	Site Status

. Site St	ntus
a.	Debris: No Change
b.	Surface Staining: N/A
c.	Storm Drains: No Change
d.	Monitoring Wells: All checked secure and OK at this time
e.	Light Poles: N/A
f.	Pavement Condition: No Change
4. Other:	



666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114

302-999-3860

INSPECTOR: BILL SHATTUCK

Maintenance Performed DATE: 11/18/2015

	a. Locks/Gate: All checked secure at this time
	b. Breaches: No breaches at this time
	c. Slatted Fencing Condition: No Change
2.	Vegetative Overgrowth: No Change
3.	Site Status
	a. Debris: No Change
	b. Surface Staining: N/A
	c. Storm Drains: No Change
	d. Monitoring Wells: All checked secure and OK at this time
	e. Light Poles: N/A
	f. Pavement Condition: No Change
4.	Other:



Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

INSPECTOR: BILL SHATTUCK DATE: 11-24-15
Maintenance Performed (Check all that apply)
1. Fence a. Locks/Gate: ALL CHECKED SECLURE AT THIS TIME b. Breaches: MD BREACHES AT THIS TIME
c. Slatted Fencing Condition: No CHANGE d. Vegetative Overgrowth: No CHANGE
2. Site Status a. Debris: No CHANKE b. Surface Staining: NIM c. Storm Drains: Nb CHANKE d. Monitoring Wells: ALL CHECKED SECURE & OK AT THIS TIME
e. Light Poles: N/M f. Pavement Condition: NO CHANGE
3. Other:
Required Maintenance Activities:



Maintenance

S.E. Baker & Company

Integrated Services For Real Estate Management, Brokerage & Acquisitions

DATE: 12/04/2015

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114

302-999-3860

INSPECTOR: BILL SHATTUCK	DATE: 12/04/2015

1.	Fence a. Locks/Gate: All checked secure at this time
	b. Breaches: No breaches at this time
	c. Slatted Fencing Condition: No Change
2.	Vegetative Overgrowth: No Change
3.	Site Status
	a. Debris: No Change
	b. Surface Staining: N/A
	c. Storm Drains: No Change
	d. Monitoring Wells: All checked secure at this time
	e. Light Poles: N/A
	f. Pavement Condition: No Change
4.	Other:



Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114

302-999-3860 INSPECTOR: BILL SHATTUCK

INSPECTOR: BILL SHATTUCK	DATE: 12/11/2015	
Mairitananaa		

Maintenance Performed (Check all that apply) 1. Fence Locks/Gate: All checked secure at this date b. Breaches: No breaches at this date c. Slatted Fencing Condition: No Change 2. Vegetative Overgrowth: No Change 3. Site Status a. Debris: No Change b. Surface Staining: N/A c. Storm Drains: No Change d. Monitoring Wells: All checked secure at this date e. Light Poles: N/A f. Pavement Condition: No Change 4. Other: Required Maintenance Activities:



Integrated Services For Real Estate Management, Brokerage & Acquisitions


DATE: 12/18/2015

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114 302-999-3860

INSPECTOR: BILL SHATTUCK


-	1. Fence	
	a. Locks/Gate: Secure at this date	_
	b. Breaches: No breaches at this date	
	c. Slatted Fencing Condition: No Change	
	Vegetative Overgrowth: No Change	_
	3. Site Status	
	a. Debris: No Change	
	b. Surface Staining: N/A	
	c. Storm Drains: No Change	
	d. Monitoring Wells: All checked secure at this date	_
	e. Light Poles: N/A	
	f. Pavement Condition: No Change	
	4. Other:	



Integrated Services For Real Estate Management, Brokerage & Acquisitions

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

INSPECTOR:	BILL SHATTUCK DATE: 12.21.15
Maintenance Performed (Check all that ap	ply)
b. Brecc. Slad. Ve	Debris: NO CHANGE
c. d. e.	Storm Drains: NO CHANGE Monitoring Wells: ALL CHECKED SECURE AT THIS DATE Light Poles: NA Pavement Condition: LIGHT CHANGE
<i>5.</i> Outer.	
Required Maint	enance Activities:



Integrated Services For Real Estate Management, Brokerage & Acquisitions

12.28.15

666 ROCHESTER DRIVING PARK SITE SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT: JACOB LARSEN 801-915-8114

ADI LOTA	OR: BILL SHATTUCK DATE:	
Iaintenance erformed	;	
errormed Check all tha	nat apply)	` i
1. Fer	ence	
a.	Locks/Gate: CHECKED SECURE AT THIS	DATE
ъ.	Breaches: NO BREACHES AT THIS DATE	
c.	Slatted Fencing Condition: NO CHANGE	
	. Vegetative Overgrowth: <u>いる これみいら</u> ど	
2. Sit	te Status	
	a. Debris: No CHANIGE.	
	b. Surface Staining: H/M	
,	c. Storm Drains: NO CHANGE	
	d. Monitoring Wells: ALL CHECKED SECURE A	
	e. Light Poles: N/A	
	f. Pavement Condition: NO CHANGE	
3. Ot	Other:	
	•	

Required Maintenance Activities: