

July 10, 2017

Todd M. Caffoe, P.E.
Environmental Engineer 2
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **April through June 2017 Quarterly Progress Report**
Index # B8-0735-07-01
DuPont Rochester Driving Park Site (#C828142)


Dear Mr. Caffoe:

On behalf of DuPont's Corporate Remediation Group (CRG), Parsons is pleased to provide this quarterly progress report summarizing project activities for April through June 2017 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), began on June 2, 2008 and continue to be conducted weekly on behalf of DuPont to assess site conditions and maintain the site as needed. Reports from the 12 weekly inspections completed during April, May, and June 2017 are attached. A hole in the fence along Argo Park was noted and restored on May 5, 2017. There are currently no other issues or action items to report during this quarter.

Contact me at (315) 552-9721 or Nancy Grosso of DuPont at (302) 999-3114 with any questions.

Sincerely,



PARSONS

Heather Philip.
Project Manager

Attachment: Site Inspection Reports (12)

cc: Bernette Schilling, NYSDEC
Julia Kenney, NYSDOH
Joseph Biondolillo, Mark Gregor, City of Rochester
Jeff Danzinger, Day Environmental
John Frazer, Monroe County Health Dept.
Steve Rahaime, Doug Fletcher, DuPont
Nancy Grosso, DuPont CRG
Mary Cedeno, CRG Projects Database/Project No. 507463
Wade Silkworth, Monroe County Department of Public Health
Parsons File: 446896 – correspondence sent

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 4/05/2017

Maintenance
Performed
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
 - b. Breaches: No breaches at this time
 - c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
 - b. Surface Staining: No change
 - c. Storm Drains: No change
 - d. Monitoring Wells: No change
 - e. Light Poles: N/A
 - f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 4/12/2017

Maintenance
Performed
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 4/19/2017

Maintenance
Performed
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 4/26/2017

Maintenance
Performed
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
 - b. Breaches: No breaches at this time
 - c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
 - b. Surface Staining: No change
 - c. Storm Drains: No change
 - d. Monitoring Wells: No change
 - e. Light Poles: N/A
 - f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 5/03/2017

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- ____ 4. Other: _____

Required Maintenance Activities: _____

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 5/10/2017

Maintenance
Performed
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 5/17/2017

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- ____ 4. Other: _____

Required Maintenance Activities: _____

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 5/24/2017

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- ____ 4. Other: _____

Required Maintenance Activities: _____

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 6/02/2017

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- ____ 4. Other: Chain link fence was cut on along Argo Park – hole was reported by
lawn service contractor morning of 5/31 and corrected that afternoon.

Required Maintenance Activities: _____

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 6/14/2017

Maintenance
Performed
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
 - b. Breaches: No breaches at this time
 - c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
 - b. Surface Staining: No change
 - c. Storm Drains: No change
 - d. Monitoring Wells: No change
 - e. Light Poles: N/A
 - f. Pavement Condition: No change
4. Other

Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 6/21/2017

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
- ____ 2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- ____ 4. Other _____

Required Maintenance Activities: _____

666 ROCHESTER DRIVING PARK SITE
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 6/28/2017

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- ____ 4. Other: Confirmed that City of Rochester cut inside the fence line Monday
June 26th.

Required Maintenance Activities: _____
