

November 14, 2017

Todd M. Caffoe, P.E.  
Environmental Engineer 2  
New York State Department of Environmental Conservation – Region 8  
6274 East Avon-Lima Road  
Avon, New York 14414

RE: **July through September 2017 Quarterly Progress Report**  
**Index # B8-0735-07-01**  
**DuPont Rochester Driving Park Site (#C828142)**


Dear Mr. Caffoe:

On behalf of DuPont's Corporate Remediation Group (CRG), Parsons is pleased to provide this quarterly progress report summarizing project activities for July through September 2017 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), began on June 2, 2008 and continue to be conducted weekly on behalf of DuPont to assess site conditions and maintain the site as needed. Reports from the 12 weekly inspections completed during July, August, and September 2017 are attached. There are currently no other issues or action items to report during this quarter.

Contact me at (315) 552-9721 or Nancy Grosso of DuPont at (302) 999-3114 with any questions.

Sincerely,



**PARSONS**

Heather Philip.  
Project Manager

Attachment: Site Inspection Reports (13)

cc: Bernette Schilling, NYSDEC  
Julia Kenney, NYSDOH  
Joseph Biondolillo, Mark Gregor, City of Rochester  
Jeff Danzinger, Day Environmental  
John Frazer, Monroe County Health Dept.  
Steve Rahaim, Doug Fletcher, DuPont  
Nancy Grosso, DuPont CRG  
Mary Cedeno, CRG Projects Database/Project No. 507463  
Wade Silkworth, Monroe County Department of Public Health  
Parsons File: 446896 – correspondence sent

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 7/05/2017

Maintenance  
Performed  
(Check all that apply)

- \_\_\_\_ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
- \_\_\_\_ 2. Vegetative Overgrowth: No change
- \_\_\_\_ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- \_\_\_\_ 4. Other: \_\_\_\_\_
- \_\_\_\_\_
- Required Maintenance Activities: \_\_\_\_\_
- \_\_\_\_\_

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 7/12/2017

Maintenance  
Performed  
(Check all that apply)

- \_\_\_\_ 1. Fence
- a. Locks/Gate: All checked secure
  - b. Breaches: No breaches at this time
  - c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
- \_\_\_\_ 3. Site Status
- a. Debris: No change
  - b. Surface Staining: No change
  - c. Storm Drains: No change
  - d. Monitoring Wells: No change
  - e. Light Poles: N/A
  - f. Pavement Condition: No change
- \_\_\_\_ 4. Other: \_\_\_\_\_
- \_\_\_\_\_
- Required Maintenance Activities: \_\_\_\_\_
- \_\_\_\_\_

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 7/19/2017

Maintenance  
Performed  
(Check all that apply)

- \_\_\_\_ 1. Fence
- a. Locks/Gate: All checked secure
  - b. Breaches: No breaches at this time
  - c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
- \_\_\_\_ 3. Site Status
- a. Debris: No change
  - b. Surface Staining: No change
  - c. Storm Drains: No change
  - d. Monitoring Wells: No change
  - e. Light Poles: N/A
  - f. Pavement Condition: No change
- \_\_\_\_ 4. Other: \_\_\_\_\_

Required Maintenance Activities: \_\_\_\_\_

\_\_\_\_\_

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 7/26/2017

Maintenance  
Performed  
(Check all that apply)

- \_\_\_\_ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
- \_\_\_\_ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- \_\_\_\_ 4. Other: \_\_\_\_\_

Required Maintenance Activities: \_\_\_\_\_

\_\_\_\_\_

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 8/2/2017

Maintenance  
Performed  
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 8/9/2017

Maintenance  
Performed  
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 8/16/2017

Maintenance  
Performed  
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:



666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 8/23/2017

Maintenance  
Performed  
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 8/30/2017

Maintenance  
Performed  
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 9/6/2017

Maintenance  
Performed  
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
  - b. Breaches: No breaches at this time
  - c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
  - b. Surface Staining: No change
  - c. Storm Drains: No change
  - d. Monitoring Wells: No change
  - e. Light Poles: N/A
  - f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 9/13/2017

Maintenance  
Performed  
(Check all that apply)

1. Fence
- a. Locks/Gate: All checked secure
  - b. Breaches: No breaches at this time
  - c. Slatted Fencing Condition: No change
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris: No change
  - b. Surface Staining: No change
  - c. Storm Drains: No change
  - d. Monitoring Wells: No change
  - e. Light Poles: N/A
  - f. Pavement Condition: No change
4. Other:
- Required Maintenance Activities:

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 9/20/2017

Maintenance  
Performed  
(Check all that apply)

- \_\_\_\_ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
- \_\_\_\_ 2. Vegetative Overgrowth: No change
- \_\_\_\_ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- \_\_\_\_ 4. Other: \_\_\_\_\_
- \_\_\_\_\_
- Required Maintenance Activities: \_\_\_\_\_
- \_\_\_\_\_

666 ROCHESTER DRIVING PARK SITE  
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:  
NANCY GROSSO  
(302) 999-3114

INSPECTOR: BILL SHATTUCK

DATE: 9/27/2017

Maintenance  
Performed  
(Check all that apply)

- \_\_\_\_ 1. Fence
- a. Locks/Gate: All checked secure
- b. Breaches: No breaches at this time
- c. Slatted Fencing Condition: No change
- \_\_\_\_ 2. Vegetative Overgrowth: No change
- \_\_\_\_ 3. Site Status
- a. Debris: No change
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change
- \_\_\_\_ 4. Other: \_\_\_\_\_
- \_\_\_\_\_
- Required Maintenance Activities: \_\_\_\_\_
- \_\_\_\_\_