

April 11, 2023

Timothy Schneider, P.E.
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **January through March 2023 Quarterly Progress Report**
Index # B8-0735-07-01
DuPont Rochester Driving Park Site (#C828142)

Dear Mr. Schneider:

On behalf of Corteva Agriscience (formerly DuPont), Parsons is pleased to provide this quarterly progress report summarizing project activities for January through March 2023 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), began on June 2, 2008 and continue to be conducted weekly on behalf of Corteva to assess site conditions and maintain the site as needed. Reports from the 13 weekly inspections completed during January, February, and March are attached. Note that on March 15, 2023, it was observed that the swing gates at the end of Birr Street were badly damaged and a hole had also been cut into the fence near the gate at Gunnison Park. Quotes to repair the fence are currently being obtained.

Please contact me at (513) 317-2984 or Nancy Grosso of Corteva at (302) 485-3015 with any questions.

Sincerely,



Attachment: Site Inspection Reports (13)

cc: David Pratt, NYSDEC
Julia Kenney, NYSDOH
Joseph Biondolillo, City of Rochester
Jeff Danzinger, Day Environmental
Pat McGee, Corteva Legal
Doug Fletcher, Corteva Environmental Remediation
Nancy Grosso, Corteva Environmental Remediation
Darla Kobasko, CER Projects Database/Project No. 507463
Starr O'Neil, Monroe County Health Dept.
Michael Mendoza, Monroe County Health Dept.
James Mikochik, Parsons

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 1/4/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 1/11/2023

Maintenance
Performed
(Check all that apply)

1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
3. Site Status
- a. Debris
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 1/18/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 1/25/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 2/1/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 2/8/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 2/15/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 2/22/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 3/1/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 3/8/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches.
- b. Breaches: No breaches at this time.
- c. Slatted Fencing Condition: No breaches at this time.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 3/15/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches. Both swing gates at end of Birr St. have
been badly damage. Last winter we pulled them closed as best we could.
Obtaining a quote to replace. Beyond repair.
- b. Breaches: Someone cut open a 3' x 2' hole in the bottom of one section
near the gate at the end of Gunnison Park. Obtaining a quote to replace
damaged section.
- c. Slatted Fencing Condition: One section, across 4 posts, became detached.
Joel added zip ties to re-secure it to the top rail. Obtaining a quote for a
more permanent solution.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 3/22/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches. Both swing gates at end of Birr St. have been badly damaged. Last winter we pulled them closed as best we could. Obtaining a quote to replace. Beyond repair.
 - b. Breaches: Someone cut open a 3' x 2' hole in the bottom of one section near the gate at the end of Gunnison Park. Obtaining a quote to replace damaged section.
 - c. Slatted Fencing Condition: One section, across 4 posts, became detached. Joel added zip ties to re-secure it to the top rail. Obtaining a quote for a more permanent solution.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
 - b. Surface Staining: No change
 - c. Storm Drains: No change
 - d. Monitoring Wells: No change
 - e. Light Poles: N/A
 - f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Joel Panasiewicz

DATE: 3/29/2023

Maintenance
Performed
(Check all that apply)

- ____ 1. Fence
- a. Locks/Gate: No new breaches. Both swing gates at end of Birr St. have
been badly damaged. Last winter we pulled them closed as best we
could. Obtaining a quote to replace. Beyond repair.
- b. Breaches: Someone cut open a 3' x 2' hole in the bottom of one section
near the gate at the end of Gunnison Park. Obtaining a quote to replace
damaged section.
- c. Slatted Fencing Condition: One section, across 4 posts, became detached.
Joel added zip ties to re-secure it to the top rail. Obtaining a quote for a
more permanent solution.
2. Vegetative Overgrowth: No change
- ____ 3. Site Status
- a. Debris _____
- b. Surface Staining: No change
- c. Storm Drains: No change
- d. Monitoring Wells: No change
- e. Light Poles: N/A
- f. Pavement Condition: No change