PARSONS

301 Plainfield Road, Suite 350 | Syracuse, New York 13212
P: 315.451.9560 | F: 315.451.9570 | www.parsons.com

July 10, 2024

Josh Ramsey
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **April through June 2024 Quarterly Progress Report**
Index # B8-0735-07-01
DuPont Rochester Driving Park Site (#C828142)

Dear Mr. Ramsey:

On behalf of Corteva Agriscience (formerly DuPont), Parsons is pleased to provide this quarterly progress report summarizing project activities for April through June 2024 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Weekly site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), began on June 2, 2008 to assess site conditions and maintain the site as needed. On December 7, 2023, NYSDEC approved reducing the monitoring frequency from weekly to monthly inspections. Reports from the three inspections completed in April, May and June are attached.

Please contact me at (513) 317-2984 or Doug Fletcher of Corteva at (980) 262-4443 with any questions.

Sincerely,

Karen Fields

Attachment: Site Inspection Reports (3)

cc: David Pratt, NYSDEC
Julia Kenney, NYSDOH
Joseph Biondolillo, City of Rochester
Jeff Danzinger, Day Environmental
Pat McGee, Corteva Legal
Doug Fletcher, Corteva Environmental Remediation
Darla Kobasko, CER Projects Database/Project No. 507463
Starr O'Neil, Monroe County Health Dept.
Michael Mendoza, Monroe County Health Dept.

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
NANCY GROSSO
302-485-3015

INSPECTOR: Tim Springer DATE: 4/30/24

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: Found 5 more stolen cars in lot and the gates ripped off. Stuart Baker sent email with photos to all contacts on 4/24/24. All 5 were towed off property. Working with RPD Officer Sutton. Fence still breached. Stuart reaching out to fence companies.
   b. Breaches: Yes
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: _____

___ 3. Site Status
   a. Debris Nothing found in the lot. Reported stolen cars have been removed.
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
DOUG FLETCHER
980-262-4443

INSPECTOR: Tim Springer DATE: 5/31/24

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: Stuart Baker sent email with photos to all contacts on 4/24/24 regarding the damage to the gates/fence. SEB has reached out to NYS Fence. Waiting for direction from Dupont regarding other alternatives.
   b. Breaches: Yes
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: _____

___ 3. Site Status
   a. Debris Nothing found in the lot. Reported stolen cars have been removed.
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
DOUG FLETCHER
980-262-4443

INSPECTOR: Tim Springer DATE: 6/30/24

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: Fence gates are still damaged from individuals breaking in to dump stolen cars. City of Rochester Police have assisted and added large stone blocks to stop cars from entering.
   b. Breaches: Yes
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: _____

___ 3. Site Status
   a. Debris Nothing found in the lot. Reported stolen cars have been removed.
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change



Photo of the cement blocks that were installed by the City of Rochester to prevent site entry.