PARSONS

301 Plainfield Road, Suite 350 | Syracuse, New York 13212
P: 315.451.9560 | F: 315.451.9570 | www.parsons.com

January 7, 2025

Josh Ramsey
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **October through December 2024 Quarterly Progress Report**
Index # B8-0735-07-01
DuPont Rochester Driving Park Site (#C828142)

Dear Mr. Ramsey:

On behalf of Corteva Agriscience (formerly known as E.I. DuPont de Nemours and Company), Parsons is pleased to provide this quarterly progress report summarizing project activities for October through December 2024 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Weekly site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), began on June 2, 2008 to assess site conditions and maintain the site as needed. On December 7, 2023, NYSDEC approved reducing the monitoring frequency from weekly to monthly inspections. Reports from the three inspections completed in October, November and December are attached.

Corteva continues to work with a prospective purchaser and NYSDEC on a capping/redevelopment plan for the property.

Please contact me at (513) 317-2984 or Doug Fletcher of Corteva at (980) 262-4443 with any questions.

Sincerely,

Karen Fields

Attachment: Site Inspection Reports (3)

cc: David Pratt, NYSDEC
Julia Kenney, NYSDOH
Joseph Biondolillo, City of Rochester
Jeff Danzinger, Day Environmental
Pat McGee, Corteva Legal
Doug Fletcher, Corteva Environmental Remediation
Darla Kobasko, CER Projects Database/Project No. 507463
Starr O'Neil, Monroe County Health Dept.
Marielena Veléz de Brown, Monroe County Health Dept.
Tyson Campbell, DuPont

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
DOUG FLETCHER
980-262-4443

INSPECTOR: Tim Springer DATE: 10/31/24

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: No new breaches. Cement blocks placed by the City of Rochester have helped keep stolen cars out of the lot.
   b. Breaches: Stuart Baker is obtaining estimates to repair the fence/gate.
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: No change

___ 3. Site Status
   a. Debris No change
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
DOUG FLETCHER
980-262-4443

INSPECTOR: Tim Springer DATE: 11/30/24

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: No new breaches. Cement blocks placed by the City of Rochester have helped keep stolen cars out of the lot.
   b. Breaches: Stuart Baker has obtained 2 estimates to repair the fence/gate.
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: No change

___ 3. Site Status
   a. Debris No change
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
DOUG FLETCHER
980-262-4443

INSPECTOR: Tim Springer DATE: 12/31/24

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: No new breaches. Cement blocks placed by the City of Rochester have helped keep stolen cars out of the lot.
   b. Breaches: Stuart Baker has obtained 2 estimates to repair the fence/gate.
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: No change

___ 3. Site Status
   a. Debris No change
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change