PARSONS

301 Plainfield Road, Suite 350 | Syracuse, New York 13212
P: 315.451.9560 | F: 315.451.9570 | www.parsons.com

July 7, 2026

Josh Ramsey
New York State Department of Environmental Conservation – Region 8
6274 East Avon-Lima Road
Avon, New York 14414

RE: **April through June 2026 Quarterly Progress Report**
Index # B8-0735-07-01
DuPont Rochester Driving Park Site (#C828142)

Dear Mr. Ramsey:

On behalf of EIDP, Inc. (formerly known as E.I. DuPont de Nemours and Company), Parsons is pleased to provide this quarterly progress report summarizing project activities for April through June 2026 pursuant to the requirements of the Brownfield Site Cleanup Agreement for the 666 Driving Park Site located in the City of Rochester, NY.

Weekly site inspections, as requested by New York State Department of Environmental Conservation (NYSDEC), began on June 2, 2008 to assess site conditions and maintain the site as needed. On December 7, 2023, NYSDEC approved reducing the monitoring frequency from weekly to monthly inspections. Reports from the three inspections completed in April, May and June are attached. No security issues were identified this quarter. Other site activities include submittal of the revised Remedial Action Work Plan (RAWP) on May 22, 2026.

Please contact me at (513) 317-2984 or Andrew Joslyn of DuPont at (302) 295-5731 with any questions.

Sincerely,

Karen Fulds

Attachment: Site Inspection Reports (3)

cc: Julia Kenney, NYSDOH
Jane Forbes, City of Rochester
Jeff Danzinger, Day Environmental
Pat McGee, Corteva Legal
Doug Fletcher, Corteva Environmental Remediation
Darla Kobasko, CER Projects Database/Project No. 607463
Starr O'Neil, Monroe County Health Dept.
Marielena Veléz de Brown, Monroe County Health Dept.
Andrew Joslyn, DuPont

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
DOUG FLETCHER
980-262-4443

INSPECTOR: Tim Springer DATE: 4/30/26

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: No Change all secure.
   b. Breaches: No Change
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: No change

___ 3. Site Status
   a. Debris No change
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
DOUG FLETCHER
980-262-4443

INSPECTOR: Tim Springer DATE: 5/31/26

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: No Change all secure.
   b. Breaches: No Change
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: Grass is getting high inside the fenced in area.

___ 3. Site Status
   a. Debris No change
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change

666 ROCHESTER DRIVING PARK
SITE INSPECTION & MAINTENANCE CHECKLIST

EMERGENCY CONTACT:
DOUG FLETCHER
980-262-4443

INSPECTOR: Tim Springer DATE: 6/30/26

Maintenance
Performed
(Check all that apply)

___ 1. Fence
   a. Locks/Gate: No Change all secure.
   b. Breaches: No Change
   c. Slatted Fencing Condition: No change

2. Vegetative Overgrowth: Grass is getting high inside the fenced in area.

___ 3. Site Status
   a. Debris No change
   b. Surface Staining: No change
   c. Storm Drains: No change
   d. Monitoring Wells: No change
   e. Light Poles: N/A
   f. Pavement Condition: No change