

**New York State - Department of Environmental Conservation  
Division of Environmental Remediation  
Periodic Review Evaluation Report**

**Period covered by -- 2010-11**

<b>Site Code:</b> C849004	<b>Site Name:</b> Seneca Market 1, LLC site	<b>Class:</b> C																		
<b>Program Lead:</b> Brownfield Cleanup Program	<b>Site Management Funding Source:</b> Volunteer																			
<b>Start Date:</b> 12/31/2008	ACT																			
<b>IC/EC Certification:</b>	<b>Received Date:</b>	<b>Accept Date:</b> 06/18/2010																		
<b>DEC Inspection Date:</b> --- Last Date of DEC Inspection																				
<b>Report Used for Evaluation:</b> Site Management, Longterm Monitoring																				
<b>ROD Compliance?</b> Yes																				
<b>Long Term Monitoring (effectiveness of remedy):</b> Yes <b>Frequency:</b>																				
<b>Treatment System (Monitoring performance of remedy):</b> Yes <b>Frequency:</b>		<b>Number of Wells:</b> 5																		
<b>Problem Status:</b>																				
<table style="width: 100%; border: none;"> <tr> <td style="width: 35%;"><b>Engineering Controls Elements</b></td> <td style="width: 65%;">Slight</td> </tr> <tr> <td>Remedial System Changes</td> <td></td> </tr> <tr> <td>Vapor Mitigation System</td> <td></td> </tr> <tr> <td><b>Health &amp; Safety / Site Conditions Elements</b></td> <td>Slight</td> </tr> <tr> <td>Personnel Access</td> <td></td> </tr> <tr> <td>Public Access</td> <td></td> </tr> <tr> <td>Soil Vapor Intrusion</td> <td></td> </tr> <tr> <td>Vapor Migration</td> <td></td> </tr> <tr> <td>Well Location/ Height / Access</td> <td></td> </tr> </table>			<b>Engineering Controls Elements</b>	Slight	Remedial System Changes		Vapor Mitigation System		<b>Health &amp; Safety / Site Conditions Elements</b>	Slight	Personnel Access		Public Access		Soil Vapor Intrusion		Vapor Migration		Well Location/ Height / Access	
<b>Engineering Controls Elements</b>	Slight																			
Remedial System Changes																				
Vapor Mitigation System																				
<b>Health &amp; Safety / Site Conditions Elements</b>	Slight																			
Personnel Access																				
Public Access																				
Soil Vapor Intrusion																				
Vapor Migration																				
Well Location/ Height / Access																				
<b>Comments/Changes/Attachments:</b>																				
<b>ROD/Consent Order Modifications?</b> No																				
<b>Site reclassification recommended:</b>																				
<b>Next Review:</b>		<b>Priority:</b> 01																		
<b>Project Manager:</b> cbtheoba		<b>Reviewer:</b> BXPUTZIG																		
<b>Signature:</b>	<b>Date:</b>	<b>Signature:</b> <b>Date:</b> 06/18/2010																		
Name	Region or Bureau	Telephone																		
Name	Region or Bureau	Telephone																		

**New York State - Department of Environmental Conservation**  
**Division of Environmental Remediation**  
**Periodic Review Evaluation Report**

Contaminant of concern	OU	Media/Receptor		
BENZENE	00			
DICHLOROETHYLENE	00			
ETHYLBENZENE	00			
TETRACHLOROETHYLENE (PCE)	00			
TRICHLOROETHENE (TCE)	00			
VINYL CHLORIDE	00			
XYLENE (MIXED)	00			
ACETONE	00			
ACETONE	01			
BENZENE	01			
DICHLOROETHYLENE	01			
ETHYLBENZENE	01			
TETRACHLOROETHYLENE (PCE)	01			
TRICHLOROETHENE (TCE)	01			
VINYL CHLORIDE	01			
XYLENE (MIXED)	01			
<b>Evaluation:</b> The Remedy is performing properly and is effective.				
Remedies	OU	Site of Treatment	Date in Place	Remedy Effective
Excavation (removal offsite)	01	XX		Ongoing

<b>Next Review:</b>			<b>Priority:</b> 01		
<b>Project Manager:</b> cbtheoba			<b>Reviewer:</b> BXPOTZIG		
Signature:		Date:	Signature:		Date: 06/18/2010
Name	Region or Bureau	Telephone	Name	Region or Bureau	Telephone