



SITE INSPECTION REPORT

Site Name: Scott Rotary Seals

Site Number: C905036

Location: 301 Franklin Street, Olean, NY 14760

Inspection Date: June 5, 2026

Site Project Manager: Brad Demo

Personnel Onsite: N/A (only inspected building exterior on this date).

Weather Conditions: AM: Sunny, warm.

Description of Work Performed: NYSDEC conducting routine site exterior inspection.

- Site cover in acceptable condition. No signs of erosion or excavation. No compromised asphalt or concrete.

Inspector: Bradley Demo

Signature:

A handwritten signature in black ink, appearing to read "Bradley Demo".

Site Inspection Report

Scott Rotary Seals

June 5, 2026

Page 2

Photolog:



Cover conditions/rip rap.

Site Inspection Report

Scott Rotary Seals

June 5, 2026

Page 3



Cover conditions/gravel.



Asphalt cover conditions facing south.

Site Inspection Report

Scott Rotary Seals

June 5, 2026

Page 5



Cover conditions facing SSW.

Site Inspection Report

Scott Rotary Seals

June 5, 2026

Page 6



Cover/site conditions, west side of building.

Site Inspection Report

Scott Rotary Seals

June 5, 2026

Page 7



Cover/site conditions facing NNW.