



SITE INSPECTION REPORT

Site Name: 202 Franklin Street

Site Number: C905043

Location: 202 Franklin Street, Olean, NY 14760

Inspection Date: 6/5/2026

Site Project Manager: Bradley Demo

Personnel Onsite: N/A

Weather Conditions: Sunny, 75°F

Description of Work Performed:

- NYSDEC onsite conducting routine inspection.
- Asphalt parking lot repairs, gravel cover, and vegetative cover are all in adequate condition.
- Monitoring wells not inspected on this date.

Inspector: Bradley Demo

Signature: 

Photolog:



Stone/vegetative cover.



Corner parking lot/stone/vegetative cover conditions.



Same as above, alternative view.