

National Fuel Gas Distribution Corporation

2018 PERIODIC REVIEW REPORT


Former Buffalo Service Station – Off-Site

Site #C915194a


Buffalo, Erie County, New York

January 2019

A large, solid orange geometric shape, resembling a stylized triangle or a section of a larger triangle, is positioned in the bottom right corner of the page. It is composed of two overlapping triangles, creating a complex, angular form that extends from the bottom edge towards the top right corner.



Nicholas (Klaus) Beyrle, PG
Staff Geologist



Scott Powlin, PG
Principle Geologist

2018 PERIODIC REVIEW REPORT

Former Buffalo Service Station – Off-Site
Site #C915194a
Buffalo, Erie County, New York

Prepared for:
National Fuel Gas Distribution Corporation
6363 Main Street
Williamsville, New York 14221-5887

Prepared by:
Arcadis of New York, Inc.
One Lincoln Center
110 West Fayette Street
Suite 300
Syracuse
New York 13202
Tel 315 446 9120
Fax 315 449 0017

Our Ref.:
B0023310.0000

Date:
January 2019

This document is intended only for the use of the individual or entity for which it was prepared and may contain information that is privileged, confidential and exempt from disclosure under applicable law. Any dissemination, distribution or copying of this document is strictly prohibited.

CONTENTS

Acronyms and Abbreviations.....	ii
1 Introduction	1
1.1 Background.....	1
1.1.1 Site Location and History	1
1.1.2 Summary of Impacts and Remedial Actions	1
1.2 Objectives	2
2 IC Effectiveness Monitoring	2
2.1 Site-Wide Inspection	2
2.2 Property Owner Interview	3
2.2.1 City of Buffalo	3
2.2.2 NYSTA.....	3
3 Certification	3
4 References.....	4

FIGURES

Figure 1 Site Location Map

Figure 2 Site Map

APPENDICES

Appendix A Site Inspection Form

Appendix B Photographic Log

Appendix C Phone Call Log and FOIA Information

Appendix D Certification Form

ACRONYMS AND ABBREVIATIONS

BSS	Former Buffalo Service Station
IC	Institutional Control
PRR	Periodic Review Report
NYSDEC	New York State Department of Environmental Conservation
NYSTA	New York State Thruway Authority
SMP	Site Management Plan

1 INTRODUCTION

This *Periodic Review Report* (PRR) is required by Section 4.3 of the May 2016 Site Management Plan (SMP; Arcadis, 2016) for the Former Buffalo Service Station (BSS) Off-Site site (hereinafter referred to as the “Site”) located in Buffalo, Erie County, New York. The SMP addresses the means for implementing Institutional Controls (ICs) that are required by the Environmental Easement for the portion of the Site owned by the City of Buffalo (City) and an Environmental Notice for the portion of the Site owned by the New York State Thruway Authority (NYSTA). As of the date of this PRR, an Environmental Notice is pending between the New York State Department of Environmental Conservation (NYSDEC) and NYSTA for the portion of the Site owned by the NYSTA. National Fuel submitted a November 21, 2017 letter to the NYSDEC in response to August 2017 comments from the NYSTA on the May 2016 Site Management Plan (SMP). In that letter, National Fuel requested that the NYSDEC provide final approval of the May 2016 SMP and provide NYSTA with an environmental notice for NYSTA’s property that comprises the western portion of the site. The NYSDEC provided a revised version of the SMP to National Fuel on January 15, 2019 in response to National Fuel’s November 21, 2017 letter. National Fuel is currently reviewing the revised SMP. The certification provided in this PRR assumes that the ICs identified for the portion of the Site owned by the NYSTA will be the same as those identified in the Environmental Easement for the City property.

This PRR has been developed in accordance with Section 6.3 of the Department of Environmental Remediation (DER)-10 Technical Guidance for Site Investigation and Remediation (NYSDEC, 2010). This PRR documents inspection and efficacy of the ICs implemented at the Site during the reporting period of January 1, 2018 to December 31, 2018.

1.1 Background

1.1.1 Site Location and History

The Site is located in the City of Buffalo, County of Erie, New York (Figure 1), and is approximately 120 feet by 180 feet extending from the eastern edge of Fourth Street, under and to the west edge of the New York State Interstate I-190 overpass (Figure 2). The portion of the Site that lies beneath Fourth Street is owned by the City of Buffalo, and the portion beneath the I-190 overpass is owned by the NYSTA. The eastern portion of the Site contains a 6-foot tall galvanized chain-link fence placed by the NYSTA to deter trespassing under the I-190 overpass. The western boundary of the Site is denoted by a chain-link fence that is located between the Site and a railroad. Groundwater in the vicinity of the Site is not used as a drinking water supply (Groundwater Technology, 1996). The Site was historically the location of the confluence between the former Wilkeson Slip and the former Erie Canal (Figure 2).

1.1.2 Summary of Impacts and Remedial Actions

As summarized in the SMP, it is possible that a small region of residual coal tar remains beneath Fourth Street at a depth of approximately 15 to 19 feet below ground surface. Previous investigations indicated that the tar (and related dissolved phase impacts from the tar) does not appear to be present in the portion of the Site west of Fourth Street (underneath the I-190 overpass). The tar likely originated from the former Buffalo Service Station site located adjacent to, and northeast of, the Site (Figure 2).

The remedial action for the site consists of compliance with the Environmental Easement and Environmental Notice (pending) and the ICs described in the SMP. The ICs consist of:

1. The Site may be used for commercial and industrial use.
2. The Site may not be used for a higher level of use, such as unrestricted residential, or restricted residential use as defined in DER-10, without an amendment to each the Environmental Easement and Environmental Notice, respectively, as approved by the NYSDEC.
3. Compliance with the Environmental Easement, and Environmental Notice, and the SMP by the owners of the Site and National Fuel and its successors.
4. ICs identified in the Environmental Easement and Environmental Notice may not be discontinued without an amendment to or extinguishment of the Environmental Easement and/or Environmental Notice, respectively.
5. All future activities on the Site that will disturb remaining impacts must be conducted in accordance with the SMP.
6. Use of the groundwater underlying the Site is prohibited.
7. Vegetable gardens and farming on the Site are prohibited.
8. Data and information pertinent to Site management must be reported at the frequency and in a manner as defined in the SMP.

1.2 Objectives

As described in the SMP, ICs are established for the Site and are required to protect human health and the environment. The purpose of the ICs is to prevent future exposure to remaining impacts by controlling disturbances of the subsurface impacts, and limit use and development of the Site to commercial or industrial uses only.

The Site Monitoring Plan provided in Section 3 of the SMP describes requirements for evaluating the effectiveness and condition of the ICs. National Fuel or its successor is responsible for Site monitoring, including inspections and reporting. Because there is no active remediation system or media sampling required for the Site, performance monitoring is not applicable.

2 IC EFFECTIVENESS MONITORING

This section summarizes effectiveness monitoring of the Site ICs. The effectiveness monitoring consisted of conducting a site-wide inspection and contacting the property owners to conduct interviews regarding compliance with ICs for 2018.

2.1 Site-Wide Inspection

As discussed in Section 3.2 of the SMP, a comprehensive site-wide inspection is required for the first 5 years and once every 3 years thereafter. The site-wide inspection for the 2018 monitoring period was

conducted on January 8, 2019. During the inspection, ICs were observed to be effective at protecting human health and the environment at the Site, as follows:

- Obvious indications of recent intrusive disturbance to the subsurface were not observed on the City or NYSTA properties; and
- Land use was observed to be commercial or industrial, which is consistent with that identified in the SMP.

The completed site inspection form, as required by Section 3.2 of the SMP, is included as Appendix A. A photographic log for photographs taken during the Site inspection is included as Appendix B.

2.2 Property Owner Interview

Arcadis contacted representatives from each property owner comprising the Site to inquire whether potential activities (i.e. intrusive activities) or land-use changes occurred in 2018 that would have violated the ICs. A summary of the correspondence is provided below, and documentation is included as Appendix C.

2.2.1 City of Buffalo

On January 8, 2019, Mr. Nicholas Beyrle of Arcadis submitted a Freedom of Information Act (FOIA) request via email to Mr. Michael Finn from the City of Buffalo Department of Public Works for information to determine whether intrusive activities were conducted on the City of Buffalo portion of the Site in 2018. A copy of the FOIA request is provided in Appendix C. Information received from the FOIA request (also in Appendix C) confirmed that no intrusive activities occurred on the City of Buffalo portion of the Site and that the ICs remained effective during 2018.

2.2.2 NYSTA

On January 8, 2019, Mr. Nicholas Beyrle of Arcadis spoke with Mr. Paul Zakrzewski from the NYSTA. Mr. Zakrzewski indicated that no subsurface work was conducted on the NYSTA portion of the Site by NYSTA or third-party contractors and that no change in use of the property had occurred in 2018. To the best of his knowledge, the ICs remained effective during 2018.

3 CERTIFICATION

Certification for the institutional controls is outlined by site management requirements presented in Section 6.3(b) of DER-10. As noted in Section 4.3 of the SMP, the certification shall be submitted annually for the first five years and then every three years thereafter, or an alternate period of time that NYSDEC may allow. The certification form enclosed in this PRR as Appendix D covers the certification period from January 1, 2018 to December 31, 2018.

4 REFERENCES


Arcadis, 2016. Site Management Plan, Former Buffalo Service Station – Off-site, New York, May 2016.

Groundwater Technology, 1996. Sensitive Receptor Survey Report National Fuel Gas Distribution Corporation Buffalo Service Center, Buffalo, New York, April 5, 1996.



NYSDEC, 2010. DER-10 Technical Guidance for Site Investigation and Remediation, May 2010.

FIGURES






REFERENCE: BASE MAP USGS 7.5. MIN. TOPO. QUADS., BUFFALO NW, NY-ON, AND BUFFALO NE, 1965.



FORMER BUFFALO SERVICE STATION - OFF-SITE BUFFALO, NEW YORK PERIODIC REVIEW REPORT

SITE LOCATION MAP



APPENDIX A

Site Inspection Form



Site Inspection Form

Former Buffalo Service Station - Off-Site Area - Buffalo, New York

Date/Time: 02/08/2019

Weather: Overcast

Personnel: Nicholas Beyle

Temperature: ~40°F

General Requirements

Photographs will be attached to document the condition of each inspection item identified below.
A written description of any item(s) that is considered to be in poor condition is required.

1. Fourth Street Conditions:

Pavement condition	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Poor*
Signs of intrusive activities	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*
Evidence of saw-cut asphalt	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*
Evidence of trenching or excavation	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*
Evidence of Settlement	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*

2. Site Security Fencing Around NYSTA Property:

Condition	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Poor/Damaged*
Gate Locked Upon Arrival	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes*

3. NYSTA Property Conditions:

Standing Water	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*
Missing Stone/Vegetation	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*
Signs of intrusive activities	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*
Evidence of Settlement	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*
Damage/failure of existing structures	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes*

4. Notes:

Fourth Street Conditions: Pavement Conditions - Some filled in potholes and sealed cracks.

NYSTA Property Conditions: standing water - Small puddles of standing water observed, appear to be ephemeral. The elevated expressway drains to this area.

* Indicates condition should be reported to OM&M Coordinator and NYSDEC.

APPENDIX B

Photographic Log



Project Photographs

Former Buffalo Service Station – Off-Site
Site #C915194A



Photo: 1

Date:

1/8/2019

Description:

Photograph showing City of Buffalo Property within the Site limits. Photograph looking west showing cover materials are in good condition with no observable disturbance to the subsurface (northern portion).

Location: Former Buffalo Service Station – Off-Site, City of Buffalo Property



Photo: 2

Date:

1/8/2019

Description:

Photograph showing City of Buffalo Property within the Site limits. Photograph looking west showing cover materials are in good condition with no observable disturbance to the subsurface (center portion).

Location: Former Buffalo Service Station – Off-Site, City of Buffalo Property

Project Photographs

Former Buffalo Service Station – Off-Site
Site #C915194A



Photo: 3

Date:

1/8/2019

Description:

Photograph showing City of Buffalo Property within the Site limits. Photograph looking west showing cover materials are in good condition with no observable disturbance to the subsurface (southern portion).

Location: Former Buffalo Service Station – Off-Site, City of Buffalo Property



Photo: 4

Date:

1/8/2019

Description:

Photograph showing City of Buffalo Property and NYSTA Property within the Site limits. Photograph looking south showing cover materials are in good condition with no observable disturbance to the subsurface.

Location: Former Buffalo Service Station – Off-Site, City of Buffalo/NYSTA Property

Project Photographs

Former Buffalo Service Station – Off-Site
Site #C915194A



Photo: 5

Date:

1/8/2019

Description:

Photograph showing City of Buffalo Property and NYSTA Property within the Site limits. Photograph looking south showing cover materials are in good condition with no observable disturbance to the subsurface (close-up view).

Location: Former Buffalo Service Station – Off-Site, City of Buffalo/NYSTA Property



Photo: 6

Date:

1/8/2019

Description:

Photograph showing NYSTA Property within the Site limits. Photograph looking west showing cover materials are in good condition with no observable disturbance to the subsurface (northern portion).

Location: Former Buffalo Service Station – Off-Site, NYSTA Property

Project Photographs

Former Buffalo Service Station – Off-Site
Site #C915194A



Photo: 7

Date:

1/8/2019

Description:

Photograph showing NYSTA Property within the Site limits. Photograph looking west showing cover materials are in good condition with no observable disturbance to the subsurface (center portion).

Location: Former Buffalo Service Station – Off-Site, NYSTA Property



Photo: 8

Date:

1/8/2019

Description:

Photograph showing NYSTA Property within the Site limits. Photograph looking west showing cover materials are in good condition with no observable disturbance to the subsurface (southern portion).

Location: Former Buffalo Service Station – Off-Site, NYSTA Property

APPENDIX C

Phone Call Log and FOIA Information



RECORD OF CONVERSATION

Person Called	Paul Zakrzewski	Arcadis of New York, Inc. One Lincoln Center 110 West Fayette Street Suite 300 Syracuse New York 13202 Tel 315 446 9120 Fax 315 449 0017
Title/Position	New York State Thruway Authority (NYSTA) Coordinator of Transportation Development Projects, Buffalo Division	
Phone Number	716.635.6253	
Date of Call	January 8, 2019	
Call Purpose	Verification of work completed at Site	
Site Name	Former Buffalo Service Station – Off-Site	
Client	National Fuel	

Call Log

January 8, 2019, Nicholas Beyrle of Arcadis contacted Paul Zakrzewski of the NYSTA to inquire whether subsurface work was conducted on the NYSTA property comprising the western portion of the National Fuel Former Buffalo Service Station – Off-Site (Site). Mr. Zakrzewski issues permits to third-parties allowing them to conduct work on NYSTA property and also is in charge of NYSTA workers conducting subsurface work on NYSTA property. According to Mr. Zakrzewski, NYSTA did not conduct subsurface work or issue permits to third-parties to conduct subsurface work on NYSTA property for the parcel comprising a portion of the Site in 2018. In addition, the land use for the site has not changed.



MAYOR
BYRON W. BROWN
COMMISSIONER
JAMES COMERFORD JR.

CITY OF BUFFALO

DEPARTMENT OF PERMIT & INSPECTION SERVICES

RECORD REQUEST FORM

Under the provisions of the New York FREEDOM OF INFORMATION LAW (F.O.I.L.), Article 6 of the Public Officers Law, I hereby request the records or portions thereof that I have reasonably described in Part "B" of this form.

PART A - APPLICANT INFORMATION

1. Name of Applicant: _____
2. Company Name: _____
3. Address: _____ State: _____ Zip Code: _____
4. Type of Business: _____
5. Telephone Number: _____ Fax Number: _____
6. E-Mail: _____ ☐ I do not want to receive any information via e-mail.

PART B – INFORMATION REQUESTED

Describe the records that you are requesting in the space provided below. Please include as much detail as possible such as dates, titles, or any other information that may assist us in locating the record(s) you are seeking. Please be mindful that the record or document that you are requesting may not exist.

PART C – METHODS OF REVIEW

- ☐ I would like an appointment to review the records that I am requesting in the Office of the City of Buffalo Department of Economic Development, Permit & Inspection Services. If I desire copies, I understand that I will be charged a fee in accordance with the schedule listed below in the section entitled "Fees." I also understand that copies may not be immediately available.
- ☐ I would like the requested documents mailed to me. I understand that I will be billed for copying charges and will not receive the documents until I have remitted payment to the address listed in the section entitled "Submission of Request." I understand that I will be charged a fee in accordance with the schedule listed below in the section entitled "Fees."
- ☐ I would like the requested information provided via an electronic format.

PART D – FEES

If you should desire copies of records, the following fees will apply in accordance with 16 NYCRR §6-1.2. Advanced payment is required before records will be released. Please make check or money orders payable to the **City of Buffalo**.

CHARGES FOR COPYING:

Pages up to 9" x 14" \$.25 ea. Pages over 9" x 14" \$.70 ea.

The fee for special reproductions such as photocopies for large items shall be based upon the average unit cost of copying a record, excluding fixed costs of the department, such as operator salaries.

PART E – SUBMISSION OF REQUEST

After you have reasonably described the records you wish to inspect or obtain, please sign this form and return it to the address listed below. Requests may be mailed or hand delivered. Please note that you do not have to complete this form in order to request records from this Department, however, it will facilitate access to the records.

CITY OF BUFFALO DEPARTMENT OF ECONOMIC DEVELOPMENT, PERMIT & INSPECTION SERVICES

ATTN: RECORDS ACCESS OFFICER

65 NIAGARA SQUARE, CITY HALL ROOM 301

BUFFALO, NEW YORK 14202

PART F – COMMERCIAL PURPOSES CERTIFICATION & AFFIRMATION

THIS SECTION MUST ONLY BE COMPLETED IF YOU ARE REQUESTING A LIST OF NAMES AND ADDRESSES. By signing below, I certify that such list(s) will not be used for commercial or fundraising purpose. Section 87(2)(b) and 89(2)(b)(iii) of the New York State Public Officers Law permit the City of Buffalo to seek a certification from an applicant seeking disclosure of a list of names and addresses, that such list will not be used for commercial or fundraising purposes.

Signature: _____ **Print Name:** _____ **Date:** _____

I hereby affirm that the information I have provided on this request form is correct.

Signature: _____ **Print Name:** _____ **Date:** _____

PART G – DISPOSITION OF REQUEST-----DO NOT WRITE BELOW THIS LINE-----

☐ **REQUEST RECEIVED** – The Department of Economic Development, Permit & Inspection Services is reviewing your request. The Department will notify you as to whether your request will be granted or denied on or about the following date: _____.

☐ **APPROVED** – The approximate date the records will be available: _____. To arrange for access to the records, contact: _____

☐ **DENIED** – For the reason(s) checked: References are to Section 87 of the NYS Public Officers Law

- ☐ Records are specifically exempted from disclosure by state or federal statute 2 (a)
- ☐ Disclosure would constitute an unwarranted invasion of personal privacy 2(b)
- ☐ Disclosure would impair present or imminent contract awards or collective bargaining negotiations 2 (c)
- ☐ Records are exempt from disclosure under the Law Enforcement Exemption 2 (e)
- ☐ Disclosure could endanger the life or safety of any person 2 (f)
- ☐ Records are exempt from disclosure under the Inter/Intra – Agency Materials Exemption 2 (g)
- ☐ Other: _____

☐ **MATERIAL REDACTED** _____


☐ **UNAVAILABLE** – For the reason(s) indicated:

- ☐ Records Requested were not described in sufficient detail
- ☐ The records you have requested are not maintained by this department
- ☐ This Department maintains the records you have requested, but the records could not be located after a diligent search.
- ☐ Other: _____


SIGNED: _____ **TITLE:** _____ **DATE:** _____

PART H – APPEALS

If you are denied access to records or portions of records, you may submit a written appeal the Commissioner of Economic Development, Permit & Inspection Services, City Hall, Room 324. Such appeal must be made within **thirty (30) days** after you receive the denial. Please attach a copy of this completed form when filing your appeal. The Appeals Officer will evaluate the appeal and respond to you in writing within **ten (10) business days** after receipt of the appeal.




REFERENCE: BASE MAP USGS 7.5. MIN. TOPO. QUADS., BUFFALO NW, NY-ON, AND BUFFALO NE, 1965.



FORMER BUFFALO SERVICE STATION - OFF-SITE BUFFALO, NEW YORK PERIODIC REVIEW REPORT

SITE LOCATION MAP



APPENDIX D

Certification Form





Enclosure 2
NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Site Management Periodic Review Report Notice
Institutional and Engineering Controls Certification Form



Site Details **Box 1**

Site No. **C915194A**

Site Name: Former Buffalo Service Station - Off-Site

Site Address: 249 West Genesee Street Zip Code: 14202
City/Town: Buffalo
County: Erie
Site Acreage: 0.6

Reporting Period: January 1, 2018 to December 31, 2018

- | | YES | NO |
|--|-------------------------------------|-------------------------------------|
| 1. Is the information above correct? | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| If NO, include handwritten above or on a separate sheet. | | |
| 2. Has some or all of the site property been sold, subdivided, merged, or undergone a tax map amendment during this Reporting Period? | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 3. Has there been any change of use at the site during this Reporting Period (see 6NYCRR 375-1.11(d))? | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 4. Have any federal, state, and/or local permits (e.g., building, discharge) been issued for or at the property during this Reporting Period? | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| If you answered YES to questions 2 thru 4, include documentation or evidence that documentation has been previously submitted with this certification form. | | |
| 5. Is the site currently undergoing development? | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

- Box 2**
- | | YES | NO |
|--|-------------------------------------|--------------------------|
| 6. Is the current site use consistent with the use(s) listed below?
Commercial and Industrial | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 7. Are all ICs/ECs in place and functioning as designed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**IF THE ANSWER TO EITHER QUESTION 6 OR 7 IS NO, sign and date below and
DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.**

A Corrective Measures Work Plan must be submitted along with this form to address these issues.

Signature of Owner, Remedial Party or Designated Representative

Date

Description of Institutional ControlsParcelOwnerInstitutional Control

Ground Water Use Restriction
Site Management Plan
Landuse Restriction

- i) Use of groundwater for potable and non-potable purposes is prohibited.
- ii) Implementation of Soil/Fill Management Plan.
- iii) Property shall remain as commercial/industrial use only

Description of Engineering Controls

None Required

Not Applicable/No EC's

Periodic Review Report (PRR) Certification Statements

1. I certify by checking "YES" below that:

a) the Periodic Review report and all attachments were prepared under the direction of, and reviewed by, the party making the certification;

b) to the best of my knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted engineering practices; and the information presented is accurate and complete.

YES NO

☒ ☐

2. If this site has an IC/EC Plan (or equivalent as required in the Decision Document), for each Institutional or Engineering control listed in Boxes 3 and/or 4, I certify by checking "YES" below that all of the following statements are true:

(a) the Institutional Control and/or Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;

(b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment;

(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;

(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and

(e) if a financial assurance mechanism is required by the oversight document for the site, the mechanism remains valid and sufficient for its intended purpose established in the document.

YES NO

☒ ☐

**IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and
DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.**

A Corrective Measures Work Plan must be submitted along with this form to address these issues.

Signature of Owner, Remedial Party or Designated Representative

Date

IC CERTIFICATIONS
SITE NO. C915195

Box 6

SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1, 2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

I Lee HART at 6303 MAIN STREET, WILLIAMSVILLE, NY
print name print business address

am certifying as _____ (Owner or Remedial Party)

for the Site named in the Site Details Section of this form.

X [Signature]
Signature of Owner, Remedial Party, or Designated Representative
Rendering Certification

1-22-19
Date

Arcadis of New York, Inc.

One Lincoln Center

110 West Fayette Street

Suite 300

Syracuse, New York 13202

Tel 315 446 9120

Fax 315 449 0017

www.arcadis.com

A decorative graphic consisting of three thin orange lines. One line is horizontal, extending from the left edge of the page towards the right. Two other lines are diagonal, starting from the bottom left and extending towards the top right, intersecting the horizontal line.