



SITE INSPECTION REPORT

Site Name: NOCO #S41

Site Number: C915211

Location: 1055 Genesee Street, Buffalo NY

Inspection Date: 8/15/2025

Site Inspectors: Bradley Demo

Weather Conditions: Sunny, warm, wind negligible.

Description of Work Performed: Institutional controls inspection

Details:

All institutional controls being maintained. No evidence of groundwater use or excavation. Site cover in good condition. Building onsite in good condition. 4 of 5 onsite monitoring wells observed to be covered and in good condition. Monitoring well in southwest portion of site could not be visually located. Likely overgrown with grass and/or covered with debris.

Issues Noted: None.

Inspector: Bradley Demo

Signature: *Bradley W. Demo*

Attachments: Photolog

Photolog:



Monitoring well/site conditions.



Site cover conditions.

Site Inspection Report
NOCO #S41 (C915211)
August 15, 2025
Page 4



Monitoring well/site conditions.



Site cover conditions.



Site cover conditions.



Monitoring well/site conditions.



Monitoring well/site conditions.