

Phase I Environmental Site Assessment

111 Hydraulic Building Project

797/799 Seneca St
819 Seneca St
111 Hydraulic St
105 Hydraulic St
742 Carroll St
746 Carroll St
764 Carroll St
768 Carroll St
777 Seneca St
Buffalo, New York 14210

Prepared For:

598 Main Street LLC
726 Exchange Street, Suite 504
Buffalo, NY 14210

Prepared By:

AFI Environmental
PO Box 4049
Niagara Falls, New York 14304
(716) 283-7645
Project No. xb-Door Store Phase I

February 2010

RECEIVED
NYSDEC - REGION 9

MAR 03 2010

FOIL
REL UNREL

Volume II of II

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Tank Id Number: 223762
Tank Number: 11
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 55467
Tank Id Number: 174824
Tank Number: 1
Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Site Id: 55467
Tank Id Number: 174828
Tank Number: 5
Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Site Id: 55467
Tank Id Number: 174827
Tank Number: 4
Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Site Id: 55467
Tank Id Number: 174825
Tank Number: 2
Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Site Id: 55467
Tank Id Number: 174828
Tank Number: 5
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 223764
Tank Number: 13
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 223759
Tank Number: 8
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 174829

RECEIVED
NYSDEC - REGION 9

MAR 03 2010

FOIL

REL UNREL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Tank Number: 6
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 223760
Tank Number: 9
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 223761
Tank Number: 10
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 223765
Tank Number: 14
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 174826
Tank Number: 3
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 174830
Tank Number: 7
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 223762
Tank Number: 11
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 223763
Tank Number: 12
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 174827
Tank Number: 4

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 174824
Tank Number: 1
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 223766
Tank Number: 15
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 174825
Tank Number: 2
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55467
Tank Id Number: 174829
Tank Number: 6
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 223766
Tank Number: 15
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 223763
Tank Number: 12
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 223760
Tank Number: 9
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 174826
Tank Number: 3
Equipment: B00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 223765
Tank Number: 14
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 223761
Tank Number: 10
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 223759
Tank Number: 8
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 223764
Tank Number: 13
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 223762
Tank Number: 11
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 174830
Tank Number: 7
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 174825
Tank Number: 2
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 174827
Tank Number: 4
Equipment: B01
Code Name: Painted/Asphalt Coating

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Type: Tank External Protection

Site Id: 55467
Tank Id Number: 174824
Tank Number: 1
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 174828
Tank Number: 5
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 55467
Tank Id Number: 174827
Tank Number: 4
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 223763
Tank Number: 12
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 174828
Tank Number: 5
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 223761
Tank Number: 10
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 174825
Tank Number: 2
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 223760
Tank Number: 9
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Site Id: 55467
Tank Id Number: 223764
Tank Number: 13
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 174826
Tank Number: 3
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 174824
Tank Number: 1
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 174829
Tank Number: 6
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 223766
Tank Number: 15
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 223762
Tank Number: 11
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 223765
Tank Number: 14
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467
Tank Id Number: 223759
Tank Number: 8
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55467

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Tank Id Number: 174830
Tank Number: 7
Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Site Id: 55467
Tank Id Number: 174827
Tank Number: 4
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55467
Tank Id Number: 223765
Tank Number: 14
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55467
Tank Id Number: 174824
Tank Number: 1
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55467
Tank Id Number: 223764
Tank Number: 13
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55467
Tank Id Number: 223762
Tank Number: 11
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55467
Tank Id Number: 223760
Tank Number: 9
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55467
Tank Id Number: 223761
Tank Number: 10
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55467
Tank Id Number: 174828

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Tank Number:	5
Equipment:	D00
Code Name:	No Piping
Type:	Pipe Type
Site Id:	55467
Tank Id Number:	223763
Tank Number:	12
Equipment:	D00
Code Name:	No Piping
Type:	Pipe Type
Site Id:	55467
Tank Id Number:	223766
Tank Number:	15
Equipment:	D00
Code Name:	No Piping
Type:	Pipe Type
Site Id:	55467
Tank Id Number:	174825
Tank Number:	2
Equipment:	D00
Code Name:	No Piping
Type:	Pipe Type
Site Id:	55467
Tank Id Number:	174826
Tank Number:	3
Equipment:	D00
Code Name:	No Piping
Type:	Pipe Type
Site Id:	55467
Tank Id Number:	223759
Tank Number:	8
Equipment:	D00
Code Name:	No Piping
Type:	Pipe Type
Site Id:	55467
Tank Id Number:	174829
Tank Number:	6
Equipment:	D01
Code Name:	Steel/Carbon Steel/Iron
Type:	Pipe Type
Site Id:	55467
Tank Id Number:	174830
Tank Number:	7
Equipment:	D01
Code Name:	Steel/Carbon Steel/Iron
Type:	Pipe Type
Site Id:	55467
Tank Id Number:	174829
Tank Number:	6

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 174830
Tank Number: 7
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 223763
Tank Number: 12
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 223765
Tank Number: 14
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 223762
Tank Number: 11
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 223759
Tank Number: 8
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 223760
Tank Number: 9
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 223766
Tank Number: 15
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 174826
Tank Number: 3
Equipment: E00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 223764
Tank Number: 13
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 223761
Tank Number: 10
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 55467
Tank Id Number: 174826
Tank Number: 3
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 223763
Tank Number: 12
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 174827
Tank Number: 4
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 174828
Tank Number: 5
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 223766
Tank Number: 15
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 223764
Tank Number: 13
Equipment: F00
Code Name: None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 223761
Tank Number: 10
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 223759
Tank Number: 8
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 223760
Tank Number: 9
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 223762
Tank Number: 11
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 174829
Tank Number: 6
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 174824
Tank Number: 1
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 174825
Tank Number: 2
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55467
Tank Id Number: 223765
Tank Number: 14
Equipment: F00
Code Name: None
Type: Pipe External Protection

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO, INC. (Continued)

A100294739

Site Id: 55467
Tank Id Number: 174830
Tank Number: 7
Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

R75
NE
1/4-1/2
0.313 mi.
1655 ft.
STAUFFENBURGER RESIDENCE
865 EAST EAGLE STREET
BUFFALO, NY

NY Spills
NY Hist Spills
S104498107
N/A

Site 1 of 3 in cluster R

Relative:
Higher

Actual:
591 ft.

NY Spills:
Site ID: 303288
Facility Addr2: Not reported
Facility ID: 9204851
Spill Number: 9204851
Facility Type: ER
SWIS: 1502
Investigator: COOKE
Referred To: Not reported
Spill Date: 7/1/1992
Reported to Dept: 7/27/1992
CID: 30
Spill Cause: Deliberate
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Citizen
Cleanup Ceased: 10/19/1992
Cleanup Meets Std: True
Last Inspection: 7/30/1992
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: No spill occurred. No DEC Response. No corrective action required.
Spill Closed Dt: 10/19/1992
Remediation Phase: 0
Date Entered In Computer: 7/29/1992
Spill Record Last Update: 10/28/1992
Spiller Name: Not reported
Spiller Company: KOPERA
Spiller Address: 865 EAST EAGLE STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 245054
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JDC" 07/27/92: JDC CONTACTED JOE JORDON, BSA TO INVESTIGATE SPILL. 07/29/92: LETTER SENT TO PROPERTY OWNER BY BSA TO CEASE AND DESIST. ADDITIONAL LOCATION ON EAGLE TO BE INVESTIGATED BY BSA.
Remarks: WASTE OIL SPILLAGE FROM SEVERAL LEAKING CARS
Material:
Site ID: 303288
Operable Unit ID: 972370
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STAUFFENBURGER RESIDENCE (Continued)

S104498107

Material ID: 409095
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9204851
Investigator: JDC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 07/01/1992 12:00
Reported to Dept Date/Time: 07/27/92 09:16
SWIS: 14
Spiller Name: KOPERA
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: 865 EAST EAGLE STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spill Cause: Deliberate
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 09
Spill Notifier: Citizen
PBS Number: Not reported
Cleanup Ceased: 10/19/92
Cleanup Meets Std: True
Last Inspection: 07/30/92
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STAUFFENBURGER RESIDENCE (Continued)

S104498107

Spill Class: No spill occurred. No DEC Response. No corrective action required.
Spill Closed Dt: 10/19/92
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/29/92
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/28/92
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927

DEC Remarks: 07/27/92: JDC CONTACTED JOE JORDON, BSA TO INVESTIGATE SPILL. 07/29/92: LETTER
SENT TO PROPERTY OWNER BY BSA TO CEASE AND DESIST. ADDITIONAL LOCATION ON EAGLE
TO BE INVESTIGATED BY BSA.

Remark: WASTE OIL SPILLAGE FROM SEVERAL LEAKING CARS

Q76
ENE
1/4-1/2
0.316 mi.
1668 ft.

METALICO BUFFALO INC
127 FILLMORE AVE
BUFFALO, NY 14210

RCRA-SQG 1011490536
NYR000157974

Site 4 of 4 in cluster Q

Relative:
Lower

Actual:
589 ft.

RCRA-SQG:

Date form received by agency: 06/27/2008
Facility name: METALICO BUFFALO INC
Facility address: 127 FILLMORE AVE
BUFFALO, NY 14210
EPA ID: NYR000157974
Mailing address: FILLMORE AVE
BUFFALO, NY 14210
Contact: JAMES T BUCKI
Contact address: FILLMORE AVE
BUFFALO, NY 14210
Contact country: US
Contact telephone: (716) 583-2720
Contact email: BHCJTB@AOL.COM
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous
waste during any calendar month and accumulates less than 6000 kg of
hazardous waste at any time; or generates 100 kg or less of hazardous

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METALICO BUFFALO INC (Continued)

1011490536

waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: GEORGE OSTENDORF
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2006
Owner/Op end date: Not reported

Owner/operator name: METALICO INC
Owner/operator address: NORTH AVE EAST
CRANFORD, NJ 07016
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/01/1998
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

S77
South
1/4-1/2
0.322 mi.
1698 ft.

NIAGARA MOHAWK STATION 59
809 PERRY ST
BUFFALO, NY 14210

Site 1 of 3 in cluster S

Relative:
Higher

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NIAGARA MOHAWK STATION 59
Facility address: 809 PERRY ST
BUFFALO, NY 142101446
EPA ID: NYD981486566
Mailing address: ERIE BLVD WEST
SYRACUSE, NY 13202

Actual:
599 ft.

RCRA-NonGen 1000232840
FINDS NYD981486566

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NIAGARA MOHAWK STATION 59 (Continued)

1000232840

Contact: Not reported
Contact address: ERIE BLVD WEST
SYRACUSE, NY 13202
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NIAGARA MOHAWK POWER CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NIAGARA MOHAWK POWER CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: NIAGARA MOHAWK STATION 59
Classification: Not a generator, verified

Date form received by agency: 07/08/1999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NIAGARA MOHAWK STATION 59 (Continued)

1000232840

Facility name: NIAGARA MOHAWK STATION 59
Classification: Not a generator, verified

Date form received by agency: 05/27/1986
Facility name: NIAGARA MOHAWK STATION 59
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110009472793

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

S78
South
1/4-1/2
0.322 mi.
1698 ft.

NIAGARA MOHAWK STATION 12
809 PERRY STREET
BUFFALO, NY

NY Spills **S102174492**
NY Hist Spills **N/A**

Site 2 of 3 in cluster S

Relative:
Higher

Actual:
599 ft.

NY Spills:
Site ID: 112451
Facility Addr2: Not reported
Facility ID: 9200367
Spill Number: 9200367
Facility Type: ER
SWIS: 1502
Investigator: PRINGLE
Referred To: Not reported
Spill Date: 4/8/1992
Reported to Dept: 4/8/1992
CID: 30
Spill Cause: Vandalism
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: 4/11/1994
Cleanup Meets Std: True
Last Inspection: 4/11/1994
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 4/12/1994
Remediation Phase: 0
Date Entered In Computer: 4/16/1992
Spill Record Last Update: 9/29/1999
Spiller Name: Not reported
Spiller Company: NIAGARA MOHAWK
Spiller Address: 144 KENSINGTON AVENUE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NIAGARA MOHAWK STATION 12 (Continued)

S102174492

Spiller City,St,Zip: BUFFALO, NY 14214
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 98221
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MNP" 04/14/92: 4/14/92 MNP INSP. MOST OF CONTAM. SOIL REMOVED, SHEEN IN EXCAVATION, FREE PRODUCT BEING VACCED FROM SUMP. MW TO BE INSTALLED. 02/25/93: 2/25/93 MNP TELECON W/ FRANK GRABOWSKI - N.M. SETUP INSP. & MEETING ON 3/5/93. 03/05/93: 3/5/93 MNP INSP. & MEETING W/ FRANK GRABOWSKI - N.M. SLIGHT SHEEN & DEFINITE ODOR NOTED AFTER BAILING MW. WATER TO BE SAMPLED FOR MINERAL OIL. NEED DISPOSAL RECEIPTS & RECOVERY INFO. 01/26/94: MF - 1/26/94 SITE VISIT - COULD NOT ACCESS SITE DUE TO SNOW. SUBSTATION UNMANNED AND COULD NOT SPEAK TO ANYONE. 03/11/94: F.GRABOWSKI& FG TO CHECK SITE WHEN ACCESSIBLE-AFTER SNOW MELT. NIMO SUBMITTED ALL REQUESTED INFOR & DISPOSED OF CONTAMINATED SOIL. 04/12/94: MNP SITE VISIT 4/11/94. ALL CONTAMINATED MATERIAL HAD BEEN REMOVED FROM THE SITE. THE SITE CAN BE CLOSED.
Remarks: SPILL OF TRANSFORMER OIL ON GROUND, THEN SEEPED INTO BLDG. DRAINS; CAUSED BY VANDALS.

Material:

Site ID: 112451
Operable Unit ID: 964304
Operable Unit: 01
Material ID: 415172
Material Code: 0016A
Material Name: NON PCB OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 890
Units: Gallons
Recovered: 800
Resource Affected: Soil
Oxygenate: False
Site ID: 112451
Operable Unit ID: 964304
Operable Unit: 01
Material ID: 415173
Material Code: 0020A
Material Name: TRANSFORMER OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NIAGARA MOHAWK STATION 12 (Continued)

S102174492

Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9200367
Investigator: MNP
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 04/08/1992 13:45
Reported to Dept Date/Time: 04/08/92 15:50
SWIS: 14
Spiller Name: NIAGARA MOHAWK
Spiller Contact: Not reported
Spiller Phone: (716) 831-7426
Spiller Address: 144 KENSINGTON AVENUE
Spiller City,St,Zip: BUFFALO, NY 14214
Spill Cause: Vandalism
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: 04/11/94
Cleanup Meets Std: True
Last Inspection: 04/11/94
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates a file or hazard. DEC Response. Willing
Responsible Party. Corrective action taken.
Spill Closed Dt: 04/12/94
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/16/92
Date Spill Entered In Computer Data File: Not reported
Update Date: 09/29/99
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NIAGARA MOHAWK STATION 12 (Continued)

S102174492

Material:

Material Class Type: Petroleum

Quantity Spilled: 890

Unkonwn Quantity Spilled: False

Units: Gallons

Quantity Recovered: 800

Unkonwn Quantity Recovered: False

Material: NON PCB OIL

Class Type: NON PCB OIL

Times Material Entry In File: 2798

CAS Number: Not reported

Last Date: 19940928

Material Class Type: Petroleum

Quantity Spilled: 0

Unkonwn Quantity Spilled: False

Units: Pounds

Quantity Recovered: 0

Unkonwn Quantity Recovered: False

Material: TRANSFORMER OIL

Class Type: TRANSFORMER OIL

Times Material Entry In File: 533

CAS Number: Not reported

Last Date: 19940926

DEC Remarks: 04/14/92: 4/14/92 MNP INSP. MOST OF CONTAM. SOIL REMOVED, SHEEN IN EXCAVATION, FREE PRODUCT BEING VACCED FROM SUMP. MW TO BE INSTALLED. 02/25/93: 2/25/93 MNP TELECON W/ FRANK GRABOWSKI - N.M. SETUP INSP. MEETING ON 3/5/93. 03/05/93: 3/5/93MNP INSP. MEETING W/ FRANK GRABOWSKI - N.M. SLIGHT SHEEN DEFINITE ODOR NOTED AFTER BAILING MW. WATER TO BE SAMPLED FOR MINERAL OIL. NEED DISPOSAL RECEIPTS RECOVERY INFO. 01/26/94: MF - 1/26/94 SITE VISIT - COULD NOT ACCESS SITE DUE TO SNOW. SUBSTATION UNMANNED AND COULD NOT SPEAK TO ANYONE. 03/11/94: F.GRABOWSKI FG TO CHECK SITE WHEN ACCESSIBLE-AFTER SNOW MELT. NIMO SUBMITTED ALL REQUESTED INFOR DISPOSED OF CONTAMINATED SOIL. 04/12/94: MNP SITE VISIT 4/11/94. ALL CONTAMINATED MATERIAL HAD BEEN REMOVED FROM THE SITE. THE SITE CAN BE CLOSED.

Remark: SPILL OF TRANSFORMER OIL ON GROUND, THEN SEEPED INTO BLDG. DRAINS; CAUSED BY VANDALS.

S79
South
1/4-1/2
0.322 mi.
1698 ft.

STATION 12
809 PERRY ST
BUFFALO, NY 14210

Site 3 of 3 in cluster S

RCRA-NonGen 1000413612
FINDS NYD980783179
MANIFEST

Relative:
Higher

RCRA-NonGen:

Date form received by agency: 01/01/2007

Facility name: STATION 12

Facility address: 809 PERRY ST
BUFFALO, NY 14210

EPA ID: NYD980783179

Mailing address: ERIE BLVD W
SYRACUSE, NY 13202

Contact: Not reported

Contact address: ERIE BLVD W
SYRACUSE, NY 13202

Contact country: US

Contact telephone: Not reported

Contact email: Not reported

Actual:
599 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STATION 12 (Continued)

1000413612

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: STATION 12
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Facility name: STATION 12
Classification: Small Quantity Generator

Date form received by agency: 11/20/1984
Facility name: STATION 12
Classification: Large Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number

EPA ID Number

STATION 12 (Continued)

1000413612

Violation Status: No violations found

FINDS:

Registry ID: 110004392559

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD980783179
Country: USA
Mailing Name: NIAGARA MOHAWK POWER CORPORATION
Mailing Contact: F J GRABOWSKI
Mailing Address: 144 KENSINGTON AVENUE
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14214
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-831-7426

Document ID: NYB1391913
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 1287ABOK
Trans2 State ID: Not reported
Generator Ship Date: 900723
Trans1 Recv Date: 900723
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900724
Part A Recv Date: 900831
Part B Recv Date: 900907
Generator EPA ID: NYD980783179
Trans1 EPA ID: OKD981514474
Trans2 EPA ID: Not reported
TSDF ID: PAD981113749
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 06552
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 90
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STATION 12 (Continued)

1000413612

Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYG0202176
Manifest Status: Not reported
Trans1 State ID: OHD987056751
Trans2 State ID: Not reported
Generator Ship Date: 03/11/1998
Trans1 Recv Date: 03/11/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/11/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980783179
Trans1 EPA ID: OHD981100969
Trans2 EPA ID: Not reported
TSDF ID: K97656ME
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 01987
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

R80
NE
1/4-1/2
0.333 mi.
1760 ft.

WASTE OIL
152 JAMES STREET
BUFFALO, NY
Site 2 of 3 in cluster R

NY Spills S102178573
NY Hist Spills N/A

Relative:
Higher

NY Spills:
Site ID: 149209
Facility Addr2: Not reported
Facility ID: 9401956
Spill Number: 9401956
Facility Type: ER
SWIS: 1502
Investigator: RMCROSSE

Actual:
591 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WASTE OIL (Continued)

S102178573

Referred To: Not reported
Spill Date: 5/1/1994
Reported to Dept: 5/10/1994
CID: 30
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Passenger Vehicle
Spill Notifier: Affected Persons
Cleanup Ceased: 5/13/1994
Cleanup Meets Std: True
Last Inspection: 5/12/1994
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 5/13/1994
Remediation Phase: 0
Date Entered In Computer: 5/17/1994
Spill Record Last Update: 11/23/1994
Spiller Name: Not reported
Spiller Company: KINNITH MILLER
Spiller Address: 823 EGAL STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 126948
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "RMC" 05/12/94: RMC/SITE FOUND CAR TO LEAKING SIGNIFICANT AMOUNT OF OIL FROM ENGIN, SENT OWNER REPAIR LETTER, NO FURTHER ACTION REQUIRED, CLOSE OUT.

Remarks: PLATE NUMBER B54 6FB LEAKING OIL

Material:

Site ID: 149209
Operable Unit ID: 995632
Operable Unit: 01
Material ID: 385694
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WASTE OIL (Continued)

S102178573

Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9401956
Investigator: RMC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/01/1994 12:00
Reported to Dept Date/Time: 05/10/94 09:30
SWIS: 14
Spiller Name: KINNITH MILLER
Spiller Contact: Not reported
Spiller Phone: () -
Spiller Address: 823 EGAL STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 06
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: 05/13/94
Cleanup Meets Std: True
Last Inspection: 05/12/94
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/13/94
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/17/94
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/23/94
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WASTE OIL (Continued)

S102178573

Material:

Material Class Type: Petroleum

Quantity Spilled: 0

Unkonwn Quantity Spilled: False

Units: Gallons

Quantity Recovered: 0

Unkonwn Quantity Recovered: False

Material: WASTE OIL

Class Type: WASTE OIL

Times Material Entry In File: 9509

CAS Number: Not reported

Last Date: 19940927

DEC Remarks: 05/12/94: RMC/SITE FOUND CAR TO LEAKING SIGNIFICANT AMOUNT OF OIL FROM ENGIN,
SENT OWNER REPAIR LETTER, NO FURTHER ACTION REQUIRED, CLOSE OUT.

Remark: PLATE NUMBER B54 6FB LEAKING OIL

R81
NE
1/4-1/2
0.333 mi.
1760 ft.

MILLER RESIDENCE
152 JAMES STREET
BUFFALO, NY

Site 3 of 3 in cluster R

NY Spills S102178440
NY Hist Spills N/A

Relative:
Higher

Actual:
591 ft.

NY Spills:

Site ID: 149208

Facility Addr2: Not reported

Facility ID: 9315011

Spill Number: 9315011

Facility Type: ER

SWIS: 1502

Investigator: RMCROSSE

Referred To: Not reported

Spill Date: 3/22/1994

Reported to Dept: 3/22/1994

CID: 30

Spill Cause: Housekeeping

Water Affected: Not reported

Spill Source: Passenger Vehicle

Spill Notifier: Affected Persons

Cleanup Ceased: 3/21/1994

Cleanup Meets Std: True

Last Inspection: 3/21/1994

Recommended Penalty: Penalty Not Recommended

UST Trust: False

Spill Class: No spill occured. No DEC Response. No corrective action required.

Spill Closed Dt: 3/22/1994

Remediation Phase: 0

Date Entered In Computer: 3/24/1994

Spill Record Last Update: 5/11/2005

Spiller Name: Not reported

Spiller Company: NONE

Spiller Address: Not reported

Spiller City,St,Zip: NY

Spiller Company: 999

Contact Name: Not reported

Contact Phone: Not reported

DEC Region: 9

DER Facility ID: 126948

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILLER RESIDENCE (Continued)

S102178440

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"RMC" 03/21/94: RMC/SITE FOUND PLACE WHERE MOTOR IS BEING CHANGED,
MINOR DRIPS FROM R+R, NO OVERT SPILLAGE, NO ACTION REQUIRED, CLOSE
OUT.
Remarks: PERSON CHANGING OIL IN FRONT OF 154 JAMES STREET WAS SPILLING OIL
ONTO STREET

Material:
Site ID: 149208
Operable Unit ID: 996937
Operable Unit: 01
Material ID: 386790
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 9
Spill Number: 9315011
Investigator: RMC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 03/22/1994 14:00
Reported to Dept Date/Time: 03/22/94 14:15
SWIS: 14
Spiller Name: NONE
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Housekeeping
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 06

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILLER RESIDENCE (Continued)

S102178440

Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: 03/21/94
Cleanup Meets Std: True
Last Inspection: 03/21/94
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: No spill occured. No DEC Response. No corrective action required.
Spill Closed Dt: 03/21/94
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/24/94
Date Spill Entered In Computer Data File: Not reported
Update Date: 03/31/94
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927
DEC Remarks: 03/21/94: RMC/SITE FOUND PLACE WHERE MOTOR IS BEING CHANGED, MINOR DRIPS FROM R+R, NO OVERT SPILLAGE, NO ACTION REQUIRED, CLOSE OUT.
Remark: PERSON CHANGING OIL IN FRONT OF 154 JAMES STREET WAS SPILLING OIL ONTO STREET

T82
WSW
1/4-1/2
0.334 mi.
1762 ft.

WORLD AUTO PARTS INC
221-233 LARKIN STREET
BUFFALO, NY

Site 1 of 2 in cluster T

NY Spills **S104498101**
NY Hist Spills **N/A**

Relative:
Equal

Actual:
590 ft.

NY Spills:
Site ID: 261845
Facility Addr2: Not reported
Facility ID: 9204432
Spill Number: 9204432
Facility Type: ER
SWIS: 1502
Investigator: RMCROSSE
Referred To: Not reported
Spill Date: 7/1/1992

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WORLD AUTO PARTS INC (Continued)

S104498101

Reported to Dept: 7/16/1992
CID: 30
Spill Cause: Housekeeping
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: DEC
Cleanup Ceased: 1/28/1993
Cleanup Meets Std: True
Last Inspection: 1/14/1993
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 1/28/1993
Remediation Phase: 0
Date Entered In Computer: 7/27/1992
Spill Record Last Update: 2/1/1993
Spiller Name: Not reported
Spiller Company: WORLD AUTO PARTS INC
Spiller Address: BOX 307
Spiller City,St,Zip: BUFFALO, NY 14240
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 213835
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"RMC" 07/14/92: RMC/SITE 16 TRUCKS 8 HAVE USED OIL UNDER THEM, PATH
LEADS TO STORM SEWER. 01/11/93: RMC/SITE - UNCHANGED; NO ONE AROUND.
01/23/93: RMC/ROBERT MAYER/PHONE - ADVISED TO USE SPEEDY-DRI ON
SPILLS AND TO INFORM EMPLOYEES OF PROPER PETROLEUM HANDLING METHODS.
LETTER SENT. 01/28/93: RMC/FILE REVIEW RP WILL TAKE STEPS TO LESSEN
PROBLEM IN THE SALVAGE YARD, LETTER SENT FOR THE RECORD. CLOSE OUT.
OIL UNDER SEVERAL TRUCKS
Remarks:
Material:
Site ID: 261845
Operable Unit ID: 971824
Operable Unit: 01
Material ID: 412157
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Sewer
Oxygenate: False
Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WORLD AUTO PARTS INC (Continued)

S104498101

Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9204432
Investigator: RMC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 07/01/1992 12:00
Reported to Dept Date/Time: 07/16/92 13:00
SWIS: 14
Spiller Name: WORLD AUTO PARTS INC
Spiller Contact: Not reported
Spiller Phone: (716) 826-6066
Spiller Address: BOX 307
Spiller City, St, Zip: BUFFALO, NY 14240
Spill Cause: Housekeeping
Reported to Dept: In Sewer
Water Affected: Not reported
Spill Source: 01
Spill Notifier: DEC
PBS Number: Not reported
Cleanup Ceased: 01/28/93
Cleanup Meets Std: True
Last Inspection: 01/14/93
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 01/28/93
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/27/92
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/01/93
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WORLD AUTO PARTS INC (Continued)

S104498101

Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 07/14/92: RMC/SITE 16 TRUCKS 8 HAVE USED OIL UNDER THEM, PATH LEADS TO STORM SEWER. 01/11/93: RMC/SITE - UNCHANGED; NO ONE AROUND. 01/23/93: RMC/ROBERT MAYER/PHONE - ADVISED TO USE SPEEDY-DRI ON SPILLS AND TO INFORM EMPLOYEES OF PROPER PETROLEUMHANDLING METHODS. LETTER SENT. 01/28/93: RMC/FILE REVIEW RP WILL TAKE STEPS TO LESSEN PROBLEM IN THE SALVAGE YARD, LETTER SENT FOR THE RECORD. CLOSE OUT.
Remark: OIL UNDER SEVERAL TRUCKS

T83
WSW
1/4-1/2
0.336 mi.
1774 ft.

**NATIONAL GRID TRUCK
ROSEVILLE / LARKIN STREET
BUFFALO, NY**

**NY Spills S109063245
N/A**

Site 2 of 2 in cluster T

**Relative:
Equal**

**Actual:
590 ft.**

NY Spills:
Site ID: 398298
Facility Addr2: Not reported
Facility ID: 0802205
Spill Number: 0802205
Facility Type: ER
SWIS: 1542
Investigator: TDJOHNSO
Referred To: Not reported
Spill Date: 5/27/2008
Reported to Dept: 5/27/2008
CID: 444
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 5/28/2008
Remediation Phase: 0
Date Entered In Computer: 5/27/2008
Spill Record Last Update: 8/8/2008
Spiller Name: LISA MONTSANO
Spiller Company: NATIONAL GRID TRUCK
Spiller Address: ROSEVILLE & LARKIN STREET
Spiller City,St,Zip: BUFFALO, NY
Spiller Company: 001
Contact Name: LISA MONTSANO
Contact Phone: (716) 479-5339

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GRID TRUCK (Continued)

S109063245

DEC Region: 9
DER Facility ID: 347661
DEC Memo: 05/27/08 National Grid spill response team responded to spill on paved parking area. Hydraulic fluid was soaked up with absorbent material and washed clean. 05/28/08 Checked site, cleanup complete.
FILE CLOSED ELECTRONIC COPY ONLY
Remarks: LINE LEAKED AND CREW TO CLEAN

Material:
Site ID: 398298
Operable Unit ID: 1155191
Operable Unit: 01
Material ID: 2146051
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

84
West
1/4-1/2
0.339 mi.
1788 ft.

ALP STEEL
650 EXCHANGE ST
BUFFALO, NY 14210

RCRA-CESQG 1000447081
FINDS NYD986912491
MANIFEST

Relative:
Lower

Actual:
589 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: ALP STEEL CORP
Facility address: 650 EXCHANGE ST
BUFFALO, NY 14210
EPA ID: NYD986912491
Mailing address: EXCHANGE ST
BUFFALO, NY 14210
Contact: ROBERT JR WAVER
Contact address: EXCHANGE ST
BUFFALO, NY 14210
Contact country: US
Contact telephone: (716) 854-3030
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: ALP STEEL CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ALP STEEL CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: ALP STEEL CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/10/1992
Facility name: ALP STEEL CORP
Site name: ALP STEEL
Classification: Large Quantity Generator

Date form received by agency: 09/11/1990
Facility name: ALP STEEL CORP
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/12/2001
Date achieved compliance: 01/12/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/19/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/24/1991
Date achieved compliance: 04/12/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/31/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 05/02/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/12/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 01/12/2001
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Evaluation date: 02/21/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/24/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 04/12/1991
Evaluation lead agency: State

Evaluation date: 11/21/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004452654

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD986912491
Country: USA
Mailing Name: ALP STEEL CORP
Mailing Contact: ROBERT WAVER
Mailing Address: PO BOX 1085
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14220
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-854-3030

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: VTR000500090
Trans2 State ID: NYD980761191
Generator Ship Date: 11/21/2007
Trans1 Recv Date: 11/21/2007
Trans2 Recv Date: 12/3/2007
TSD Site Recv Date: 12/4/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986912491

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: PAD067098822
Waste Code: Not reported
Quantity: 110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 001215917FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: NJA1779210
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: NJDEPES50
Trans2 State ID: S50060
Generator Ship Date: 940325
Trans1 Recv Date: 940325
Trans2 Recv Date: 940329
TSD Site Recv Date: 940330
Part A Recv Date: 940404
Part B Recv Date: 940526
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSD ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA2826818
Manifest Status: Not reported
Trans1 State ID: NYD980761191
Trans2 State ID: NYD980761191
Generator Ship Date: 02/04/1999
Trans1 Recv Date: 02/04/1999
Trans2 Recv Date: 02/10/1999
TSD Site Recv Date: 02/25/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986912491
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSD ID: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA1887953
Manifest Status: Completed copy
Trans1 State ID: 50060
Trans2 State ID: S50060
Generator Ship Date: 941222
Trans1 Recv Date: 941222
Trans2 Recv Date: 941227
TSD Site Recv Date: 941228
Part A Recv Date: 950103
Part B Recv Date: 950109
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSD ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA3036512
Manifest Status: Not reported
Trans1 State ID: NYD980761191
Trans2 State ID: NYD980761191
Generator Ship Date: 10/14/1999
Trans1 Recv Date: 10/14/1999
Trans2 Recv Date: 11/04/1999
TSD Site Recv Date: 02/04/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986912491
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSD ID: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MIA9556183
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Trans1 State ID: NYR000100362
Trans2 State ID: NYD097644801
Generator Ship Date: 01/28/2005
Trans1 Recv Date: 01/28/2005
Trans2 Recv Date: 02/03/2005
TSD Site Recv Date: 02/17/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986912491
Trans1 EPA ID: Not reported
Trans2 EPA ID: AC25372NY
TSD ID: MID060975844
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: Not reported
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA3036531
Manifest Status: Not reported
Trans1 State ID: NYD980761191
Trans2 State ID: NYD980761191
Generator Ship Date: 05/23/2000
Trans1 Recv Date: 05/23/2000
Trans2 Recv Date: 05/31/2000
TSD Site Recv Date: 06/15/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986912491
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSD ID: S50060
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 00
Manifest Tracking Num: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2362050
Manifest Status: Completed copy
Trans1 State ID: HC6341
Trans2 State ID: Not reported
Generator Ship Date: 910620
Trans1 Recv Date: 910620
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910621
Part A Recv Date: 910627
Part B Recv Date: 910702
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSDF ID: NYD043815703
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 01400
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2362536
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 80357VNY
Trans2 State ID: Not reported
Generator Ship Date: 910411
Trans1 Recv Date: 910411
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910411

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Part A Recv Date: 910418
Part B Recv Date: 910514
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD982792814
Trans2 EPA ID: Not reported
TSD ID: OHD980681571
Waste Code: F005 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 21600
Units: P - Pounds
Number of Containers: 072
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MIA9556183
Manifest Status: Not reported
Trans1 State ID: NYR000100362
Trans2 State ID: NYD097644801
Generator Ship Date: 01/28/2005
Trans1 Recv Date: 01/28/2005
Trans2 Recv Date: 02/03/2005
TSD Site Recv Date: 02/17/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986912491
Trans1 EPA ID: Not reported
Trans2 EPA ID: AC25372NY
TSD ID: MID060975844
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA8393742
Manifest Status: Completed copy
Trans1 State ID: HC6341
Trans2 State ID: Not reported
Generator Ship Date: 910228
Trans1 Recv Date: 910228
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910228
Part A Recv Date: 910311
Part B Recv Date: 910315
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSDF ID: NYD043815703
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2362428
Manifest Status: Completed copy
Trans1 State ID: JD2082
Trans2 State ID: Not reported
Generator Ship Date: 910912
Trans1 Recv Date: 910912
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

TSD Site Recv Date: 910912
Part A Recv Date: 910919
Part B Recv Date: 910920
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSD ID: NYD043815703
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA2169708
Manifest Status: Completed copy
Trans1 State ID: S50060
Trans2 State ID: Not reported
Generator Ship Date: 960716
Trans1 Recv Date: 960716
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960717
Part A Recv Date: 960801
Part B Recv Date: 960802
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4558977
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: JD2082
Trans2 State ID: JD2082
Generator Ship Date: 911205
Trans1 Recv Date: 911205
Trans2 Recv Date: 911223
TSD Site Recv Date: 911223
Part A Recv Date: Not reported
Part B Recv Date: 920108
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSDF ID: NYD043815703
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4560552
Manifest Status: Completed copy
Trans1 State ID: JY9260
Trans2 State ID: Not reported
Generator Ship Date: 920409
Trans1 Recv Date: 920409
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920415
Part A Recv Date: 920417
Part B Recv Date: 920429
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

TSD ID: NYD043815703
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYG0201321
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: JD2082NY
Trans2 State ID: 24269SNY
Generator Ship Date: 970421
Trans1 Recv Date: 970421
Trans2 Recv Date: 970505
TSD Site Recv Date: 970506
Part A Recv Date: 970429
Part B Recv Date: 970523
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSD ID: OHD055522429
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Document ID: NYB8023365
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PM2759NY
Trans2 State ID: PR5398NY
Generator Ship Date: 961209
Trans1 Recv Date: 961209
Trans2 Recv Date: 961226
TSD Site Recv Date: 961227
Part A Recv Date: 961227
Part B Recv Date: 970116
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSDF ID: OHD055522429
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4559112
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: JD2082
Trans2 State ID: NJT440LL
Generator Ship Date: 920124
Trans1 Recv Date: 920124
Trans2 Recv Date: 920207
TSD Site Recv Date: 920212
Part A Recv Date: 920203
Part B Recv Date: 920221
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSDF ID: VTD982766537
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: VTA0048260
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: JD2082NY
Trans2 State ID: NY24269S
Generator Ship Date: 921217
Trans1 Recv Date: 921217
Trans2 Recv Date: 921222
TSD Site Recv Date: 921223
Part A Recv Date: 921230
Part B Recv Date: 930113
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSDF ID: VTD982766537
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: VTA0035821
Manifest Status: Completed copy
Trans1 State ID: JD2082
Trans2 State ID: PB2740NY
Generator Ship Date: 920716
Trans1 Recv Date: 920716

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALP STEEL (Continued)

1000447081

Trans2 Recv Date: 920717
TSD Site Recv Date: 920722
Part A Recv Date: Not reported
Part B Recv Date: 920730
Generator EPA ID: NYD986912491
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSD ID: VTD982766537
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

[Click this hyperlink](#) while viewing on your computer to access
6 additional NY_MANIFEST: record(s) in the EDR Site Report.

U85 **MILLER LUMBER CO INC**
NE **893 EAGLE ST**
1/4-1/2 **BUFFALO, NY 14210**
0.344 mi.
1814 ft. **Site 1 of 2 in cluster U**

UST **U003317170**
HIST UST **N/A**

Relative:
Higher

Actual:
591 ft.

UST:
Facility Id: 9-386669
Region: STATE
DEC Region: 9
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 186202.56297
UTM Y: 4754487.4016000004
Site ID: 53756

Tank Number: 1
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 1/1/1960
Capacity Gallons: 1000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: 9/1/1992

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILLER LUMBER CO INC (Continued)

U003317170

Tank ID: 164073
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: Not reported
Register: True
Trade Sec: False
Modified By: TRANSLAT
Last Modified: 3/4/2004

Tank Number: 2
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 1/1/1960
Capacity Gallons: 1000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: 9/1/1992
Tank ID: 164074
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: Not reported
Register: True
Trade Sec: False
Modified By: TRANSLAT
Last Modified: 3/4/2004

UST_PBS_BSAFFIL:

Site Id: 53756
Program Number: 9-386669
Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN
Company Name: JOHN A KRESS JR
Contact Type: Not reported
Contact Name: Not reported
Address1: 15 DEER RUN
Address2: Not reported
City: WILLIAMSVILLE
State: NY
Zip Code: 14221
Country Code: 001
Phone: (716) 688-5102
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 53756
Program Number: 9-386669
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: ZZZ
Company Name: JOHN A KRESS JR
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILLER LUMBER CO INC (Continued)

U003317170

Contact Name: Not reported
Address1: 15 DEER RUN
Address2: Not reported
City: WILLIAMSVILLE
State: NY
Zip Code: 14221
Country Code: 001
Phone: (716) 688-5102
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 53756
Program Number: 9-386669
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: JOHN A KRESS JR
Contact Type: Not reported
Contact Name: JOHN A KRESS III
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 688-5837
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 53756
Program Number: 9-386669
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: MILLER LUMBER CO INC
Contact Type: Not reported
Contact Name: MILLER LUMBER CO INC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 854-3220
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILLER LUMBER CO INC (Continued)

U003317170

UST_AST_PBS_BSEQUIP:

Site Id: 53756
Tank Id Number: 164074
Tank Number: 2
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: H04
Code Name: Groundwater Well
Type: Tank Leak Detection

Site Id: 53756
Tank Id Number: 164074
Tank Number: 2
Equipment: H04
Code Name: Groundwater Well
Type: Tank Leak Detection

Site Id: 53756
Tank Id Number: 164074
Tank Number: 2
Equipment: I00
Code Name: None
Type: Overfill

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: I00
Code Name: None
Type: Overfill

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 53756
Tank Id Number: 164074
Tank Number: 2
Equipment: J02
Code Name: Suction
Type: Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILLER LUMBER CO INC (Continued)

U003317170

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 53756
Tank Id Number: 164074
Tank Number: 2
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 53756
Tank Id Number: 164074
Tank Number: 2
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 53756
Tank Id Number: 164074
Tank Number: 2
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 53756
Tank Id Number: 164074
Tank Number: 2
Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Site Id: 53756

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILLER LUMBER CO INC (Continued)

U003317170

Tank Id Number: 164074
Tank Number: 2
Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Site Id: 53756
Tank Id Number: 164073
Tank Number: 1
Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

HIST UST:

PBS Number: 9-386669
SPDES Number: Not reported
Emergency Contact: JOHN A KRESS III
Emergency Telephone: (716) 688-5837
Operator: MILLER LUMBER CO INC
Operator Telephone: (716) 854-3220
Owner Name: JOHN A KRESS JR
Owner Address: 15 DEER RUN
Owner City,St,Zip: WILLIAMSVILLE, NY 14221
Owner Telephone: (716) 688-5102
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Name: JOHN A KRESS JR
Mailing Address: 15 DEER RUN
Mailing Address 2: Not reported
Mailing City,St,Zip: WILLIAMSVILLE, NY 14221
Mailing Contact: Not reported
Mailing Telephone: (716) 688-5102
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons)
and Subpart 360-14.
Facility Addr2: Not reported
SWIS ID: 1402
Old PBS Number: Not reported
Facility Type: OTHER RETAIL SALES
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 07/20/1987
Expiration Date: 07/20/1992
Renew Flag: False
Renewal Date: 19920501
Total Capacity: 0
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: 0
Dead Letter: True
CBS Number: Not reported
Town or City: BUFFALO (C)
County Code: 14

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILLER LUMBER CO INC (Continued)

U003317170

Town or City: 02
Region: 9

Tank Id: 1
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: 19600101
Capacity (gals): 1000
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 10
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 10
Second Containment: None
Leak Detection: Groundwater Well
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 09/01/1992
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 2
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: 19600101
Capacity (gals): 1000
Product Stored: LEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 10
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 10
Second Containment: None
Leak Detection: 30
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 09/01/1992
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

86
NNE
1/4-1/2
0.347 mi.
1831 ft.

CONRAIL
CLINTON / LORD STREETS
BUFFALO, NY

NY Spills
NY Hist Spills

S105056167
N/A

Relative:
Higher

Actual:
593 ft.

NY Spills:

Site ID: 254641
Facility Addr2: Not reported
Facility ID: 9207418
Spill Number: 9207418
Facility Type: ER
SWIS: 1502
Investigator: SORGI
Referred To: Not reported
Spill Date: 9/26/1992
Reported to Dept: 9/26/1992
CID: Not reported
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: 11/22/1993
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.

Spill Closed Dt: 11/22/1993
Remediation Phase: 0

Date Entered In Computer: 9/29/1992
Spill Record Last Update: 11/23/1993
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 208562

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MJS" 11/22/93: MJS REVIEWED FILE. CONRAIL CONTRACTED OH MATERIALS TO CLEAN UP (ONLY 1 GAL. SPILLED). NO FURTHER ACTION REQUIRED. MJS TO CLOSE FILE.

Remarks: POLICE DEPT NOTIFIED CONRAIL; CONRAIL PICKED UP MATERIAL

Material:

Site ID: 254641
Operable Unit ID: 971058
Operable Unit: 01
Material ID: 408058
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONRAIL (Continued)

S105056167

Recovered: No
Resource Affected: Soil
Oxygenate: False
Site ID: 254641
Operable Unit ID: 971058
Operable Unit: 01
Material ID: 408059
Material Code: 0567A
Material Name: FURFURYL MERCAPTAN
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9207418
Investigator: MJS
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 09/26/1992 13:29
Reported to Dept Date/Time: 09/26/92 14:23
SWIS: 14
Spiller Name: UNKNOWN
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: 11/22/93
Cleanup Meets Std: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONRAIL (Continued)

S105056167

Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Spill Closed Dt: 11/22/93
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 09/29/92
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/23/93
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
Material Class Type: Hazardous Material
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: FURFURYL MERCAPTAN
Class Type: FURFURYL MERCAPTAN
Times Material Entry In File: 1
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: 11/22/93: MJS REVIEWED FILE. CONRAIL CONTRACTED OH MATERIALS TO CLEAN UP ONLY 1 GAL. SPILLED). NO FURTHER ACTION REQUIRED. MJS TO CLOSE FILE.
Remark: POLICE DEPT NOTIFIED CONRAIL; CONRAIL PICKED UP MATERIAL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

V87 NYS THRUWAY AUTH - BIN 5512269
SW VAN RENSSELAER ST & PERRY ST
1/4-1/2 BUFFALO, NY 14210
0.353 mi.
1866 ft. Site 1 of 5 in cluster V

RCRA-NonGen 1000553257
FINDS NYD986956720
MANIFEST

Relative:
Lower

Actual:
589 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYS THRUWAY AUTH - BIN 5512269
Facility address: VAN RENSSELAER ST & PERRY ST
BUFFALO, NY 14210
EPA ID: NYD986956720
Mailing address: GENESEE ST
CHEEKTOWAGA, NY 14225
Contact: ERNEST SCAROTTA
Contact address: GENESEE ST
CHEEKTOWAGA, NY 14225
Contact country: US
Contact telephone: (716) 631-9017
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: MELI F P CONST DIV ENGR
Owner/operator address: 3901 GENESEE ST
CHEEKTOWAGA, NY 14225
Owner/operator country: US
Owner/operator telephone: (716) 631-9017
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MELI F P CONST DIV ENGR
Owner/operator address: 3901 GENESEE ST
CHEEKTOWAGA, NY 14225
Owner/operator country: US
Owner/operator telephone: (716) 631-9017
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512269 (Continued)

1000553257

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: NYS THRUWAY AUTH - BIN 5512269
Classification: Not a generator, verified

Date form received by agency: 01/23/1992
Facility name: NYS THRUWAY AUTH - BIN 5512269
Site name: NYS THRUWAY
Classification: Large Quantity Generator

Date form received by agency: 06/05/1991
Facility name: NYS THRUWAY AUTH - BIN 5512269
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 09/28/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA Contractor/Grantee

FINDS:

Registry ID: 110008052445

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD986956720
Country: USA
Mailing Name: NEW YORK STATE THRUWAY AUTHORITY
Mailing Contact: PHILIP J. LAKSO
Mailing Address: PO BOX 103
Mailing Address 2: Not reported
Mailing City: ELMA
Mailing State: NY
Mailing Zip: 14059
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-631-9017

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512269 (Continued)

1000553257

Document ID: NYB2824632
Manifest Status: Completed copy
Trans1 State ID: 86431ZNY
Trans2 State ID: Not reported
Generator Ship Date: 910830
Trans1 Recv Date: 910830
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910830
Part A Recv Date: 910912
Part B Recv Date: 910912
Generator EPA ID: NYD986956720
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 21200
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2824641
Manifest Status: Completed copy
Trans1 State ID: 46765ANY
Trans2 State ID: Not reported
Generator Ship Date: 910903
Trans1 Recv Date: 910903
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910904
Part A Recv Date: 910912
Part B Recv Date: 910912
Generator EPA ID: NYD986956720
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 24940
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512269 (Continued)

1000553257

Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

88
NW
1/4-1/2
0.357 mi.
1886 ft.

DEPT OF INSPECTIONS & LICENSES
60 GROSVENOR ST
BUFFALO, NY 14202

RCRA-NonGen **1000156401**
FINDS **NYD980765747**

Relative:
Equal

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: DEPT OF INSPECTIONS & LICENSES
Facility address: 60 GROSVENOR ST
BUFFALO, NY 14202
EPA ID: NYD980765747
Mailing address: CITY HALL
BUFFALO, NY 14202
Contact: Not reported
Contact address: CITY HALL
BUFFALO, NY 14202
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Actual:
590 ft.

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEPT OF INSPECTIONS & LICENSES (Continued)

1000156401

Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: DEPT OF INSPECTIONS & LICENSES
Classification: Not a generator, verified

Date form received by agency: 12/11/2000
Facility name: DEPT OF INSPECTIONS & LICENSES
Classification: Not a generator, verified

Date form received by agency: 05/02/1984
Facility name: DEPT OF INSPECTIONS & LICENSES
Classification: Not a generator, verified

Date form received by agency: 01/11/1984
Facility name: DEPT OF INSPECTIONS & LICENSES
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004390560

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

U89
NE
1/4-1/2
0.359 mi.
1896 ft.
RONALD BALD
182 JAMES STREET
BUFFALO, NY
Site 2 of 2 in cluster U

NY Spills **S102176519**
NY Hist Spills **N/A**

Relative:
Higher

Actual:
591 ft.

NY Spills:
Site ID: 108992
Facility Addr2: Not reported
Facility ID: 8808189
Spill Number: 8808189
Facility Type: ER
SWIS: 1502
Investigator: MXFRANKS
Referred To: Not reported
Spill Date: 1/13/1989
Reported to Dept: 1/13/1989
CID: 30
Spill Cause: Deliberate
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Health Department
Cleanup Ceased: 1/17/1989
Cleanup Meets Std: True
Last Inspection: 1/13/1989
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Not reported
Spill Closed Dt: 1/17/1989
Remediation Phase: 0
Date Entered In Computer: 1/13/1989
Spill Record Last Update: 1/20/1989
Spiller Name: Not reported
Spiller Company: RONALD BALD
Spiller Address: 182 JAMES STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 95775
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MF" 01/13/89: MF SITE VISIT, OIL IN SEWER, GAVE SPILLER PADS TO CLEAN SAME. NOTIFIED BSA, THE WILL INSPECT. 01/17/89: MF TELECON BSA, CREW WAS SENT & THEY WERE SATISFIED WITH CLEANUP. NO FUTHER ACTION NECESSARY.
Remarks: AUTO REPAIRS BEING DONE ON THE STREET. OIL GETTING INTO SEWER.

Material:
Site ID: 108992
Operable Unit ID: 923827
Operable Unit: 01
Material ID: 452951
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: Yes

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RONALD BALD (Continued)

S102176519

Resource Affected: Sewer
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 8808189
Investigator: MF
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 01/13/1989 11:00
Reported to Dept Date/Time: 01/13/89 11:30
SWIS: 14
Spiller Name: RONALD BALD
Spiller Contact: Not reported
Spiller Phone: (716) 855-0228
Spiller Address: 182 JAMES STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spill Cause: Deliberate
Reported to Dept: In Sewer
Water Affected: Not reported
Spill Source: 09
Spill Notifier: Health Department
PBS Number: Not reported
Cleanup Ceased: 01/17/89
Cleanup Meets Std: True
Last Inspection: 01/13/89
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 01/17/89
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/13/89
Date Spill Entered In Computer Data File: Not reported
Update Date: 01/20/89
Is Updated: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RONALD BALD (Continued)

S102176519

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 2
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 1
Unkonwn Quantity Recovered: False
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927

DEC Remarks: 01/13/89: MF SITE VISIT, OIL IN SEWER, GAVE SPILLER PADS TO CLEAN SAME.
NOTIFIED BSA, THE WILL INSPECT. 01/17/89: MF TELECON BSA, CREW WAS SENT
THEY WERE SATISFIED WITH CLEANUP. NO FUTHER ACTION NECESSARY.

Remark: AUTO REPAIRS BEING DONE ON THE STREET. OIL GETTING INTO SEWER.

W90
SSE
1/4-1/2
0.360 mi.
1902 ft.

GEORGE BURNETT INC.
I190 THRUWAY RAMP N4
BUFFALO, NY

Site 1 of 3 in cluster W

NY Spills **S102176605**
NY Hist Spills **N/A**

Relative:
Higher

Actual:
600 ft.

NY Spills:
Site ID: 116977
Facility Addr2: Not reported
Facility ID: 8810112
Spill Number: 8810112
Facility Type: ER
SWIS: 1502
Investigator: ROSS
Referred To: Not reported
Spill Date: 3/30/1989
Reported to Dept: 3/30/1989
CID: Not reported
Spill Cause: Traffic Accident
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: 3/30/1989
Cleanup Meets Std: True
Last Inspection: 3/30/1989
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Not reported
Spill Closed Dt: 3/30/1989
Remediation Phase: 0
Date Entered In Computer: 3/30/1989
Spill Record Last Update: 4/4/1989
Spiller Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GEORGE BURNETT INC. (Continued)

S102176605

Spiller Company: GEORGE BURNETT INC.
Spiller Address: Not reported
Spiller City,St,Zip: BUFFALO, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 101763
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"LQR" 03/30/89: CAF ON SITE SPILLER CLEANED UP AND CEMENT MIXED AND
FIXED ROAD. 03/30/89: CAF ON SITE SPILLER CLEANED UP, REMAINING
CEMENT MIXED WITH RAIN AND FLUSHED OVER ROAD. 09/29/95: This is
additional information about material spilled from the translation of
the old spill file: PORTLAND CEMENT.
Remarks: TRUCK TIPPED OVER

Material:

Site ID: 116977
Operable Unit ID: 926340
Operable Unit: 01
Material ID: 451291
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 15000
Units: Pounds
Recovered: 15000
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 8810112
Investigator: LQR
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 03/30/1989 11:15
Reported to Dept Date/Time: 03/30/89 12:35
SWIS: 14

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GEORGE BURNETT INC. (Continued)

S102176605

Spiller Name: GEORGE BURNETT INC.
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: BUFFALO, NY
Spill Cause: Traffic Accident
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 07
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: 03/30/89
Cleanup Meets Std: True
Last Inspection: 03/30/89
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 03/30/89
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/30/89
Date Spill Entered In Computer Data File: Not reported
Update Date: 04/04/89
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 15000
Unkonwn Quantity Spilled: False
Units: Pounds
Quantity Recovered: 15000
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929

DEC Remarks: 03/30/89: CAF ON SITE SPILLER CLEANED UP AND CENMENT MIXED AND FIXED ROAD.
03/30/89: CAF ON SITE SPILLER CLEANED UP, REMAINING CEMENT MIXED WITH RAIN AND
FLUSHED OVER ROAD. 09/29/95: This is additional information about material
spilled from the translation of the old spill file: PORTLAND CEMENT.
Remark: TRUCK TIPPED OVER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W91 **TRUCK LEAK**
SSE **I190 RAMP AT SMITH STREET**
1/4-1/2 **BUFFALO, NY**
0.360 mi.
1902 ft. **Site 2 of 3 in cluster W**

NY Spills **S102177287**
NY Hist Spills **N/A**

Relative:
Higher

Actual:
600 ft.

NY Spills:

Site ID: 59979
Facility Addr2: Not reported
Facility ID: 9002853
Spill Number: 9002853
Facility Type: ER
SWIS: 1502
Investigator: FIX
Referred To: Not reported
Spill Date: 6/12/1990
Reported to Dept: 6/12/1990
CID: Not reported
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Police Department
Cleanup Ceased: 6/15/1990
Cleanup Meets Std: True
Last Inspection: 6/15/1990
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Not reported
Spill Closed Dt: 6/15/1990
Remediation Phase: 0
Date Entered In Computer: 6/13/1990
Spill Record Last Update: 7/5/1990
Spiller Name: Not reported
Spiller Company: BEAMER TRANSPORTATION CO.
Spiller Address: UNION AND MILL STREETS
Spiller City,St,Zip: MACHIAS, NY 14101
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 58618
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"CAF" 06/13/90: CAF SITE VISIT ROADWAY CLEAR,OIL/WATER MIX 5 GAL
DRAWN FROM BASIN WITH HAND PUMP. 06/15/90: CAF SITE VISIT CLEANUP
COMPLETED,NO FURTHER ACTION PLANNED. BASIN WITH HAND PUMP.
DUMP TRUCK LEAKED HYDRAULIC OIL TO JUNCTION OF I190 AND SMITH STREET

Remarks:

Material:

Site ID: 59979
Operable Unit ID: 942978
Operable Unit: 01
Material ID: 437582
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Soil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRUCK LEAK (Continued)

S102177287

Oxygenate: False
Site ID: 59979
Operable Unit ID: 942978
Operable Unit: 01
Material ID: 437583
Material Code: 0016A
Material Name: NON PCB OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 15
Units: Gallons
Recovered: 15
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9002853
Investigator: CAF
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 06/12/1990 15:50
Reported to Dept Date/Time: 06/12/90 16:23
SWIS: 14
Spiller Name: BEAMER TRANSPORTATION CO.
Spiller Contact: Not reported
Spiller Phone: (716) 353-8522
Spiller Address: UNION AND MILL STREETS
Spiller City,St,Zip: MACHIAS, NY 14101
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 07
Spill Notifier: Police Department
PBS Number: Not reported
Cleanup Ceased: 06/15/90
Cleanup Meets Std: True
Last Inspection: 06/15/90
Recommended Penalty: Penalty Not Recommended

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRUCK LEAK (Continued)

S102177287

Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 06/15/90
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/13/90
Date Spill Entered In Computer Data File: Not reported
Update Date: 07/05/90
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 15
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 15
Unkonwn Quantity Recovered: False
Material: NON PCB OIL
Class Type: NON PCB OIL
Times Material Entry In File: 2798
CAS Number: Not reported
Last Date: 19940928
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: HYDRAULIC OIL
Class Type: HYDRAULIC OIL
Times Material Entry In File: 1846
CAS Number: Not reported
Last Date: 19940728

DEC Remarks: 06/13/90: CAF SITE VISIT ROADWAY CLEAR,OIL/WATER MIX 5 GAL DRAWN FROM BASIN
WITH HAND PUMP. 06/15/90: CAF SITE VISIT CLEANUP COMPLETED,NO FURTHER ACTION
PLANNED. BASIN WITH HAND PUMP.
Remark: DUMP TRUCK LEAKED HYDRAULIC OIL TO JUNCTION OF I190 AND SMITH STREET

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

92 BUDDY'S TOWING
NNE 822 CLINTON STREET
1/4-1/2 BUFFALO, NY
0.363 mi.
1916 ft.

NY Spills S102178451
NY Hist Spills N/A

Relative:
Higher

Actual:
595 ft.

NY Spills:
Site ID: 278997
Facility Addr2: Not reported
Facility ID: 9315317
Spill Number: 9315317
Facility Type: ER
SWIS: 1502
Investigator: FXGALLEG
Referred To: Not reported
Spill Date: 3/25/1994
Reported to Dept: 3/25/1994
CID: 30
Spill Cause: Housekeeping
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Citizen
Cleanup Ceased: 5/15/1995
Cleanup Meets Std: True
Last Inspection: 5/9/1995
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 5/15/1995
Remediation Phase: 0
Date Entered In Computer: 3/30/1994
Spill Record Last Update: 10/8/1999
Spiller Name: Not reported
Spiller Company: BUDDY'S TOWING
Spiller Address: 822 CLINTON STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 226537
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"FG" 03/30/94: 3/30/94 MNP INSP. WASTE OIL SPILLAGE ON VACANT LOT.
ESTIMATE OVER 100 GALS. OIL SPILLED. OIL PUDDLED ALONG ALLEY FENCE.
NO ONE AT BUDDY'S, SEE SKETCH & PICTURES. 04/01/94: 4/1/94 MNP
TELECON TO BUDDY'S TOWING. SPOKE W/ BOB DITTMAN, OWNER ED LAWLER ON
VACATION IN FLORIDA UNTIL 4/13/94. ADVISED ABOUT NEED CLEANUP.
SENDING LETTER. 04/18/94: 4/18/94 MNP INSP. & MEETING W/ ED LAWLER -
BUDDY'S TOWING. SHOWED HIM SPILLAGE NEEDING CLEANUP. HE ALREADY
CONTACTED BRIAN HANAKA - WASTE MAN. TO GET PRICE ON ROLLOFF &
DISPOSAL. WILL DO WORK ASAP. 06/22/94: 6/22/94 MNP INSP. SPOKE W/ ED
LAWLER - BUDDY'S TOWING. CLEANUP STARTED. OIL STAINED AREAS REMAIN,
SHOWED HIM AREAS NEEDING MORE CLEANUP. WE DISCUSSED SAMPLING &
LANDFILL REQUIREMENTS. 08/04/94: 8/4/94 MNP INSP. SPOKE W/ ED LAWLER
- BUDDY'S TOWING. OIL STAINS, MORE CLEANUP NEEDED. HE AGREED TO CALL
FOR ANOTHER INSP. I LOOKED AT SAMPLE RESULTS, NON-HAZ SOIL OK TO
DISPOSE. 09/19/94: 9/19/94 MNP INSP. SPOKE W/ ED LAWLER - BUDDY'S
TOWING. CLEANUP SATISFACTORY, CONTAM. SOIL ON PLASTIC, NOT COVERED.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUDDY'S TOWING (Continued)

S102178451

Remarks: LAWLER WILL COVER PILE, TO DISPOSE SOIL AT CID & SEND DISPOSAL RECEIPTS. 03/31/95: LTR SENT REQUESTING SAMPLE RESULTS & DISPOSAL RECPT. RESPONSE DUE 4/17/95. 05/09/95: SITE VISIT 5/9/95. MR LAWLER GAVE ME ANALYTICAL RESULTS & APPROVAL FORM FOR DISPOSAL AT CID. CONTAM SOIL REMOVED FROM SITE. WASTE OIL REMOVED FROM SITE. 05/15/95: SOIL DISPOSAL RECPT REC'D FROM CID. SITE CAN BE CLOSED. 55-GAL. WASTE OIL DRUMS SPILLED ON VACANT LOT.

Material:

Site ID: 278997
Operable Unit ID: 993492
Operable Unit: 01
Material ID: 387078
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9315317
Investigator: FG
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 03/25/1994 12:00
Reported to Dept Date/Time: 03/25/94 12:15
SWIS: 14
Spiller Name: BUDDY'S TOWING
Spiller Contact: Not reported
Spiller Phone: (716) 856-6923
Spiller Address: 822 CLINTON STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spill Cause: Housekeeping
Reported to Dept: On Land
Water Affected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUDDY'S TOWING (Continued)

S102178451

Spill Source: 01
Spill Notifier: Citizen
PBS Number: Not reported
Cleanup Ceased: 05/15/95
Cleanup Meets Std: True
Last Inspection: 05/09/95
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/15/95
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/30/94
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/08/99
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Pounds
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927

DEC Remarks: 03/30/94: 3/30/94 MNP INSP. WASTE OIL SPILLAGE ON VACANT LOT. ESTIMATE OVER 100 GALS. OIL SPILLED. OIL PUDDLED ALONG ALLEY FENCE. NO ONE AT BUDDY S, SEE SKETCH PICTURES. 04/01/94: 4/1/94 MNP TELECON TO BUDDY S TOWING. SPOKE W/ BOB DITTMAN, OWNER ED LAWLER ON VACATION IN FLORIDA UNTIL 4/13/94. ADVISED ABOUT NEED CLEANUP. SENDING LETTER. 04/18/94: 4/18/94 MNP INSP. MEETING W/ ED LAWLER - BUDDY S TOWING. SHOWED HIM SPILLAGE NEEDING CLEANUP. HE ALREADY CONTACTED BRIAN HANAKA - WASTE MAN. TO GET PRICE ON ROLLOFF DISPOSAL. WILL DO WORK ASAP. 06/22/94: 6/22/94 MNP INSP. SPOKE W/ ED LAWLER - BUDDY S TOWING. CLEANUP STARTED. OIL STAINED AREAS REMAIN, SHOWED HIM AREAS NEEDING MORE CLEANUP. WE DISCUSSED SAMPLING LANDFILL REQUIREMENTS. 08/04/94: 8/4/94 MNP INSP. SPOKE W/ ED LAWLER - BUDDY S TOWING. OIL STAINS, MORE CLEANUP NEEDED. HE AGREED TO CALL FOR ANOTHER INSP. I LOOKED AT SAMPLE RESULTS, NON-HAZ SOIL OK TO DISPOSE. 09/19/94: 9/19/94 MNP INSP. SPOKE W/ ED LAWLER - BUDDY S TOWING. CLEANUP SATISFACTORY, CONTAM. SOIL ON PLASTIC, NOT COVERED. LAWLER WILL COVER PILE, TO DISPOSE SOIL AT CID SEND DISPOSAL RECEIPTS. 03/31/95: LTR SENT REQUESTING SAMPLE RESULTS DISPOSAL RECPT. RESPONSE DUE 4/17/95. 05/09/95: SITE VISIT 5/9/95. MR LAWLER GAVE ME ANALYTICAL RESULTS APPROVAL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUDDY'S TOWING (Continued)

S102178451

FORM FOR DISPOSAL AT CID. CONTAM SOIL REMOVED FROM SITE. WASTE OIL REMOVED FROM SITE. 05/15/95: SOIL DISPOSAL RECPT RECD FROM CID. SITE CAN BE CLOSED.
Remark: 55-GAL. WASTE OIL DRUMS SPILLED ON VACANT LOT.

W93
SSE
1/4-1/2
0.366 mi.
1931 ft.

NYS THRUWAY AUTH - BIN 5512249
SMITH ST & PERRY ST
BUFFALO, NY 14210

RCRA-NonGen **1000553259**
FINDS **NYD986956746**
MANIFEST

Site 3 of 3 in cluster W

Relative:
Higher

RCRA-NonGen:

Actual:
598 ft.

Date form received by agency: 01/01/2007
Facility name: NYS THRUWAY AUTH - BIN 5512249
Facility address: SMITH ST & PERRY ST
BUFFALO, NY 14210
EPA ID: NYD986956746
Mailing address: GENESEE ST
CHEEKTOWAGA, NY 14225
Contact: ERNEST SCAROZZA
Contact address: GENESEE ST
CHEEKTOWAGA, NY 14225
Contact country: US
Contact telephone: (716) 631-9017
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: MELI F P CONST DIV ENGR
Owner/operator address: 3901 GENESEE ST
CHEEKTOWAGA, NY 14225
Owner/operator country: US
Owner/operator telephone: (716) 631-9017
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MELI F P CONST DIV ENGR
Owner/operator address: 3901 GENESEE ST
CHEEKTOWAGA, NY 14225
Owner/operator country: US
Owner/operator telephone: (716) 631-9017
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512249 (Continued)

1000553259

Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: NYS THRUWAY AUTH - BIN 5512249
Classification: Not a generator, verified

Date form received by agency: 01/23/1992
Facility name: NYS THRUWAY AUTH - BIN 5512249
Site name: NYS THRUWAY
Classification: Large Quantity Generator

Date form received by agency: 06/05/1991
Facility name: NYS THRUWAY AUTH - BIN 5512249
Classification: Not a generator, verified

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 07/30/1993
Date achieved compliance: 06/17/1995
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/18/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 04/30/1993
Date achieved compliance: 03/18/1995
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/24/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512249 (Continued)

1000553259

Evaluation Action Summary:

Evaluation date: 09/28/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 03/18/1995
Evaluation lead agency: EPA Contractor/Grantee

Evaluation date: 09/28/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 06/17/1995
Evaluation lead agency: EPA Contractor/Grantee

FINDS:

Registry ID: 110008052463

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD986956746
Country: USA
Mailing Name: NEW YORK STATE THRUWAY AUTHORITY
Mailing Contact: SHIRLEY E. PORTER
Mailing Address: 3901 GENESEE STREET
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14225
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-631-9817

Document ID: NYB2425050
Manifest Status: Completed copy
Trans1 State ID: NY81187V
Trans2 State ID: Not reported
Generator Ship Date: 911011
Trans1 Recv Date: 911011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911011
Part A Recv Date: 911028
Part B Recv Date: 911104
Generator EPA ID: NYD986956746
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 22960

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512249 (Continued)

1000553259

Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2425068
Manifest Status: Completed copy
Trans1 State ID: 85863DNY
Trans2 State ID: Not reported
Generator Ship Date: 911011
Trans1 Recv Date: 911011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911011
Part A Recv Date: 911028
Part B Recv Date: 911104
Generator EPA ID: NYD986956746
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 18400
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2425671

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512249 (Continued)

1000553259

Manifest Status: Completed copy
Trans1 State ID: 86428ZNY
Trans2 State ID: Not reported
Generator Ship Date: 911101
Trans1 Recv Date: 911101
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911105
Part A Recv Date: Not reported
Part B Recv Date: 911113
Generator EPA ID: NYD986956746
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 43020
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2425293
Manifest Status: Completed copy
Trans1 State ID: 86431ZNY
Trans2 State ID: Not reported
Generator Ship Date: 911018
Trans1 Recv Date: 911018
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911021
Part A Recv Date: Not reported
Part B Recv Date: 911106
Generator EPA ID: NYD986956746
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 26360
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512249 (Continued)

1000553259

Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2425284
Manifest Status: Completed copy
Trans1 State ID: 14971VNY
Trans2 State ID: Not reported
Generator Ship Date: 911018
Trans1 Recv Date: 911018
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911018
Part A Recv Date: Not reported
Part B Recv Date: 911106
Generator EPA ID: NYD986956746
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 28580
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4405185
Manifest Status: Completed copy
Trans1 State ID: 86431ZNY
Trans2 State ID: Not reported
Generator Ship Date: 911107
Trans1 Recv Date: 911107
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS THRUWAY AUTH - BIN 5512249 (Continued)

1000553259

TSD Site Recv Date: 911111
Part A Recv Date: Not reported
Part B Recv Date: 911118
Generator EPA ID: NYD986956746
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 24800
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

X94
North
1/4-1/2
0.368 mi.
1945 ft.
AUSTIN RESIDENCE
712 CLINTON STREET
BUFFALO, NY
Site 1 of 2 in cluster X

NY Spills **S102174629**
NY Hist Spills **N/A**

Relative:
Equal

Actual:
590 ft.

NY Spills:
Site ID: 171178
Facility Addr2: Not reported
Facility ID: 9304396
Spill Number: 9304396
Facility Type: ER
SWIS: 1502
Investigator: PRINGLE
Referred To: Not reported
Spill Date: 6/30/1993
Reported to Dept: 7/1/1993
CID: 30
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Citizen
Cleanup Ceased: 8/4/1993
Cleanup Meets Std: True
Last Inspection: 8/4/1993
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AUSTIN RESIDENCE (Continued)

S102174629

Spill Closed Dt: 8/4/1993
Remediation Phase: 0
Date Entered In Computer: 7/12/1993
Spill Record Last Update: 11/4/1993
Spiller Name: Not reported
Spiller Company: SUSPECT AMHERST PLUMBING
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 144049
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MNP" 08/04/93: 8/4/93 MNP INSP. NO PETRO. OR SHEEN OBSERVED IN YARD.
STAIN NOTED IN STREET. SPOKE W/ COMPLANANT, NO ACTION NECESSARY,
COMPLETE.

Remarks: GASOLINE DUMPED ON ADJACENT PROPERTY. OIL DUMPED IN BACKYARD

Material:

Site ID: 171178
Operable Unit ID: 982810
Operable Unit: 01
Material ID: 397901
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9304396
Investigator: MNP
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AUSTIN RESIDENCE (Continued)

S102174629

Spill Date/Time: 06/30/1993 12:00
Reported to Dept Date/Time: 07/01/93 16:10
SWIS: 14
Spiller Name: SUSPECT AMHERST PLUMBING
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Citizen
PBS Number: Not reported
Cleanup Ceased: 08/04/93
Cleanup Meets Std: True
Last Inspection: 08/04/93
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Spill Closed Dt: 08/04/93
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/12/93
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/04/93
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 08/04/93: 8/4/93 MNP INSP. NO PETRO. OR SHEEN OBSERVED IN YARD. STAIN NOTED IN STREET. SPOKE W/ COMPLANANT, NO ACTION NECESSARY, COMPLETE.
Remark: GASOLINE DUMPED ON ADJACENT PROPERTY. OIL DUMPED IN BACKYARD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

V95 TYSON DELI
SW 665 PERRY STREET
1/4-1/2 BUFFALO, NY 14210
0.371 mi.
1960 ft. Site 2 of 5 in cluster V

AST 1001422463
HIST AST N/A

Relative:
Higher

Actual:
594 ft.

AST:

Region: STATE
DEC Region: 9
Site Status: Waste Oil Storer
Facility Id: 9-600394
Program Type: PBS
UTM X: 185295.53080000001
UTM Y: 4753769.0801499998
Expiration Date: 2013/06/08

Tank Number: 001
Tank Id: 173152
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Tank Model: 201
Pipe Model: Not reported
Install Date: 5/1/1998
Capacity Gallons: 300
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Trade Sec: False
Modified By: LDGOMEZ
Last Modified: 9/20/2007

Tank Number: 002
Tank Id: 219500
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 8/27/2007
Capacity Gallons: 525
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Trade Sec: False
Modified By: LDGOMEZ
Last Modified: 9/20/2007

UST_PBS_BSAFFIL:

Site Id: 55242
Program Number: 9-600394
Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TYSON DELI (Continued)

1001422463

Company Name: TYSON DELI
Contact Type: Not reported
Contact Name: ROBERT KELLER
Address1: 665 PERRY STREET
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14210
Country Code: 001
Phone: (716) 826-6400
Phone Ext: Not reported
Email: ROBERT.KELLER@TYSON.COM
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 3/8/2006

Site Id: 55242
Program Number: 9-600394
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: TYSON FOODS - DELI DIVISION - RUSSE
Contact Type: Not reported
Contact Name: ROBERT KELLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (716) 826-6400
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 3/8/2006

Site Id: 55242
Program Number: 9-600394
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: E
Company Name: TYSON FOODS - DELI DIVISION - RUSSE
Contact Type: UTILITIES SUPERVISOR
Contact Name: ROBERT KELLER
Address1: 665 PERRY STREET
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14210
Country Code: 001
Phone: (716) 826-6400
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 3/8/2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TYSON DELI (Continued)

1001422463

Site Id: 55242
Program Number: 9-600394
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: TYSON DELI
Contact Type: Not reported
Contact Name: ROBERT KELLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 826-6400
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 3/8/2006

UST_AST_PBS_BSEQUIP:

Site Id: 55242
Tank Id Number: 219500
Tank Number: 002
Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Site Id: 55242
Tank Id Number: 173152
Tank Number: 001
Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Site Id: 55242
Tank Id Number: 219500
Tank Number: 002
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 55242
Tank Id Number: 173152
Tank Number: 001
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 55242
Tank Id Number: 173152
Tank Number: 001
Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TYSON DELI (Continued)

1001422463

Site Id:	55242
Tank Id Number:	219500
Tank Number:	002
Equipment:	I01
Code Name:	Float Vent Valve
Type:	Overfill
Site Id:	55242
Tank Id Number:	173152
Tank Number:	001
Equipment:	J02
Code Name:	Suction
Type:	Dispenser
Site Id:	55242
Tank Id Number:	219500
Tank Number:	002
Equipment:	J02
Code Name:	Suction
Type:	Dispenser
Site Id:	55242
Tank Id Number:	219500
Tank Number:	002
Equipment:	L00
Code Name:	None
Type:	Piping Leak Detection
Site Id:	55242
Tank Id Number:	173152
Tank Number:	001
Equipment:	L00
Code Name:	None
Type:	Piping Leak Detection
Site Id:	55242
Tank Id Number:	219500
Tank Number:	002
Equipment:	K01
Code Name:	Catch Basin
Type:	Spill Prevention
Site Id:	55242
Tank Id Number:	173152
Tank Number:	001
Equipment:	K01
Code Name:	Catch Basin
Type:	Spill Prevention
Site Id:	55242
Tank Id Number:	219500
Tank Number:	002
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Site Id:	55242

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TYSON DELI (Continued)

1001422463

Tank Id Number: 173152
Tank Number: 001
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 55242
Tank Id Number: 173152
Tank Number: 001
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 55242
Tank Id Number: 219500
Tank Number: 002
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 55242
Tank Id Number: 173152
Tank Number: 001
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55242
Tank Id Number: 219500
Tank Number: 002
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 55242
Tank Id Number: 219500
Tank Number: 002
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55242
Tank Id Number: 173152
Tank Number: 001
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 55242
Tank Id Number: 173152
Tank Number: 001
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 55242
Tank Id Number: 219500

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TYSON DELI (Continued)

1001422463

Tank Number: 002
Equipment: F00
Code Name: None
Type: Pipe External Protection

HIST AST:

PBS Number: 9-600394
SWIS Code: 1402
Operator: CLIFF LINK
Facility Phone: (716) 826-6400
Facility Addr2: Not reported
Facility Type: OTHER
Emergency: MIKE WOLF
Emergency Tel: (716) 826-6400
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: RUSSEY FOODS
Owner Address: 665 PERRY STREET
Owner City,St,Zip: BUFFALO, NY 14210
Federal ID: Not reported
Owner Tel: (716) 826-6400
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: VIREN SITWALA
Mailing Name: RUSSEY FOODS
Mailing Address: 665 PERRY STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: BUFFALO, NY 14210
Mailing Telephone: (716) 826-6400
Owner Mark: First Owner
Facility Status: 4 - Subpart 360-14 only (active)
Certification Flag: False
Certification Date: 06/08/1998
Expiration: 06/08/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 300
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: BUFFALO (C)
County Code: 14
Town or City Code: 02
Region: 9

Tank ID: 001
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19980501
Capacity (Gal): 300
Product Stored: USED OIL
Tank Type: Steel/carbon steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TYSON DELI (Continued)

1001422463

Tank Internal: 0
Tank External: 01
Pipe Location: Aboveground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 00
Tank Containment: Diking
Leak Detection: 00
Overfill Protection: 15
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

V96
SW
1/4-1/2
0.371 mi.
1960 ft.

INSIDE BUILDING
665 PERRY ST
BUFFALO, NY

NY Spills S107416365
N/A

Relative:
Higher

Actual:
594 ft.

Site 3 of 5 in cluster V
NY Spills:
Site ID: 354600
Facility Addr2: Not reported
Facility ID: 0508908
Spill Number: 0508908
Facility Type: ER
SWIS: 1502
Investigator: JFOTTO
Referred To: Not reported
Spill Date: 10/25/2005
Reported to Dept: 10/25/2005
CID: 30
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. No DEC Response. No corrective action required.
Spill Closed Dt: 10/26/2005
Remediation Phase: 0
Date Entered In Computer: 10/25/2005
Spill Record Last Update: 10/26/2005
Spiller Name: RICHARD HUGHES
Spiller Company: TYSON FOODS
Spiller Address: 665 PERRY ST
Spiller City,St,Zip: BUFFALO, NY
Spiller Company: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

INSIDE BUILDING (Continued)

S107416365

Contact Name: RICHARD HUGHES
Contact Phone: (716) 912-6045
DEC Region: 9
DER Facility ID: 304619
DEC Memo: 10/26/05 REFERRED TO THE DIV OF AIR FOR FOLLOWUP. NO ACTION NECESSARY
BY SPILLS. CLOSED THERE IS NO PAPER FILE FOR THIS SPILL
Remarks: AMMONIA RELEASE - CALLED NATIONAL RESPONSE - BELIEVED TO BE LESS THAN
100 LBS. - CONTROLLED IN LESS THAN ONE MINUTE

Material:

Site ID: 354600
Operable Unit ID: 1111997
Operable Unit: 01
Material ID: 2102042
Material Code: 0025A
Material Name: AMMONIA
Case No.: 07664417
Material FA: Hazardous Material
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Air
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

V97
SW
1/4-1/2
0.371 mi.
1960 ft. **RUSSEY FOODS**
665 PERRY STREET
BUFFALO, NY 14210
Site 4 of 5 in cluster V

RCRA-SQG 1004571762
FINDS NYD986971158
MANIFEST
MANIFEST

Relative:
Higher

RCRA-SQG:

Actual:
594 ft.

Date form received by agency: 07/26/2007
Facility name: TYSON FOOD INC
Facility address: 665 PERRY ST
BUFFALO, NY 14210
EPA ID: NYD986971158
Mailing address: PERRY ST
BUFFALO, NY 14210
Contact: LOUIS SOLOMON
Contact address: PERRY ST
BUFFALO, NY 14210
Contact country: US
Contact telephone: (716) 826-6400
Contact email: Not reported
EPA Region: 02

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSEY FOODS (Continued)

1004571762

Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 07/25/2007
Facility name: TYSON FOOD INC
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Facility name: TYSON FOOD INC
Site name: RUSSEY FOODS
Classification: Small Quantity Generator

Date form received by agency: 05/07/1992
Facility name: TYSON FOOD INC
Site name: RUSSEY FOODS
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 07/17/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/07/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Evaluation date: 05/22/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110000566361

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AFS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

US EPA Risk Management Plan (RMP) database stores the risk management plans reported by companies that handle, manufacture, use, or store certain flammable or toxic substances, as required under section 112(r) of the Clean Air Act (CAA).

NJ MANIFEST:

Manifest Code: NJA3155578
EPA ID: NYD986971158
Date Shipped: 20040616
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040616
Date Trans2 Transported Waste: 040712
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040712
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 08310422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3155635
EPA ID: NYD986971158
Date Shipped: 20040929
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: MOD095038998
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040929
Date Trans2 Transported Waste: 041013
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 041013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 12170421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3155621
EPA ID: NYD986971158
Date Shipped: 20040824
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040824
Date Trans2 Transported Waste: 040901
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040901
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 10260422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3155556
EPA ID: NYD986971158
Date Shipped: 20040223
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSEY FOODS (Continued)

1004571762

Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040223
Date Trans2 Transported Waste: 040303
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040303
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 03310421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA4015949
EPA ID: NYD986971158
Date Shipped: 20041230
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 041230
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 050118

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 02160595
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3155561
EPA ID: NYD986971158
Date Shipped: 20040319
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: MOR000505347
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040319
Date Trans2 Transported Waste: 040330
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040331
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 04290422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3155562
EPA ID: NYD986971158
Date Shipped: 20040416
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040416
Date Trans2 Transported Waste: 040427
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040427
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 05120421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA4015908
EPA ID: NYD986971158
Date Shipped: 20041105
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: MOD095038998
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 041105
Date Trans2 Transported Waste: 041129
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 041129

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 01050521
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA4015931
EPA ID: NYD986971158
Date Shipped: 20041207
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: NYD980769947
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 041207
Date Trans2 Transported Waste: 041213
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 041222
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 02230595
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3155616
EPA ID: NYD986971158
Date Shipped: 20040713
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Transporter 2 EPA ID: MOR000505347
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040713
Date Trans2 Transported Waste: 040716
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040728
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 08310422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA4014102
EPA ID: NYD986971158
Date Shipped: 20050418
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 050418
Date Trans2 Transported Waste: 050429
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 050429

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 06090525
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA4015972
EPA ID: NYD986971158
Date Shipped: 20050325
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 050325
Date Trans2 Transported Waste: 050412
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 050412
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 05270521
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA4015970
EPA ID: NYD986971158
Date Shipped: 20050201
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 050201
Date Trans2 Transported Waste: 050201
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 050209
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04150521
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA4015971
EPA ID: NYD986971158
Date Shipped: 20050301
TSDF EPA ID: NJR000022442
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: NJD071629976
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 050301
Date Trans2 Transported Waste: 050309
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 050309

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 04220522
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

NY MANIFEST:

EPA ID: NYD986971158
Country: USA
Mailing Name: RUSSER FOOD PRODUCTS
Mailing Contact: LOU
Mailing Address: 665 PERRY ST
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14210
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-826-6400

Document ID: NYC7074854
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 07/10/2003
Trans1 Recv Date: 07/10/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/10/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: NYD981556541
Trans2 EPA ID: Not reported
TSDF ID: NY37056AR
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC7017928
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 03/13/2003
Trans1 Recv Date: 03/13/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/14/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: NYD981556541
Trans2 EPA ID: Not reported
TSDF ID: NY92865AT
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC6992190
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 05/27/2003
Trans1 Recv Date: 05/27/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/27/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: NYD981556541
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

TSD ID: NY92865AT
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC7109166
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 08/29/2003
Trans1 Recv Date: 08/29/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/29/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: NYD981556541
Trans2 EPA ID: Not reported
TSD ID: NY10386JE
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Document ID: NYC7053006
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 10/16/2003
Trans1 Recv Date: 10/16/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/16/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: NYD981556541
Trans2 EPA ID: Not reported
TSDF ID: NY11382JS
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 4/19/2007
Trans1 Recv Date: 4/19/2007
Trans2 Recv Date: 5/2/2007
TSD Site Recv Date: 5/3/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 425
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSEY FOODS (Continued)

1004571762

Year: 07
Manifest Tracking Num: 000023336SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 8/30/2007
Trans1 Recv Date: 8/30/2007
Trans2 Recv Date: 9/12/2007
TSD Site Recv Date: 9/13/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 2
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000256140SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 4/19/2007
Trans1 Recv Date: 4/19/2007

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Trans2 Recv Date: 5/2/2007
TSD Site Recv Date: 5/3/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 205
Units: P - Pounds
Number of Containers: 3
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000256486SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 11/16/2007
Trans1 Recv Date: 11/16/2007
Trans2 Recv Date: 11/30/2007
TSD Site Recv Date: 12/1/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 2
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000541940SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD097644801
Trans2 State ID: Not reported
Generator Ship Date: 4/19/2007
Trans1 Recv Date: 4/19/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 4/24/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: OHD066060609
Waste Code: Not reported
Quantity: 5
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 002249991JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD097644801
Trans2 State ID: Not reported
Generator Ship Date: 4/19/2007
Trans1 Recv Date: 4/19/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 4/24/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Trans2 EPA ID: Not reported
TSDF ID: OHD066060609
Waste Code: Not reported
Quantity: 45
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 002249991JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD097644801
Trans2 State ID: Not reported
Generator Ship Date: 4/19/2007
Trans1 Recv Date: 4/19/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 4/24/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: OHD066060609
Waste Code: Not reported
Quantity: 75
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 002249991JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD097644801
Trans2 State ID: Not reported
Generator Ship Date: 4/19/2007
Trans1 Recv Date: 4/19/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 4/24/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: OHD066060609
Waste Code: Not reported
Quantity: 2
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 002249991JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: NJA1788864
Manifest Status: Completed copy
Trans1 State ID: NYRW9920
Trans2 State ID: NJDEPE086
Generator Ship Date: 940425
Trans1 Recv Date: 940425
Trans2 Recv Date: 940429
TSD Site Recv Date: 940429
Part A Recv Date: Not reported
Part B Recv Date: 940512
Generator EPA ID: NYD986971158
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ILD984908202
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00050
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA1788908
Manifest Status: Completed copy
Trans1 State ID: NYGR1992
Trans2 State ID: NJDEPE086
Generator Ship Date: 940608
Trans1 Recv Date: 940608
Trans2 Recv Date: 940613
TSD Site Recv Date: 940613
Part A Recv Date: 940615
Part B Recv Date: 940624
Generator EPA ID: NYD986971158
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ILD984908202
TSD ID: NJD002182897
Waste Code: F003 - UNKNOWN
Quantity: 02038
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA1788913
Manifest Status: Completed copy
Trans1 State ID: NYGR1992

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Trans2 State ID: NJDEPO869
Generator Ship Date: 940520
Trans1 Recv Date: 940520
Trans2 Recv Date: 940526
TSD Site Recv Date: 940527
Part A Recv Date: 940601
Part B Recv Date: 940610
Generator EPA ID: NYD986971158
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F003 - UNKNOWN
Quantity: 02185
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2009-01-27
Trans1 Recv Date: 2009-01-27
Trans2 Recv Date: 2009-02-04
TSD Site Recv Date: 2009-02-06
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 75.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000542098SKS
Import Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2009-07-15
Trans1 Recv Date: 2009-07-15
Trans2 Recv Date: 2009-07-24
TSD Site Recv Date: 2009-07-29
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986971158
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 80.0
Units: P - Pounds
Number of Containers: 4.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 001985005SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2009-01-27
Trans1 Recv Date: 2009-01-27
Trans2 Recv Date: 2009-02-05
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Part B Recv Date:	Not reported
Generator EPA ID:	NYD986971158
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID:	ILD980613913
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000542097SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	OKD981588791
Generator Ship Date:	2009-02-26
Trans1 Recv Date:	2009-02-26
Trans2 Recv Date:	2009-03-05
TSD Site Recv Date:	2009-03-08
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986971158
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID:	KYD053348108
Waste Code:	Not reported
Quantity:	25.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000542221SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1004571762

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

[Click this hyperlink](#) while viewing on your computer to access
122 additional NY_MANIFEST: record(s) in the EDR Site Report.

V98
SW
1/4-1/2
0.371 mi.
1960 ft.

**RUSSER FOODS
665 PERRY STREET
BUFFALO, NY**

**NY Spills 1001756455
NY Hist Spills N/A**

Site 5 of 5 in cluster V

**Relative:
Higher**

**Actual:
594 ft.**

NY Spills:
Site ID: 352203
Facility Addr2: Not reported
Facility ID: 0550937
Spill Number: 0550937
Facility Type: ER
SWIS: 1502
Investigator: RMCROSSE
Referred To: Not reported
Spill Date: 9/2/2005
Reported to Dept: 9/7/2005
CID: 30
Spill Cause: Human Error
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Possible release with minimal potential for fire or hazard or Known
release with no damage. DEC Response. Willing Responsible Party.
Corrective action taken.
Spill Closed Dt: 9/9/2005
Remediation Phase: 0
Date Entered In Computer: 9/7/2005
Spill Record Last Update: 9/9/2005
Spiller Name: Not reported
Spiller Company: RE LEWIS
Spiller Address: Not reported
Spiller City,St,Zip: IA
Spiller Company: 999
Contact Name: RICH HUGUGS
Contact Phone: (716) 566-3189
DEC Region: 9
DER Facility ID: 244067
DEC Memo: 09/07/05 RMC/FILE. DOA NOTIFIED, REPORT DUE 9/30/05. 09/09/05
RMC/FILE. RECEIVED REPORT, NO FURTHER ACTION NECESSARY. CLOSE OUT.
Remarks: CONTRACTOR CUT 1/2 INCH LIQUID LINE, AMMONIA LOSS 741 POUNDS, FIRE
DEPT USED WATER, NO ONE HURT. REPORTED TO NRC WITH IN 2 HOURS.
UNKNOWN AS TO WHY A SPILL NUMBER WAS NOT GENERATED, HE WILL SEND A
COPY OF THE NRC REPORT WITH THE INCIDENT REPORT.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1001756455

Material:

Site ID: 352203
Operable Unit ID: 1109713
Operable Unit: 01
Material ID: 2099732
Material Code: 0025A
Material Name: AMMONIA
Case No.: 07664417
Material FA: Hazardous Material
Quantity: 741
Units: Pounds
Recovered: No
Resource Affected: Air, Sewer
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 343818
Facility Addr2: Not reported
Facility ID: 0500760
Spill Number: 0500760
Facility Type: ER
SWIS: 1500
Investigator: JFOTTO
Referred To: Not reported
Spill Date: 4/18/2005
Reported to Dept: 4/18/2005
CID: 30
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 4/19/2005
Remediation Phase: 0
Date Entered In Computer: 4/18/2005
Spill Record Last Update: 4/21/2005
Spiller Name: RICHARD HUGHES
Spiller Company: TYSON FOODS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1001756455

Spiller Address: 665 PERRY ST
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller Company: 001
Contact Name: RICHARD HUGHES
Contact Phone: (716) 566-3189
DEC Region: 9
DER Facility ID: 290419
DEC Memo: 04/19/05 JFO REFERRED THIS SPILL TO THE DIV OF AIR. NRC WAS NOTIFIED
(INCIDENT # 756150). NO ACTION NECESSARY BY SPILLS. 04/21/05 RMC/RICH
HUGHES/PHONE. UPDATE ON AMOUNT RELEASED, .4 POUNDS BY CALCULATION.
CLOSED
Remarks: re Fridgeration system shut down. Contractor is going to take care of
it in the morning. NRC has been contacted

Material:
Site ID: 343818
Operable Unit ID: 1102497
Operable Unit: 01
Material ID: 582715
Material Code: 0025A
Material Name: AMMONIA
Case No.: 07664417
Material FA: Hazardous Material
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Air
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

[Click this hyperlink](#) while viewing on your computer to access
additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:
Region of Spill: 9
Spill Number: 9814031
Investigator: JDC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 02/19/1999 16:15
Reported to Dept Date/Time: 02/19/99 17:13

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSER FOODS (Continued)

1001756455

SWIS: 14
Spiller Name: SAFETY KLEEN CORP
Spiller Contact: TOM FARNSWORTH
Spiller Phone: (716) 826-8931
Spiller Phone: () -
Spiller Address: 41 NORTH GATES AVENUE
Spiller City,St,Zip: LACKAWANNA, NY 14218-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 07
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: 02/23/99
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 02/24/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 02/19/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 03/01/99
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 10
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 10
Unkonwn Quantity Recovered: False
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927

DEC Remarks: 02/23/99: JDC ON SITE AND FOUND NO EVIDENCE OF A SPILL. PERRY STREET AND AT THE LOADING DOCKS WERE FREE OF ANY SPILLAGE. CONTACTED TOM FARNSWORTH AT SAFETY CLEAN AND LEARNED THAT SPILL HAD BEEN CLEANED UP, DEBRIS DRUMMED AND REMOVED TO THEIR FACILITY AT 41 NORTH GATES FOR DISPOSAL. REQUESTED HE SEND AN INCIDENT REPORT FOR OUR REVIEW. 02/24/99: JDC REVIEWED INCIDENT REPORT AND FOUND SATISFACTORY. NO FURTHER ACTION WILL BE REQUIRED. INCIDENT DID OCCUR AT THE LOADING DOCKS.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RUSSEY FOODS (Continued)

1001756455

Remark: mechanical failure of the pump on their truck - pig absorbant safety kleen
corn cob for clean up

X99
North
1/4-1/2
0.376 mi.
1984 ft.

TRUCO ENGINE
705 CLINTON ST
BUFFALO, NY 14210

MANIFEST 1009233126
N/A

Site 2 of 2 in cluster X

Relative:
Equal

Actual:
590 ft.

NY MANIFEST:
EPA ID: NYP000908264
Country: USA
Mailing Name: TRUCO ENGINE
Mailing Contact: JAMES E O'CONNOR
Mailing Address: 116 GRAND ISLAND BLVD
Mailing Address 2: Not reported
Mailing City: TONAWANDA
Mailing State: NY
Mailing Zip: 14150
Mailing Zip4: 6604
Mailing Country: USA
Mailing Phone: 716-656-9826

Document ID: MIA3190467
Manifest Status: Completed copy
Trans1 State ID: E37435ME
Trans2 State ID: Not reported
Generator Ship Date: 930709
Trans1 Recv Date: 930709
Trans2 Recv Date: Not reported
TSD Site Recv Date: 930712
Part A Recv Date: 930719
Part B Recv Date: 930730
Generator EPA ID: NYP000908264
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSDF ID: MID096963194
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00495
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 93
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Y100 **STOP N GAS**
ENE **161 FILLMORE AVE**
1/4-1/2 **BUFFALO, NY 14201**
0.381 mi.
2011 ft. **Site 1 of 3 in cluster Y**

UST **U003317540**
HIST UST **N/A**
NY Spills
NY Hist Spills

Relative:
Higher

Actual:
593 ft.

UST:

Facility Id: 9-386340
Region: STATE
DEC Region: 9
Site Status: Active
Program Type: PBS
Expiration Date: 2012/09/19
UTM X: 186333.07814
UTM Y: 4754386.1688900003
Site ID: 53728

Tank Number: 41
Tank Status: Closed - In Place
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 1/1/1959
Capacity Gallons: 10000
Tightness Test Method: 14
Next Test Date: Not reported
Date Tank Closed: 8/1/1996
Tank ID: 165666
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 8/1/1992
Register: True
Trade Sec: False
Modified By: TRANSLAT
Last Modified: 3/4/2004

Tank Number: 42
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 1/1/1959
Capacity Gallons: 10000
Tightness Test Method: 14
Next Test Date: 4/17/2006
Date Tank Closed: Not reported
Tank ID: 165667
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 4/17/2001
Register: True
Trade Sec: False
Modified By: LDGOMEZ
Last Modified: 8/3/2007

Tank Number: 43
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Install Date: 1/1/1968
Capacity Gallons: 5000
Tightness Test Method: 14
Next Test Date: 4/17/2006
Date Tank Closed: Not reported
Tank ID: 165668
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 4/17/2001
Register: True
Trade Sec: False
Modified By: LDGOMEZ
Last Modified: 8/3/2007

UST_PBS_BSAFFIL:

Site Id: 53728
Program Number: 9-386340
Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN
Company Name: SADO GAS SALES
Contact Type: Not reported
Contact Name: KEVIN SAXON
Address1: 4100 ST FRANCIS DRIVE
Address2: Not reported
City: HAMBURG
State: NY
Zip Code: 14075
Country Code: 001
Phone: (716) 627-4435
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 8/10/2007

Site Id: 53728
Program Number: 9-386340
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: E
Company Name: SADO GAS
Contact Type: VICE PRESIDENT
Contact Name: KEVIN SAXON
Address1: 4100 ST. FRANCIS DRIVE
Address2: Not reported
City: HAMBURG
State: NY
Zip Code: 14075
Country Code: 001
Phone: Not reported
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 8/3/2007

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Site Id: 53728
Program Number: 9-386340
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: STOP N GAS
Contact Type: Not reported
Contact Name: SADO GAS SALES INC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (716) 822-7088
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: THKNIZEK
Date Last Modified: 7/28/2009

Site Id: 53728
Program Number: 9-386340
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: SADO GAS
Contact Type: Not reported
Contact Name: KEVIN SAXON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (716) 627-4435
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 8/3/2007

UST_AST_PBS_BSEQUIP:

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: H04
Code Name: Groundwater Well
Type: Tank Leak Detection

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: H04
Code Name: Groundwater Well
Type: Tank Leak Detection

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: H04
Code Name: Groundwater Well
Type: Tank Leak Detection

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: I00
Code Name: None
Type: Overfill

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Site Id: 53728

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Tank Id Number: 165666
Tank Number: 41
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Site Id: 53728
Tank Id Number: 165666

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Tank Number: 41
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Site Id: 53728
Tank Id Number: 165666
Tank Number: 41
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 53728
Tank Id Number: 165667
Tank Number: 42
Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Site Id: 53728
Tank Id Number: 165668
Tank Number: 43
Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

HIST UST:

PBS Number: 9-386340
SPDES Number: Not reported
Emergency Contact: R SAXON-V PRES-SADO GAS SALES
Emergency Telephone: (716) 662-5141
Operator: SADO GAS SALES INC
Operator Telephone: (716) 822-7088
Owner Name: J H WILLIAMS-LEASED SADO GAS
Owner Address: 16952 S PASSAGE ISLAND
Owner City,St,Zip: JUPITER, FL 33458
Owner Telephone: (305) 878-9430

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: SADO GAS SALES
Mailing Address: 4100 ST FRANCIS DRIVE
Mailing Address 2: Not reported
Mailing City,St,Zip: HAMBURG, NY 14075
Mailing Contact: ROBERT SAXON
Mailing Telephone: (716) 627-4435
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Facility Addr2: Not reported
SWIS ID: 1402
Old PBS Number: Not reported
Facility Type: RETAIL GASOLINE SALES
Inspected Date: 19951106
Inspector: JES
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 05/04/2001
Expiration Date: 09/19/2002
Renew Flag: False
Renewal Date: 19920701
Total Capacity: 15000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: BUFFALO (C)
County Code: 14
Town or City: 02
Region: 9

Tank Id: 41
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: 19590101
Capacity (gals): 10000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: 10
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: 39
Overfill Prot: Catch Basin, None
Dispenser: Submersible
Date Tested: 08/01/1992
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Date Closed: 08/01/1996
Test Method: Tankology [Vacutect]
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 42
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 19590101
Capacity (gals): 10000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Fiberglass Liner (FRP)
Tank External: 10
Pipe Location: Underground
Pipe Type: STAINLESS STEEL ALLOY
Pipe Internal: Fiberglass Liner (FRP)
Pipe External: 30
Second Containment: None
Leak Detection: 39
Overfill Prot: Catch Basin, Float Vent Valve
Dispenser: Submersible
Date Tested: 04/17/2001
Next Test Date: 04/17/2006
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Tankology [Vacutect]
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 43
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 19680101
Capacity (gals): 5000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Fiberglass Liner (FRP)
Tank External: 10
Pipe Location: Underground
Pipe Type: STAINLESS STEEL ALLOY
Pipe Internal: Fiberglass Liner (FRP)
Pipe External: 30
Second Containment: None
Leak Detection: 39
Overfill Prot: Catch Basin, Float Vent Valve
Dispenser: Submersible
Date Tested: 04/17/2001
Next Test Date: 04/17/2006
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Tankology [Vacutect]
Deleted: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Updated: True
Lat/long: Not reported

NY Spills:

Site ID: 240107
Facility Addr2: Not reported
Facility ID: 9603697
Spill Number: 9603697
Facility Type: ER
SWIS: 1502
Investigator: TEDIEFFE
Referred To: Not reported
Spill Date: 6/17/1996
Reported to Dept: 6/17/1996
CID: 30
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 3/16/2001
Recommended Penalty: Penalty Not Recommended
UST Trust: True
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not Closed
Remediation Phase: 1
Date Entered In Computer: 6/17/1996
Spill Record Last Update: 2/13/2004
Spiller Name: ROBERT SAXON
Spiller Company: SADO GAS SALES
Spiller Address: 4100 ST FRANCIS DR
Spiller City,St,Zip: HAMBURG, NY
Spiller Company: 001
Contact Name: ROBERT SAXON
Contact Phone: (716) 856-5687
DEC Region: 9
DER Facility ID: 197512
DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TED" 6/17/96 MLD CALLED FG TO RESPOND TO SPILL. FG RESPONDED. LINE LEAK DETECTOR FAILED ON THURS 6/13/96. BOB SAXON NOTIFIED DEC WHEN SPILL FOUND. TRENCHES WERE DUG ALONG THE LINES, AROUND THE TANKS AND ALONG THE ISLAND. PRODUCT WAS FOUND AT THE NORTH OF THE ISLAND. THAT PUMP WAS SHUT DOWN. TRENCHES WERE APPRO. 5 FEET DEEP. APPROX. 100 GAL OF PRODUCT HAD BEEN COLLECTED INTO DRUMS. CONTAMINATED SOIL WAS STAGED ON PLASTIC IN BACK. NEW FIBERGLASS LINES WERE BEING INSTALLED TO REPLACE THE LEAKING LINE. BOB SAXON WAS GOING TO CONTINUE TO DIG TO CLEAN TO THE CLAY LAYER, INSTALL WELLS & SAMPLE, THEN DISPOSE OF SOIL. THERE WAS OLD FILL APPROX. 3-4 FT DEEP ON SITE. WORK WAS TO CONTINUE TOMORROW. 6/18/96 FG SITE VISIT. TRENCHING CONTINUED FURTHER WEST. ADD'L PRODUCT FOUND. CONTINUING TO CLEAN UP AND INSTALL NEW LINE TODAY. 6/25/96 BOB SAXON CALLED TO SAY THAT HE WILL BE INSTALLING A TWELVE INCH WELL IN A TRENCH THAT HE DUG ON SITE FOR PUMPING. HE IS LOOKING INTO DISCHARGE TO THE BUFFALO SEWER AUTHORITY. HE SAID THEY REMOVED AS MUCH OF THE CONTAMINATED MATERIAL AS POSSIBLE BUT THERE REMAINED A SHEEN ON THE WATER. HE SAID HE DUG A TRENCH

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

ALONG THE SIDE STREET 12 FEET DEEP TO CHECK FOR OFF SITE MIGRATION BUT FOUND NOTHING BUT CLAY. HE WILL PROVIDE A WRITTEN DOCUMENTATION OF ALL THE WORK HE IS AND WILL BE DOING ON SITE. HE SAID HE WILL BE INSTALLING 5 WELLS ON SITE AND WILL BE ABLE TO DETERMINE GROUNDWATER FLOW. SOIL SAMPLES WERE ALSO COLLECTED FOR ANALYSIS. 6/25/96 FG SITE VISIT. TRENCHES WERE BACKFILLED WITH PEA GRAVEL, PER JIM MCCANN, CONTRACTOR ON SITE. TRENCH REMAINED OPEN AT THE WEST END. MINOR CONTAMINATION NOTED. APPARENTLY, THE WATER IS TO FLOW TO THIS AREA THROUGH ALL THE TRENCHES THAT START AT THE PUMP ISLAND. CONTAMINATION IS STAGED ON PLASTIC ON THE SITE. 6/25/96 BOB SAXON SUBMITTED A LTR STATING WORK COMPLETED TO DATE. AFTER RESULTS FROM WATER ON SITE ARE RECEIVED, FURTHER REMEDIATION/INVESTIGATION WILL BE CONSIDERED. HE AGREED TO PROVIDE ALL INFO REQUESTED IN MY 6/19/96 LTR. 7/31/96 RECD MEMO DATED 7/18/96 FROM BOB SAXON. HE WILL DISPOSE OF WATERS FROM WELL TO SEWER AUTHORITY. PROVIDED BSA PERMIT. HE WILL SUBMIT ALL ANALYTICAL BY THE FIRST WEEK IN AUGUST. 8/30/96 RECD MEMO DATED 8/26/96 FROM BOB SAXON. HE SUBMITTED DISPOSAL RECPTS FOR SOIL STAGED ON SITE & FOR DRUMS OF CONTAMINATED WATER & SLUDGES. HE SUBMITTED GW DATA FOR RECOVERY WELL WHICH SHOWS DATA ABOVE STARS. HE SUBMITTED SOIL RESULTS FROM BELOW TANK 41 WHICH WAS FILLED IN PLACE-RESULTS BELOW STARS. FG SPOKE TO BOB SAXON & REQUESTED SAMPLING OF ALL WELLS. MR. SAXON AGREED & SAID THE CARBON DATA AFTER IS PROBABLY A LAB ERROR. HE PLANS ON RESAMPLING RIGHT AWAY & WILL CALL W/A DATE. 9/9/96 RECD LANDFILL SAMPLING DATA FROM EXCAVATED SOIL. 2/5/97 LTR SENT TO BOB SAXON REQUESTING THE GROUNDWATER ANALYTICAL DATA FROM THE FIVE ON SITE WELLS AND AN AMOUNT OF WATER THAT HAS BEEN PUMPED TO THE BSA. 2/6/97 FG SITE INSPECTION. I COULD NOT OPEN THE WELL COVER. NO APPARENT ACTIVITY ON SITE. SOIL PILE HAS BEEN REMOVED FROM SITE. 3/19/97 SADO SUBMITTED DATA ON THE WELL ON SITE - #3. CONTAMINATION REMAINS. ADDL GW PUMPING WILL BEGIN LATER THIS MONTH. 4/23/97 FG RNL SITE VISIT. NO SYSTEM OPERATING ON SITE. LTR SENT REQUIRING PUMPING AS STATED. RESPONSE IS DUE 5/15/97. 5/15/97 SADO SUBMITTED LTR STATING THAT THEY ARE PLACING BACTERIA FOR BIOENHANCEMENT IN THE WELL. THEY ARE TO ADD MORE BACTERIA THE FIRST WEEK IN JUNE. THEY HAVE ALREADY MADE TWO ADDITIONS. SADO IS TO SAMPLE BEFORE THE NEXT ADDITION AND SUBMIT RESULTS. 8/26/97 LTR SENT REQUESTING SUBMISSION OF ANALYTICAL FOR WELLS ON SITE AND AN UPDATE ON THE STATUS OF THE SITE. RESPONSE IS DUE 9/19/97. 10/27/97 RECD ANALYTICAL RESULTS FROM 9/23/97 FOR RECOVERY WELL ON SITE. LEVELS ARE SLIGHTLY ABOVE STARS. BIOREMEDIATION IS CONTINUING. SAXON INDICATED THAT SAMPLES WILL BE COLLECTED IN 3 MONTHS. RESULTS SHOULD BE DUE IN JANUARY 1998. 3/12/98 SADO SUBMITTED ANALYTICAL RESULTS FROM WELL SAMPLING. RESULTS ARE BELOW STARS. SADO REQUESTED SITE CLOSURE. 4/3/98 LTR SENT TO SADO REQUESTING ADDL YEAR OF SAMPLING AND SOIL SAMPLING TO CONFIRM TREATMENT EFFECTIVENESS. RESPONSE IS DUE 4/24/98. 4/28/98 SAXON SUBMITTED SCHEDULE FOR SAMPLING BEGINNING IN JUNE 1998 AND ENDING MARCH 1999. 1/31/00 LTR SENT TO SADO REQUESTING A REMEDIATION PROPOSAL BY 2/18/00. 2/10/00 RECD SADO RESPONSE TO MY LTR. THEY SAID THEY COLLECTED GROUNDWATER SAMPLES AND WILL SUBMIT THEM AND IS REQUESTING A MEETING TO DISCUSS THE SITE. 2/21/00 RECD GROUNDWATER RESULTS FROM THE 12 INCH WELL. THE RESULTS ARE MTBE 86.1 PPB AND BENZENE 150.4 AND O-XYLENE 5.3. 7/1/00 LTR SENT TO SADO REQUIRING ADDL GROUNDWATER AND SOIL ANALYSIS PER MY 4/6/98 LETTER. A RESPONSE IS DUE BY 7/21/00. 7/12/00 KEVIN SAXON CALLED AND SAID HE WILL COLLECT A SOIL SAMPLE FROM THE AREA SURROUNDING THE WELL TO CONFIRM THAT REMEDIATION IS COMPLETE. HE WILL HAVE NATURE'S WAY COMPLETE IT. THEY WILL CALL ME WHEN THEY PLAN ON COMPLETING THE WORK.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

9/1/00 KEVIN SAXON SAID THAT HE HAD NATURE'S WAY COMPLETE SOME BORINGS ON SITE AND HE HAS NOT RECEIVED THE DATA YET. HE WILL GET THE INFORMATION FROM NATURE'S WAY AND THEN SUBMIT IT TO THE NYSDEC. 9/12/00 RECD RESULTS OF NATURE'S WAY SUBSURFACE INVESTIGATION. 4 GEOPRBE SAMPLES WERE COLLECTED: SAMPLE LOCATION TOTAL 8021 RESULTS PPM EP1 30 EP2 14 EP3 26 EP4 28 LETTER INDICATES THAT NATURE'S WAY WILL BE WORKING WITH SADO GAS TO DEVELOP AN APPROPRIATE PLAN TO DEAL WITH THE SUBSURFACE CONTAMINATION AND WILL SUBMIT IT ASAP. 1/29/01 KEVIN SAXON WITH SADO CALLED AND SAID HE WILL GET BACK TO ME WITHIN TWO WEEKS REGARDING WHAT HE WILL DO ON SITE. R. SAVAGE IS ON VACATION AND WILL BE BACK THEN. THE SITE SOIL SAMPLES EXCEED THE NEW TAGM 4046 LEVELS. 3/1/01 KEVIN SAXON SENT A FAX STATING THAT HE AND RUSS SAVAGE WILL BE MEETING ON 3/7/01 AND WILL SUBMIT A WORK PLAN AND SCHEDULE AFTER. 3/16/01 FG SITE INSPECTION. NATURE'S WAY ON SITE COMPLETING BORINGS. THEY PLAN ON COMPLETING 34 POINTS ON THE SITE AND WORK WILL CONTINUE ON MONDAY. ALL THE POINTS THEY HAVE COMPLETED SO FAR ARE PETROLEUM CONTAMINATED. THEY ARE CONTAMINATED TO 8 FT. THIS IS THE DEPTH OF THE BORINGS. I TOLD NATURE'S WAY TO DO SOME AT GREATER DEPTH. THEY WILL CALL DALE GRAMZA TO CONFIRM. 10/15/01: FG ON EXTENDED LEAVE, SITE REASSIGNED TO TED.

Remarks: gas co said line leak detector had break in line-area has been dug up for futher investigation revealing diffinite leak of gasoline affecting land only-gasoline is being pumped into drums and contaminated soil being dug up

Material:

Site ID: 240107
Operable Unit ID: 1034841
Operable Unit: 01
Material ID: 349976
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: True
Site ID: 240107
Operable Unit ID: 1034841
Operable Unit: 01
Material ID: 573473
Material Code: 1213A
Material Name: MTBE (METHYL-TERT-BUTYL ETHER)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Soil
Oxygenate: True

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 9603697
Investigator: TED
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 06/17/1996 16:00
Reported to Dept Date/Time: 06/17/96 18:02
SWIS: 14
Spiller Name: SADO GAS SALES
Spiller Contact: ROBERT SAXON
Spiller Phone: (716) 856-5687
Spiller Contact: ROBERT SAXON
Spiller Phone: (716) 856-5687
Spiller Address: 4100 ST FRANCIS DR
Spiller City,St,Zip: HAMBURG, NY
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 05
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: 03/16/01
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: True
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/17/96
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/19/01
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0

Unkonwn Quantity Recovered: True

Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929

DEC Remarks: 6/17/96 MLD CALLED FG TO RESPOND TO SPILL. FG RESPONDED. LINE LEAK DETECTOR FAILED ON THURS 6/13/96. BOB SAXON NOTIFIED DEC WHEN SPILL FOUND. TRENCHES WERE DUG ALONG THE LINES, AROUND THE TANKS AND ALONG THE ISLAND. PRODUCT WAS FOUND AT THE NORTH OF THE ISLAND. THAT PUMP WAS SHUT DOWN. TRENCHES WERE APPROX. 5 FEET DEEP. APPROX. 100 GAL OF PRODUCT HAD BEEN COLLECTED INTO DRUMS. CONTAMINATED SOIL WAS STAGED ON PLASTIC IN BACK. NEW FIBERGLASS LINES WERE BEING INSTALLED TO REPLACE THE LEAKING LINE. BOB SAXON WAS GOING TO CONTINUE TO DIG TO CLEAN TO THE CLAY LAYER, INSTALL WELLS SAMPLE, THEN DISPOSE OF SOIL. THERE WAS OLD FILL APPROX. 3-4 FT DEEP ON SITE. WORK WAS TO CONTINUE TOMORROW. 6/18/96 FG SITE VISIT. TRENCHING CONTINUED FURTHER WEST. ADD L PRODUCT FOUND. CONTINUING TO CLEAN UP AND INSTALL NEW LINE TODAY. 6/25/96 BOB SAXON CALLED TO SAY THAT HE WILL BE INSTALLING A TWELVE INCH WELL IN A TRENCH THAT HE DUG ON SITE FOR PUMPING. HE IS LOOKING INTO DISCHARGE TO THE BUFFALO SEWER AUTHORITY. HE SAID THEY REMOVED AS MUCH OF THE CONTAMINATED MATERIAL AS POSSIBLE BUT THERE REMAINED A SHEEN ON THE WATER. HE SAID HE DUG A TRENCH ALONG THE SIDE STREET 12 FEET DEEP TO CHECK FOR OFF SITE MIGRATION BUT FOUND NOTHING BUT CLAY. HE WILL PROVIDE A WRITTEN DOCUMENTATION OF ALL THE WORK HE IS AND WILL BE DOING ON SITE. HE SAID HE WILL BE INSTALLING 5 WELLS ON SITE AND WILL BE ABLE TO DETERMINE GROUNDWATER FLOW. SOIL SAMPLES WERE ALSO COLLECTED FOR ANALYSIS. 6/25/96 FG SITE VISIT. TRENCHES WERE BACKFILLED WITH PEA GRAVEL, PER JIM MCCANN, CONTRACTOR ON SITE. TRENCH REMAINED OPEN AT THE WEST END. MINOR CONTAMINATION NOTED. APPARENTLY, THE WATER IS TO FLOW TO THIS AREA THROUGH ALL THE TRENCHES THAT START AT THE PUMP ISLAND. CONTAMINATION IS STAGED ON PLASTIC ON THE SITE. 6/25/96 BOB SAXON SUBMITTED A LTR STATING WORK COMPLETED TO DATE. AFTER RESULTS FROM WATER ON SITE ARE RECEIVED, FURTHER REMEDIATION/INVESTIGATION WILL BE CONSIDERED. HE AGREED TO PROVIDE ALL INFO REQUESTED IN MY 6/19/96 LTR. 7/31/96 RECD MEMO DATED 7/18/96 FROM BOB SAXON. HE WILL DISPOSE OF WATERS FROM WELL TO SEWER AUTHORITY. PROVIDED BSA PERMIT. HE WILL SUBMIT ALL ANALYTICAL BY THE FIRST WEEK IN AUGUST. 8/30/96 RECD MEMO DATED 8/26/96 FROM BOB SAXON. HE SUBMITTED DISPOSAL RECPTS FOR SOIL STAGED ON SITE FOR DRUMS OF CONTAMINATED WATER SLUDGES. HE SUBMITTED GW DATA FOR RECOVERY WELL WHICH SHOWS DATA ABOVE STARS. HE SUBMITTED SOIL RESULTS FROM BELOW TANK 41 WHICH WAS FILLED IN PLACE-RESULTS BELOW STARS. FG SPOKE TO BOB SAXON REQUESTED SAMPLING OF ALL WELLS. MR. SAXON AGREED SAID THE CARBON DATA AFTER IS PROBABLY A LAB ERROR. HE PLANS ON RESAMPLING RIGHT AWAY WILL CALL W/A DATE. 9/9/96 RECD LANDFILL SAMPLING DATA FROM EXCAVATED SOIL. 2/5/97 LTR SENT TO BOB SAXON REQUESTING THE GROUNDWATER ANALYTICAL DATA FROM THE FIVE ON SITE WELLS AND AN AMOUNT OF WATER THAT HAS BEEN PUMPED TO THE BSA. 2/6/97 FG SITE INSPECTION. I COULD NOT OPEN THE WELL COVER. NO APPARENT ACTIVITY ON SITE. SOIL PILE HAS BEEN REMOVED FROM SITE. 3/19/97 SADO SUBMITTED DATA ON THE WELL ON SITE - 3. CONTAMINATION REMAINS. ADDL GW PUMPING WILL BEGIN LATER THIS MONTH. 4/23/97 FG RNL SITE VISIT. NO SYSTEM

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STOP N GAS (Continued)

U003317540

OPERATING ON SITE. LTR SENT REQUIRING PUMPING AS STATED. RESPONSE IS DUE 5/15/97. 5/15/97 SADO SUBMITTED LTR STATING THAT THEY ARE PLACING BACTERIA FOR BIOENHANCEMENT IN THE WELL. THEY ARE TO ADD MORE BACTERIA THE FIRST WEEK IN JUNE. THEY HAVEALREADY MADE TWO ADDITIONS. SADO IS TO SAMPLE BEFORE THE NEXT ADDITION AND SUBMIT RESULTS. 8/26/97 LTR SENT REQUESTING SUBMISSION OF ANALYTICAL FOR WELLS ON SITE AND AN UPDATE ON THE STATUS OF THE SITE. RESPONSE IS DUE 9/19/97. 10/27/97 RECD ANALYTICAL RESULTS FROM 9/23/97 FOR RECOVERY WELL ON SITE. LEVELS ARE SLIGHTLY ABOVE STARS. BIOREMEDIATION IS CONTINUING. SAXON INDICATED THAT SAMPLES WILL BE COLLECTED IN 3 MONTHS. RESULTS SHOULD BE DUE IN JANUARY 1998. 3/12/98 SADO SUBMITTED ANALYTICAL RESULTS FROM WELL SAMPLING. RESULTS ARE BELOW STARS. SADO REQUESTED SITE CLOSURE. 4/3/98 LTR SENT TO SADO REQUESTING ADDL YEAR OF SAMPLING AND SOIL SAMPLING TO CONFIRM TREATMENT EFFECTIVENESS. RESPONSE IS DUE 4/24/98. 4/28/98 SAXON SUBMITTED SCHEDULE FOR SAMPLING BEGINNING IN JUNE 1998 AND ENDING MARCH 1999. 1/31/00 LTR SENT TO SADO REQUESTING A REMEDIATION PROPOSAL BY 2/18/00. 2/10/00 RECD SADO RESPONSE TO MY LTR. THEY SAID THEY COLLECTED GROUNDWATER SAMPLES AND WILL SUBMIT THEM AND IS REQUESTING A MEETING TO DISCUSS THE SITE. 2/21/00 RECD GROUNDWATER RESULTS FROM THE 12 INCH WELL. THE RESULTS ARE MTBE 86.1 PPB AND BENZENE 150.4 AND O-XYLENE 5.3. 7/1/00 LTR SENT TO SADO REQUIRING ADDL GROUNDWATER AND SOIL ANALYSIS PER MY 4/6/98 LETTER. A RESPONSE IS DUE BY 7/21/00. 7/12/00 KEVIN SAXON CALLED AND SAID HE WILL COLLECT A SOIL SAMPLE FROM THE AREA SURROUNDING THE WELL TO CONFIRM THAT REMEDIATION IS COMPLETE. HE WILL HAVE NATURE SWAY COMPLETE IT. THEY WILL CALL ME WHEN THEY PLAN ON COMPLETING THE WORK. 9/1/00 KEVIN SAXON SAID THAT HE HAD NATURE S WAY COMPLETE SOME BORINGS ON SITE AND HE HAS NOT RECEIVED THE DATA YET. HE WILL GET THE INFORMATION FROM NATURE S WAY AND THEN SUBMIT IT TO THE NYSDEC. 9/12/00 RECD RESULTS OF NATURE S WAY SUBSURFACE INVESTIGATION. 4 GEOPRBE SAMPLES WERE COLLECTED: SAMPLE LOCATION TOTAL 8021 RESULTS PPM
EP1 30 EP214 EP3 26
EP4 28 LETTER INDICATES THAT NATURE S WAY WILL BE WORKING WITH SADO GAS TO DEVELOP AN APPROPRIATE PLAN TO DEAL WITH THE SUBSURFACE CONTAMINATION AND WILL SUBMIT IT ASAP. 1/29/01KEVIN SAXON WITH SADO CALLED AND SAID HE WILL GET BACK TO ME WITHIN TWO WEEKS REGARDING WHAT HE WILL DO ON SITE. R. SAVAGE IS ON VACATION AND WILL BE BACK THEN. THE SITE SOIL SAMPLES EXCEED THE NEW TAGM 4046 LEVELS. 3/1/01 KEVIN SAXON SENT A FAX STATING THAT HE AND RUSS SAVAGE WILL BE MEETING ON 3/7/01 AND WILL SUBMIT A WORK PLAN AND SCHEDULE AFTER. 3/16/01 FG SITE INSPECTION. NATURE S WAY ON SITE COMPLETING BORINGS. THEY PLAN ON COMPLETING 34 POINTS ON THE SITE AND WORK WILL CONTINUE ON MONDAY. ALL THE POINTS THEY HAVE COMPLETED SO FAR ARE PETROLEUM CONTAMINATED. THEY ARE CONTAMINATED TO 8 FT. THIS IS THE DEPTH OF THE BORINGS. I TOLD NATURE S WAY TO DO SOME AT GREATER DEPTH. THEY WILL CALL DALE GRAMZA TO CONFIRM. 10/15/01: FG ON EXTENDED LEAVE, SITE REASSIGNED TO TED.

Remark: gas co said line leak detector had break in line-area has been dug up for futher investigation revealing diffinite leak of gasoline affecting land only-gasoline is being pumped into drums and contaminated soil being dug up

101
NNW
1/4-1/2
0.392 mi.
2069 ft.

FORMER MOBIL SERVICE STATION
683 CLINTON ST.
BUFFALO, NY 14206

UST U004118705
N/A

Relative:
Equal

UST:

Facility Id: 9-600989
Region: STATE
DEC Region: 9
Site Status: Unregulated

Actual:
590 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER MOBIL SERVICE STATION (Continued)

U004118705

Program Type: PBS
Expiration Date: N/A
UTM X: Not reported
UTM Y: Not reported
Site ID: 391070

Tank Number: 1
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: 5/10/1988
Tank ID: 220750
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: Not reported
Register: True
Trade Sec: False
Modified By: askalsk
Last Modified: 12/14/2007

Tank Number: 2
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: 5/10/1988
Tank ID: 220751
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: Not reported
Register: True
Trade Sec: False
Modified By: askalsk
Last Modified: 12/14/2007

Tank Number: 3
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: 5/10/1988
Tank ID: 220752
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER MOBIL SERVICE STATION (Continued)

U004118705

Register: True
Trade Sec: False
Modified By: aeskalsk
Last Modified: 12/14/2007

Tank Number: 4
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: 5/10/1988
Tank ID: 220753
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: Not reported
Register: True
Trade Sec: False
Modified By: aeskalsk
Last Modified: 12/14/2007

102
SSW
1/4-1/2
0.392 mi.
2070 ft.

STANFORD SEED CO
560 FULTON ST
BUFFALO, NY 14210

RCRA-NonGen **1000314812**
FINDS **NYD008915373**
MANIFEST

Relative:
Higher

Actual:
594 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: STANFORD SEED CO
Facility address: 560 FULTON ST
BUFFALO, NY 14210
EPA ID: NYD008915373
Mailing address: FULTON ST
BUFFALO, NY 14210
Contact: Not reported
Contact address: FULTON ST
BUFFALO, NY 14210
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: JAMES BILLINGS
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STANFORD SEED CO (Continued)

1000314812

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: JAMES BILLINGS
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: STANFORD SEED CO
Classification: Not a generator, verified

Date form received by agency: 08/09/1995
Facility name: STANFORD SEED CO
Classification: Not a generator, verified

Date form received by agency: 12/29/1989
Facility name: STANFORD SEED CO
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 08/03/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STANFORD SEED CO (Continued)

1000314812

Registry ID: 110004342890

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD008915373
Country: USA
Mailing Name: STANFORD SEED
Mailing Contact: STANFORD SEED
Mailing Address: 560 FULTON STREET
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14240
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-825-3300

Document ID: NYB1565802
Manifest Status: Completed after the designated time period for a TSDf to get a copy to the DEC
Trans1 State ID: 10245P/NY
Trans2 State ID: Not reported
Generator Ship Date: 900326
Trans1 Recv Date: 900326
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900330
Part A Recv Date: 900723
Part B Recv Date: 900514
Generator EPA ID: NYD008915373
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDf ID: TND980729305
Waste Code: B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB
Quantity: 00662
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TP - Tanks, portable
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 90
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STANFORD SEED CO (Continued)

1000314812

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

103
SE
1/4-1/2
0.401 mi.
2119 ft.

NORFOLK & WESTERN RAILWAY CO
105 SELKIRK ST
BUFFALO, NY 14210

RCRA-NonGen
FINDS
MANIFEST

1004755896
NY0000693531

Relative:
Higher

Actual:
593 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NORFOLK & WESTERN RAILWAY CO
Facility address: 105 SELKIRK ST
BUFFALO, NY 14210
EPA ID: NY0000693531
Mailing address: SELKIRK ST
BUFFALO, NY 14210
Contact: GARLAND KING
Contact address: SELKIRK ST
BUFFALO, NY 14210
Contact country: US
Contact telephone: (716) 828-0546
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NORFOLK SOUTHERN CORP
Owner/operator address: 110 FRANKLIN RD SE
ROANOKE, VA 24042
Owner/operator country: US
Owner/operator telephone: (703) 981-4154
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NORFOLK SOUTHERN CORP
Owner/operator address: 110 FRANKLIN RD SE
ROANOKE, VA 24042
Owner/operator country: US
Owner/operator telephone: (703) 981-4154
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NORFOLK & WESTERN RAILWAY CO (Continued)

1004755896

On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: NORFOLK & WESTERN RAILWAY CO
Classification: Not a generator, verified

Date form received by agency: 09/09/1994
Facility name: NORFOLK & WESTERN RAILWAY CO
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004319238

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NY0000693531
Country: USA
Mailing Name: NORFOLK SOUTHERN
Mailing Contact: G L KING
Mailing Address: 105 SELKIRK STREET
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14210
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-828-0546

Document ID: MIA3493548
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 941122
Trans1 Recv Date: 941122
Trans2 Recv Date: 941202

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NORFOLK & WESTERN RAILWAY CO (Continued)

1004755896

TSD Site Recv Date: 941206
Part A Recv Date: 941222
Part B Recv Date: 950123
Generator EPA ID: NY0000693531
Trans1 EPA ID: NYD986974244
Trans2 EPA ID: Not reported
TSD ID: MID980615298
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

104
NW
1/4-1/2
0.402 mi.
2120 ft.

PRIME STOP II
155 JEFFERSON & S DIVISION ST
BUFFALO, NY 14210

UST U003318751
HIST UST N/A

Relative:
Lower

UST:
Facility Id: 9-600111
Region: STATE
DEC Region: 9
Site Status: Active
Program Type: PBS
Expiration Date: 2011/06/30
UTM X: 185215.22068
UTM Y: 4754610.1669500005
Site ID: 54978

Actual:
589 ft.

Tank Number: 1
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 7/1/1975
Capacity Gallons: 8000
Tightness Test Method: 21
Next Test Date: 4/13/2010
Date Tank Closed: Not reported
Tank ID: 170737
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 4/13/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Register: True
Trade Sec: False
Modified By: LJJUDD
Last Modified: 6/30/2006

Tank Number: 2
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 7/1/1975
Capacity Gallons: 10000
Tightness Test Method: 21
Next Test Date: 4/13/2010
Date Tank Closed: Not reported
Tank ID: 170738
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 4/13/2005
Register: True
Trade Sec: False
Modified By: LJJUDD
Last Modified: 6/30/2006

Tank Number: 3
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 7/1/1975
Capacity Gallons: 12000
Tightness Test Method: 21
Next Test Date: 4/13/2010
Date Tank Closed: Not reported
Tank ID: 170739
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 4/13/2005
Register: True
Trade Sec: False
Modified By: LJJUDD
Last Modified: 6/30/2006

UST_PBS_BSAFFIL:
Site Id: 54978
Program Number: 9-600111
Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN
Company Name: Not reported
Contact Type: Not reported
Contact Name: SALEH MUTHANA
Address1: 115 ONEIDA STREET
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14210

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Country Code: 001
Phone: (716) 893-1839
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LJJUDD
Date Last Modified: 6/30/2006

Site Id: 54978
Program Number: 9-600111
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: PRIME STOP II
Contact Type: Not reported
Contact Name: SALEH MUTHANA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (716) 855-0509
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: THKNIZEK
Date Last Modified: 8/22/2008

Site Id: 54978
Program Number: 9-600111
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: SALEH MUTHANA
Contact Type: Not reported
Contact Name: SALEH MUTHANA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (716) 893-1839
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: THKNIZEK
Date Last Modified: 8/22/2008

Site Id: 54978
Program Number: 9-600111
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: E
Company Name: SALEH MUTHANA
Contact Type: OWNER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Contact Name: SALEH MUTHANA
Address1: 115 ONEIDA STREET
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14206
Country Code: 001
Phone: (716) 893-1839
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: THKNIZEK
Date Last Modified: 8/22/2008

UST_AST_PBS_BSEQUIP:

Site Id: 54978
Tank Id Number: 170739
Tank Number: 3
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 54978
Tank Id Number: 170737
Tank Number: 1
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 54978
Tank Id Number: 170738
Tank Number: 2
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 54978
Tank Id Number: 170738
Tank Number: 2
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 54978
Tank Id Number: 170739
Tank Number: 3
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 54978
Tank Id Number: 170737
Tank Number: 1
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Site Id: 54978
Tank Id Number: 170738
Tank Number: 2
Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Site Id: 54978
Tank Id Number: 170739
Tank Number: 3
Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Site Id: 54978
Tank Id Number: 170737
Tank Number: 1
Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Site Id: 54978
Tank Id Number: 170738
Tank Number: 2
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 54978
Tank Id Number: 170737
Tank Number: 1
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 54978
Tank Id Number: 170739
Tank Number: 3
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 54978
Tank Id Number: 170739
Tank Number: 3
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 54978
Tank Id Number: 170737
Tank Number: 1
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 54978

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Tank Id Number:	170738
Tank Number:	2
Equipment:	K01
Code Name:	Catch Basin
Type:	Spill Prevention
Site Id:	54978
Tank Id Number:	170739
Tank Number:	3
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Site Id:	54978
Tank Id Number:	170738
Tank Number:	2
Equipment:	A03
Code Name:	Fiberglass Liner (FRP)
Type:	Tank Internal Protection
Site Id:	54978
Tank Id Number:	170737
Tank Number:	1
Equipment:	A03
Code Name:	Fiberglass Liner (FRP)
Type:	Tank Internal Protection
Site Id:	54978
Tank Id Number:	170737
Tank Number:	1
Equipment:	B08
Code Name:	Retrofitted Impressed Current
Type:	Tank External Protection
Site Id:	54978
Tank Id Number:	170738
Tank Number:	2
Equipment:	B08
Code Name:	Retrofitted Impressed Current
Type:	Tank External Protection
Site Id:	54978
Tank Id Number:	170739
Tank Number:	3
Equipment:	B08
Code Name:	Retrofitted Impressed Current
Type:	Tank External Protection
Site Id:	54978
Tank Id Number:	170739
Tank Number:	3
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location
Site Id:	54978
Tank Id Number:	170738

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Tank Number: 2
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 54978
Tank Id Number: 170737
Tank Number: 1
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 54978
Tank Id Number: 170737
Tank Number: 1
Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Site Id: 54978
Tank Id Number: 170739
Tank Number: 3
Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Site Id: 54978
Tank Id Number: 170738
Tank Number: 2
Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Site Id: 54978
Tank Id Number: 170737
Tank Number: 1
Equipment: F08
Code Name: Retrofitted Impressed Current
Type: Pipe External Protection

Site Id: 54978
Tank Id Number: 170738
Tank Number: 2
Equipment: F08
Code Name: Retrofitted Impressed Current
Type: Pipe External Protection

Site Id: 54978
Tank Id Number: 170739
Tank Number: 3
Equipment: F08
Code Name: Retrofitted Impressed Current
Type: Pipe External Protection

HIST UST:

PBS Number: 9-600111
SPDES Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Emergency Contact: MOHAMED A. ABUHAMRA
Emergency Telephone: (716) 852-4011
Operator: MOHAMED A. ABUHAMRA
Operator Telephone: (716) 855-0509
Owner Name: MOHAMED ABUHAMRA
Owner Address: 24 PALM STREET
Owner City,St,Zip: LACKAWANNA, NY 14218
Owner Telephone: (716) 628-1680
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: BUFFALO SUCCESS INC.
Mailing Address: 155 JEFFERSON AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: BUFFALO, NY 14210
Mailing Contact: Not reported
Mailing Telephone: (716) 855-0509
Owner Mark: Second Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Facility Addr2: Not reported
SWIS ID: 1402
Old PBS Number: Not reported
Facility Type: RETAIL GASOLINE SALES
Inspected Date: 19950630
Inspector: JES
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 12/10/1999
Expiration Date: 06/07/2004
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 30000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: BUFFALO (C)
County Code: 14
Town or City: 02
Region: 9

Tank Id: 1
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 19750701
Capacity (gals): 8000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Fiberglass Liner (FRP)
Tank External: 30
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Pipe External: 30
Second Containment: None
Leak Detection: None
Overfill Prot: Automatic Shut-Off, Catch Basin
Dispenser: Suction
Date Tested: 11/01/1999
Next Test Date: 11/01/2004
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 2
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 19750701
Capacity (gals): 10000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Fiberglass Liner (FRP)
Tank External: 30
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 30
Second Containment: None
Leak Detection: None
Overfill Prot: Automatic Shut-Off, Catch Basin
Dispenser: Suction
Date Tested: 11/01/1999
Next Test Date: 11/01/2004
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 3
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 19750701
Capacity (gals): 12000
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 30
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 30
Second Containment: None
Leak Detection: None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIME STOP II (Continued)

U003318751

Overfill Prot: Automatic Shut-Off, Catch Basin
Dispenser: Suction
Date Tested: 11/01/1999
Next Test Date: 11/01/2004
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

**Z105
WNW
1/4-1/2
0.403 mi.
2129 ft.**

**NYSDEC
JEFFERSON / MYRTLE
BUFFALO, NY 14203**

**MANIFEST 1009235276
N/A**

Site 1 of 2 in cluster Z

**Relative:
Equal**

**Actual:
590 ft.**

NY MANIFEST:
EPA ID: NYP003601333
Country: USA
Mailing Name: NYSDEC
Mailing Contact: KEVIN N GLASER
Mailing Address: 270 MICHIGAN AVE REG 9
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14203
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-851-7220

Document ID: NYB4559049
Manifest Status: Completed copy
Trans1 State ID: JD2082
Trans2 State ID: Not reported
Generator Ship Date: 920108
Trans1 Recv Date: 920108
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920109
Part A Recv Date: 920122
Part B Recv Date: 920122
Generator EPA ID: NYP003601333
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSDF ID: NYD043815703
Waste Code: F003 - UNKNOWN
Quantity: 00560
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 010
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDEC (Continued)

1009235276

Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4560615
Manifest Status: Completed copy
Trans1 State ID: JD2082
Trans2 State ID: OH044
Generator Ship Date: 920626
Trans1 Recv Date: 920626
Trans2 Recv Date: 920701
TSD Site Recv Date: 920702
Part A Recv Date: 920721
Part B Recv Date: 920716
Generator EPA ID: NYP003601333
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: OHD053576294
TSDF ID: OHD053576294
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00424
Units: K - Kilograms (2.2 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4560759
Manifest Status: Completed copy
Trans1 State ID: E69849ME
Trans2 State ID: Not reported
Generator Ship Date: 921019
Trans1 Recv Date: 921019
Trans2 Recv Date: Not reported
TSD Site Recv Date: 921019
Part A Recv Date: 921030
Part B Recv Date: 921029
Generator EPA ID: NYP003601333

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDEC (Continued)

1009235276

Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 20221
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4560768
Manifest Status: Completed copy
Trans1 State ID: 79633ZNY
Trans2 State ID: Not reported
Generator Ship Date: 921019
Trans1 Recv Date: 921019
Trans2 Recv Date: Not reported
TSD Site Recv Date: 921019
Part A Recv Date: 921030
Part B Recv Date: 921029
Generator EPA ID: NYP003601333
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 21192
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDEC (Continued)

1009235276

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYG2518668
Manifest Status: Not reported
Trans1 State ID: NYD986980753
Trans2 State ID: Not reported
Generator Ship Date: 05/07/2002
Trans1 Recv Date: 05/07/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/10/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP003601333
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 45742JDNY
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00700
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 02
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

106
North
1/4-1/2
0.413 mi.
2178 ft.

**BUFFALO SWITCH
271 BRISTOL
BUFFALO, NY 14206**

UST U003317842
HIST UST N/A

Relative:
Higher

UST:
Facility Id: 9-423270
Region: STATE
DEC Region: 9
Site Status: Active
Program Type: PBS

Actual:
591 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO SWITCH (Continued)

U003317842

Expiration Date: 2012/09/19
UTM X: 185870.72636999999
UTM Y: 4754816.5430199997
Site ID: 54046

Tank Number: 1
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 6/1/1987
Capacity Gallons: 6000
Tightness Test Method: 11
Next Test Date: Not reported
Date Tank Closed: Not reported
Tank ID: 177912
Tank Location: 5
Tank Type: Equivalent technology
Date Test: 7/1/1990
Register: True
Trade Sec: False
Modified By: TRANSLAT
Last Modified: 3/4/2004

Tank Number: 1-A
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: 6/1/1988
Tank ID: 177913
Tank Location: 5
Tank Type: Equivalent technology
Date Test: Not reported
Register: True
Trade Sec: False
Modified By: TRANSLAT
Last Modified: 3/4/2004

UST_PBS_BSAFFIL:

Site Id: 54046
Program Number: 9-423270
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: E
Company Name: SPRINT COMMUNICATIONS CO L.P.
Contact Type: EHS MANAGER
Contact Name: JERRY F. KIDWELL
Address1: 2003 EDMUND HALLEY DRIVE
Address2: Not reported
City: RESTON
State: VA
Zip Code: 20191
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO SWITCH (Continued)

U003317842

Phone: (703) 433-4083
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 9/4/2007

Site Id: 54046
Program Number: 9-423270
Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN
Company Name: SPRINT COMMUNICATION CO. L.P.
Contact Type: Not reported
Contact Name: JERRY KIDWELL
Address1: 2003 EDMUND HALLEY DRIVE
Address2: MS VARESS0301-3201
City: RESTON
State: VA
Zip Code: 20191
Country Code: 001
Phone: (703) 433-4083
Phone Ext: Not reported
Email: JERRY.F.KIDWELL@SPRINT.COM
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 9/4/2007

Site Id: 54046
Program Number: 9-423270
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: SPRINT COMMUNICATIONS CO L.P.
Contact Type: Not reported
Contact Name: JOE SURIANI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (800) 521-0579
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 54046
Program Number: 9-423270
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: BUFFALO SWITCH
Contact Type: Not reported
Contact Name: JOE SURIANI

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO SWITCH (Continued)

U003317842

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 856-2325
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

UST_AST_PBS_BSEQUIP:

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 54046
Tank Id Number: 177913
Tank Number: 1-A
Equipment: G07
Code Name: Excavation/Trench Liner System
Type: Tank Secondary Containment

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 54046
Tank Id Number: 177913
Tank Number: 1-A
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 54046
Tank Id Number: 177913
Tank Number: 1-A
Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 54046

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO SWITCH (Continued)

U003317842

Tank Id Number: 177913
Tank Number: 1-A
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Site Id: 54046
Tank Id Number: 177913
Tank Number: 1-A
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Site Id: 54046
Tank Id Number: 177913
Tank Number: 1-A
Equipment: 800
Code Name: None
Type: Tank External Protection

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Site Id: 54046
Tank Id Number: 177913

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO SWITCH (Continued)

U003317842

Tank Number: 1-A
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 54046
Tank Id Number: 177913
Tank Number: 1-A
Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Site Id: 54046
Tank Id Number: 177912
Tank Number: 1
Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Site Id: 54046
Tank Id Number: 177913
Tank Number: 1-A
Equipment: F06
Code Name: Wrapped
Type: Pipe External Protection

HIST UST:

PBS Number: 9-423270
SPDES Number: Not reported
Emergency Contact: JOE SURIANI
Emergency Telephone: (800) 521-0579
Operator: JOE SURIANI
Operator Telephone: (716) 856-2325
Owner Name: SPRINT COMMUNICATIONS CO L.P.
Owner Address: 2330 SHAWNEE MISSION PKWY (KSWESA0113)
Owner City,St,Zip: WESTWOOD, KS 66205
Owner Telephone: (913) 624-3368
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: SPRINT COMMUNICATION CO. L.P.
Mailing Address: 2330 SHAWNEE MISSION PKWY
Mailing Address 2: KSWESA0113
Mailing City,St,Zip: WESTWOOD, KS 66205

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO SWITCH (Continued)

U003317842

Mailing Contact: CATHY GOSNELL
Mailing Telephone: (913) 624-3368
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: Not reported
SWIS ID: 1402
Old PBS Number: Not reported
Facility Type: OTHER
Inspected Date: 19950424
Inspector: JES
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 09/15/1997
Expiration Date: 09/19/2002
Renew Flag: True
Renewal Date: 19921117
Total Capacity: 6000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: BUFFALO (C)
County Code: 14
Town or City: 02
Region: 9

Tank Id: 1
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 19870601
Capacity (gals): 6000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Fiberglass reinforced plastic [FRP]
Tank Internal: Fiberglass Liner (FRP)
Tank External: 40
Pipe Location: Underground
Pipe Type: STAINLESS STEEL ALLOY
Pipe Internal: Fiberglass Liner (FRP)
Pipe External: 40
Second Containment: None
Leak Detection: 40
Overfill Prot: High Level Alarm, Catch Basin
Dispenser: Suction
Date Tested: 07/01/1990
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Leak Computer [ACUTEST]
Deleted: False
Updated: True
Lat/long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO SWITCH (Continued)

U003317842

Tank Id: 1
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 1000
Product Stored: DIESEL
Tank Type: Fiberglass reinforced plastic [FRP]
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Wrapped (Piping)
Second Containment: Vault (w/o access)
Leak Detection: Not reported
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 06/01/1988
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Y107
ENE
1/4-1/2
0.425 mi.
2246 ft.

**CSX TRANSPORTATION BUFFALO
FILLMORE / EAGLE
BUFFALO, NY**

**MANIFEST S108850408
N/A**

Site 2 of 3 in cluster Y

**Relative:
Higher**

PA MANIFEST:
Manifest Number: 001059538JJK
Manifest Type: T
Generator Epa Id: NYP000961136
Generator Date: 12/20/06
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD Epa Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: 904-366-4174
Page Number: 1
Line Number: 1
Waste Number: D001
Container Number: 1
Container Type: DM
Waste Quantity: 85
Unit: G
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

**Actual:
595 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CSX TRANSPORTATION BUFFALO (Continued)

S108850408

Manifest Number: 001059538JJJ
Manifest Type: T
Generator Epa Id: NYP000961136
Generator Date: 12/20/06
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD Epa Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: 904-366-4174
Page Number: 1
Line Number: 2
Waste Number: D001
Container Number: 1
Container Type: DF
Waste Quantity: 95
Unit: G
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Manifest Number: 001059538JJJ
Manifest Type: T
Generator Epa Id: NYP000961136
Generator Date: 12/20/06
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD Epa Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: 904-366-4174
Page Number: 1
Line Number: 3
Waste Number: D001
Container Number: 2
Container Type: CF
Waste Quantity: 280
Unit: G
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Manifest Number: 001059538JJJ
Manifest Type: T
Generator Epa Id: NYP000961136
Generator Date: 12/20/06
Mailing Address: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CSX TRANSPORTATION BUFFALO (Continued)

S108850408

Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD Epa Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: 904-366-4174
Page Number: 1
Line Number: 3
Waste Number: F003
Container Number: 2
Container Type: CF
Waste Quantity: 280
Unit: G
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Y108
ENE
1/4-1/2
0.425 mi.
2246 ft.

**CSX TRANSPORTATION
FILLMORE / EAGLE
BUFFALO, NY**

MANIFEST S108650959
N/A

Site 3 of 3 in cluster Y

Relative:
Higher

NY MANIFEST:
EPA ID: NYP000961136
Country: USA
Mailing Name: CSX TRANSPORTATION
Mailing Contact: CSX TRANSPORTATION
Mailing Address: 500 WATER ST
Mailing Address 2: J-275
Mailing City: JACKSONVILLE
Mailing State: FL
Mailing Zip: 32202
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 904-366-4174

Actual:
595 ft.

NY MANIFEST:
No Manifest Records Available

AA109
North
1/4-1/2
0.426 mi.
2250 ft.

**BRISTOL STREET SITE
208 BRISTOL STREET
BUFFALO, NY 14202**

CERC-NFRAP 1001216956
NY0002326437

Site 1 of 2 in cluster AA

Relative:
Higher

CERC-NFRAP:
Site ID: 0204155
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

Actual:
591 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BRISTOL STREET SITE (Continued)

1001216956

CERCLIS-NFRAP Site Contact Name(s):

Contact Title: OTHR-RG-CO
Contact Name: GEORGE ZACHOS
Contact Tel: (732) 321-6621

CERCLIS-NFRAP Assessment History:

Action: NON-NPL PRP SEARCH
Date Started: 03/04/1998
Date Completed: Not reported
Priority Level: Not reported

Action: REMOVAL ASSESSMENT
Date Started: 03/04/1998
Date Completed: 04/28/1998
Priority Level: Not reported

Action: ADMINISTRATIVE RECORDS
Date Started: 05/31/1998
Date Completed: Not reported
Priority Level: Admin Record Compiled for a Removal Event

Action: REMOVAL
Date Started: 06/16/1998
Date Completed: 07/07/1998
Priority Level: Cleaned up

Action: DD
Date Started: Not reported
Date Completed: 07/03/2001
Priority Level: Not reported

Action: AM
Date Started: Not reported
Date Completed: 07/03/2001
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: Not reported
Date Completed: 09/30/2001
Priority Level: Not reported

Action: COMMUNITY INVOLVEMENT
Date Started: Not reported
Date Completed: Not reported
Priority Level: Not reported

AA110
North
1/4-1/2
0.426 mi.
2250 ft.

**BUFFALO CITY OF
208 BRISTOL AVE
BUFFALO, NY 14206**

Site 2 of 2 in cluster AA

**Relative:
Higher**

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: BUFFALO CITY OF
Facility address: 208 BRISTOL AVE
BUFFALO, NY 14206

**Actual:
591 ft.**

**RCRA-NonGen 1001203141
FINDS NYR000045039
MANIFEST**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

EPA ID: NYR000045039
Mailing address: CITY HALL
BUFFALO, NY 14202
Contact: Not reported
Contact address: CITY HALL
BUFFALO, NY 14202
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: CITY OF BUFFALO
Owner/operator address: 905 CITY HALL
BUFFALO, NY 14202
Owner/operator country: US
Owner/operator telephone: (716) 851-4852
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF BUFFALO
Owner/operator address: 905 CITY HALL
BUFFALO, NY 14202
Owner/operator country: US
Owner/operator telephone: (716) 851-4852
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: BUFFALO CITY OF

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Classification: Not a generator, verified

Date form received by agency: 06/29/1999

Facility name: BUFFALO CITY OF

Classification: Not a generator, verified

Date form received by agency: 02/24/1998

Facility name: BUFFALO CITY OF

Site name: CITY OF BUFFALO/DIV OF PLANNING

Classification: Large Quantity Generator

Date form received by agency: 09/22/1997

Facility name: BUFFALO CITY OF

Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110000814021

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYR000045039
Country: USA
Mailing Name: BUFFALO MUNICIPAL HOUSING AUTHORITY
Mailing Contact: DENNIS SUTTON
Mailing Address: 300 PERRY STREET
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14204
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-851-4852

Document ID: NYB7390206
Manifest Status: Completed copy
Trans1 State ID: 81241PNY
Trans2 State ID: Not reported
Generator Ship Date: 970926
Trans1 Recv Date: 970926
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970930
Part A Recv Date: 971113
Part B Recv Date: 971017
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD051809952

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 13245
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4700889
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 86240DNY
Trans2 State ID: Not reported
Generator Ship Date: 970929
Trans1 Recv Date: 970929
Trans2 Recv Date: Not reported
TSD Site Recv Date: 971001
Part A Recv Date: 971113
Part B Recv Date: 971029
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 11031
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Mgmt Method Type Code: Not reported

Document ID: NYB4700871
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 862400NY
Trans2 State ID: Not reported
Generator Ship Date: 970929
Trans1 Recv Date: 970929
Trans2 Recv Date: Not reported
TSD Site Recv Date: 971002
Part A Recv Date: 971113
Part B Recv Date: 971029
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 12955
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB7390215
Manifest Status: Completed copy
Trans1 State ID: 609145NY
Trans2 State ID: 862900NY
Generator Ship Date: 970929
Trans1 Recv Date: 970929
Trans2 Recv Date: 971002
TSD Site Recv Date: 971002
Part A Recv Date: 971113
Part B Recv Date: 971020
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: NYD051809952
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 14751
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB7390161
Manifest Status: Completed copy
Trans1 State ID: XG240DNY
Trans2 State ID: Not reported
Generator Ship Date: 970926
Trans1 Recv Date: 970926
Trans2 Recv Date: Not reported
TSD Site Recv Date: 971001
Part A Recv Date: 971113
Part B Recv Date: 971020
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 12882
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB7390197
Manifest Status: Completed copy
Trans1 State ID: 86240NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Trans2 State ID: Not reported
Generator Ship Date: 970926
Trans1 Recv Date: 970926
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970929
Part A Recv Date: 971113
Part B Recv Date: 971016
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 12819
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB4700862
Manifest Status: Completed copy
Trans1 State ID: 86240DNY
Trans2 State ID: Not reported
Generator Ship Date: 970929
Trans1 Recv Date: 970929
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970930
Part A Recv Date: 971113
Part B Recv Date: 971020
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 13381
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB7390188
Manifest Status: Completed copy
Trans1 State ID: 802400NY
Trans2 State ID: Not reported
Generator Ship Date: 970926
Trans1 Recv Date: 970926
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970929
Part A Recv Date: 971113
Part B Recv Date: 971016
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 12537
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8499717
Manifest Status: Not reported
Trans1 State ID: NYR000045724
Trans2 State ID: Not reported
Generator Ship Date: 07/07/1998
Trans1 Recv Date: 07/07/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/08/1998
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 71060NNY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 02613
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8817921
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 2216A2NY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 23877
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8817939
Manifest Status: Not reported
Trans1 State ID: NYD982792814
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/05/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/06/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 80362VNY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 20902
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8817948
Manifest Status: Not reported
Trans1 State ID: NYR000045724
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 64061NNY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Quantity: 21301
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8817957
Manifest Status: Not reported
Trans1 State ID: NYR000045724
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 69658ENY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 20693
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Document ID: NYB8817966
Manifest Status: Not reported
Trans1 State ID: NYR000045724
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 93451KNY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 20593
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8817975
Manifest Status: Not reported
Trans1 State ID: NYR000045724
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 93452KNY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 22444
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8817984
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 3172A1NY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 19858
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8817993
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 29614KNY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 21455
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8818002
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 3169A1NY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 23387
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8818344
Manifest Status: Not reported
Trans1 State ID: NYD982792814
Trans2 State ID: Not reported
Generator Ship Date: 05/07/1998
Trans1 Recv Date: 05/07/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/07/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 43473E
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 18625
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8818353
Manifest Status: Not reported
Trans1 State ID: NYD982792814
Trans2 State ID: Not reported
Generator Ship Date: 05/07/1998
Trans1 Recv Date: 05/07/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/07/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045039
Trans1 EPA ID: NYD049836679

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY OF (Continued)

1001203141

Trans2 EPA ID: Not reported
TSDF ID: 80362VNY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 17055
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

[Click this hyperlink](#) while viewing on your computer to access
6 additional NY_MANIFEST: record(s) in the EDR Site Report.

111
West
1/4-1/2
0.433 mi.
2286 ft.

NYSDOT D256989
HAMBURG & EXCHANGE ST CONRAIL
BUFFALO, NY 14203

RCRA-NonGen **1001124946**
FINDS **NYR000033209**
MANIFEST

Relative:
Equal

Actual:
590 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYSDOT D256989
Facility address: HAMBURG & EXCHANGE ST CONRAIL
RTE 16 HWY RECON REPLACE 3 BRG
BUFFALO, NY 14203
EPA ID: NYR000033209
Mailing address: GEN DOVOVAN BLDG 125 MAIN ST
BUFFALO, NY 142033088
Contact: LARRY GRAZIANO
Contact address: GEN DOVOVAN BLDG 125 MAIN ST
BUFFALO, NY 142033088
Contact country: US
Contact telephone: (716) 847-3122
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NYSDOT - EMINENT DOMAIN
Owner/operator address: GEN DONOVAN BLDG 125 MAIN ST
BUFFALO, NY 14203
Owner/operator country: US
Owner/operator telephone: (716) 847-3122

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT D256989 (Continued)

1001124946

Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT - EMINENT DOMAIN
Owner/operator address: GEN DONOVAN BLDG 125 MAIN ST
BUFFALO, NY 14203
Owner/operator country: US
Owner/operator telephone: (716) 847-3122
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: NYSDOT D256989
Classification: Not a generator, verified

Date form received by agency: 12/13/1996
Facility name: NYSDOT D256989
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110008097031

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT D256989 (Continued)

1001124946

NY MANIFEST:

EPA ID: NYR000033209
Country: USA
Mailing Name: NYSDOT BIN 2011980
Mailing Contact: EUGENE F WARDZINSKI
Mailing Address: GEN DONOVAN BLDG 125 MAIN ST
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14203
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-627-2222

Document ID: MAH7547180
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 13908MA
Trans2 State ID: 45946OR
Generator Ship Date: 961219
Trans1 Recv Date: 961219
Trans2 Recv Date: 961220
TSD Site Recv Date: 961226
Part A Recv Date: 970117
Part B Recv Date: 970116
Generator EPA ID: NYR000033209
Trans1 EPA ID: MOD095038998
Trans2 EPA ID: MOD095038998
TSDF ID: MAD000604447
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00010
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00350
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00750
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT D256989 (Continued)

1001124946

Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAJ3002100
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 13908MA
Trans2 State ID: 45946OR
Generator Ship Date: 961219
Trans1 Recv Date: 961219
Trans2 Recv Date: 961220
TSD Site Recv Date: 961226
Part A Recv Date: 970117
Part B Recv Date: 970116
Generator EPA ID: NYR000033209
Trans1 EPA ID: MOD095038998
Trans2 EPA ID: MOD095038998
TSDF ID: MAD000604447
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00010
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00150
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDOT D256989 (Continued)

1001124946

Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Z112
WNW
1/4-1/2
0.442 mi.
2336 ft.

**ZINSSER CO INC AT SCHNITTERS WAREHOUSE
519 HAMBURG ST
BUFFALO, NY 14204**

**RCRA-NonGen
FINDS
MANIFEST**

1001119614
NYR000029033

Site 2 of 2 in cluster Z

**Relative:
Lower**

**Actual:
589 ft.**

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: ZINSSER CO INC AT SCHNITTERS WAREHOUSE
Facility address: 519 HAMBURG ST
BUFFALO, NY 14215
EPA ID: NYR000029033
Mailing address: BELMONT DR
SOMERSET, NJ 08873
Contact: DANIEL H KLEIN
Contact address: BELMONT DR
SOMERSET, NJ 08873
Contact country: US
Contact telephone: (908) 874-7888
Contact email: DCSINC1@EARTHLINK.NET
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: MESMER REFRIGERATION
Owner/operator address: 519 HAMBURG ST
BUFFALO, NY 14204
Owner/operator country: US
Owner/operator telephone: (716) 855-0576
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SCHNITTERS WAREHOUSE
Owner/operator address: HAMBURG ST
BUFFALO, NY 14215
Owner/operator country: US
Owner/operator telephone: (908) 874-7888
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/04/2004
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZINSSER CO INC AT SCHNITTERS WAREHOUSE (Continued)

1001119614

Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: ZINSSER CO INC AT SCHNITTERS WAREHOUSE
Classification: Not a generator, verified

Date form received by agency: 08/31/2004
Facility name: ZINSSER CO INC AT SCHNITTERS WAREHOUSE
Classification: Not a generator, verified

Date form received by agency: 05/06/2004
Facility name: ZINSSER CO INC AT SCHNITTERS WAREHOUSE
Classification: Small Quantity Generator

Date form received by agency: 07/08/1999
Facility name: ZINSSER CO INC AT SCHNITTERS WAREHOUSE
Site name: V G C CORP
Classification: Not a generator, verified

Date form received by agency: 09/10/1996
Facility name: ZINSSER CO INC AT SCHNITTERS WAREHOUSE
Site name: V G C CORP
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 08/26/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004528271

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZINSSER CO INC AT SCHNITTERS WAREHOUSE (Continued)

1001119614

corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYR000029033
Country: USA
Mailing Name: V G C CORP
Mailing Contact: KENNETH PEARCE
Mailing Address: 519 HAMBURG STREET
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14204
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-834-5632

Document ID: NJA2693726
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 960906
Trans1 Recv Date: 960906
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960917
Part A Recv Date: Not reported
Part B Recv Date: 961010
Generator EPA ID: NYR000029033
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 06972
Units: P - Pounds
Number of Containers: 016
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00458
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00545
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZINSSER CO INC AT SCHNITTERS WAREHOUSE (Continued)

1001119614

Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: TXA0070375
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 99999
Trans2 State ID: 40582
Generator Ship Date: 960916
Trans1 Recv Date: 960916
Trans2 Recv Date: 960924
TSD Site Recv Date: 961006
Part A Recv Date: 960926
Part B Recv Date: 961113
Generator EPA ID: NYR000029033
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: NYD980769947
TSDF ID: TXD077603371
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00527
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA2693775
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 960916
Trans1 Recv Date: 960916
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960924
Part A Recv Date: 960926
Part B Recv Date: 961018

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZINSSER CO INC AT SCHNITTERS WAREHOUSE (Continued)

1001119614

Generator EPA ID: NYR000029033
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F003 - UNKNOWN
Quantity: 04367
Units: P - Pounds
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 01700
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 01230
Units: P - Pounds
Number of Containers: 030
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA2693776
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 960916
Trans1 Recv Date: 960916
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960924
Part A Recv Date: 960926
Part B Recv Date: 961018
Generator EPA ID: NYR000029033
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00340
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZINSSER CO INC AT SCHNITTERS WAREHOUSE (Continued)

1001119614

Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00715
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA2693729
Manifest Status: Completed after the designated time period for a TSDf to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 960913
Trans1 Recv Date: 960913
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960920
Part A Recv Date: 960926
Part B Recv Date: 961008
Generator EPA ID: NYR000029033
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDf ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00872
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 03275
Units: P - Pounds
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 01501
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZINSSER CO INC AT SCHNITTERS WAREHOUSE (Continued)

1001119614

Number of Containers: 036
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 01363
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA2693725
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 960906
Trans1 Recv Date: 960906
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960919
Part A Recv Date: 960920
Part B Recv Date: 961008
Generator EPA ID: NYR000029033
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F003 - UNKNOWN
Quantity: 06550
Units: P - Pounds
Number of Containers: 012
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 02179
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZINSSER CO INC AT SCHNITTERS WAREHOUSE (Continued)

1001119614

Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA2693724
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: S00602
Generator Ship Date: 960913
Trans1 Recv Date: 960913
Trans2 Recv Date: 961008
TSD Site Recv Date: 961012
Part A Recv Date: 960926
Part B Recv Date: 961211
Generator EPA ID: NYR000029033
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: NYD980769947
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00490
Units: P - Pounds
Number of Containers: 014
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00083
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 02712
Units: P - Pounds
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ZINSSER CO INC AT SCHNITTERS WAREHOUSE (Continued)

1001119614

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NJA2683725
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 960906
Trans1 Recv Date: 960906
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960917
Part A Recv Date: Not reported
Part B Recv Date: 970124
Generator EPA ID: NYR000029033
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F003 - UNKNOWN
Quantity: 06550
Units: P - Pounds
Number of Containers: 012
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 02579
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

113
ESE
1/4-1/2
0.445 mi.
2352 ft.

BATTAGLIA TRUCKING
1037 SENECA ST
BUFFALO, NY 14210

RCRA-NonGen 1006810474
FINDS NYR000112763
SWF/LF

Relative:
Higher

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: BATTAGLIA TRUCKING
Facility address: 1037 SENECA ST
BUFFALO, NY 14210

Actual:
599 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BATTAGLIA TRUCKING (Continued)

1006810474

EPA ID: NYR000112763
Mailing address: BULLIS RD
ELMA, NY 14059
Contact: PETER J BATTAGLIA
Contact address: BULLIS RD
ELMA, NY 14059
Contact country: US
Contact telephone: (716) 827-5421
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: PETER BATTAGLIA
Owner/operator address: BULLIS RD
ELMA, NY 14059
Owner/operator country: US
Owner/operator telephone: (716) 674-0463
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/10/2002
Owner/Op end date: Not reported

Owner/operator name: BATTAGLIA TRUCKING
Owner/operator address: SENECA ST
BUFFALO, NY 14210
Owner/operator country: US
Owner/operator telephone: (716) 827-5421
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/10/2002
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: BATTAGLIA TRUCKING

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BATTAGLIA TRUCKING (Continued)

1006810474

Classification: Not a generator, verified

Date form received by agency: 01/10/2002
Facility name: BATTAGLIA TRUCKING
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110014358827

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SWF/LF:

Flag: ACTIVE
Region Code: 9
Phone Number: 7166740463
Owner Name: Battaglia Demolition; Inc.
Owner Type: Private
Owner Address: 611 Bullis Road
Owner Addr2: Not reported
Owner City,St,Zip: Elma, NY 14059
Owner Email: Not reported
Owner Phone: 7166740463
Contact Name: Peter Battaglia; Jr.
Contact Address: 611 Bullis Road
Contact Addr2: Not reported
Contact City,St,Zip: Elma, NY 14059
Contact Email: Not reported
Contact Phone: 7166740463
Activity Desc: C&D processing - regulated
Activity Number: 15W31
Active: Yes
East Coordinate: 186229
North Coordinate: 4753444
Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
Regulatory Status: Permit
Waste Type: Construction & Demolition Debris;Brick;Concrete;Rock;Wood (Clean);Wood (Contaminated)
Authorization #: 9-1402-00897/00001
Authorization Date: 2/14/2008
Expiration Date: 2/13/2013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AB114 NYSDEC/SPILL
WNW 550 SENECA ST
1/4-1/2 BUFFALO, NY 14200
0.462 mi.
2440 ft.

RCRA-NonGen 1007205432
MANIFEST NYP000933515

Site 1 of 2 in cluster AB

Relative:
Higher

Actual:
596 ft.

RCRA-NonGen:
Date form received by agency: 03/03/1998
Facility name: NYSDEC/SPILL
Facility address: 550 SENECA ST
BUFFALO, NY 142000000
EPA ID: NYP000933515
Mailing address: 50 WOLF RD
ALBANY, NY 122330000
Contact: REPORTING SECTION
Contact address: 50 WOLF RD
ALBANY, NY 122330000
Contact country: US
Contact telephone: (518) 457-0532
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: Unknown
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: Unknown
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: Unknown
Used oil processor: Unknown
User oil refiner: Unknown
Used oil fuel marketer to burner: Unknown
Used oil Specification marketer: Unknown
Used oil transfer facility: Unknown
Used oil transporter: Unknown
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 03/02/1998
Facility name: NYSDEC/SPILL
Classification: Not a generator, verified

Date form received by agency: 03/01/1998
Facility name: NYSDEC/SPILL
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP000933515
Country: USA
Mailing Name: NYSDEC - REGION 9
Mailing Contact: NYSDEC - REGION 9

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDEC/SPILL (Continued)

1007205432

Mailing Address: 270 MICHIGAN AVE
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14203
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-851-7220

Document ID: NJA2601345
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: S50060
Trans2 State ID: S50060
Generator Ship Date: 970304
Trans1 Recv Date: 970304
Trans2 Recv Date: 970305
TSD Site Recv Date: 970319
Part A Recv Date: 970428
Part B Recv Date: 970428
Generator EPA ID: NYP000933515
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: NYD980761191
TSDF ID: NJD002200046
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00030
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00385
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYSDEC/SPILL (Continued)

1007205432

Mgmt Method Type Code: Not reported

115
South
1/4-1/2
0.462 mi.
2441 ft.

#33 BILINGUAL CENTER
157 ELK STREET
BUFFALO, NY 14210

UST U004122331
N/A

Relative:
Higher

Actual:
595 ft.

UST:

Facility Id: 9-601019
Region: STATE
DEC Region: 9
Site Status: Active
Program Type: PBS
Expiration Date: 2013/04/11
UTM X: Not reported
UTM Y: Not reported
Site ID: 396222

Tank Number: 1
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 9/1/2006
Capacity Gallons: 10000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: Not reported
Tank ID: 222418
Tank Location: 5
Tank Type: Equivalent technology
Date Test: Not reported
Register: True
Trade Sec: False
Modified By: LDGOMEZ
Last Modified: 4/11/2008

UST_PBS_BSAFFIL:

Site Id: 396222
Program Number: 9-601019
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: C01
Company Name: BUFFALO BOARD OF EDUCATION
Contact Type: ASSISTANT ENGINEER
Contact Name: WILLIAM MOSS
Address1: 65 NIAGARA SQUARE, ROOM 406
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14202
Country Code: 001
Phone: (716) 816-3048
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

#33 BILINGUAL CENTER (Continued)

U004122331

Date Last Modified: 4/11/2008

Site Id: 396222
Program Number: 9-601019
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: BUFFALO BOARD OF EDUCATION
Contact Type: Not reported
Contact Name: WILLIAM MOSS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 816-3048
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 4/11/2008

Site Id: 396222
Program Number: 9-601019
Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN
Company Name: BUFFALO BOARD OF EDUCATION
Contact Type: Not reported
Contact Name: WILLIAM MOSS
Address1: 65 NIAGARA STREET, ROOM 406
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14202
Country Code: 001
Phone: (716) 816-3048
Phone Ext: Not reported
Email: WMOSS@BUFFALOSCHOOLS.ORG
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 4/11/2008

Site Id: 396222
Program Number: 9-601019
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: #33 BILINGUAL CENTER
Contact Type: Not reported
Contact Name: KEVIN STESIAK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

#33 BILINGUAL CENTER (Continued)

U004122331

Country Code: 001
Phone: (716) 816-4554
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 4/11/2008

UST_AST_PBS_BSEQUIP:

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

#33 BILINGUAL CENTER (Continued)

U004122331

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: D11
Code Name: Flexible Piping
Type: Pipe Type

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Site Id: 396222
Tank Id Number: 222418
Tank Number: 1
Equipment: F05
Code Name: Jacketed
Type: Pipe External Protection

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

116 WNY PROFESSIONAL FLOORING; INC.
WNW 505 HAMBURG STREET
1/4-1/2 BUFFALO, NY 14220
0.472 mi.
2495 ft.

SWRCY S108468377
N/A

Relative:
Equal

SWRCY:

Actual:
590 ft.

Region: 9
Facility Address 2: Not reported
Phone Number: 7168643875
Owner Type: Private
Owner Name: Karol Kellner
Owner Address: 505 Hamburg Street
Owner Address 2: Not reported
Owner City,St,Zip: Buffalo, NY 14220
Owner Email: Not reported
Owner Phone: 7168520262
Contact Name: Not reported
Contact Address: Not reported
Contact Address 2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Source separated solid waste recyclables
Activity Number: 15M19
Active: Yes
East Coordinate: 184985
North Coordinate: 4754382
Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
Regulatory Status: Registration
Permit #: 15M19
Auth. Date: 3/15/2007
Expiration Date: Not reported
Waste Types: Not reported

AB117 CENTRAL AUTO
WNW 541 SENECA ST
1/4-1/2 BUFFALO, NY 14202
0.479 mi.
2527 ft.

RCRA-NonGen 1001489164
FINDS NYR000072058
MANIFEST

Relative:
Higher

RCRA-NonGen:

Actual:
591 ft.

Date form received by agency: 01/01/2007
Facility name: CENTRAL AUTO
Facility address: 541 SENECA ST
BUFFALO, NY 14202
EPA ID: NYR000072058
Mailing address: CITY HALL
BUFFALO, NY 14202
Contact: DENNIS SUTTON
Contact address: CITY HALL
BUFFALO, NY 14202
Contact country: US
Contact telephone: (716) 851-4852
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRAL AUTO (Continued)

1001489164

Owner/Operator Summary:

Owner/operator name: CITY OF BUFFALO
Owner/operator address: 901 CITY HALL
BUFFLO, NY 14202
Owner/operator country: US
Owner/operator telephone: (716) 851-4852
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF BUFFALO
Owner/operator address: 901 CITY HALL
BUFFLO, NY 14202
Owner/operator country: US
Owner/operator telephone: (716) 851-4852
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: CENTRAL AUTO
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Facility name: CENTRAL AUTO
Site name: CITY OF BUFFALO-541 SENECA ST
Classification: Large Quantity Generator

Date form received by agency: 06/07/1999
Facility name: CENTRAL AUTO
Classification: Small Quantity Generator

Violation Status: No violations found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRAL AUTO (Continued)

1001489164

FINDS:

Registry ID: 110004553484

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYR000072058
Country: USA
Mailing Name: BUFFALO CITY OF-DEPT OF COMM DEVELOPMENT
Mailing Contact: DENNIS SUTTON
Mailing Address: 901 CITY HALL
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14202
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-851-4852

Document ID: MAM2724030
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: Not reported
Generator Ship Date: 07/01/1999
Trans1 Recv Date: 07/01/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/07/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072058
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSDF ID: MA38323
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00005
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00400
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRAL AUTO (Continued)

1001489164

Waste Code: F001 - UNKNOWN
Quantity: 00550
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAM2724040
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: Not reported
Generator Ship Date: 07/01/1999
Trans1 Recv Date: 07/01/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/07/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072058
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSD ID: MA38323
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00650
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 01380
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00070
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRAL AUTO (Continued)

1001489164

Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAM2724050
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: Not reported
Generator Ship Date: 07/01/1999
Trans1 Recv Date: 07/01/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/07/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072058
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSDF ID: MA38323
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00007
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00045
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRAL AUTO (Continued)

1001489164

Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAM2724060
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: Not reported
Generator Ship Date: 07/01/1999
Trans1 Recv Date: 07/01/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/07/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072058
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSDF ID: MA38323
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00130
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRAL AUTO (Continued)

1001489164

Document ID: MAM2724090
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: Not reported
Generator Ship Date: 07/01/1999
Trans1 Recv Date: 07/01/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/01/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072058
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSDF ID: MA38323
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00040
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: PAE7919483
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: MOD095038998
Generator Ship Date: 07/01/1999
Trans1 Recv Date: 07/01/1999
Trans2 Recv Date: 07/07/1999
TSD Site Recv Date: 07/19/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072058
Trans1 EPA ID: PAD981113749
Trans2 EPA ID: Not reported
TSDF ID: PAAHMA383

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRAL AUTO (Continued)

1001489164

Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00173
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

AC118
NE
1/4-1/2
0.497 mi.
2626 ft.

**SCHOOL 40
89 CLARE STREET
BUFFALO, NY**

**LTANKS S106123918
N/A**

Site 1 of 2 in cluster AC

**Relative:
Higher**

**Actual:
596 ft.**

LTANKS:
Site ID: 84878
Spill No: 0375440
Spill Date: 1/5/2004
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: No spill occurred. No DEC Response. No corrective action required.
Spill Closed Dt: 12/10/2004
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 1502
Investigator: JFOTTO
Referred To: Not reported
Reported to Dept: 1/5/2004
CID: 30
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 11/5/2004
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/5/2004
Spill Record Last Update: 12/10/2004
Spiller Name: WILLIAM MOSS
Spiller Company: BUFFALO BOARD OF EDUCATIO
Spiller Address: Not reported
Spiller City,St,Zip: BUFFALO, NY 14202-
Spiller County: 001
Spiller Contact: ROLLEY GARDNER
Spiller Phone: (706) 851-3806

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCHOOL 40 (Continued)

S106123918

Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 78027
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JFO" 05/26/04 JFO TELCON WITH BILL MOSS. THEY ARE HAVING A MEETING NEXT WEEK TO DISCUSS WEATHER OF NOT THEY CAN EXCAVATE SAFELY WHILE SCHOOL IS IN SESSION. HE WILL GET BACK TO ME. 11/05/04 JFO CALL FROM ENV SRV GROUP. BOB LENHART SAID THEY REMOVED THE TANK ON OCTOBER 12, AND FOUND NO CONTAMINATION. THEY SAMPLED THE SIDEWALLS AND BOTTOM FOR 8260 AND 8270 STARS. THEY DID NOTIFY PBS. THE HOLE IS STILL OPEN AND I WILL INSPECT. THEY FAXED THE RESULTS, ALL COMPOUNDS ARE BELOW STARS. 11/05/04 JFO ON SITE NO ONE AVAILABLE. THE HOLE LOOKS CLEAN. THERE IS EXCAVATED SOIL ON SITE BUT THERE IS NO ODORS OR VISUAL CONTAMINATION. THERE ARE 9 DRUMS ON SITE FOR DISPOSAL. 11/09/04 JFO CALL TO BOB LENHART. HE WILL SEND RECEIPTS FOR THE TANK BOTTOMS AND DRUMS OF CONTAMINATED WATER. 12/02/04 JFO CALL TO BILL MOSS FOR THE DISPOSAL RECEIPTS FOR THE DRUMS. LEFT A MESSAGE ON HIS MACHINE. 12/10/04 JFO RECEIVED THE RECEIPTS FOR THE TANK BOTTOMS (13 DRUMS). NO FURTHER ACTION REQUIRED. CLOSED
Remarks: tank test failure

Material:

Site ID: 84878
Operable Unit ID: 882270
Operable Unit: 01
Material ID: 559928
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AC119 SCHOOL #40
NE 89 CLARE ST
1/4-1/2 BUFFALO, NY 14206
0.497 mi.
2626 ft. Site 2 of 2 in cluster AC

UST U003318046
HIST UST N/A

Relative:
Higher

Actual:
596 ft.

UST:

Facility Id: 9-425486
Region: STATE
DEC Region: 9
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 186305.65937000001
UTM Y: 4754746.35230000004
Site ID: 54111

Tank Number: 1
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 12/1/1974
Capacity Gallons: 10000
Tightness Test Method: 03
Next Test Date: Not reported
Date Tank Closed: 10/12/2004
Tank ID: 167287
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 8/1/1998
Register: True
Trade Sec: False
Modified By: AESKALSK
Last Modified: 1/25/2005

UST_PBS_BSAFFIL:

Site Id: 54111
Program Number: 9-425486
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: C01
Company Name: BUFFALO BOARD OF EDUCATION
Contact Type: Not reported
Contact Name: Not reported
Address1: 65 NIAGARA SQUARE ROOM 406
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14206
Country Code: 001
Phone: (716) 851-3028
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 54111
Program Number: 9-425486

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCHOOL #40 (Continued)

U003318046

Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN
Company Name: BUFFALO BOARD OF EDUCATION
Contact Type: Not reported
Contact Name: WILLIAM MOSS
Address1: RM 406 CITY HALL
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14206
Country Code: 001
Phone: (716) 851-3028
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 54111
Program Number: 9-425486
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: BUFFALO BOARD OF EDUCATION
Contact Type: Not reported
Contact Name: WILLIAM MOSS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (716) 851-3028
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: BFGRABER
Date Last Modified: 8/6/2007

Site Id: 54111
Program Number: 9-425486
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: SCHOOL #40
Contact Type: Not reported
Contact Name: KEVIN STESIAK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 851-3806
Phone Ext: Not reported
Email: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCHOOL #40 (Continued)

U003318046

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

UST_AST_PBS_BSEQUIP:

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCHOOL #40 (Continued)

U003318046

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Site Id: 54111
Tank Id Number: 167287
Tank Number: 1
Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

HIST UST:

PBS Number: 9-425486
SPDES Number: Not reported
Emergency Contact: NONE
Emergency Telephone: (716) 851-3612
Operator: RALEIGH GARDNER
Operator Telephone: (716) 851-3806
Owner Name: BUFFALO BOARD OF EDUCATION
Owner Address: PLANT DEPT 406 CITY HALL
Owner City,St,Zip: BUFFALO, NY 14206
Owner Telephone: (716) 851-3612
Owner Type: Local Government
Owner Subtype: Not reported
Mailing Name: BUFFALO BOARD OF EDUCATION
Mailing Address: RM 406 CITY HALL
Mailing Address 2: Not reported
Mailing City,St,Zip: BUFFALO, NY 14206
Mailing Contact: DAVID F. BAKER, P.E.
Mailing Telephone: (716) 842-3269
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Facility Addr2: Not reported
SWIS ID: 1402
Old PBS Number: Not reported
Facility Type: SCHOOL
Inspected Date: 19950403
Inspector: BAJ
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 09/10/1998
Expiration Date: 12/14/2002
Renew Flag: False
Renewal Date: 19921001
Total Capacity: 10000
FAMT: True
Facility Screen: No Missing Data

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCHOOL #40 (Continued)

U003318046

Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: BUFFALO (C)
County Code: 14
Town or City: 02
Region: 9

Tank Id: 1
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 19741201
Capacity (gals): 10000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 10
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 10
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: 08/01/1998
Next Test Date: 08/01/2003
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

120
South
1/4-1/2
0.498 mi.
2629 ft.

BUFFALO COLOR CORPORATION SITE AREA C
229 ELK STREET
BUFFALO, NY 14210

BROWNFIELDS S109059138
N/A

Relative:
Higher

BROWNFIELDS:

Program: BCP
Site Code: 394151

Actual:
592 ft.

Site Description: There had been continuous production of dyestuffs and organic chemicals at the facility for over 100 years. On July, 1, 1977 Buffalo Color Corporation (BCC) purchased certain assets from Allied Chemical (Honeywell), including the plant and the right to produce certain chemicals. In 1995, NYSDEC issued a Part 373 Post-Closure Permit to BCC. The permit required BCC to conduct a RCRA Facility Investigation for the site. Various remedial alternatives were examined in more detail in a Corrective Measures Study Report for BCC, dated January 2000. BCC filed for bankruptcy in 2003. The Property, located in an industrial area in the City of Buffalo, Erie County, New York, occupies approximately 6.03 acres along the south side of Elk Street and the west side of Lee Street. The area surrounding the Property is generally zoned for heavy industry and has been utilized for heavy industrial activity since the mid-1800s.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION SITE AREA C (Continued)

S109059138

CSX railroad tracks are located to the west of the Property. Honeywell International is located to the north, and PVS Chemicals, Inc. is located to the southeast of the Property. The former Exxon Mobil refinery and bulk petroleum terminal is located to the east of PVS Chemicals. Areas A and B of the Buffalo Color Site are located to the south. The nearest residential areas are located approximately 1,000 feet north and east of the Property. In 2005 Honeywell entered into an Order on Consent to address groundwater contamination at the site by designing and installing an interim groundwater collection system. This collection system is currently operational but does not stop all migration of groundwater towards the Buffalo River. Honeywell completed a bulk chemical removal at the Site in 2007. Honeywell entered into an Order on Consent to perform an RI/FS in 2006. The RIFS was completed in 2008 and is the basis for a Brownfield Cleanup remedial work plan submitted in early 2009. The land has been used for the production of dyestuff and organic chemicals for more than one hundred years. Dyestuff production began in the late 1800s and continued until 2003, when operations ceased. The future use for this site is for commercial and industrial. The known contaminants at this site are petroleum, chlorinated solvents, other VOCs, SVOCs and metals which are impacting the soil and groundwater. The Brownfield Cleanup Plan application has been approved as of April 27, 2009. The Remedial Work Plan was approved in May 2009. Design activities will continue into 2010.

Env Problem: Very few volatile organic compounds (VOCs) are found on site. However, metals such as mercury, lead and arsenic are found in the surface and subsurface soil. Semi-volatiles are found throughout Area C. The fill and upper portion of the native silt and clay soils is often stained. The shallow groundwater contains concentrations of chlorobenzene and aniline. Various metals and inorganic compounds are found in the groundwater. The deep groundwater is only slightly impacted.

Health Problem: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

AD121
ESE
1/2-1
0.534 mi.
2821 ft.

CTS CRUSHING & RECYCLING
1070 SENECA STREET
BUFFALO, NY 14240

SWF/LF S105841298
N/A

Relative:
Equal

Actual:
590 ft.

Site 1 of 3 in cluster AD

SWF/LF:
Flag: ACTIVE
Region Code: 9
Phone Number: Not reported
Owner Name: CTS Crushing & Recycling
Owner Type: Private
Owner Address: 320 Crabapple Lane
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14227
Owner Email: Not reported
Owner Phone: 7166684444
Contact Name: Michael Fronckowiak
Contact Address: 320 Crabapple Lane
Contact Addr2: Not reported
Contact City,St,Zip: Cheektowaga, NY 14227
Contact Email: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CTS CRUSHING & RECYCLING (Continued)

S105841298

Contact Phone: 7166684444
Activity Desc: C&D processing - registered
Activity Number: 15W33
Active: Yes
East Coordinate: 186498
North Coordinate: 4753757
Accuracy Code: Not reported
Regulatory Status: Registration
Waste Type: Not reported
Authorization #: 15W33
Authorization Date: 2/23/2001
Expiration Date: Not reported

AD122
ESE
1/2-1
0.534 mi.
2821 ft.

LEAKING TANK ON AUTO
SENECA / PEABODY STREET
BUFFALO, NY

Site 2 of 3 in cluster AD

LTANKS **S102234164**
HIST LTANKS **N/A**

Relative:
Equal

Actual:
590 ft.

LTANKS:
Site ID: 244083
Spill No: 9603814
Spill Date: 6/19/1996
Spill Cause: Tank Failure
Spill Source: Passenger Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 6/20/1996
Facility Addr2: Not reported
Cleanup Ceased: 6/20/1996
Cleanup Meets Standard: True
SWIS: 1502
Investigator: FXGALLEG
Referred To: Not reported
Reported to Dept: 6/19/1996
CID: 196
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: 6/20/1996
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 6/19/1996
Spill Record Last Update: 10/8/1999
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: REFUSED
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 200471
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FG" 6/20/96 SITE VISIT. NO GASOLINE PUDDLES FOUND. ALL HAD BEEN FLUSHED AWAY AS IT HAD JUST RAINED. NO FURTHER ACTION NECESSARY. SITE CAN BE CLOSED.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LEAKING TANK ON AUTO (Continued)

S102234164

Remarks: CALLER STATES THAT A GAS TANK ON A VAN BROKE. BUFFALO CITY FIRE DEPT. DID ARRIVE ON THE SCENE. FIREFIGHTERS FLUSHED GAS DOWN THE SEWER. CALLER STATES THAT PUDDLES ARE STILL ON THE SIDE OF THE STREET.

Material:

Site ID: 244083
Operable Unit ID: 1031453
Operable Unit: 01
Material ID: 350093
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Sewer
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:

Region of Spill: 9
Spill Number: 9603814
Spill Date: 06/19/1996
Spill Time: 16:00
Spill Cause: Tank Failure
Resource Affectd: In Sewer
Water Affected: Not reported
Spill Source: Passenger Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 06/20/96
Cleanup Ceased: 06/20/96
Cleanup Meets Standard: True
Investigator: FG
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 06/19/96

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LEAKING TANK ON AUTO (Continued)

S102234164

Reported to Department Time: 20:14
SWIS: 14
Spiller Contact: REFUSED
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Citizen
PBS Number: Not reported
Last Inspection: 06/20/96
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 06/19/96
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/08/99
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929

DEC Remarks: 6/20/96 SITE VISIT. NO GASOLINE PUDDLES FOUND. ALL HAD BEEN FLUSHED AWAY AS IT HAD JUST RAINED. NO FURTHER ACTION NECESSARY. SITE CAN BE CLOSED.
Spill Cause: CALLER STATES THAT A GAS TANK ON A VAN BROKE. BUFFALO CITY FIRE DEPT. DID ARRIVE ON THE SCENE. FIREFIGHTERS FLUSHED GAS DOWN THE SEWER. CALLER STATES THAT PUDDLES ARE STILL ON THE SIDE OF THE STREET.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AD123 VACANT LOT
ESE 1070 SENECA STREET
1/2-1 BUFFALO, NY
0.534 mi.
2821 ft. Site 3 of 3 in cluster AD

SWF/LF S104653506
LTANKS N/A
NY Spills
NY Hist Spills

Relative:
Equal

SWF/LF:

Flag: ACTIVE
Region Code: 9
Phone Number: 7164401877
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: Steve Johnson
Contact Address: Wood to Fuel; LLC
Contact Addr2: 1212 Abbott Road
Contact City,St,Zip: Lackawanna, NY 14128
Contact Email: Not reported
Contact Phone: 7164401877
Activity Desc: Composting - yard waste - registered
Activity Number: 15Y19
Active: Yes
East Coordinate: 186474
North Coordinate: 4753837
Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
Regulatory Status: Registration
Waste Type: Not reported
Authorization #: 15Y19
Authorization Date: 9/30/2008
Expiration Date: Not reported

LTANKS:

Site ID: 197112
Spill No: 0300655
Spill Date: 4/18/2003
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 8/6/2003
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 1502
Investigator: MXFRANKS
Referred To: Not reported
Reported to Dept: 4/18/2003
CID: 30
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 4/18/2003
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/18/2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VACANT LOT (Continued)

S104653506

Spill Record Last Update: 8/6/2003
Spiller Name: GREG KURK
Spiller Company: KURK OIL
Spiller Address: 2130 CLINTON ST
Spiller City,St,Zip: BUFFALO, NY 14206-
Spiller County: 001
Spiller Contact: DON GERRY
Spiller Phone: (716) 668-4444
Spiller Extension: Not reported
DEC Region: 9
DER Facility ID: 164068
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MF" 04/18/03: MF S/I/GREG KURK, RP/DON GERRY, CUSTOM TOP SOIL, SITE
OWNER/C&W, CARL CROSSEN, RON. KURK OIL OVERFILLED SITE DIESEL TANKER
TRUCK. LOST APPX 20 GALLONS TO THE SURFACE. NO DRAINS INVOLVED. C&W
TO REMEDIATE. 04/22/03: MF LETTER SENT. 05/13/03: MF RECEIVED FAX OF
EXCAVATION SAMPLING RESULTS. 8021 STARS & 8270 STARS. WALLS - MTBE -
255 NAPHTHALENE - 625 8270 - BDL'S BOTTOM - MTBE - 265 8270 - BDL'S
05/23/03: MF RECEIVED REPORT WITH SOIL DISPOSAL RECEIPTS. THEY WANT
CLOSURE. 08/06/03: MF 'I' LETTER TO RP DUE TO MTBE OVER TAGM.
Remarks: SMALLER TRUCK ON SITE TO TRANSPORT FUEL TO OTHER VEHICLES - WHILE
FILLING THE SMALL TANKER - IT WAS OVERFILLED

Material:
Site ID: 197112
Operable Unit ID: 867012
Operable Unit: 01
Material ID: 508730
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Spills:
Site ID: 104772
Facility Addr2: Not reported
Facility ID: 0075152
Spill Number: 0075152

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VACANT LOT (Continued)

S104653506

Facility Type: ER
SWIS: 1502
Investigator: RJJONAK
Referred To: Not reported
Spill Date: 6/1/2000
Reported to Dept: 6/8/2000
CID: 30
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: 3/19/2001
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 5/11/2001
Remediation Phase: 0
Date Entered In Computer: 6/8/2000
Spill Record Last Update: 5/14/2003
Spiller Name: Not reported
Spiller Company: HARRISON INDUSTRIAL PARK
Spiller Address: PO BOX 1001
Spiller City,St,Zip: BUFFALO, NY 14240-
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 92488
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"RJJ" 6/13/2000:RJJ SITE INVESTIGATION AT 1000...MEET WITH RICH
CROUCH,BARRON & ASSOCIATES,HE STARTED TO DIG TEST PITS,AT VARIOUS
LOCATIONS,IN THE 30 ACRES OF PROPERTY,WHICH IS AT 1070 SENECA
ST...ONE OF THE PITS HAD A HIGH PID READING AND AN ODOR...RICH TOLD
ME THAT THE CURRENT OWNER OF THE PROPERTY IS HARRISON INDUSTRIAL PARK
INC.,ADDRESS,P.O. BOX 1011,BUFFALO,N.Y. 14240...THE SBL # OF THE
PROPERTY IS 122.36-1-2.11...I WILL DRAFT AND SEND HARRISON A
RESPONSIBLE PARTY LETTER...RICH ALSO SAID THAT THE CLIENT,WHICH WANTS
TO PURCHASE THE PROPERTY,MAY DO THE REMEDIATION...HE WILL GET BACK TO
ME ON HIS FINDINGS. 6/15/2000:TED KOSIOR,HARRISON INDUSTRIAL
PARK,INC.,TELECON RJJ...HE WANTED TO KNOW WHY I SENT HIM THE
'REPOSNSIBLE PARTY LETTER'...I TOLD HIM THAT RICH CROUCH,FROM BARRON
ASSOCIATES,DUG SOME TEST PITS AND IN ONE OF THEM,THEY FOUND PETROLEUM
ODORS...TED WILL CONTACT RICH AND GET BACK TO ME ON THEIR NEXT
STEP-OF-ACTION. 9/5/2000:BILL HEITZENRATER,AFI,TELECON RJJ,BILL SAID
THAT HE WILL BE HANDLING THIS SITE FOR INDUSTRIAL REALTORS,PART OF
HARRISON PROPERITES,THE PROPERTY OWNERS...HE WANTED TO KNOW WHAT I
KNEW OF THIS SITE,I TOLD HIM THAT I WAS WAITING FOR THE PHASE 11
REPORT FROM RICH CROUCH,TO DETERMINE WHAT THE EXTENT OF CONTAMINATION
ON THIS SITE IS...BILL WILL CONTACT RICH AND GET THE REPORT AND THAN
SEND ME HIS REPORT AND ACTION PLAN...BILL TELEPHONE # IS
(716)283-7645 CELL PHONE # 622-6008. 9/7/2000:RECEIVED A LETTER FROM
BILL HEITZENRATER EXPLAING THAT THEY WILL SEND ME THEIR INVESTIGATION
PLAN IN ABOUT 3 WEEKS. 9/22/2000:RECEIVED THE PHASE 11 SITE WORK PLAN
FROM AFI ,AND TALKED WITH BILL HEITZENRATER AND TOLD HIM THAT I

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VACANT LOT (Continued)

S104653506

APPROVE THIS PLAN...HE WILL CALL ME WHEN THEY START. 9/27/2000:BILL HEITZENRATER TELECON RJJ SAID THAT THEY WILL START REMEDIATING THE SITE TOMORROW...THEY WILL EXCAVATE 3 AREAS,WHERE THEY ENCOUNTERED HIGH PID READINGS,AND STAGE THE SOIL ON PLASTIC. 11/22/2000: RECEIVED THE PHASE 11 ENVIRONMENTAL SITE ASSESSMENT FROM AFI...THE SOIL ANALYTICAL CAME BACK ALL BELOW OUR 'STARS',BUT THEY WANT TO BIO THE CONTAMINATED SOIL ON THE PARCAL OF LAND,THAT THEY ARE NOT BUYING,BUT STILL OWNED BY HARRISON INDUSTRIAL...I TALKED WITH PETER BUECHI AND HE SAID THAT THIS WOULD BE ACCECPTABLE BECAUSE THE RP IS HARRISON AND IT'S ON THEIR PROPERTY...I WILL CONTACT BILL HEITZENRATER AND INFORM HIM OF THIS...ALSO,I DRAFTED AND SENT A LETTER EXPLAINING THE ABOVE PARAGRAPH. 1/16/2001: BILL HEITZENRATER TELECON RJJ SAID THAT THEY STARTING TO CLEAN LAND FOR THE BIOREMEDIATION OF THE CONTAMINATED SOIL. 3/7/2001: RJJ TALKED WITH PEGGY BOGECKI,MANAGER OF SENECA ST. COMMUNITY CENTER,SHE IS CONCERNED OF THE BIO-SOIL,WHICH IS CLOSE TO THEIR BUILDING...I EXPLAINED THE SITUATION TO BILL HEITZENRATER AND HE SAID THAT THEY WILL MOVE THE SOIL PILE ABOUT 100' AWAY FROM THEIR BUILDING AND PUT UP A FENCE...PEGGY WAS HAPPY WITH THIS. 3/7/2001: BRIAN DOMBECK TELECON RJJ SAID THAT IN THE BACK OF THE PROPERTY,THERE IS AN OLD TRANSFORMER WHICH WAS BUIRED OVER AND COVERED WITH BACKFILL...I CALLED BILL HEITZENRATER AND HE WILL HAVE CUSTOM TOPSOIL(NEW PROPERTY OWNER'S) CALL ME...IF THERE ARE ANY PCB CONCERNS, WE WILL ANALYZE THE SOIL. 3/8/2001: MIKE FRONCKOWIAK,CUSTOM TOPSOIL,TELECON RJJ,I TOLD HIM ABOUT THE TRANSFORMER AND HE SAID THAT HE WILL LOCATE IT AND HAVE IT ANALYZED FOR ANY PCB LEAKAGE. 3/15/2001: RJJ/PJB AT SITE AT 1000...AFI IS STILL BRINGING THE CONTAMINATED SOIL TO THE BIO-SITE,THEY SHOULD BE DONE TODAY,THEN THEY WILL BEGIN TO MOVE THE SOIL PILE NEAREST THE COMMUNITY CENTER TO THE OTHER BIO-SITE,THEN COVER IT AND PUT UP A FENCE...SINCE THE STREET IS GETTING DIRTY FROM THE SOIL,AFI IS GETTING A BOBCAT/SWEEPER TO CLEAN UP THE STREET...I TELECON RICH CROUCH,BARRON & ASSOCIATES,AND ASKED HIM IF HE COULD SEND ME THE SITE MAP AS TO WHERE EXACTLY THE TEST PITS HE TOOK WHERE...HE WILL ASK CTS FIRST,THEN SEND ME IT...HE DID SAY THAT THERE WAS NO TEST PIT TAKEN ON THE ONE ACRE WHERE THE BIO-SITE IS SINCE THIS WAS THE ONE ACRE THAT CTS WAS NOT BUYING. 3/15/2001: MIKE FRONCKOWIAK TELECON RJJ,(481-4444),SAID THAT THEY HAVE HIRED AFI TO TAKE A SAMPLE OF THE TRANSFORMERS AND TO HAVE THEM DISPOSED OF. 3/16/2001: RJJ AT A MEETING WITH BRIAN SCHECTMAN,V-P HARRISON INDUSTRIAL,CRAIG SLATER,THEIR ATTORNEY,BILL HEITZENRATER,AFI,AND COUNCILMAN FONTANA,CITY HALL...WE DISCUSSED 1070 SENECA ST. AND THE PROBLEM WITH THE BIO-CELL,NEXT TO THE COMMUNITY CENTER...AFTER THE DISCUSSION,MR. SCHECTMAN AGREED TO TRANSPORT ALL OF THE CONTAMINATED SOIL TO MODERN LANDFILL,STARTING TODAY...I HAD HIM FILL OUT THE 'APPLICATION FOR TREATMENT OR DISPOSAL OF AN INDUSTRIAL WASTE STREAM FORM' AND HAD MARK HANNS APPROVE IT,THEN I FAXED IT TO MIKE GULLO AT MODERN...CRAIG SLATER WILL RELEASE A STATEMENT TO THE PRESS EXPLAINING HIS CLIENT'S ACTIONS,ALL WITH DEC'S APPROVAL...I EXPLAINED ALL THIS TO THE COMMUNITY CENTER...THEY WERE HAPPY THAT THE SOIL WILL BE REMOVED...CRAIG SLATER ASKED ME TO DRAFT A LETTER EXPLAINING THAT THE DEC IS IN FAVOR OF DISPOSAL,RATHER THAN HAVING THE PROBLEMS WITH THE BIO-CELL...I WILL DRAFT AND SEND HIM THIS LETTER. 3/19/2001: HARRISON INDUSTRIAL HAS STARTED TO BEGIN TO TRANSPORT THE CONTAMINATED FROM THE BIO-CELL TO MODERN LANDFILL...THIS SHOULD TAKE ABOUT 1 WEEK TO COMPLETE. 3/20/2001: HARRISON INDUSTRIAL HAS DECIDED TO CHANGE THEIR LANDFILL FROM MODERN TO CID,SO NOW CID NEEDS THE ANALYTICAL DATA,BEFORE THEY WILL ACCEPT THE SOIL...THIS WILL TAKE A COUPLE OF DAYS,FOR NOW,THERE WILL BE NO

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VACANT LOT (Continued)

S104653506

HAULING OF SOIL,UNTIL CID GIVES THE OK. 3/23/2001: RJJ TELECON MIKE FRONCKOWIAK,CTS,AND ASKED IF HE HAD ANY INFORMATION ON THE TRANSFORMERS...HE SAID THAT HE WILL CALL BILL HEIZENRATER,AFI,AND CHECK ON THIS. 3/27/2001: RJJ TELECON MIKE FRONCKOWIAK,CTS,HE SAID THAT THEY HIRED PARADIGM ENVIRONMENTAL TO SAMPLE THE TRANSFORMERS AND TAKE COMPOSITE SOIL SAMPLES NEARBY,FOR PCB'S...AFTER THE ANALYTICAL COMES BACK,THEY WILL DISPOSE OF THE TRANSFORMERS. 4/25/2001: RECEIVED THE ANALYTICAL RESULTS FROM THE TRANSFORMERS,WHICH TURNED OUT NOT TO BE TRANSFORMERS,THE RESULTS WERE NON-DETECT FOR PCB'S...I FAXED THESE RESULTS TO BOB GOGEL,PRESIDENT SENECA-BABCOCK BLOCK ASSOCIATION. 5/11/2001: RECEIVED THE FINAL CLOSURE REPORT FROM AFI ENVIRONMENTAL FROM 1070 SENECA ST,WHICH INCLUDES THE SOIL DISPOSAL RECEIPTS...THEY DISPOSED 404.54 TONS OF SOIL AT MODERN AND 3309.21 TONS OF SOIL AT BFI...SINCE THEY DID NOT TAKE A SIDEWALL SAMPLE,WE WILL MAKE THIS SITE 'INACTIVE'...DRAFTED AND SENT AN 'INACTIVE' LETTER TO WILLIAM HEITZENRATER,AFI...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. DURING PHASE II SITE ASSESSMENT WORK, PETROLEUM ODORS WERE OBSERVED IN ONE TEST PIT, FILL IS INDUSTRIAL OVER SILT W/SOME CLAY,ODORS NOTED AT THE INDUSTRIAL FILL/SILT INTERFACE.

Remarks:

Material:

Site ID: 104772
Operable Unit ID: 836523
Operable Unit: 01
Material ID: 538695
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 0075152
Investigator: RJJ
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VACANT LOT (Continued)

S104653506

Notifier Phone: Not reported
Spill Date/Time: 06/01/2000 12:00
Reported to Dept Date/Time: 06/08/00 12:21
SWIS: 14
Spiller Name: HARRISON INDUSTRIAL PARK
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: PO BOX 1001
Spiller City,St,Zip: BUFFALO, NY 14240-
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: 03/19/01
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/11/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/08/00
Date Spill Entered In Computer Data File: 12:27
Update Date: 11/14/01
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929

DEC Remarks: 6/13/2000:RJJ SITE INVESTIGATION AT 1000...MEET WITH RICH CROUCH,BARRON ASSOCIATES,HE STARTED TO DIG TEST PITS,AT VARIOUS LOCATIONS,IN THE 30 ACRES OF PROPERTY,WHICH IS AT 1070 SENECA ST...ONE OF THE PITS HAD A HIGH PID READING AND AN ODOR...RICHTOLD ME THAT THE CURRENT OWNER OF THE PROPERTY IS HARRISON INDUSTRIAL PARK INC.,ADDRESS,P.O. BOX 1011,BUFFALO,N.Y. 14240...THE SBL OF

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VACANT LOT (Continued)

S104653506

THE PROPERTY IS 122.36-1-2.11...I WILL DRAFT AND SEND HARRISON A RESPONSIBLE PARTY LETTER...RICH ALSO SAID THAT THE CLIENT,WHICH WANTS TO PURCHASE THE PROPERTY,MAY DO THE REMEDIATION...HE WILL GET BACK TO ME ON HIS FINDINGS. 6/15/2000:TED KOSIOR,HARRISON INDUSTRIAL PARK,INC.,TELECON RJJ...HE WANTED TO KNOW WHY I SENT HIM THE RESPONSIBLE PARTY LETTER ...I TOLD HIM THAT RICH CROUCH,FROM BARRON ASSOCIATES,DUG SOME TEST PITS AND IN ONE OF THEM,THEY FOUND PETROLEUM ODORS...TED WILL CONTACT RICH AND GET BACK TO ME ON THEIR NEXT STEP-OF-ACTION. 9/5/2000:BILL HEITZENRATER,AFI,TELECON RJJ,BILL SAID THAT HEWILL BE HANDLING THIS SITE FOR INDUSTRIAL REALTORS,PART OF HARRISON PROPERITES,THE PROPERTY OWNERS...HE WANTED TO KNOW WHAT I KNEW OF THIS SITE,I TOLD HIM THAT I WAS WAITING FOR THE PHASE 11 REPORT FROM RICH CROUCH,TO DETERMINE WHAT THE EXTENT OF CONTAMINATION ON THIS SITE IS...BILL WILL CONTACT RICH AND GET THE REPORT AND THAN SEND ME HIS REPORT AND ACTION PLAN...BILL TELEPHONE IS 716)283-7645 CELL PHONE 622-6008. 9/7/2000:RECEIVED A LETTER FROM BILL HEITZENRATER EXPLAING THAT THEY WILL SEND ME THEIR INVESTIGATION PLAN IN ABOUT 3 WEEKS. 9/22/2000:RECEIVED THE PHASE 11 SITE WORK PLAN FROM AFI ,AND TALKED WITH BILL HEITZENRATER AND TOLD HIM THAT I APPROVE THIS PLAN...HE WILL CALL ME WHEN THEY START. 9/27/2000:BILL HEITZENRATER TELECON RJJ SAID THAT THEY WILL START REMEDIATING THE SITE TOMORROW...THEY WILL EXCAVATE 3 AREAS,WHERE THEY ENCOUNTERED HIGH PID READINGS,AND STAGE THE SOIL ON PLASTIC. 11/22/2000: RECEIVED THE PHASE 11 ENVIRONMENTAL SITE ASSESSMENT FROM AFI...THE SOIL ANALYTICAL CAME BACK ALL BELOW OUR STARS,BUT THEY WANT TO BIO THE CONTAMINATED SOIL ON THE PARCAL OF LAND,THAT THEY ARE NOT BUYING,BUT STILL OWNED BY HARRISON INDUSTRIAL...I TALKED WITH PETER BUECHI AND HE SAID THAT THIS WOULD BE ACCEPABLE BECAUSE THE RP IS HARRISON AND IT S ON THEIR PROPERTY...I WILL CONTACT BILL HEITZENRATER AND INFORM HIM OF THIS...ALSO,I DRAFTED AND SENT A LETTER EXPLAINING THE ABOVE PARAGRAPH. 1/16/2001: BILL HEITZENRATER TELECON RJJ SAID THAT THEY STARTING TO CLEAN LAND FOR THE BIOREMEDIATION OF THE CONTAMINATED SOIL. 3/7/2001: RJJ TALKED WITH PEGGY BOGECKI,MANAGER OF SENECA ST. COMMUNITY CENTER,SHE IS CONCERNED OF THE BIO-SOIL,WHICH IS CLOSE TO THEIR BUILDING...I EXPLAINED THE SITUATION TO BILL HEITZENRATER AND HE SAID THAT THEY WILL MOVE THE SOIL PILE ABOUT 100' AWAY FROM THEIR BUILDING AND PUT UP A FENCE...PEGGY WAS HAPPY WITH THIS. 3/7/2001: BRIAN DOMBECK TELECON RJJ SAID THAT IN THE BACK OF THE PROPERTY,THERE IS AN OLD TRANSFORMERWHICH WAS BUIED OVER AND COVERED WITH BACKFILL...I CALLED BILL HEITZENRATER AND HE WILL HAVE CUSTOM TOPSOIL NEW PROPERTY OWNER S) CALL ME...IF THERE ARE ANY PCB CONCERNS, WE WILL ANALYZE THE SOIL. 3/8/2001: MIKE FRONCKOWIAK,CUSTOM TOPSOIL,TELECON RJJ,I TOLD HIM ABOUT THE TRANSFORMER AND HE SAID THAT HE WILL LOCATE IT AND HAVE IT ANALYZED FOR ANY PCB LEAKAGE. 3/15/2001: RJJ/PJB AT SITE AT 1000...AFI IS STILL BRINGING THE CONTAMINATED SOIL TO THE BIO-SITE,THEY SHOULD BE DONE TODAY,THEN THEY WILL BEGIN TO MOVE THE SOIL PILE NEAREST THE COMMUNITY CENTER TO THE OTHER BIO-SITE,THEN COVER IT AND PUT UP A FENCE...SINCE THE STREET IS GETTING DIRTY FROM THE SOIL,AFI IS GETTING A BOBCAT/SWEEPER TO CLEAN UP THE STREET...I TELECON RICH CROUCH,BARRON ASSOCIATES,AND ASKED HIM IF HE COULD SEND ME THE SITE MAP AS TO WHERE EXACTLY THE TEST PITS HE TOOK WHERE...HE WILL ASK CTS FIRST,THEN SEND ME IT...HE DID SAY THAT THERE WAS NO TEST PIT TAKEN ON THE ONE ACRE WHERE THE BIO-SITE IS SINCE THISWAS THE ONE ACRE THAT CTS WAS NOT BUYING. 3/15/2001: MIKE FRONCKOWIAK TELECON RJJ, 481-4444),SAID THAT THEY HAVE HIRED AFI TO TAKE A SAMPLE OF THE TRANSFORMERS AND TO HAVE THEM DISPOSED OF. 3/16/2001: RJJ AT A MEETING WITH BRIAN SCHECTMAN,V-PHARRISON INDUSTRIAL,CRAIG SLATER,THEIR ATTORNEY,BILL HEITZENRATER,AFI,AND COUNCILMAN FONTANA,CITY HALL...WE DISCUSSED 1070 SENECA ST. AND THE PROBLEM WITH THE BIO-CELL,NEXT TO THE COMMUNITY CENTER...AFTER THE DISCUSSION,MR. SCHECTMAN AGREED TO TRANSPORT ALL OF THE CONTAMINATED SOIL TO MODERN LANDFILL,STARTING TODAY...I HAD HIM FILL OUT THE APPLICATION FOR TREATMENT OR DISPOSAL OF AN INDUSTRIL WASTE STREAM FORM AND HAD MARK HANNS APPROVE IT,THEN I FAXED IT TO MIKE GULLO AT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VACANT LOT (Continued)

S104653506

MODERN...CRAIG SLATER WILL RELEASE A STATEMENT TO THE PRESS EXPLAINING HIS CLIENT S ACTIONS,ALL WITH DEC S APPROVAL...I EXPLAINED ALL THIS TO THE COMMUNITY CENTER...THEY WERE HAPPY THAT THE SOIL WILL BE REMOVED...CRAIG SLATER ASKED ME TO DRAFT A LETTER EXPLAINING THAT THE DEC IS IN FAVOR OF DISPOSAL,RATHER THAN HAVING THE PROBLEMS WITH THE BIO-CELL...I WILL DRAFT AND SEND HIM THIS LETTER. 3/19/2001: HARRISON INDUSTRIAL HAS STARTED TO BEGIN TO TRANSPORT THE CONTAMINATED FROM THE BIO-CELL TO MODERN LANDFILL...THIS SHOULD TAKE ABOUT 1 WEEK TO COMPLETE. 3/20/2001: HARRISON INDUSTRIAL HAS DECIDED TO CHANGE THEIR LANDFILL FROM MODERN TO CID,SO NOW CID NEEDS THE ANALYTICAL DATA,BEFORE THEY WILL ACCEPT THE SOIL...THIS WILL TAKE A COUPLE OF DAYS,FOR NOW,THERE WILL BE NO HAULING OF SOIL,UNTIL CID GIVES THE OK. 3/23/2001: RJJ TELECON MIKE FRONCKOWIAK,CTS,AND ASKED IF HE HAD ANY INFORMATION ON THE TRANSFORMERS...HE SAID THAT HE WILL CALL BILL HEIZENRATER,AFL,AND CHECK ON THIS. 3/27/2001: RJJ TELECON MIKE FRONCKOWIAK,CTS,HE SAID THAT THEY HIRED PARADIGM ENVIRONMENTAL TO SAMPLE THE TRANSFORMERS AND TAKE COMPOSITE SOIL SAMPLES NEARBY,FOR PCB S...AFTER THE ANALYTICAL COMES BACK,THEY WILL DISPOSE OF THE TRANSFORMERS. 4/25/2001: RECEIVED THE ANALYTICAL RESULTS FROM THE TRANSFORMERS,WHICH TURNED OUT NOT TO BE TRANSFORMERS,THE RESULTS WERE NON-DETECT FOR PCB S...I FAXED THESE RESULTS TO BOB GOGEL,PRESIDENT SENECA-BABCOCK BLOCK ASSOCIATION. 5/11/2001: RECEIVED THE FINAL CLOSURE REPORT FROM AFL ENVIRONMENTAL FROM 1070 SENECA ST,WHICH INCLUDES THE SOIL DISPOSAL RECEIPTS...THEY DISPOSED 404.54 TONS OF SOIL AT MODERN AND 3309.21 TONS OF SOIL AT BFI...SINCE THEY DID NOT TAKE A SIDEWALL SAMPLE,WE WILL MAKE THIS SITE INACTIVE ...DRAFTED AND SENT AN INACTIVE LETTER TO WILLIAM HEITZENRATER,AFL...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.

Remark: DURING PHASE II SITE ASSESSMENT WORK, PETROLEUM ODORS WERE OBSERVED IN ONE TEST PIT, FILL IS INDUSTRIAL OVER SILT W/SOME CLAY,ODORS NOTED AT THE INDUSTRIAL FILL/SILT INTERFACE.

124
SE
1/2-1
0.543 mi.
2865 ft.

BATTAGLIA C&D PROCESSING
1037 - 1055 SENECA STREET
BUFFALO, NY 14210

SWRCY S109580342
N/A

Relative:
Higher

Actual:
595 ft.

SWRCY:
Region: 9
Facility Address 2: Not reported
Phone Number: 7166740463
Owner Type: Private
Owner Name: Battaglia Demolition; Inc.
Owner Address: 611 Bullis Road
Owner Address 2: Not reported
Owner City,St,Zip: Elma, NY 14059
Owner Email: Not reported
Owner Phone: 7166740463
Contact Name: Peter Battaglia; Jr.
Contact Address: 611 Bullis Road
Contact Address 2: Not reported
Contact City,St,Zip: Elma, NY 14059
Contact Email: Not reported
Contact Phone: 7166740463
Activity Desc: Source separated solid waste recyclables
Activity Number: 15M23
Active: Yes
East Coordinate: 186229
North Coordinate: 4753444
Accuracy Code: 4.2.1 - Utilization of GIS and Facility Mapping System

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BATTAGLIA C&D PROCESSING (Continued)

S109580342

Regulatory Status: Registration
Permit #: 15M23
Auth. Date: 3/2/2009
Expiration Date: Not reported
Waste Types: Source Separated Recyclables (Metal/Glass/Paper/Plastic)

AE125 **UNIVERSAL IRONS & METAL**
ENE **993 CLINTON ST**
1/2-1 **BUFFALO, NY 14201**
0.555 mi.
2929 ft. **Site 1 of 7 in cluster AE**

CERCLIS **1000481574**
NYD986910206

Relative: CERCLIS:
Equal Site ID: 0203413
Federal Facility: Not a Federal Facility
Actual: NPL Status: Not on the NPL
590 ft. Non NPL Status: Referred to Removal - NFRAP

CERCLIS Site Contact Name(s):

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20001

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20001

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 22700

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20002

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNIVERSAL IRONS & METAL (Continued)

1000481574

Contact Title: 20002

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20002

Site Description: ABANDONED SCRAP METAL REPROCESSING & RECYCLING FACILITY, WITHIN A MIXED INDUSTRIAL COMMERCIAL RESIDENTIAL AREA. SITE HAS PCB/LEAD SOIL CONTAMINATION, SEVERAL TRANSFORMERS W/PCB- CONTAMINATED OIL & SEVERAL SMALL CONTAINERS WITH VARIOUS PTR PD

CERCLIS Assessment History:

Action: Public Notice Published
Date Started: Not reported
Date Completed: 2/13/1991 0:00:00
Priority Level: Not reported

Action: REMOVAL
Date Started: 10/15/1990 0:00:00
Date Completed: 4/26/1991 0:00:00
Priority Level: Stabilized

Action: NON-NPL PRP SEARCH
Date Started: 8/14/1990 0:00:00
Date Completed: 7/18/1991 0:00:00
Priority Level: Viable PRPs - Cannot Do Work

Action: REMOVAL ASSESSMENT
Date Started: 11/26/1990 0:00:00
Date Completed: 9/30/1991 0:00:00
Priority Level: Not reported

Action: DISCOVERY
Date Started: Not reported
Date Completed: 12/16/1991 0:00:00
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: Not reported
Date Completed: 12/16/1991 0:00:00
Priority Level: Higher priority for further assessment

Action: ISSUE REQ LTTRS (104e)
Date Started: Not reported
Date Completed: 1/7/1992 0:00:00
Priority Level: Not reported

Action: REMOVAL
Date Started: 11/25/1991 0:00:00
Date Completed: 2/24/1992 0:00:00
Priority Level: Cleaned up

Action: ISSUE REQ LTTRS (104e)
Date Started: Not reported
Date Completed: 5/28/1992 0:00:00
Priority Level: Not reported

Action: ISSUE REQ LTTRS (104e)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNIVERSAL IRONS & METAL (Continued)

1000481574

Date Started: Not reported
Date Completed: 6/10/1992 0:00:00
Priority Level: Not reported

Action: ISSUE REQ LTTRS (104e)
Date Started: Not reported
Date Completed: 3/8/1993 0:00:00
Priority Level: Not reported

Action: SITE INSPECTION
Date Started: 1/21/1993 0:00:00
Date Completed: 6/30/1993 0:00:00
Priority Level: NFRAP: No further Remedial Action planned

Action: ISSUE REQ LTTRS (104e)
Date Started: Not reported
Date Completed: 7/28/1993 0:00:00
Priority Level: Not reported

Action: Notice Letters Issued
Date Started: Not reported
Date Completed: 1/26/1995 0:00:00
Priority Level: Not reported

Action: REMOVAL NEGOTIATIONS
Date Started: 1/26/1995 0:00:00
Date Completed: 9/29/1995 0:00:00
Priority Level: Not reported

Action: Lodged By DOJ
Date Started: Not reported
Date Completed: 2/7/2002 0:00:00
Priority Level: Not reported

Action: SECTION 107 LITIGATION
Date Started: 9/29/1995 0:00:00
Date Completed: 1/7/2003 0:00:00
Priority Level: Not reported

Action: CONSENT DECREE
Date Started: Not reported
Date Completed: 1/7/2003 0:00:00
Priority Level: Not reported

AE126 BERN METALS
ENE 22 BENDER STREET
1/2-1 BUFFALO, NY 14201
0.567 mi.
2992 ft. Site 2 of 7 in cluster AE

Relative: CERCLIS:
Equal Site ID: 0202697
Federal Facility: Not a Federal Facility
Actual: NPL Status: Not on the NPL
590 ft. Non NPL Status: Referred to Removal - NFRAP

CERCLIS 1000305569
MANIFEST NYD013703632

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS (Continued)

1000305569

CERCLIS Site Contact Name(s):

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20001

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20001

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 22700

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20002

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20002

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20002

Site Description: ABANDONED METAL-WASTE REPROCESSING AND RECYCLING INDUSTRY.ABANDONED METAL-WASTE REPROCESSING AND RECYCLING INDUSTRY.

CERCLIS Assessment History:

Action: REMOVAL
Date Started: 4/21/1988 0:00:00
Date Completed: 7/8/1988 0:00:00
Priority Level: Stabilized

Action: REMOVAL
Date Started: 1/9/1989 0:00:00
Date Completed: 3/15/1989 0:00:00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS (Continued)

1000305569

Priority Level:	Stabilized
Action:	DISCOVERY
Date Started:	Not reported
Date Completed:	6/30/1989 0:00:00
Priority Level:	Not reported
Action:	SITE INSPECTION
Date Started:	6/30/1989 0:00:00
Date Completed:	9/27/1989 0:00:00
Priority Level:	NFRAP: No further Remedial Action planned
Action:	PRELIMINARY ASSESSMENT
Date Started:	Not reported
Date Completed:	2/28/1990 0:00:00
Priority Level:	NFRAP: No further Remedial Action planned
Action:	REMOVAL
Date Started:	6/27/1990 0:00:00
Date Completed:	6/29/1990 0:00:00
Priority Level:	Stabilized
Action:	REMOVAL
Date Started:	9/28/1990 0:00:00
Date Completed:	10/23/1990 0:00:00
Priority Level:	Stabilized
Action:	NON-NPL PRP SEARCH
Date Started:	8/14/1990 0:00:00
Date Completed:	7/18/1991 0:00:00
Priority Level:	Not reported
Action:	REMOVAL
Date Started:	11/26/1990 0:00:00
Date Completed:	8/22/1991 0:00:00
Priority Level:	Stabilized
Action:	ISSUE REQ LTTRS (104e)
Date Started:	Not reported
Date Completed:	1/7/1992 0:00:00
Priority Level:	Not reported
Action:	REMOVAL
Date Started:	10/15/1991 0:00:00
Date Completed:	1/8/1992 0:00:00
Priority Level:	Stabilized
Action:	ISSUE REQ LTTRS (104e)
Date Started:	Not reported
Date Completed:	4/9/1992 0:00:00
Priority Level:	Not reported
Action:	Special Notice Issued
Date Started:	Not reported
Date Completed:	4/20/1992 0:00:00
Priority Level:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS (Continued)

1000305569

Action:	Notice Letters Issued
Date Started:	Not reported
Date Completed:	4/20/1992 0:00:00
Priority Level:	Not reported
Action:	ISSUE REQ LTTRS (104e)
Date Started:	Not reported
Date Completed:	5/8/1992 0:00:00
Priority Level:	Not reported
Action:	Notice Letters Issued
Date Started:	Not reported
Date Completed:	5/8/1992 0:00:00
Priority Level:	Not reported
Action:	Notice Letters Issued
Date Started:	Not reported
Date Completed:	6/10/1992 0:00:00
Priority Level:	Not reported
Action:	ISSUE REQ LTTRS (104e)
Date Started:	Not reported
Date Completed:	6/10/1992 0:00:00
Priority Level:	Not reported
Action:	Notice Letters Issued
Date Started:	Not reported
Date Completed:	9/2/1992 0:00:00
Priority Level:	Not reported
Action:	UNILATERAL ADMIN ORDER
Date Started:	Not reported
Date Completed:	9/29/1992 0:00:00
Priority Level:	Not reported
Action:	Notice Letters Issued
Date Started:	Not reported
Date Completed:	5/1/1993 0:00:00
Priority Level:	Not reported
Action:	PRP REMOVAL
Date Started:	9/29/1992 0:00:00
Date Completed:	3/11/1994 0:00:00
Priority Level:	Stabilized
Action:	ISSUE REQ LTTRS (104e)
Date Started:	Not reported
Date Completed:	11/10/1994 0:00:00
Priority Level:	Not reported
Action:	ADMIN ORDER ON CONSENT
Date Started:	Not reported
Date Completed:	9/29/1995 0:00:00
Priority Level:	Not reported
Action:	Lodged By DOJ
Date Started:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS (Continued)

1000305569

Date Completed: 2/7/2002 0:00:00
Priority Level: Not reported

Action: Lodged By DOJ
Date Started: Not reported
Date Completed: 2/7/2002 0:00:00
Priority Level: Not reported

Action: SECTION 107 LITIGATION
Date Started: 9/29/1995 0:00:00
Date Completed: 1/15/2003 0:00:00
Priority Level: Not reported

Action: CONSENT DECREE
Date Started: Not reported
Date Completed: 1/15/2003 0:00:00
Priority Level: Not reported

Action: CONSENT DECREE
Date Started: Not reported
Date Completed: 1/15/2003 0:00:00
Priority Level: Not reported

NY MANIFEST:

EPA ID: NYD013703632
Country: USA
Mailing Name: BBL ENVIRONMENTAL SERVICES
Mailing Contact: DOUGLAS RUSICZYK
Mailing Address: 30 CORPORATE WOODS SUITE 130
Mailing Address 2: Not reported
Mailing City: ROCHESTER
Mailing State: NY
Mailing Zip: 14623
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-292-6740

Document ID: NYG1111707
Manifest Status: Not reported
Trans1 State ID: NYD982792814
Trans2 State ID: Not reported
Generator Ship Date: 11/18/1998
Trans1 Recv Date: 11/19/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/23/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD013703632
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 71072NNY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00150
Units: P - Pounds
Number of Containers: 002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS (Continued)

1000305569

Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYG1111698
Manifest Status: Not reported
Trans1 State ID: NYD982792814
Trans2 State ID: Not reported
Generator Ship Date: 11/19/1998
Trans1 Recv Date: 11/19/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/23/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD013703632
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 71072NNY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 02000
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AE127 **BERN METAL CORP.**
ENE **22 BENDER STREET**
1/2-1 **BUFFALO, NY 14206**
0.567 mi.
2992 ft. **Site 3 of 7 in cluster AE**

SHWS **S108524844**
ENG CONTROLS **N/A**
INST CONTROL

Relative:
Equal

Actual:
590 ft.

SHWS:

Program: HW
Site Code: 58664
Classification: SITE IS PROPERLY CLOSED - REQUIRES CONTINUED MANAGEMENT
Region: 9
Acres: 3.700
HW Code: 915135
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 6/18/2009 1:54:00 PM
Updated By: MLDOSTER
Site Description:

The site consisted of two properties known as: Bern Metals (~3.7 acres) and Universal Metals (~1.5 acres). The site was an abandoned scrap reprocessor. Based upon complaints from citizens, DEC conducted a Phase I Investigation in 1987. Approximately two hundred 55 gallon drums were found on the Bern Metals property, along with other wastes including: metal turnings, waste chemicals, sludges, battery cases, spilled battery acids. Subsequently, 25 leaking transformers containing PCBs were found on the Universal Metals property. In 1990 USEPA conducted an emergency removal at the site. Drums, gas cylinders and transformers, were removed from the site. Under order by USEPA in 1994, a group of potentially responsible parties (PRPs) remediated neighboring residential properties and erected a fence around the contaminated site. The PRPs conducted a Remedial Investigation and Feasibility Study (RI/FS) of the site during the period 1993-1995. The Record of Decision (ROD) was signed in 1996 which required the contaminated soils be consolidated and properly capped. Under a separate New York State consent order, the PRPs consolidated and capped the waste onto the property known as Bern Metals (approximate acreage of 3.7 acres), completing the project in 2002. The long-term Operation, Maintenance and Monitoring Plan is in effect and is being implemented by the City of Buffalo. The Universal Metals property has been remediated as required by the ROD. This parcel no longer poses any environmental or human health threats.

Env Problem: With remediation of site, the wastes are contained. The environmental impacts have been mitigated and environmental threats have been removed. The site is being monitored and maintained under a long term Operation and Maintenance Plan by the City of Buffalo.

Health Problem: This site is located in a mixed industrial/residential area in the City of Buffalo that is served by public water. There are no known private wells in the immediate area. Therefore, human exposures to site-related contaminants via drinking water are not expected. Elevated levels of lead, up to 176,000 milligrams per kilogram, were present on-site in subsurface soils. These soils have been consolidated and capped on the site. NYSDOH coordinated blood lead testing of nearby residents in 1991 and no elevated blood lead levels attributable to the site were found. The USEPA replaced nearby residential yard soils with clean soil in 1992 and 1993. Along with the consolidation and capping of site soils, institutional controls and fencing are in place to protect public health.

Dump: False
Structure: False
Lagoon: False
Landfill: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METAL CORP. (Continued)

S108524844

Pond: False
Disp Start: 1956
Disp Term: 1983
Lat/Long: 42:52:36:0 / 78:50:16:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 11/18/1999 12:00:00 PM
Updated By: INITIAL
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BERN METAL CORP./UNIVERSAL IRON & ME
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: BERN METAL CORP./UNIVERSAL IRON & ME
Owner Address: 100 CLAREMONT AVE.
Owner Addr2: Not reported
Owner City,St,Zip: KENMORE, NY 14223
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: Not reported
Owner Company: Bern Metal Corp./Universal Iron & Metal
Owner Address: 22 Bender Street/993 Clinton Street
Owner Addr2: Not reported
Owner City,St,Zip: Buffalo, NY 14206
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: BERN METAL CORP./UNIVERSAL IRON & ME
Owner Address: 1021 CLINTON ST.
Owner Addr2: Not reported
Owner City,St,Zip: BUFFALO, NY
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: O.ROBERT KOLSKY
Owner Address: 56 TRISTAN LANE
Owner Addr2: Not reported
Owner City,St,Zip: WILLIAMSVILLE, NY 14221
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: Gerald Arwitz, Executor of Estate
Owner Address: 100 Claremont Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Kenmore, NY 14223
Owner Country: United States of America
Own Op: Owner

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METAL CORP. (Continued)

S108524844

Sub Type: C01
Owner Name: DENNIS SUTTON
Owner Company: CITY OF BUFFALO
Owner Address: 65 NIAGARA SQUARE
Owner Addr2: 920 CITY HALL
Owner City,St,Zip: BUFFALO, NY 14202
Owner Country: United States of America
HW Code: 915135
Waste Type: BATTERY ACIDS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915135
Waste Type: LEAD
Waste Quantity: "
Waste Code: Not reported
HW Code: 915135
Waste Type: CHROMIUM LEATHER FINES
Waste Quantity: "
Waste Code: Not reported
HW Code: 915135
Waste Type: METAL SLUDGES
Waste Quantity: "
Waste Code: Not reported
HW Code: 915135
Waste Type: PCB OIL
Waste Quantity: 25 GALLONS
Waste Code: Not reported
HW Code: 915135
Waste Type: PCB SOIL
Waste Quantity: 30 TONS
Waste Code: Not reported
HW Code: 915135
Waste Type: GAS CYLINDERS
Waste Quantity: 16
Waste Code: Not reported
Crossref ID: NYD013703632
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS

ENG CONTROLS:

Site Code: 58664
Control Name: Cover System
HW Code: 915135
Control Code: 15
Control Type: ENG
Date Record Added: 7/14/2004 10:13:00 AM
Date Rec Updated: 10/19/2009 1:14:31 PM
Updated By: DSSZYMAN
Site Description: The site consisted of two properties known as: Bern Metals (~3.7 acres) and Universal Metals (~1.5 acres). The site was an abandoned scrap reprocessor. Based upon complaints from citizens, DEC conducted a Phase I Investigation in 1987. Approximately two hundred 55 gallon drums were found on the Bern Metals property, along with other wastes including: metal turnings, waste chemicals, sludges, battery cases,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METAL CORP. (Continued)

S108524844

Env Problem: spilled battery acids. Subsequently, 25 leaking transformers containing PCBs were found on the Universal Metals property. In 1990 USEPA conducted an emergency removal at the site. Drums, gas cylinders and transformers, were removed from the site. Under order by USEPA in 1994, a group of potentially responsible parties (PRPs) remediated neighboring residential properties and erected a fence around the contaminated site. The PRPs conducted a Remedial Investigation and Feasibility Study (RI/FS) of the site during the period 1993-1995. The Record of Decision (ROD) was signed in 1996 which required the contaminated soils be consolidated and properly capped. Under a separate New York State consent order, the PRPs consolidated and capped the waste onto the property known as Bern Metals (approximate acreage of 3.7 acres), completing the project in 2002. The long-term Operation, Maintenance and Monitoring Plan is in effect and is being implemented by the City of Buffalo. The Universal Metals property has been remediated as required by the ROD. This parcel no longer poses any environmental or human health threats. With remediation of site, the wastes are contained. The environmental impacts have been mitigated and environmental threats have been removed. The site is being monitored and maintained under a long term Operation and Maintenance Plan by the City of Buffalo.

Health Problem: This site is located in a mixed industrial/residential area in the City of Buffalo that is served by public water. There are no known private wells in the immediate area. Therefore, human exposures to site-related contaminants via drinking water are not expected. Elevated levels of lead, up to 176,000 milligrams per kilogram, were present on-site in subsurface soils. These soils have been consolidated and capped on the site. NYSDOH coordinated blood lead testing of nearby residents in 1991 and no elevated blood lead levels attributable to the site were found. The USEPA replaced nearby residential yard soils with clean soil in 1992 and 1993. Along with the consolidation and capping of site soils, institutional controls and fencing are in place to protect public health.

Site Code: 58664

Control Name: Fencing/Access Control

HW Code: 915135

Control Code: 22

Control Type: ENG

Date Record Added: 7/14/2004 10:13:00 AM

Date Rec Updated: 10/19/2009 1:14:31 PM

Updated By: DSSZYMAN

Site Description: The site consisted of two properties known as: Bern Metals (~3.7 acres) and Universal Metals (~1.5 acres). The site was an abandoned scrap reprocessor. Based upon complaints from citizens, DEC conducted a Phase I Investigation in 1987. Approximately two hundred 55 gallon drums were found on the Bern Metals property, along with other wastes including: metal turnings, waste chemicals, sludges, battery cases, spilled battery acids. Subsequently, 25 leaking transformers containing PCBs were found on the Universal Metals property. In 1990 USEPA conducted an emergency removal at the site. Drums, gas cylinders and transformers, were removed from the site. Under order by USEPA in 1994, a group of potentially responsible parties (PRPs) remediated neighboring residential properties and erected a fence around the contaminated site. The PRPs conducted a Remedial Investigation and Feasibility Study (RI/FS) of the site during the period 1993-1995. The Record of Decision (ROD) was signed in 1996

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METAL CORP. (Continued)

S108524844

Env Problem: which required the contaminated soils be consolidated and properly capped. Under a separate New York State consent order, the PRPs consolidated and capped the waste onto the property known as Bern Metals (approximate acreage of 3.7 acres), completing the project in 2002. The long-term Operation, Maintenance and Monitoring Plan is in effect and is being implemented by the City of Buffalo. The Universal Metals property has been remediated as required by the ROD. This parcel no longer poses any environmental or human health threats.

Health Problem: With remediation of site, the wastes are contained. The environmental impacts have been mitigated and environmental threats have been removed. The site is being monitored and maintained under a long term Operation and Maintenance Plan by the City of Buffalo.

This site is located in a mixed industrial/residential area in the City of Buffalo that is served by public water. There are no known private wells in the immediate area. Therefore, human exposures to site-related contaminants via drinking water are not expected. Elevated levels of lead, up to 176,000 milligrams per kilogram, were present on-site in subsurface soils. These soils have been consolidated and capped on the site. NYSDOH coordinated blood lead testing of nearby residents in 1991 and no elevated blood lead levels attributable to the site were found. The USEPA replaced nearby residential yard soils with clean soil in 1992 and 1993. Along with the consolidation and capping of site soils, institutional controls and fencing are in place to protect public health.

INST CONTROL:

Site Code: 58664
Control Name: Ground Water Use Restriction
HW Code: 915135
Control Code: 08
Control Type: INST
Dt record added: 7/14/2004 10:13:00 AM
Dt rec updated: 10/19/2009 1:14:31 PM
Updated By: DSSZYMAN
Site Code: 58664
Site Description: The site consisted of two properties known as: Bern Metals (~3.7 acres) and Universal Metals (~1.5 acres). The site was an abandoned scrap reprocessor. Based upon complaints from citizens, DEC conducted a Phase I Investigation in 1987. Approximately two hundred 55 gallon drums were found on the Bern Metals property, along with other wastes including: metal turnings, waste chemicals, sludges, battery cases, spilled battery acids. Subsequently, 25 leaking transformers containing PCBs were found on the Universal Metals property. In 1990 USEPA conducted an emergency removal at the site. Drums, gas cylinders and transformers, were removed from the site. Under order by USEPA in 1994, a group of potentially responsible parties (PRPs) remediated neighboring residential properties and erected a fence around the contaminated site. The PRPs conducted a Remedial Investigation and Feasibility Study (RI/FS) of the site during the period 1993-1995. The Record of Decision (ROD) was signed in 1996 which required the contaminated soils be consolidated and properly capped. Under a separate New York State consent order, the PRPs consolidated and capped the waste onto the property known as Bern Metals (approximate acreage of 3.7 acres), completing the project in 2002. The long-term Operation, Maintenance and Monitoring Plan is in effect and is being implemented by the City of Buffalo. The Universal Metals property has been remediated as required by the ROD. This

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METAL CORP. (Continued)

S108524844

parcel no longer poses any environmental or human health threats.

Env Problem: With remediation of site, the wastes are contained. The environmental impacts have been mitigated and environmental threats have been removed. The site is being monitored and maintained under a long term Operation and Maintenance Plan by the City of Buffalo.

Health Problem: This site is located in a mixed industrial/residential area in the City of Buffalo that is served by public water. There are no known private wells in the immediate area. Therefore, human exposures to site-related contaminants via drinking water are not expected. Elevated levels of lead, up to 176,000 milligrams per kilogram, were present on-site in subsurface soils. These soils have been consolidated and capped on the site. NYSDOH coordinated blood lead testing of nearby residents in 1991 and no elevated blood lead levels attributable to the site were found. The USEPA replaced nearby residential yard soils with clean soil in 1992 and 1993. Along with the consolidation and capping of site soils, institutional controls and fencing are in place to protect public health.

Site Code: 58664
Control Name: Legacy Restriction
HW Code: 915135
Control Code: A
Control Type: INST
Dt record added: 7/14/2004 10:13:00 AM
Dt rec updated: 10/19/2009 1:14:31 PM
Updated By: DSSZYMAN
Site Code: 58664
Site Description: The site consisted of two properties known as: Bern Metals (~3.7 acres) and Universal Metals (~1.5 acres). The site was an abandoned scrap reprocessor. Based upon complaints from citizens, DEC conducted a Phase I Investigation in 1987. Approximately two hundred 55 gallon drums were found on the Bern Metals property, along with other wastes including: metal turnings, waste chemicals, sludges, battery cases, spilled battery acids. Subsequently, 25 leaking transformers containing PCBs were found on the Universal Metals property. In 1990 USEPA conducted an emergency removal at the site. Drums, gas cylinders and transformers, were removed from the site. Under order by USEPA in 1994, a group of potentially responsible parties (PRPs) remediated neighboring residential properties and erected a fence around the contaminated site. The PRPs conducted a Remedial Investigation and Feasibility Study (RI/FS) of the site during the period 1993-1995. The Record of Decision (ROD) was signed in 1996 which required the contaminated soils be consolidated and properly capped. Under a separate New York State consent order, the PRPs consolidated and capped the waste onto the property known as Bern Metals (approximate acreage of 3.7 acres), completing the project in 2002. The long-term Operation, Maintenance and Monitoring Plan is in effect and is being implemented by the City of Buffalo. The Universal Metals property has been remediated as required by the ROD. This parcel no longer poses any environmental or human health threats.

Env Problem: With remediation of site, the wastes are contained. The environmental impacts have been mitigated and environmental threats have been removed. The site is being monitored and maintained under a long term Operation and Maintenance Plan by the City of Buffalo.

Health Problem: This site is located in a mixed industrial/residential area in the City of Buffalo that is served by public water. There are no known private wells in the immediate area. Therefore, human exposures to

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METAL CORP. (Continued)

S108524844

site-related contaminants via drinking water are not expected. Elevated levels of lead, up to 176,000 milligrams per kilogram, were present on-site in subsurface soils. These soils have been consolidated and capped on the site. NYSDOH coordinated blood lead testing of nearby residents in 1991 and no elevated blood lead levels attributable to the site were found. The USEPA replaced nearby residential yard soils with clean soil in 1992 and 1993. Along with the consolidation and capping of site soils, institutional controls and fencing are in place to protect public health.

AE128
ENE
1/2-1
0.567 mi.
2992 ft.

BERN METALS - USEPA ERRD
22 BENDER AVE
BUFFALO, NY 14206
Site 4 of 7 in cluster AE

RCRA-NonGen **1000447082**
CONSENT **NYD986910057**
FINDS
MANIFEST

Relative:
Equal

Actual:
590 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: BERN METALS - USEPA ERRD
Facility address: 22 BENDER AVE
BUFFALO, NY 142062803
EPA ID: NYD986910057
Mailing address: WOODBRIDGE AVE BLDG 209
EDISON, NY 08817
Contact: Not reported
Contact address: WOODBRIDGE AVE BLDG 209
EDISON, NY 08817
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: BERN METALS BANKRUPT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BERN METALS BANKRUPT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: BERN METALS - USEPA ERRD
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: BERN METALS - USEPA ERRD
Classification: Not a generator, verified

Date form received by agency: 03/12/1992
Facility name: BERN METALS - USEPA ERRD
Site name: BERN METALS SITE
Classification: Large Quantity Generator

Date form received by agency: 08/15/1990
Facility name: BERN METALS - USEPA ERRD
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 12/12/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

CONSENT:

EPA ID: NYD986910057
Site ID: Not reported
Case Title: U.S. V. ALLIED SIGNAL, INC., ET AL. (BERN METALS)
Court Num: 95-0950
District: New York, West
Entered Date: 20030107
Full-text of the consent decree for this site issued by the United States District Court is available from EDR. Contact your EDR Account Executive.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

FINDS:

Registry ID: 110004451600

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CERCLIS (Comprehensive Environmental Response, Compensation, and Liability Information System) is the Superfund database that is used to support management in all phases of the Superfund program. The system contains information on all aspects of hazardous waste sites, including an inventory of sites, planned and actual site activities, and financial information.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

NY MANIFEST:

EPA ID: NYD986910057
Country: USA
Mailing Name: USEPA
Mailing Contact: KEVIN M MATHEIS
Mailing Address: 2890 WOODBRIDGE
Mailing Address 2: Not reported
Mailing City: EDISON
Mailing State: NJ
Mailing Zip: 08837
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-854-6742

Document ID: NYB2251566
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 502211IL
Trans2 State ID: Not reported
Generator Ship Date: 900129
Trans1 Recv Date: 900129

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number

EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Trans2 Recv Date: Not reported
TSD Site Recv Date: 910129
Part A Recv Date: 910207
Part B Recv Date: 910211
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 48820
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 90
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MIA2167968
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: 79629Z
Trans2 State ID: Not reported
Generator Ship Date: 910521
Trans1 Recv Date: 910521
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910522
Part A Recv Date: 910530
Part B Recv Date: 910711
Generator EPA ID: NYD986910057
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSD ID: MID000724831
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 40000
Units: P - Pounds
Number of Containers: 050
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251818
Manifest Status: Completed copy
Trans1 State ID: 1467VNY
Trans2 State ID: Not reported
Generator Ship Date: 910402
Trans1 Recv Date: 910402
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910402
Part A Recv Date: 910411
Part B Recv Date: 910411
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 41520
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251782
Manifest Status: Completed copy
Trans1 State ID: 14645VNY
Trans2 State ID: Not reported
Generator Ship Date: 910401
Trans1 Recv Date: 910401
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910401
Part A Recv Date: 910411
Part B Recv Date: 910411
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 43900
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251791
Manifest Status: Completed copy
Trans1 State ID: 22413IL
Trans2 State ID: Not reported
Generator Ship Date: 910402
Trans1 Recv Date: 910402
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910402
Part A Recv Date: 910411
Part B Recv Date: 910411
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 45980
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Mgmt Method Type Code: Not reported

Document ID: NYB2251800
Manifest Status: Completed copy
Trans1 State ID: 502211IL
Trans2 State ID: Not reported
Generator Ship Date: 910402
Trans1 Recv Date: 910402
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910402
Part A Recv Date: 910411
Part B Recv Date: 910411
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 46700
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: ARA4794580
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PC745H46
Trans2 State ID: PC936H245
Generator Ship Date: 910503
Trans1 Recv Date: 910503
Trans2 Recv Date: 910507
TSD Site Recv Date: 910513
Part A Recv Date: 910516
Part B Recv Date: 910603
Generator EPA ID: NYD986910057
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: NYD980769947
TSDF ID: ARD069748192
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00317
Units: P - Pounds
Number of Containers: 002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00007
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00011
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251404
Manifest Status: Completed copy
Trans1 State ID: 44614CNY
Trans2 State ID: Not reported
Generator Ship Date: 910328
Trans1 Recv Date: 910328
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910328
Part A Recv Date: 910405
Part B Recv Date: 910408
Generator EPA ID: NYD986910057
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 45880
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MIA2167961
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 910516
Trans1 Recv Date: 910516
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910518
Part A Recv Date: 910524
Part B Recv Date: 910703
Generator EPA ID: NYD986910057
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSDF ID: MID000724831
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 44000
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251332
Manifest Status: Completed copy
Trans1 State ID: 85859DNY
Trans2 State ID: Not reported
Generator Ship Date: 910122
Trans1 Recv Date: 910122
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910122
Part A Recv Date: 910207
Part B Recv Date: 910211

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 40820
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251062
Manifest Status: Completed copy
Trans1 State ID: 864262X-N
Trans2 State ID: Not reported
Generator Ship Date: 910116
Trans1 Recv Date: 910116
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910116
Part A Recv Date: 910125
Part B Recv Date: 910125
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 37600
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251764
Manifest Status: Completed copy
Trans1 State ID: 22413STIL
Trans2 State ID: Not reported
Generator Ship Date: 910131
Trans1 Recv Date: 910201
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910201
Part A Recv Date: 910212
Part B Recv Date: 910219
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 43860
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251215
Manifest Status: Completed copy
Trans1 State ID: 44561CNY
Trans2 State ID: Not reported
Generator Ship Date: 910118
Trans1 Recv Date: 910118
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910118
Part A Recv Date: 910207
Part B Recv Date: 910207
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 46360

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251683
Manifest Status: Completed copy
Trans1 State ID: 86435ZNY
Trans2 State ID: Not reported
Generator Ship Date: 910129
Trans1 Recv Date: 910129
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910129
Part A Recv Date: 910207
Part B Recv Date: 910211
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 46080
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251287

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Manifest Status: Completed copy
Trans1 State ID: 14645V-NY
Trans2 State ID: Not reported
Generator Ship Date: 910121
Trans1 Recv Date: 910121
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910121
Part A Recv Date: 910207
Part B Recv Date: 910131
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 50000
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251161
Manifest Status: Completed copy
Trans1 State ID: 85860D-NY
Trans2 State ID: Not reported
Generator Ship Date: 910121
Trans1 Recv Date: 910121
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910121
Part A Recv Date: 910207
Part B Recv Date: 910131
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 46700
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251080
Manifest Status: Completed copy
Trans1 State ID: 44580CNY
Trans2 State ID: Not reported
Generator Ship Date: 910116
Trans1 Recv Date: 910116
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910117
Part A Recv Date: 910125
Part B Recv Date: 910207
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 38320
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251224
Manifest Status: Completed copy
Trans1 State ID: 44562CNY
Trans2 State ID: Not reported
Generator Ship Date: 910118
Trans1 Recv Date: 910118
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

TSD Site Recv Date: 910118
Part A Recv Date: 910207
Part B Recv Date: 910207
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 43820
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251233
Manifest Status: Completed copy
Trans1 State ID: 8560DNY
Trans2 State ID: Not reported
Generator Ship Date: 910118
Trans1 Recv Date: 910118
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910118
Part A Recv Date: 910207
Part B Recv Date: 910207
Generator EPA ID: NYD986910057
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 41340
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METALS - USEPA ERRD (Continued)

1000447082

Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB2251431
Manifest Status: Completed copy
Trans1 State ID: 80724VNY
Trans2 State ID: Not reported
Generator Ship Date: 910328
Trans1 Recv Date: 910328
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910329
Part A Recv Date: 910405
Part B Recv Date: 910408
Generator EPA ID: NYD986910057
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 41820
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

[Click this hyperlink](#) while viewing on your computer to access
172 additional NY_MANIFEST: record(s) in the EDR Site Report.

AE129 **BERN METAL SITES**
ENE **18 BENDER ST**
1/2-1 **BUFFALO, NY**
0.568 mi.
3000 ft. **Site 5 of 7 in cluster AE**

LTANKS **S105996773**
N/A

Relative:
Equal

LTANKS:
Site ID: 225174
Spill No: 0275325
Spill Date: 9/17/2002
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial

Actual:
590 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METAL SITES (Continued)

S105996773

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 11/26/2002

Facility Addr2: Not reported

Cleanup Ceased: Not reported

Cleanup Meets Standard: True

SWIS: 1502

Investigator: JFOTTO

Referred To: Not reported

Reported to Dept: 9/17/2002

CID: 30

Water Affected: Not reported

Spill Notifier: Other

Last Inspection: 9/18/2002

Recommended Penalty: Penalty Not Recommended

UST Involvement: True

Remediation Phase: 0

Date Entered In Computer: 9/17/2002

Spill Record Last Update: 11/26/2002

Spiller Name: Not reported

Spiller Company: DAN TREDO

Spiller Address: 999 CLINTON

Spiller City,St,Zip: BUFFALO, NY 14206-

Spiller County: 001

Spiller Contact: LARRY LEECH CRA

Spiller Phone: (716) 853-2708

Spiller Extension: Not reported

DEC Region: 9

DER Facility ID: 185873

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"JFO" 09/18/02 JFO ON SITE MET WITH TONY OF NATURE'S WAY AND ANDY
FRAZIER (ENGINEER) WITH BBL. THE TANK IS OUT OF THE GROUND AND
SAMPLES ARE BEING COLLECTED NOW. THE CONTAMINATED SOIL HAS BEEN
PLACED ON PLASTIC. THIS IS A SUPERFUND SITE HANDLED BY JASPAL WALIA
OF DER. 11/14/02 JFO TELCON WITH GREG WEBER OF NATURE'S WAY. HE WILL
FORWARD THE ANALYTICAL RESULTS AND THE DISPOSAL RECEIPTS. 11/15/02
JFO RECEIVED THE DISPOSAL RECEIPTS FOR 460.85 TONS OF CONTAM SOIL AND
THE ANALYTICAL RESULTS FROM THE TANK PIT. RESULTS ARE NON-DETECT.
11/26/02 JFO CALL TO NATURE'S WAY FOR THE DISPOSAL RECEIPTS FOR THE
CONTAM LIQUID. HE WILL FAX. JFO RECEIVED THE RECEIPTS FOR 1200
GALLONS OF CONTAM WATER AND 4 DRUMS. NO FURTHER ACTION REQUIRED CLOSED
Not reported

Remarks: CONASTOGA ROVER ASSOC.HIRED NATURE'S WAY TO REMEDIATE THE SITE FOR
SEVERAL RP'S. THIS IS A HAZARDOUS WASTE SITE.

Material:

Site ID: 225174

Operable Unit ID: 865708

Operable Unit: 01

Material ID: 507686

Material Code: 0009

Material Name: Gasoline

Case No.: Not reported

Material FA: Petroleum

Quantity: 0

Units: Gallons

Recovered: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BERN METAL SITES (Continued)

S105996773

Resource Affected: Soil
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AF130
SW
1/2-1
0.570 mi.
3010 ft.

GIBRALTAR STEEL CORPORATION
635 SOUTH PARK AVENUE
BUFFALO, NY 14240

Site 1 of 2 in cluster AF

LTANKS
HIST LTANKS
UST
HIST UST

U003316387
N/A

Relative:
Equal

Actual:
590 ft.

LTANKS:
Site ID: 231814
Spill No: 9208402
Spill Date: 8/22/1992
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 10/19/1992
Facility Addr2: Not reported
Cleanup Ceased: 10/19/1992
Cleanup Meets Standard: True
SWIS: 1502
Investigator: BRENNAN
Referred To: Not reported
Reported to Dept: 10/19/1992
CID: 30
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/23/1992
Spill Record Last Update: 10/13/1999
Spiller Name: Not reported
Spiller Company: GIBRALTOR STEEL CORP.
Spiller Address: 635 SOUTH PARK AVENUE
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 9

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBRALTAR STEEL CORPORATION (Continued)

U003316387

DER Facility ID: 191016
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"KAB" 10/19/92: KAB - RECEIVED DOCUMENTATION CONFIRMING CLEANUP.
Remarks: RECEIVED REPORT FROM GREEN ENVIRONMENTAL. LETTER FROM GIBRALTAR METAL
STATED THAT, DURING EXCAVATION, TANK LEAKED VIRGIN #2 HEATING FUEL TO
THE SURROUNDING SOIL.

Material:

Site ID: 231814
Operable Unit ID: 975212
Operable Unit: 01
Material ID: 405504
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:

Region of Spill: 9
Spill Number: 9208402
Spill Date: 08/22/1992
Spill Time: 12:00
Spill Cause: Tank Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Possible release with minimal potential for fire or hazard or Known
release with no damage. DEC Response. Willing Responsible Party.
Corrective action taken.
Spill Closed Dt: 10/19/92
Cleanup Ceased: 10/19/92
Cleanup Meets Standard: True
Investigator: KAB
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBRALTAR STEEL CORPORATION (Continued)

U003316387

Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 10/19/92
Reported to Department Time: 14:00
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
Spiller Name: GIBRALTAR STEEL CORP.
Spiller Address: 635 SOUTH PARK AVENUE
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (716) 856-6500
Facility Extension: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/23/92
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/13/99
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Pounds
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 10/19/92: KAB - RECEIVED DOCUMENTATION CONFIRMING CLEANUP.
Spill Cause: RECEIVED REPORT FROM GREEN ENVIRONMENTAL. LETTER FROM GIBRALTAR METAL STATED THAT, DURING EXCAVATION, TANK LEAKED VIRGIN 2 HEATING FUEL TO THE SURROUNDING SOIL.

UST:

Facility Id: 9-018171

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBALTAR STEEL CORPORATION (Continued)

U003316387

Region: STATE
DEC Region: 9
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 185019.58978000001
UTM Y: 4753617.7868499998
Site ID: 52038

Tank Number: 1
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 8000
Tightness Test Method: 03
Next Test Date: Not reported
Date Tank Closed: 5/1/1993
Tank ID: 160522
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 11/1/1987
Register: True
Trade Sec: False
Modified By: TRANSLAT
Last Modified: 3/4/2004

Tank Number: 2
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 2/1/1977
Capacity Gallons: 6000
Tightness Test Method: 03
Next Test Date: Not reported
Date Tank Closed: 8/1/1992
Tank ID: 160523
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 11/1/1987
Register: True
Trade Sec: False
Modified By: TRANSLAT
Last Modified: 3/4/2004

UST_PBS_BSAFFIL:

Site Id: 52038
Program Number: 9-018171
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: GIBALTAR STEEL CORPORATION
Contact Type: Not reported
Contact Name: GIBALTAR STEEL CORPORATION
Address1: Not reported
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBALTAR STEEL CORPORATION (Continued)

U003316387

City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 856-6500
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 52038
Program Number: 9-018171
Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN
Company Name: GIBALTAR STEEL CORPORATION
Contact Type: Not reported
Contact Name: ERIC LIPKE
Address1: 635 SOUTH PARK AVENUE
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14240
Country Code: 001
Phone: (716) 856-6500
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 52038
Program Number: 9-018171
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: E
Company Name: GIBALTAR STEEL CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: 635 SOUTH PARK AVENUE
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14240
Country Code: 001
Phone: (716) 856-6500
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 52038
Program Number: 9-018171
Facility Type: Emergency Contact
Affiliation Type: 11

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBRALTAR STEEL CORPORATION (Continued)

U003316387

Affiliation Subtype: NNN
Company Name: GIBRALTAR STEEL CORPORATION
Contact Type: Not reported
Contact Name: TOM GREEN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 856-6500
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

UST_AST_PBS_BSEQUIP:

Site Id: 52038
Tank Id Number: 160522
Tank Number: 1
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 52038
Tank Id Number: 160523
Tank Number: 2
Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Site Id: 52038
Tank Id Number: 160523
Tank Number: 2
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 52038
Tank Id Number: 160522
Tank Number: 1
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 52038
Tank Id Number: 160523
Tank Number: 2
Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 52038
Tank Id Number: 160522
Tank Number: 1
Equipment: I04

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBRALTAR STEEL CORPORATION (Continued)

U003316387

Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 52038
Tank Id Number: 160522
Tank Number: 1
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 52038
Tank Id Number: 160523
Tank Number: 2
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 52038
Tank Id Number: 160523
Tank Number: 2
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 52038
Tank Id Number: 160522
Tank Number: 1
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 52038
Tank Id Number: 160522
Tank Number: 1
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 52038
Tank Id Number: 160523
Tank Number: 2
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 52038
Tank Id Number: 160522
Tank Number: 1
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 52038
Tank Id Number: 160523
Tank Number: 2
Equipment: C00
Code Name: No Piping

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBALTAR STEEL CORPORATION (Continued)

U003316387

Type:	Pipe Location
Site Id:	52038
Tank Id Number:	160522
Tank Number:	1
Equipment:	D01
Code Name:	Steel/Carbon Steel/Iron
Type:	Pipe Type
Site Id:	52038
Tank Id Number:	160523
Tank Number:	2
Equipment:	D01
Code Name:	Steel/Carbon Steel/Iron
Type:	Pipe Type
Site Id:	52038
Tank Id Number:	160523
Tank Number:	2
Equipment:	F00
Code Name:	None
Type:	Pipe External Protection
Site Id:	52038
Tank Id Number:	160522
Tank Number:	1
Equipment:	F00
Code Name:	None
Type:	Pipe External Protection

HIST UST:

PBS Number:	9-018171
SPDES Number:	Not reported
Emergency Contact:	TOM GREEN
Emergency Telephone:	(716) 856-6500
Operator:	GIBALTAR STEEL CORPORATION
Operator Telephone:	(716) 856-6500
Owner Name:	GIBALTAR STEEL CORPORATION
Owner Address:	635 SOUTH PARK AVENUE
Owner City,St,Zip:	BUFFALO, NY 14240
Owner Telephone:	(716) 856-6500
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	GIBALTAR STEEL CORPORATION
Mailing Address:	635 SOUTH PARK AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BUFFALO, NY 14240
Mailing Contact:	ERIC LIPKE
Mailing Telephone:	(716) 856-6500
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	1402
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBRALTAR STEEL CORPORATION (Continued)

U003316387

Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 03/05/1993
Expiration Date: 09/19/1996
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 0
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: 0
Dead Letter: False
CBS Number: Not reported
Town or City: BUFFALO (C)
County Code: 14
Town or City: 02
Region: 9

Tank Id: 1
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 8000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: 11/01/1987
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 05/01/1993
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: 42I52I09 / 78I51I24

Tank Id: 2
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: 19770201
Capacity (gals): 6000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GIBRALTAR STEEL CORPORATION (Continued)

U003316387

Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: 11/01/1987
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 08/01/1992
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: 42I52I09 / 78I51I24

**AG131
WNW
1/2-1
0.570 mi.
3010 ft.**

**FARGO ELECTRIC
493-503 SENECA ST
BUFFALO, NY**

**LTANKS S105997724
N/A**

Site 1 of 2 in cluster AG

**Relative:
Lower**

**Actual:
587 ft.**

LTANKS:
Site ID: 209278
Spill No: 0275500
Spill Date: 12/1/2002
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 5/1/2003
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 1502
Investigator: JFOTTO
Referred To: Not reported
Reported to Dept: 12/23/2002
CID: 30
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/29/2003
Spill Record Last Update: 5/14/2003
Spiller Name: Not reported
Spiller Company: CITY OF BUFFALO
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 001
Spiller Contact: LARRY SCHIAVONE
Spiller Phone: (716) 851-4914
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 173550
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number

EPA ID Number

FARGO ELECTRIC (Continued)

S105997724

Remarks: "JFO" 12/23/02 JFO RECEIVED THE RESULTS OF A BOTTOM SAMPLE FROM A TANK PIT EXCAVATION. THE SEMI VOLATILES ARE SLIGHTLY ABOVE TAGMS. JFO CALLED ANDY MCLELLAN AND REQUESTED SIDEWALL ANALYTICAL RESULTS. EXCAVATION IS STILL OPEN. HE WILL SAMPLE. 01/08/03 JFO REC'D THE SIDEWALL RESULTS. NORTH AND WEST SIDEWALL ARE ALSO SLIGHTLY ABOVE TAGMS. NEED DISPOSAL RECEIPTS. THIS SITE WILL BE INACTIVE. SEE SPILL #0275134 FOR FURTHER INFORMATION. 05/01/03 JFO RECEIVED THE DISPOSAL RECEIPTS FOR 142.38 TONS ON CONTAMINATED SOIL. NO FURTHER ACTION REQUIRED AT THIS TIME THIS SITE IS INACTIVE. CLOSED JFO REC'D ANALYTICAL RESULTS FOR A TANK PULL.

Material:

Site ID: 209278
Operable Unit ID: 865886
Operable Unit: 01
Material ID: 507866
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AG132
WNW
1/2-1
0.573 mi.
3023 ft.

FRANK RICHES SERVICE
490 SENECA STREET
BUFFALO, NY

Site 2 of 2 in cluster AG

LTANKS **S100119593**
HIST LTANKS **N/A**

Relative:
Lower

Actual:
587 ft.

LTANKS:

Site ID: 200032
Spill No: 9609364
Spill Date: 10/26/1996
Spill Cause: Tank Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 9/29/1997
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FRANK RICHES SERVICE (Continued)

S100119593

SWIS: 1502
Investigator: RMCROSSE
Referred To: Not reported
Reported to Dept: 10/26/1996
CID: 30
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 9/25/1997
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/26/1996
Spill Record Last Update: 11/13/1997
Spiller Name: RAYMOND MONTANEZ
Spiller Company: RAMON MONTANEZ
Spiller Address: 490 SENECA STREET
Spiller City,St,Zip: BUFFALO, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 166470
DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"RMC" 10/28/96 RMC/SITE THREE OF SIX TANKS PULLED, DIGGING OUT
CONTAMINATION, TO REINSPECT, 10/30/96 RMC/NATURE'S WAY INC.
CONTRACTOR (NWI)/SITE ALL KNOWN TANKS REMOVED, SAMPLES TAKEN, 100
YARDS SOIL STOCKPILED, DISPOSAL AND SAMPLING DUE 11/30/96 11/22/96
RMC/FILE RECEIVED EXCAVATION SAMPLE RESULTS, NO EXCEEDANCES, PLAN TO
BIO TREAT SOIL ON SITE, HAZARDOUS DETERMINATION SAMPLING DUE 12/15/96
12/31/96 RMC/NWI/PHONE REQUESTED LETTER ON SITE, DUE 1/15/97 01/29/97
RMC/NWI/PHONE AGAIN REQUESTED SAMPLING AND LETTER ON SITE, DUE
2/15/97 01/29/97 RMC/FILE RECEIVED ANALYSIS REQUIRED, FIRST BIO ROUND
DUE 5/30/97 06/03/97 RMC/WEBER/PHONE NWI ARE ACTIVELY BIOTREATING
SOIL, RESULTS DUE 8/30/97 07/14/97 RMC/SITE BIO PILES HAVE WEEDS
GROWING ON THEM, RMC ADVISED NWI TO TILL, REINSPECT 7/30 08/27/97
RMC/FILE NO RESULTS ON FILE FOR SOIL UNDER TREATMENT, LETTER,
RESPONSE DUE 9/26 09/29/97 RMC/FILE RECEIVED FOUR STARS GASOLINE
SAMPLES FOR THE SOIL UNDER TREATMENT, NO EXCEEDANCES, RMC QUESTIONED
WHY JUST STARS GASOLINE WAS RUN, ACCORDING TO RUSS SAVAGE, OF NWI, NO
CONTAMINATION WAS FOUND AROUND THE WASTE OIL OR DIESEL TANKS, RMC
REVIEWED FILE, NO EXCEEDANCES IN ANY EXCAVATION SAMPLES, NO FURTHER
ACTION REQUIRED, CLOSE OUT 05/07/98 RMC/RUSS SAVAGE/PHONE OWNER NEEDS
TO HAVE BIOTREATED SOIL REMOVED FROM PROPERTY, SAVAGE CAN USE AS FILL
ON HIS SITE ON BROADWAY IN ALDEN. RMC/RNL/MEETING OK PER RNL
during tank pull contaminated soil found

Remarks:

Material:
Site ID: 200032
Operable Unit ID: 1037453
Operable Unit: 01
Material ID: 345088
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FRANK RICH'S SERVICE (Continued)

S100119593

Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 200031
Spill No: 8710277
Spill Date: 3/8/1988
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Not reported
Spill Closed Dt: 5/16/1988
Facility Addr2: Not reported
Cleanup Ceased: 5/16/1988
Cleanup Meets Standard: True
SWIS: 1502
Investigator: COOKE
Referred To: Not reported
Reported to Dept: 3/8/1988
CID: 30
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 3/9/1988
Spill Record Last Update: 6/6/1988
Spiller Name: Not reported
Spiller Company: FRANK RICH SERVICE
Spiller Address: 490 SENECA STREET
Spiller City,St,Zip: BUFFALO, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 9
DER Facility ID: 166470
DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"JDC" 03/09/88: JDC TELCON W/ MR RICH, FACILITY OWNER - TANK TO BE
RETESTED 3/15/88 OR PRODUCT MUST BE REMOVED. 03/28/88: JDC TELCON W/
MR RICH 3/28/88 - RETEST COMPLETED (NO FAILURE) RETEST RESULTS BEING
FORWARDED. WILL CLOSE FILE UPON RECEIPT OF RETEST RESULTS. 05/16/88:
JDC RECEIVED TEST RESULTS AS REQUESTED NO FURTHER ACTION WILL BE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FRANK RICHES SERVICE (Continued)

S100119593

Remarks: REQUIRED.
3000 GAL STORAGE TANK FAILED PETRO TITE TESTING. RETEST SCHEDULED
FOR 3/15/88 BY FLEISCHMANS.

Material:

Site ID: 200031
Operable Unit ID: 915979
Operable Unit: 01
Material ID: 462050
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Groundwater
Oxygenate: False

Tank Test:

Site ID: 200031
Spill Tank Test: 1533398
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:

Region of Spill: 9
Spill Number: 9609364
Spill Date: 10/26/1996
Spill Time: 09:45
Spill Cause: Tank Failure
Resource Affected: On Land
Water Affected: Not reported
Spill Source: Gas Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 09/29/97
Cleanup Ceased: / /
Cleanup Meets Standard: True
Investigator: RMC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 10/26/96

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FRANK RICH'S SERVICE (Continued)

S100119593

Reported to Department Time: 10:06
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
Spiller Name: RAMON MONTANEZ
Spiller Address: 490 SENECA STREET
Spiller City,St,Zip: BUFFALO, NY
Spiller Cleanup Date: / /
Facility Contact: RAYMOND MONTANEZ
Facility Phone: Not reported
Facility Extension: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: 09/25/97
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/26/96
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 11/13/97
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929

DEC Remarks: 10/28/96 RMC/SITE THREE OF SIX TANKS PULLED, DIGGING OUT CONTAMINAITON, TO REINSPECT, 10/30/96 RMC/NATURE S WAY INC. CONTRACTOR (NWI)/SITE ALL KNOWN TANKS REMOVED, SAMPLES TAKEN, 100 YARDS SOIL STOCKPILED, DISPOSAL AND SAMPLING DUE 11/30/96 11/22/96RMC/FILE RECEIVED EXCAVATION SAMPLE RESULTS, NO EXCEEDANCES, PLAN TO BIO TREAT SOIL ON SITE, HAZARDOUS DETERMINATION SAMPLING DUE 12/15/96 12/31/96 RMC/NWI/PHONE REQUESTED LETTER ON SITE, DUE 1/15/97 01/29/97 RMC/NWI/PHONE AGAIN REQUESTED SAMPLING AND LETTER ON SITE, DUE 2/15/97 01/29/97 RMC/FILE RECIEVED ANALYSIS REQUIRED, FIRST BIO ROUND DUE 5/30/97 06/03/97 RMC/WEBER/PHONE NWI ARE ACTIVELY BIOTREATING SOIL, RESULTS DUE 8/30/97 07/14/97 RMC/SITE BIO PILES HAVE WEEDS GROWING ON THEM, RMC ADVISED NWI TO TILL, REINSPECT 7/30 08/27/97 RMC/FILE NO RESULTS ON FILE FOR SOIL UNDER TREATMENT,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FRANK RICH'S SERVICE (Continued)

S100119593

LETTER, RESPONSE DUE 9/26 09/29/97 RMC/FILE RECEIVED FOUR STARS GASOLINE
SAMPLES FOR THE SOIL UNDER TREATMENT, NO EXCEEDANCES, RMC QUESTIONED WHY JUST
STARS GASOLINE WAS RUN, ACCORDING TO RUSS SAVAGE, OF NWI, NO CONTAMINATION WAS
FOUND AROUND THE WASTE OIL OR DIESEL TANKS, RMC REVIEWED FILE, NO EXCEEDANCES
IN ANY EXCAVATION SAMPLES, NO FURTHER ACTION REQUIRED, CLOSE OUT 05/07/98
RMC/RUSS SAVAGE/PHONEOWNER NEEDS TO HAVE BIOTREATED SOIL REMOVED FROM PROPERTY,
SAVAGE CAN USE AS FILL ON HIS SITE ON BROADWAY IN ALDEN. RMC/RNL/MEETING OK PER
RNL

Spill Cause: during tank pull contaminated soil found

Region of Spill: 9
Spill Number: 8710277
Spill Date: 03/08/1988
Spill Time: 13:45
Spill Cause: Tank Test Failure
Resource Affected: Groundwater
Water Affected: Not reported
Spill Source: Gas Station
Spill Class: Not reported
Spill Closed Dt: 05/16/88
Cleanup Ceased: 05/16/88
Cleanup Meets Standard: True
Investigator: JDC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 03/08/88
Reported to Department Time: 13:45
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
Spiller Name: FRANK RICH SERVICE
Spiller Address: 490 SENECA STREET
Spiller City, St, Zip: BUFFALO, NY
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (716) 856-6814
Facility Extension: Not reported
Spill Notifier: Responsible Party
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 03/09/88
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 06/06/88
Is Updated: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FRANK RICH'S SERVICE (Continued)

S100119593

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728

DEC Remarks: 03/09/88: JDC TELCON W/ MR RICH, FACILITY OWNER - TANK TO BE RETESTED 3/15/88 OR PRODUCT MUST BE REMOVED. 03/28/88: JDC TELCON W/ MR RICH 3/28/88 - RETEST COMPLETED (NO FAILURE) RETEST RESULTS BEING FORWARDED. WILL CLOSE FILE UPON RECIEPT OF RETESTRESULTS. 05/16/88: JDC RECIEVED TEST RESULTES AS REQUESTED NO FURTHER ACTION WILL BE REQUIRED.

Spill Cause: 3000 GAL STORAGE TANK FAILED PETRO TITE TESTING. RETEST SCHEDULED FOR 3/15/88 BY FLEISCHMANS.

AE133 MAX BROCK COMPANY; INC.
ENE 18 METCALFE STREET
1/2-1 BUFFALO, NY 14206

SWRCY S106860924
N/A

0.575 mi.
3035 ft.

Site 6 of 7 in cluster AE

Relative:
Higher

Actual:
591 ft.

SWRCY:

Region: 9
Facility Address 2: Not reported
Phone Number: 7168526662
Owner Type: Not reported
Owner Name: Laurie Brock Lisk
Owner Address: 18 Metcalfe St
Owner Address 2: Not reported
Owner City,St,Zip: Buffalo 14206
Owner Email: Not reported
Owner Phone: 7168526662
Contact Name: Laurie Brock Lisk
Contact Address: Max Brock Company; Inc.
Contact Address 2: 18 Metcalfe Street
Contact City,St,Zip: Buffalo, NY 14206
Contact Email: Not reported
Contact Phone: 7168526662
Activity Desc: Source separated solid waste recyclables
Activity Number: 15M18
Active: Yes
East Coordinate: 186588
North Coordinate: 4754596
Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
Regulatory Status: Registration

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MAX BROCK COMPANY; INC. (Continued)

S106860924

Permit #: 15M18
Auth. Date: 3/1/2005
Expiration Date: Not reported
Waste Types: Paper (All Types)

AE134
ENE
1/2-1
0.575 mi.
3036 ft.

CLINTON ST. - BENDER AVE
CLINTON ST. & BENDER AVE
BUFFALO, NY 14206

CERCLIS **1000481606**
FINDS **NYD986954030**

Site 7 of 7 in cluster AE

Relative:
Equal

CERCLIS:
Site ID: 0203487
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

Actual:
590 ft.

CERCLIS Site Contact Name(s):

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20001

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20001

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 22700

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20002

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20000

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLINTON ST. - BENDER AVE (Continued)

1000481606

Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20002

Site Description: RES NEIGHB. CONTAM. W/LEAD FRM ADJ BERN MTL INC. - SURFACE WTR RUNOFF. SITE
HIGHER IN ELEV & SURFACE WTR CARRIED LEAD ENTRAINED PARTICULATES FRM BERN MTL
INC. INTO RESIDEN SOIL.

CERCLIS Assessment History:

Action: Notice Letters Issued
Date Started: Not reported
Date Completed: 4/20/1992 0:00:00
Priority Level: Not reported

Action: UNILATERAL ADMIN ORDER
Date Started: Not reported
Date Completed: 6/19/1992 0:00:00
Priority Level: Not reported

Action: Public Notice Published
Date Started: Not reported
Date Completed: 7/31/1992 0:00:00
Priority Level: Not reported

Action: REMOVAL ASSESSMENT
Date Started: 11/26/1990 0:00:00
Date Completed: 8/18/1992 0:00:00
Priority Level: Not reported

Action: NON-NPL PRP SEARCH
Date Started: 12/1/1992 0:00:00
Date Completed: 8/10/1993 0:00:00
Priority Level: Not reported

Action: ADMIN ORDER ON CONSENT
Date Started: Not reported
Date Completed: 9/30/1993 0:00:00
Priority Level: Not reported

Action: PREPARATION OF COST DOCM PKGE
Date Started: Not reported
Date Completed: 12/8/1993 0:00:00
Priority Level: Not reported

Action: PRP REMOVAL
Date Started: 7/6/1992 0:00:00
Date Completed: 1/11/1995 0:00:00
Priority Level: Stabilized

Action: PRP REMOVAL
Date Started: 9/30/1993 0:00:00
Date Completed: 11/20/1998 0:00:00
Priority Level: Partially Cleaned up

Action: ADMINISTRATIVE RECORDS
Date Started: 7/31/1992 0:00:00
Date Completed: 5/4/2005 0:00:00
Priority Level: Admin Record Compiled for a Removal Event

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLINTON ST. - BENDER AVE (Continued)

1000481606

FINDS:

Registry ID: 110009342817

Environmental Interest/Information System

CERCLIS (Comprehensive Environmental Response, Compensation, and Liability Information System) is the Superfund database that is used to support management in all phases of the Superfund program. The system contains information on all aspects of hazardous waste sites, including an inventory of sites, planned and actual site activities, and financial information.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

**AF135
SW
1/2-1
0.576 mi.
3039 ft.**

**SAFETY KLEEN
FOOT OF KATHERINE STREET
BUFFALO, NY**

**LTANKS S103038244
HIST LTANKS N/A**

Site 2 of 2 in cluster AF

**Relative:
Lower**

LTANKS:

Site ID: 231074
Spill No: 9408523
Spill Date: 9/26/1994
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

**Actual:
589 ft.**

Spill Closed Dt: 12/12/1994
Facility Addr2: Not reported
Cleanup Ceased: 12/12/1994
Cleanup Meets Standard: True
SWIS: 1502
Investigator: RMCROSSE
Referred To: Not reported
Reported to Dept: 9/27/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: 9/27/1994
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY KLEEN (Continued)

S103038244

Date Entered In Computer: 10/1/1994
Spill Record Last Update: 12/16/1994
Spiller Name: Not reported
Spiller Company: BOOTH OIL CO
Spiller Address: KATHERINE STREET
Spiller City,St,Zip: BUFFALO, NY 14205
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 190427
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"RMC" 09/27/94: RMC/COUCH/SITE AG TANK OVERFILL TO ROOF, THRU DOWN
SPOUTS TO GROUND, 12 55 GALLON DRUMS FOR NORMAL DISPOSAL, REPORT ON
SPILL AND WHY SPILL NOT REPORTED W/IN TWO HOURS DUE 10/30/94.
10/13/94: RMC/COUCH/SITE RECEIVED REPORT, DISPOSAL RECEIPT DUE
11/30/94. 12/12/94: RMC/CHARLIE COUCH/PHONE DISPOSAL RECEIPT TO BE
SENT DUE 12/30/94. 12/12/94: RMC/RECEIVED DISPOSAL RECEIPTS, OK,
CLOSE OUT.
Remarks: TANK OVER FILL

Material:
Site ID: 231074
Operable Unit ID: 1002654
Operable Unit: 01
Material ID: 377964
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 25
Units: Gallons
Recovered: 24
Resource Affected: Soil
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:
Region of Spill: 9
Spill Number: 9408523
Spill Date: 09/26/1994
Spill Time: 14:00
Spill Cause: Tank Overfill

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY KLEEN (Continued)

S103038244

Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/12/94
Cleanup Ceased: 12/12/94
Cleanup Meets Standard: True
Investigator: RMC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 09/27/94
Reported to Department Time: 11:39
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: BOOTH OIL CO
Spiller Address: KATHERINE STREET
Spiller City,St,Zip: BUFFALO, NY 14205
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (716) 855-2212
Facility Extention: Not reported
Spill Notifier: Responsible Party
PBS Number: Not reported
Last Inspection: 09/27/94
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/01/94
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 12/16/94
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 25
Unkonwn Quantity Spilled: False
Units: Gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY KLEEN (Continued)

S103038244

Quantity Recovered: 24
Unkonwn Quantity Recovered: False
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927
DEC Remarks: 09/27/94: RMC/COUCH/SITE AG TANK OVERFILL TO ROOF, THRU DOWN SPOUTS TO GROUND, 12 55 GALLON DRUMS FOR NORMAL DISPOSAL, REPORT ON SPILL AND WHY SPILL NOT REPORTED W/IN TWO HOURS DUE 10/30/94. 10/13/94: RMC/COUCH/SITE RECEIVED REPORT, DISPOSAL RECEIPT DUE 11/30/94. 12/12/94: RMC/CHARLIE COUCH/PHONE DISPOSAL RECEIPT TO BE SENT DUE 12/30/94. 12/12/94: RMC/RECEIVED DISPOSAL RECEIPTS, OK, CLOSE OUT.
Spill Cause: TANK OVER FILL

AH136
ESE
1/2-1
0.598 mi.
3159 ft.
Site 1 of 2 in cluster AH

BUFFALO CITY ENGINEERING
1120 SENECA STREET
BUFFALO, NY

LTANKS
HIST LTANKS
S100118244
N/A

Relative:
Higher

Actual:
592 ft.

LTANKS:
Site ID: 326294
Spill No: 8910196
Spill Date: 1/24/1990
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Spill Closed Dt: 11/27/1990
Facility Addr2: Not reported
Cleanup Ceased: 11/27/1990
Cleanup Meets Standard: True
SWIS: 1502
Investigator: PRINGLE
Referred To: Not reported
Reported to Dept: 1/24/1990
CID: 30
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: 2/15/1990
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1/29/1990
Spill Record Last Update: 12/4/1990
Spiller Name: Not reported
Spiller Company: CITY OF BUFFALO - ENGIN.
Spiller Address: ROOM 502 - CITY HALL
Spiller City,St,Zip: BUFFALO, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 262861
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MNP" 01/24/90: 1/24/90 LETTER TO COMERFORD, OPTION TO RETEST OR REMOVE TANK. 11/27/90: 11/27/90 MNP FILE REVIEW NO CONTAM. FOUND

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY ENGINEERING (Continued)

S100118244

Remarks: DURING INSP. & FINAL TANK SYSTEM TESTS ARE O.K. NO FURTHER ACTION
NEEDED, COMPLETE.
2,000 GAL. UST TANK FAILED SYSTEM TEST AT -0.4104 GPH

Material:

Site ID: 326294
Operable Unit ID: 935274
Operable Unit: 01
Material ID: 443315
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Groundwater
Oxygenate: False

Tank Test:

Site ID: 326294
Spill Tank Test: 1536718
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:

Region of Spill: 9
Spill Number: 8910196
Spill Date: 01/24/1990
Spill Time: 11:45
Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 11/27/90
Cleanup Ceased: 11/27/90
Cleanup Meets Standard: True
Investigator: MNP
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 01/24/90
Reported to Department Time: 12:10

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO CITY ENGINEERING (Continued)

S100118244

SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: CITY OF BUFFALO - ENGIN.
Spiller Address: ROOM 502 - CITY HALL
Spiller City,St,Zip: BUFFALO, NY
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (716) 851-4144
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: Not reported
Last Inspection: 02/15/90
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 01/29/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 12/04/90
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 01/24/90: 1/24/90 LETTER TO COMERFORD, OPTION TO RETEST OR REMOVE TANK.
11/27/90: 11/27/90 MNP FILE REVIEW NO CONTAM. FOUND DURING INSP. FINAL TANK
SYSTEM TESTS ARE O.K. NO FURTHER ACTION NEEDED, COMPLETE.
Spill Cause: 2,000 GAL. UST TANK FAILED SYSTEM TEST AT -0.4104 GPH

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site Database(s) EDR ID Number
EPA ID Number

AH137 1132-1146 SENECA ST.
ESE 1132-1146 SENECA STREET
1/2-1 BUFFALO, NY 14240

BROWNFIELDS S109823664
N/A

0.612 mi.
3232 ft.

Site 2 of 2 in cluster AH

Relative:
Higher

BROWNFIELDS:

Program: BCP

Site Code: 391766

Actual:
592 ft.

Site Description:

The 1132-1146 Seneca St. Site is located in an urban area. The site is located at 1132 and 1146 Seneca Street, Buffalo, Erie County. The main site features include one large abandoned building with a small open grass and gravel area to the northeast and southeast. About one half of the site area is grass covered. The site is currently inactive, and the northwest portion is zoned for manufacturing and processing and the southeast portion is zoned for vacant industrial use. The surrounding parcels are currently used for a combination of municipal, residential, commercial, light industrial, and transportation right-of-ways. The nearest residential area is less than 0.125 miles southwest. Until 2007 the site was used for manufacturing of fiberglass products. Prior uses also include manufacture of electrical equipment, lumber operations, gasoline retail, and automobile repair. Prior uses that appear to have led to site contamination include chemical storage and handling, fuel storage and handling, metal cleaning, treatment of fuel contaminated soils, and release of polychlorinated biphenyls (PCBs). The site remedial program is being performed by Flexo Transparent Inc. as a volunteer in the DEC's Brownfield Cleanup Program. In 1990 a remedial action was carried out at the site which resulted in the excavation and off-site disposal of two PCB sludge piles located in the northeast portion of the site. In 2001 a Phase I Environmental Site Assessment (ESA) and a Limited Phase II Site Investigation was conducted. In 2007, another Phase I ESA was conducted and in 2008 a Phase II investigation was performed. A Remedial Investigation and Interim Remedial Measure Work Plan was approved by the DEC in 2009, and is expected to be implemented in mid/late 2009.

Env Problem: An assessment summary will be provided when sufficient information becomes available to complete the assessment.

Health Problem: A health assessment summary will be provided when sufficient information becomes available to complete the assessment.

138 BUFFALO COLOR - DEEPWELL
SSE 340 ELK STREET
1/2-1 BUFFALO, NY

HSWDS S108146702
N/A

0.627 mi.
3308 ft.

Relative:
Lower

HSWDS:

Facility ID: Not reported

Region: 9

Facility Status: Unknown

Owner Type: Puplic

Owner: Buffalo Color Corp.

Owner Address: PO Box 7027

Owner Phone: Unknown

Operator Type: Puplic

Operator: Allied Chemical

Operator: Allied Chemical

Operator Phone: Unknown

EPA ID: NYD980507729

Actual:
589 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR - DEEPWELL (Continued)

S108146702

Registry: D
Registry Site ID: 915012C
RCRA Permitted: Unknown
Site Code: Leaking tanks, drums, lagoons, other containers
Owner City State: Buffalo, NY
Operator City State: Buffalo, NY
Quadrangle: Unknown
Latitude: Unk
Longitude: Unk
Acres: 1.00
Operator Date: 1957
Close Date: 1963
Completed: Unk
Active: Unknown
PCB's Disposed: No
Pesticides Disposed: No
Metals Disposed: Yes
Asbestos Disposed: No
Volatile Organic Compounds Disposed: No
Semi Volatile Organic Compounds Disposed: No
Analytical Info Exists for Air: Not reported
Analytical Info Exists for Ground: Groundwater
Analytical Info Exists for Surface: Not reported
Analytical Info Exists for Sediments: Not reported
Analytical Info Exists for Surface: Surface Soil
Analytical Info Exists for Substance: Subsurface
Analytical Info Exists for Waste: Not reported
Analytical Info Exists for Leachate: Not reported
Analytical Info Exists for EP Toxicity: Not reported
Analytical Info Exists for TCLP: Not reported
Threat to Environment/Public Health: N
Surface Water Contamination: Unknown
Surface Water Body Class: Unknown
Groundwater Contamination: Unknown
Groundwater Classification: Unknown
Drinking Water Contamination: Unknown
Drinking Water Supply is Active: Unknown
Any Known Fish or Wildlife: Unknown
Hazardous Exposure: Unknown
Site Has Controlled Access: Unknown
Ambient Air Contamination: Unknown
Direct Contact: Unknown
EPA Hazardous Ranking System Score: Unknown
Inventory: F
Nefrap: Not reported
Mailing: Not reported
Tax Map No: Not reported
Qualify: 0
Next Action: Not reported
Agencies: Not reported
Air: Not reported
Building: Not reported
Site Desc: Not reported
Drink: Not reported
Eptox: Not reported
Fish: Not reported
Ground: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR - DEEPWELL (Continued)

S108146702

Ground Desc: Not reported
Hazardous Threat: Not reported
Haz Threat Desc: Not reported
Leachate: Not reported
Preparer: Not reported
Sediment: Not reported
Soil: Not reported
Surface: Not reported
Status: Not reported
Surface Soil: Not reported
Surface: Not reported
TCLP: Not reported
Waste: Not reported

AI139 **HONEYWELL INC. BUFFALO RESEARCH LABORATO**
SE **20 PEABODY ST**
1/2-1 **BUFFALO, NY 14210**
0.634 mi.
3350 ft. **Site 1 of 2 in cluster AI**

Relative:
Higher

Actual:
593 ft.

RCRA-TSDF **1000248676**
CORRACTS **NYD000632315**
RCRA-LQG
FINDS
LTANKS
CBS AST
MANIFEST
MANIFEST
MANIFEST
NY Spills
NY Hist Spills
CBS

RCRA-TSDF:

Date form received by agency: 01/01/2007
Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO
Facility address: 20 PEABODY ST.
BUFFALO, NY 14210
EPA ID: NYD000632315
Mailing address: SAME AS ITEM #4
SAME AS ITEM #4, NY 14210
Contact: LANA L DOLE
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: (716) 827-6318
Contact email: LANA.DOLE@HONEYWELL.COM
EPA Region: 02
Land type: Private
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste
TSD commencement date: Not reported
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

hazardous waste during any calendar month, and accumulates more than
100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: HONEYWELL INTERNATIONAL, INC.
Owner/operator address: COLUMBIA RD. & PARK AVE.
MORRISTOWN, NJ 07960
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/01/1999
Owner/Op end date: Not reported

Owner/operator name: ALLIED SIGNAL INC
Owner/operator address: 101 COLUMBIA RD
MORRISTOWN, NJ 07962
Owner/operator country: US
Owner/operator telephone: (201) 455-2000
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: HONEYWELL INTERNATIONAL INC
Owner/operator address: 101 COLUMBIA RD
MORISTOWN, NJ 07962
Owner/operator country: US
Owner/operator telephone: (201) 455-2000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Yes
Mixed waste (haz. and radioactive): Yes
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: Yes
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 02/23/2006
Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO
Classification: Large Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Date form received by agency: 02/22/2006

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Classification: Large Quantity Generator

Date form received by agency: 02/20/2004

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: HONEYWELL BUFFALO RESEARCH LABORATORY

Classification: Large Quantity Generator

Date form received by agency: 02/18/2002

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: HONEYWELL INTERNATIONAL INC.

Classification: Large Quantity Generator

Date form received by agency: 01/01/2001

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: HONEYWELL INC.

Classification: Large Quantity Generator

Date form received by agency: 04/24/2000

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: HONEYWELL INC - BUFFALO RESEARCH

Classification: Large Quantity Generator

Date form received by agency: 04/08/1998

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: HONEYWELL INC - BUFFALO RESEARCH

Classification: Not a generator, verified

Date form received by agency: 02/23/1998

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: ALLIED SIGNAL INC.

Classification: Large Quantity Generator

Date form received by agency: 03/25/1996

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: ALLIED SIGNAL INC BUFFALO RESEARCH LAB

Classification: Large Quantity Generator

Date form received by agency: 03/29/1994

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: ALLIED SIGNAL INC BUFFALO RESEARCH LAB

Classification: Large Quantity Generator

Date form received by agency: 02/27/1992

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: ALLIED SIGNAL

Classification: Large Quantity Generator

Date form received by agency: 09/26/1991

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: HONEYWELL INC - BUFFALO RESEARCH

Classification: Large Quantity Generator

Date form received by agency: 03/01/1990

Facility name: HONEYWELL INC. BUFFALO RESEARCH LABORATO

Site name: ALLIED SIGNAL CORPORATION

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2007

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 97541

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 256339

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Amount (Lbs): 90

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 10

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 2494

Waste code: D022
Waste name: CHLOROFORM
Amount (Lbs): 3491

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 585

Waste code: D038
Waste name: PYRIDINE
Amount (Lbs): 541

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 541

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 866

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 9244

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 2494

Waste code: LABP
Waste name: LAB PACK
Amount (Lbs): 3137

Waste code: P030
Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED
Amount (Lbs): 2

Waste code: P106
Waste name: SODIUM CYANIDE
Amount (Lbs): 2

Waste code: U028
Waste name: 1,2-BENZENEDICARBOXYLIC ACID, BIS(2-ETHYLHEXYL) ESTER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Amount (Lbs): 250

Waste code: U123
Waste name: FORMIC ACID (C,T)
Amount (Lbs): 480

Waste code: U226
Waste name: ETHANE, 1,1,1-TRICHLORO-
Amount (Lbs): 25

Waste code: U328
Waste name: BENZENAMINE, 2-METHYL-
Amount (Lbs): 25

Corrective Action Summary:

Event date: 11/14/1990
Event: Notice of Contamination

Event date: 04/22/1991
Event: RFA Initiation

Event date: 04/22/1991
Event: RFA Initiation

Event date: 07/08/1991
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 08/09/1991
Event: RFA Completed

Event date: 08/27/1991
Event: CA012

Event date: 09/10/1991
Event: CA017

Event date: 06/01/1992
Event: CA023

Event date: 06/01/1992
Event: RFI Imposition

Event date: 08/11/1992
Event: CA026

Event date: 11/09/1992
Event: CA027

Event date: 03/22/1993
Event: CA028

Event date: 04/23/1993
Event: CA033

Event date: 08/11/1993

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Event:	CA037
Event date:	12/07/1993
Event:	RFA Completed
Event date:	12/07/1993
Event:	RFA Determination Of Need For An RFI, RFI is Necessary;
Event date:	12/07/1993
Event:	CA038
Event date:	04/06/1994
Event:	RFI Workplan Received
Event date:	04/06/1994
Event:	RFI Workplan Received
Event date:	05/19/1994
Event:	RFI Workplan Notice Of Deficiency Issued
Event date:	07/06/1994
Event:	Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time, because it appears to be technically infeasible or inappropriate.
Event date:	07/07/1994
Event:	CA145
Event date:	08/05/1994
Event:	RFI Workplan Approved
Event date:	09/26/1994
Event:	RFI Supplemental Implementation Begun
Event date:	10/12/1994
Event:	FI Progress Reports Received
Event date:	08/25/1995
Event:	CA183
Event date:	10/15/1997
Event:	CMS Approved
Event date:	12/11/1997
Event:	CA403
Event date:	03/09/1998
Event:	CMI Workplan Approved
Event date:	05/17/1999
Event:	Certification Of Remedy Completion Or Construction Completion

Facility Has Received Notices of Violations:

Regulation violated:	Not reported
Area of violation:	TSD - General
Date violation determined:	11/10/2000
Date achieved compliance:	02/26/2001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/24/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 04/17/1996
Date achieved compliance: 02/12/1997
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 04/17/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 2999
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 04/17/1996
Date achieved compliance: 02/12/1997
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 02/12/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 2000
Paid penalty amount: 2000

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 04/21/1994
Date achieved compliance: 03/14/1996
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 11/09/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 24750
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 04/21/1994
Date achieved compliance: 03/14/1996
Violation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 01/17/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 12000
Paid penalty amount: 12000

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 03/27/1990
Date achieved compliance: 05/03/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/30/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 07/23/1986
Date achieved compliance: 04/24/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/23/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 02/13/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/28/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/22/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/18/2002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/08/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/10/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 02/26/2001
Evaluation lead agency: State

Evaluation date: 01/24/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/19/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/31/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/30/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/14/1996
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/14/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 02/12/1997
Evaluation lead agency: State

Evaluation date: 04/21/1994
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Evaluation lead agency:	State
Evaluation date:	11/19/1993
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General
Date achieved compliance:	03/14/1996
Evaluation lead agency:	State
Evaluation date:	02/26/1992
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/14/1991
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/27/1990
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General
Date achieved compliance:	05/03/1990
Evaluation lead agency:	State
Evaluation date:	02/01/1989
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	08/13/1987
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	11/19/1986
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	07/23/1986
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	TSD - Financial Requirements
Date achieved compliance:	04/24/1989
Evaluation lead agency:	State
Evaluation date:	11/25/1985
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	08/07/1985

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 09/28/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/30/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 11/15/1983
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

CORRACTS:

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/9/1998
Action: CA500 - CMI Workplan Approved
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 4/6/1994
Action: CA110 - RFI Workplan Received
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SEWER SYSTEM(AOC1)
Actual Date: 4/6/1994
Action: CA110 - RFI Workplan Received
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Area Name: S01/SWMUS AND AOCS 2 & 3
Actual Date: 4/6/1994
Action: CA110 - RFI Workplan Received
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 4/22/1991
Action: CA010 - RFA Initiation
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: S01/SWMUS AND AOCS 2 & 3
Actual Date: 4/22/1991
Action: CA010 - RFA Initiation
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SEWER SYSTEM(AOC1)
Actual Date: 4/22/1991
Action: CA010 - RFA Initiation
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 5/17/1999
Action: CA550 - Certification Of Remedy Completion Or Construction Completion
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 5/19/1994
Action: CA140 - RFI Workplan Notice Of Deficiency Issued
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

EPA ID: NYD000632315
EPA Region: 02
Area Name: SEWER SYSTEM(AOC1)
Actual Date: 6/1/1992
Action: CA100 - RFI Imposition
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: S01/SWMUS AND AOCS 2 & 3
Actual Date: 6/1/1992
Action: CA100 - RFI Imposition
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 6/1/1992
Action: CA100 - RFI Imposition
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 7/6/1994
Action: CA225NF - Stabilization Measures Evaluation, This facility, is not amenable to stabilization activity at the, present time, because it appears to be technically infeasible or, inappropriate
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SEWER SYSTEM(AOC1)
Actual Date: 7/6/1994
Action: CA225NF - Stabilization Measures Evaluation, This facility, is not amenable to stabilization activity at the, present time, because it appears to be technically infeasible or, inappropriate
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: S01/SWMUS AND AOCS 2 & 3

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Actual Date: 7/6/1994
Action: CA225NF - Stabilization Measures Evaluation, This facility, is not amenable to stabilization activity at the, present time, because it appears to be technically infeasible or, inappropriate

NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 7/8/1991
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority

NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 8/5/1994
Action: CA150 - RFI Workplan Approved

NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SEWER SYSTEM(AOC1)
Actual Date: 8/9/1991
Action: CA050 - RFA Completed

NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: S01/SWMUS AND AOCS 2 & 3
Actual Date: 8/9/1991
Action: CA050 - RFA Completed

NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/26/1994
Action: CA180 - RFI Supplemental Implementation Begun

NAICS Code(s): 32512
Industrial Gas Manufacturing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 10/12/1994
Action: CA195 - FI Progress Reports Received
NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 10/15/1997
Action: CA350 - CMS Approved
NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 11/14/1990
Action: CA060 - Notice of Contamination
NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SEWER SYSTEM(AOC1)
Actual Date: 11/14/1990
Action: CA060 - Notice of Contamination
NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: S01/SWMUS AND AOCS 2 & 3
Actual Date: 11/14/1990
Action: CA060 - Notice of Contamination
NAICS Code(s): 32512
Industrial Gas Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 12/7/1993

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Action: CA050 - RFA Completed
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD000632315
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 12/7/1993
Action: CA070YE - RFA Determination Of Need For An RFI, RFI is Necessary
NAICS Code(s): 32512
Industrial Gas Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

FINDS:

Registry ID: 110000326969

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AFS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

US EPA Risk Management Plan (RMP) database stores the risk management plans reported by companies that handle, manufacture, use, or store certain flammable or toxic substances, as required under section 112(r) of the Clean Air Act (CAA).

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

SSTS (Section Seven Tracking System) evolved from the FIFRA and TSCA Enforcement System (FATES). SSTS tracks the registration of all pesticide-producing establishments and tracks annually the types and amounts of pesticides, active ingredients, and related devices that are produced, sold, or distributed each year.

LTANKS:

Site ID: 160776
Spill No: 0205055
Spill Date: 8/12/2002
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/1/2002
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 1502
Investigator: JFOTTO
Referred To: Not reported
Reported to Dept: 8/13/2002
CID: 30
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: 8/14/2002
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/13/2002
Spill Record Last Update: 10/7/2002
Spiller Name: CALLER
Spiller Company: HONEYWELL
Spiller Address: 20 PEABODY ST
Spiller City,St,Zip: BUFFALO, NY 14210-
Spiller County: 001
Spiller Contact: ROB PENDRYS
Spiller Phone: (716) 827-6249
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 135746
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JFO" 08/14/02 JFO ON SITE MET WITH ROB PENDRYS AND WALTER HRIBIK. HONEYWELL DETERMINED THAT ONLY 43 POUNDS (APPROX 6 GALLONS) OF PRODUCT WAS SPILLED. <1 GALLON REACHED THE DRAIN AND THE BALANCE DISIPATED WHEN IT HIT THE HOT PAVEMENT. BSA WAS NOTIFIED BY HONEYWELL. THE DRAIN WAS NOT FLOWING AND THEY WERE ABLE TO VAC THE DRAIN REMOVING 16 GALLONS OF WATER AND ACETONE WHICH WILL BE PROPERLY DISPOSED. FAXED A COPY OF THE SPILL REPORT TO ROB PENDRYS. DISPOSAL RECEIPT TO FOLLOW. 09/30/02 JFO CALL TO ROB PENDRYS FOR THE DISPOSAL RECEIPTS. HE WAS NOT IN, I LEFT A MESSAGE ON HIS MACHINE. JFO CALL FROM ROB P. HE WILL SEND RECEIPT TODAY VIA FAX. 10/01/02 JFO RECEIVED THE DISPOSAL RECEIPTS FOR THE DRUM AND CONTAMINATED WATER. NO FURTHER ACTION REQUIRED. CLOSED
Remarks: drum being moved by forklift and fell causing spill - storm sewer also affected - storm sewer was pumped out - most of spill was onto

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

asphalt

Material:

Site ID: 160776
Operable Unit ID: 856348
Operable Unit: 01
Material ID: 519264
Material Code: 0024B
Material Name: 2-PROPANONE
Case No.: 00067641
Material FA: Hazardous Material
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

CBS AST:

CBS Number: 9-000351
Region: STATE
ICS Number: Not reported
PBS Number: Not reported
MOSF Number: Not reported
Telephone: (716) 827-6200
Facility Town: BUFFALO (C)
Operator: RAYMOND L. STARK
Emrgncy Contact: JAY HOESTERMANN
Emrgncy Phone: (716) 827-6318
Expiration Date: 05/13/2000
Owner Name: ALLIED SIGNAL CORP. INC.
Owner Address: 101 COLUMBIA ROAD
Owner City,St,Zip: MORRISTOWN, NJ 07962
Owner Telephone: (201) 455-2000
Owner type: Corporate/Commercial
Facility Type: FARM
Mail Name: ALLIED SIGNAL INC
Mail Contact Addr: BUFFALO RESEARCH LABORATORY
Mail Contact Addr2: 20 PEABODY STREET
Mail Contact Contact: JAY HOESTERMANN
Mail Contact City,St,Zip: BUFFALO, NY 14210
Mail Phone: (716) 827-6318
SPDES Number: Not reported
Facility Status: ACTIVE FACILITY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Owner Sub Type: Not reported

Tank Id: HT-3

Date Entered: 05/09/1994

Capacity (Gal): 1000

Chemical: Potassium hydroxide

Tank Closed: 12/99

Tank Status: 0

Tank Type: Steel/carbon steel

Install Date: 04/94

Certified Date: 02/27/1998

CAS Number: 1310583

Substance: Single Hazardous Substance on DEC List

Tank Location: ABOVEGROUND

Intrnl Protection: None

Extrnl Protection: None,Painted/Asphalt Coating

Pipe Location: Aboveground

Pipe Type: STEEL/IRON

Pipe Internal: None

Pipe External: 00

Pipe Containment: None,None

Tank Containment: None,Painted/Asphalt Coating

Leak Detection: None,None

Overfill Protection: None,None

Haz Percent: 45

Total Tanks: 0

Tank Secret: False

Last Test: Not reported

Due Date: Not reported

Tank Error Status: No Missing Data

SWIS Code: 1402

Lat/Long: 42I52I07 / 78I50I28

Pipe Flag: False

Federal ID: Not reported

Is Updated: F

Renew Date: Not reported

Is it There: F

Deliquent: F

Date Expired: Not reported

Owner Mark: 1

Certificate Needs to be Printed: False

Fiscal Amt for Registration Fee Correct: True

Renewal Has Been Printed for Facility: True

Pre-Printed Renewal App Last Printed: 02/02/1998

Total Capacity of All Active Tanks(gal): 0

Tank Id: HT-1

Date Entered: 05/09/1994

Capacity (Gal): 1000

Chemical: Potassium hydroxide

Tank Closed: 12/99

Tank Status: 0

Tank Type: Steel/carbon steel

Install Date: 04/94

Certified Date: 02/27/1998

CAS Number: 1310583

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Substance: Single Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: None,Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Pipe Containment: None,None
Tank Containment: None,Painted/Asphalt Coating
Leak Detection: None,None
Overfill Protection: None,None
Haz Percent: 45
Total Tanks: 0
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42!52!07 / 78!50!28
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: Not reported
Is it There: F
Deliquent: F
Date Expired: Not reported
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 02/02/1998
Total Capacity of All Active Tanks(gal): 0

Tank Id: HT-2
Date Entered: 05/09/1994
Capacity (Gal): 1000
Chemical: Potassium hydroxide
Tank Closed: 12/99
Tank Status: 0
Tank Type: Steel/carbon steel
Install Date: 04/94
Certified Date: 02/27/1998
CAS Number: 1310583
Substance: Single Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: None,Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Pipe Containment: None,None
Tank Containment: None,Painted/Asphalt Coating
Leak Detection: None,None
Overfill Protection: None,None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Haz Percent: 45
Total Tanks: 0
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I52I07 / 78I50I28
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: Not reported
Is it There: F
Deliquent: F
Date Expired: Not reported
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 02/02/1998
Total Capacity of All Active Tanks(gal): 0

Tank Id: HT-6
Date Entered: 05/09/1994
Capacity (Gal): 1000
Chemical: Potassium hydroxide
Tank Closed: 12/99
Tank Status: 0
Tank Type: Steel/carbon steel
Install Date: 04/94
Certified Date: 02/27/1998
CAS Number: 1310583
Substance: Single Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: None,Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Pipe Containment: None,None
Tank Containment: None,Painted/Asphalt Coating
Leak Detection: None,None
Overfill Protection: None,None
Haz Percent: 45
Total Tanks: 0
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I52I07 / 78I50I28
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Is it There: F
Deliquent: F
Date Expired: Not reported
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 02/02/1998
Total Capacity of All Active Tanks(gal): 0

Tank Id: HT-4
Date Entered: 05/09/1994
Capacity (Gal): 1000
Chemical: Potassium hydroxide
Tank Closed: 12/99
Tank Status: 0
Tank Type: Steel/carbon steel
Install Date: 04/94
Certified Date: 02/27/1998
CAS Number: 1310583
Substance: Single Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: None,Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Pipe Containment: None,None
Tank Containment: None,Painted/Asphalt Coating
Leak Detection: None,None
Overfill Protection: None,None
Haz Percent: 45
Total Tanks: 0
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I52I07 / 78I50I28
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: Not reported
Is it There: F
Deliquent: F
Date Expired: Not reported
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 02/02/1998
Total Capacity of All Active Tanks(gal): 0

[Click this hyperlink](#) while viewing on your computer to access
2 additional NY_AST_CBS: record(s) in the EDR Site Report.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

WI MANIFEST:

Year: 05
EPA ID: NYD000632315
FID: 0
ACT Code: 201
ACT Status: A
ACT Code 1: 201
ACT Name: HW Generator - Large
Contact First Name: Not reported
Contact Last Name: Not reported
Contact Title: Not reported
Contact Address: Not reported
Contact State: Not reported
Contact City: Not reported
Contact Zip: 0
Contact Telephone: 0
Contact Extention: Not reported
Contact Email Address: Not reported
WI MANIFEST SHIP: -
Manifest DOC ID: 000250809VES
Copy Type: TSDCOPY
Gen EPA ID: NYD000632315
Gen Date: 3/31/2008
TSD Date: Not reported
TSD EPA ID: WID988566543
GEN Copy Revd Date: Not reported
TSG Copy Revd Date: 4/14/2008
Manifest DOC ID: 000250809VES
Waste Page No: 1
Waste Line No: 1
Waste Code: D009
Waste Amount: 40
Unit of Measure: P
Waste LBS: 40

WI MANIFEST TRANS: -

Mifest DOC ID: Not reported
TRAN EPA ID: Not reported
TRAN ORDER NO: Not reported
TRAN Date: Not reported

Manifest DOC ID: Not reported
Waste Page No: Not reported
Waste Line No: Not reported
Waste Code: Not reported
Waste Amount: Not reported
Unit of Measure: Not reported
Waste LBS: Not reported

Year: 06
EPA ID: NYD000632315
FID: 0
ACT Code: 201
ACT Status: A
ACT Code 1: 201
ACT Name: HW Generator - Large

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Contact First Name: Not reported
Contact Last Name: Not reported
Contact Title: Not reported
Contact Address: Not reported
Contact State: Not reported
Contact City: Not reported
Contact Zip: Not reported
Contact Telephone: Not reported
Contact Extention: Not reported
Contact Email Address: Not reported
WI MANIFEST SHIP: -
Manifest DOC ID: 000250809VES
Copy Type: TSDCOPY
Gen EPA ID: NYD000632315
Gen Date: 3/31/2008
TSD Date: Not reported
TSD EPA ID: WID988566543
GEN Copy Revd Date: Not reported
TSG Copy Revd Date: 4/14/2008
Manifest DOC ID: 000250809VES
Waste Page No: 1
Waste Line No: 1
Waste Code: D009
Waste Amount: 40
Unit of Measure: P
Waste LBS: 40

WI MANIFEST TRANS: -
Mifest DOC ID: Not reported
TRAN EPA ID: Not reported
TRAN ORDER NO: Not reported
TRAN Date: Not reported

Manifest DOC ID: Not reported
Waste Page No: Not reported
Waste Line No: Not reported
Waste Code: Not reported
Waste Amount: Not reported
Unit of Measure: Not reported
Waste LBS: Not reported

Year: 07
EPA ID: NYD000632315
FID: 0
ACT Code: 201
ACT Status: A
ACT Code 1: 201
ACT Name: HW Generator - Large
Contact First Name: Not reported
Contact Last Name: Not reported
Contact Title: Not reported
Contact Address: Not reported
Contact State: Not reported
Contact City: Not reported
Contact Zip: 0
Contact Telephone: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Contact Extention: Not reported
Contact Email Address: Not reported
WI MANIFEST SHIP: -
Manifest DOC ID: 000250809VES
Copy Type: TSDCOPY
Gen EPA ID: NYD000632315
Gen Date: 3/31/2008
TSD Date: Not reported
TSD EPA ID: WID988566543
GEN Copy Revd Date: Not reported
TSG Copy Revd Date: 4/14/2008
Manifest DOC ID: 000250809VES
Waste Page No: 1
Waste Line No: 1
Waste Code: D009
Waste Amount: 40
Unit of Measure: P
Waste LBS: 40

WI MANIFEST TRANS: -
Mifest DOC ID: Not reported
TRAN EPA ID: Not reported
TRAN ORDER NO: Not reported
TRAN Date: Not reported

Manifest DOC ID: Not reported
Waste Page No: Not reported
Waste Line No: Not reported
Waste Code: Not reported
Waste Amount: Not reported
Unit of Measure: Not reported
Waste LBS: Not reported

Year: 08
EPA ID: NYD000632315
FID: Not reported
ACT Code: 201
ACT Status: A
ACT Code 1: 201
ACT Name: HW Generator - Large
Contact First Name: Not reported
Contact Last Name: Not reported
Contact Title: Not reported
Contact Address: Not reported
Contact State: Not reported
Contact City: Not reported
Contact Zip: Not reported
Contact Telephone: Not reported
Contact Extention: Not reported
Contact Email Address: Not reported
WI MANIFEST SHIP: -
Manifest DOC ID: 000250809VES
Copy Type: TSDCOPY
Gen EPA ID: NYD000632315
Gen Date: 3/31/2008
TSD Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

TSD EPA ID: WID988566543
GEN Copy Revd Date: Not reported
TSG Copy Revd Date: 4/14/2008
Manifest DOC ID: 000250809VES
Waste Page No: 1
Waste Line No: 1
Waste Code: D009
Waste Amount: 40
Unit of Measure: P
Waste LBS: 40

WI MANIFEST TRANS: -

Mifest DOC ID: Not reported
TRAN EPA ID: Not reported
TRAN ORDER NO: Not reported
TRAN Date: Not reported

Manifest DOC ID: Not reported
Waste Page No: Not reported
Waste Line No: Not reported
Waste Code: Not reported
Waste Amount: Not reported
Unit of Measure: Not reported
Waste LBS: Not reported

NY MANIFEST:

EPA ID: NYD000632315
Country: USA
Mailing Name: HONEYWELL INC
Mailing Contact: TEWKSBURY FLOYD SUPERVISO
Mailing Address: 20 PEABODY ST
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14210
Mailing Zip4: 1599
Mailing Country: USA
Mailing Phone: 716-827-6249

Document ID: NYA7879806
Manifest Status: Completed copy
Trans1 State ID: DF1958
Trans2 State ID: Not reported
Generator Ship Date: 890120
Trans1 Recv Date: 890120
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890124
Part A Recv Date: 890126
Part B Recv Date: 890127
Generator EPA ID: NYD000632315
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported
Document ID:	NYA8085897
Manifest Status:	Completed copy
Trans1 State ID:	99829-CNY
Trans2 State ID:	Not reported
Generator Ship Date:	890119
Trans1 Recv Date:	890119
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890125
Part A Recv Date:	890126
Part B Recv Date:	890130
Generator EPA ID:	NYD000632315
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	03420

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 062
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA7880004
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: DF1959
Trans2 State ID: Not reported
Generator Ship Date: 890120
Trans1 Recv Date: 890120
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890124
Part A Recv Date: 890308
Part B Recv Date: 890224
Generator EPA ID: NYD000632315
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA7931727
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890412
Trans1 Recv Date: 890412
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890417
Part A Recv Date: 890420
Part B Recv Date: 890421
Generator EPA ID: NYD000632315
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00660
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 012
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00165

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA7879815
Manifest Status: Completed copy
Trans1 State ID: DF1959
Trans2 State ID: Not reported
Generator Ship Date: 890120
Trans1 Recv Date: 890120
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890124
Part A Recv Date: 890126
Part B Recv Date: 890127
Generator EPA ID: NYD000632315
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA7874253
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890623
Trans1 Recv Date: 890623
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890628
Part A Recv Date: 890703
Part B Recv Date: 890706
Generator EPA ID: NYD000632315
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00128
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 013
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00012
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA7931682
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890412
Trans1 Recv Date: 890412
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890417
Part A Recv Date: 890420
Part B Recv Date: 890421
Generator EPA ID: NYD000632315
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00030
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000077970
Trans2 State ID: TXR000077970
Generator Ship Date: 2009-01-14
Trans1 Recv Date: 2009-01-14
Trans2 Recv Date: 2009-01-16
TSD Site Recv Date: 2009-01-25
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 125.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000239905VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: NJD080631369
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: 2009-04-15
TSD Site Recv Date: 2009-04-21

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 45.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250170VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: NJD054126164
Generator Ship Date: 2009-05-20
Trans1 Recv Date: 2009-05-20
Trans2 Recv Date: 2009-05-30
TSD Site Recv Date: 2009-06-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 140.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250663VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: Not reported
Generator Ship Date: 2009-06-17
Trans1 Recv Date: 2009-06-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-06-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: Not reported
Quantity: 10047.0
Units: P - Pounds
Number of Containers: 18.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000369111VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000077970
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-17
Trans1 Recv Date: 2009-02-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: OHD093945293

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Waste Code: Not reported
Quantity: 350.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250136VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: NJD080631369
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: 2009-04-15
TSD Site Recv Date: 2009-04-21
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 8.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250170VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: NJD054126164
Generator Ship Date: 2009-05-05
Trans1 Recv Date: 2009-05-05
Trans2 Recv Date: 2009-05-06
TSD Site Recv Date: 2009-05-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 35.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250174VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000077970
Trans2 State ID: TXR000077970
Generator Ship Date: 2009-01-14
Trans1 Recv Date: 2009-01-14
Trans2 Recv Date: 2009-01-16
TSD Site Recv Date: 2009-01-25
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 600.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Year: 09
Manifest Tracking Num: 000239905VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000077970
Trans2 State ID: TXR000077970
Generator Ship Date: 2009-01-14
Trans1 Recv Date: 2009-01-14
Trans2 Recv Date: 2009-01-16
TSD Site Recv Date: 2009-01-25
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: ILD098642424
Waste Code: Not reported
Quantity: 17.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000239905VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: NJD080631369
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Trans2 Recv Date: 2009-04-15
TSD Site Recv Date: 2009-04-21
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 14.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250170VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: NJD080631369
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: 2009-04-15
TSD Site Recv Date: 2009-04-21
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 19.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250170VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: NJD054126164
Generator Ship Date: 2009-05-05
Trans1 Recv Date: 2009-05-05
Trans2 Recv Date: 2009-05-06
TSD Site Recv Date: 2009-05-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: ILD098642424
Waste Code: Not reported
Quantity: 100.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250174VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: NJD054126164
Generator Ship Date: 2009-05-05
Trans1 Recv Date: 2009-05-05
Trans2 Recv Date: 2009-05-06
TSD Site Recv Date: 2009-05-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000632315
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Trans2 EPA ID: Not reported
TSDF ID: ILD098642424
Waste Code: Not reported
Quantity: 35.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000250174VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H040

[Click this hyperlink](#) while viewing on your computer to access
2910 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

Manifest Code: NJA3091625
EPA ID: NYD000632315
Date Shipped: 20041001
TSDF EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD080631369
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 041001
Date Trans2 Transported Waste: 041011
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 041011
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 11030421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092101
EPA ID: NYD000632315
Date Shipped: 20040212
TSDf EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NYD982792814
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040212
Date Trans2 Transported Waste: 040227
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 040303
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 03290422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092131
EPA ID: NYD000632315
Date Shipped: 20040225
TSDf EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NYD982792814
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040225
Date Trans2 Transported Waste: 040227
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 040303
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 03290422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092097
EPA ID: NYD000632315
Date Shipped: 20040305
TSDf EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NYD982792814
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040305
Date Trans2 Transported Waste: 040310
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 040319
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04280421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092042
EPA ID: NYD000632315
Date Shipped: 20040212
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NYD982792814
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040212
Date Trans2 Transported Waste: 040227
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040305
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04020421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092124
EPA ID: NYD000632315
Date Shipped: 20040402
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040402
Date Trans2 Transported Waste: 040408
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 040409
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 05030425
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092121
EPA ID: NYD000632315
Date Shipped: 20040719
TSDf EPA ID: NJD002454544
Transporter EPA ID: NYD982792814
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040719
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 040720
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 08100422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092098
EPA ID: NYD000632315
Date Shipped: 20040122
TSDF EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040122
Date Trans2 Transported Waste: 040127
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040128
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 03090422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092122
EPA ID: NYD000632315
Date Shipped: 20040428
TSDF EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040428
Date Trans2 Transported Waste:	040510
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040511
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	05210422
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported
Manifest Code:	NJA3092104
EPA ID:	NYD000632315
Date Shipped:	20040402
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD054126164
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040402
Date Trans2 Transported Waste:	040408
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040409
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	04290422
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092099
EPA ID: NYD000632315
Date Shipped: 20040122
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040122
Date Trans2 Transported Waste: 040130
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040202
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 03170421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3091629
EPA ID: NYD000632315
Date Shipped: 20041119
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 041119
Date Trans2 Transported Waste: 041201
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 041203
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 01070521
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3091605
EPA ID: NYD000632315
Date Shipped: 20040604
TSDF EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040604
Date Trans2 Transported Waste: 040615
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040618
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 06250425
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3091606
EPA ID: NYD000632315
Date Shipped: 20040610
TSDF EPA ID: NJD002454544
Transporter EPA ID: NYD982792814
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040610
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040614
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 06290421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3091657
EPA ID: NYD000632315
Date Shipped: 20041119
TSDF EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 041119
Date Trans2 Transported Waste: 041130
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 041201
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 12150435
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3091601
EPA ID: NYD000632315
Date Shipped: 20040708
TSDf EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040708
Date Trans2 Transported Waste: 040713
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 040714
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 08190421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3091624
EPA ID: NYD000632315
Date Shipped: 20040910
TSDf EPA ID: NJD002454544
Transporter EPA ID: NYD982792814
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040910
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 040913
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 09280421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA3092119
EPA ID: NYD000632315
Date Shipped: 20040825
TSDf EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040825
Date Trans2 Transported Waste: 040908
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040910
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 10120422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 000239890VES
EPA ID: NYD000632315
Date Shipped: 10/6/2008
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/6/2008
Date Trans2 Transported Waste: 10/17/2008
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 10/17/2008
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Waste Code: D002
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 675
Unit: P
Hand Code: H141

Waste Code: D002
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 1350
Unit: P
Hand Code: H141

Waste Code: D002
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 825
Unit: P
Hand Code: H141

Manifest Code: NJA3092115
EPA ID: NYD000632315
Date Shipped: 20060104
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060104
Date Trans2 Transported Waste: 060119
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060120
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 03020621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

NY Spills:

Site ID: 71525
Facility Addr2: Not reported
Facility ID: 9908022
Spill Number: 9908022
Facility Type: ER
SWIS: 1500
Investigator: SORGI
Referred To: Not reported
Spill Date: 9/30/1999
Reported to Dept: 10/1/1999
CID: 30
Spill Cause: Human Error
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt: 1/31/2000
Remediation Phase: 0
Date Entered In Computer: 10/1/1999
Spill Record Last Update: 2/10/2000
Spiller Name: JAY HOESTERMANN
Spiller Company: ALLIED SIGNAL/HONEYWELL
Spiller Address: 20 PEABODY STREET
Spiller City,St,Zip: BUFFALO, NY 14210-001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 67669
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MJS" 10/01/99: SPILL OCCURRED AFTER-HOURS YESTERDAY, NOT REPORTED UNTIL TODAY AT 1448 HRS. SPILL ENTERED SEWER TO WATER TREATMENT PLANT. NOTHING TO SEE AT THIS POINT. MJS SPOKE WITH CHIEF BORCYNski WITH USCG REGARDING INCIDENT. 01/03/00: MJS REVIEW FILE. NO DOCUMENTATION. MJS TELECON TO JAY HOESTERMANN, LEFT MESSAGE FOR HIM TO CALL. 01/04/00: MJS TELECON FROM MR HOESTERMANN. HE WILL FORWARD A REPORT HE SUBMITTED TO BUFFALO SEWER AUTHORITY. 01/05/00: MJS RECEIVED FAXED REPORT FROM MR HOESTERMANN. SPILL CAUSED BY EMPLOYEE FILLING DRUM AND NOT WATCHING OPERATION. MATERIAL IS BORON TRIFLUORIDE DIETHYL ETHER. 47% BORON TRIFLUORIDE(165 LBS), 53% ETHYL ETHER(185 LBS) - 350 LBS TOTAL. MUCH OF SPILL WENT TO SEWER, THEY ESTIMATE GREATER THAN 100 LBS EHTYL ETHER REACHED SEWER BASED ON RECOVERY. NOTE: RECENT NAME CHANGE FROM ALLIED SIGNAL TO HONEYWELL. MJS SENT DISPOSAL RECIEPT LETTER TO RP. 01/07/00: MJS RECEIVED MAILED COPY OF SAME REPORT AS ABOVE. 01/31/00: MJS RECEIVED COPY OF HAZ-WASTE MANIFEST FOR DISPOSAL DOCUMENTATION. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE.
Remarks: employee was filling drum and overfilled - product spilled on land and did enter sewer which flows to water treatment plant - ethyl ether other product involved 53% - 185 lbs spilled

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Material:

Site ID: 71525
Operable Unit ID: 1086694
Operable Unit: 01
Material ID: 300705
Material Code: 0172B
Material Name: ETHYL ETHER
Case No.: 00060297
Material FA: Hazardous Material
Quantity: 185
Units: Pounds
Recovered: 85
Resource Affected: Sewer
Oxygenate: False
Site ID: 71525
Operable Unit ID: 1086694
Operable Unit: 01
Material ID: 300706
Material Code: 1005A
Material Name: BORON TRIFLUORIDE
Case No.: 07637072
Material FA: Hazardous Material
Quantity: 165
Units: Pounds
Recovered: No
Resource Affected: Sewer
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 71521
Facility Addr2: Not reported
Facility ID: 0304794
Spill Number: 0304794
Facility Type: ER
SWIS: 1500
Investigator: BRENNAN
Referred To: Not reported
Spill Date: 8/6/2003
Reported to Dept: 8/6/2003
CID: 30
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: No spill occurred. No DEC Response. No corrective action required.
Spill Closed Dt: 8/6/2003
Remediation Phase: 0
Date Entered In Computer: 8/6/2003
Spill Record Last Update: 8/6/2003
Spiller Name: CALLER
Spiller Company: HONEYWELL
Spiller Address: 20 PEABODY STREET
Spiller City,St,Zip: BUFFALO, NY 14210-
Spiller Company: 001
Contact Name: LANA DOLE
Contact Phone: (716) 827-6318
DEC Region: 9
DER Facility ID: 67669
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"KAB" 08/06/03: KAB RECEIVED REPORT OF FREON RELEASE. REFERRED TO
DIV. OF AIR RESOURCES FOR FOLLOW-UP. NO ACTION BY SPILLS POSSIBLE.
CLOSE OUT. *****NO PAPER FILE EXISTS FOR THIS SPILL *****
Remarks: leaking tube during maintenance

Material:

Site ID: 71521
Operable Unit ID: 871615
Operable Unit: 01
Material ID: 505646
Material Code: 0050A
Material Name: FREON
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Air
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

[Click this hyperlink](#) while viewing on your computer to access
additional NY_SPILL: detail in the EDR Site Report.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

NY Hist Spills:

Region of Spill: 9
Spill Number: 9908022
Investigator: MJS
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 09/30/1999 18:30
Reported to Dept Date/Time: 10/01/99 14:48
SWIS: 14
Spiller Name: ALLIED SIGNAL/HONEYWELL
Spiller Contact: JAY HOESTERMANN
Spiller Phone: (716) 827-6200
Spiller Phone: () -
Spiller Address: 20 PEABODY STREET
Spiller City,St,Zip: BUFFALO, NY 14210-
Spill Cause: Human Error
Reported to Dept: In Sewer
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt: 01/31/00
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/01/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/10/00
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 165
Unkonwn Quantity Spilled: False
Units: Pounds
Quantity Recovered: 0
Unkonwn Quantity Recovered: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Material: BORON TRIFLUORIDE
Class Type: BORON TRIFLUORIDE
Times Material Entry In File: 0
CAS Number: 07637072
Last Date: Not reported
Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 185
Unkonwn Quantity Spilled: False
Units: Pounds
Quantity Recovered: 85
Unkonwn Quantity Recovered: False

Material: ETHYL ETHER
Class Type: ETHYL ETHER
Times Material Entry In File: 0

CAS Number: 00060297
Last Date: Not reported

Material: DIETHYL ETHER
Class Type: DIETHYL ETHER
Times Material Entry In File: 52

CAS Number: 00060297
Last Date: Not reported

DEC Remarks: 10/01/99: SPILL OCCURRED AFTER-HOURS YESTERDAY, NOT REPORTED UNTIL TODAY AT 1448 HRS. SPILL ENTERED SEWER TO WATER TREATMENT PLANT. NOTHING TO SEE AT THIS POINT. MJS SPOKE WITH CHIEF BORCYNski WITH USCG REGARDING INCIDENT.
01/03/00: MJS REVIEWFILE. NO DOCUMENTATION. MJS TELECON TO JAY HOESTERMANN, LEFT MESSAGE FOR HIM TO CALL. 01/04/00: MJS TELECON FROM MR HOESTERMANN. HE WILL FORWARD A REPORT HE SUBMITTED TO BUFFALO SEWER AUTHORITY. 01/05/00: MJS RECEIVED FAXED REPORT FROM MR HOESTERMANN. SPILL CAUSED BY EMPLOYEE FILLING DRUM AND NOT WATCHING OPERATION. MATERIAL IS BORON TRIFLUORIDE DIETHYL ETHER. 47 BORON TRIFLUORIDE 165 LBS), 53 ETHYL ETHER 185 LBS) - 350 LBS TOTAL. MUCH OF SPILL WENT TO SEWER, THEY ESTIMATE GREATER THAN 100 LBS EHTYL ETHER REACHED SEWER BASED ON RECOVERY. NOTE: RECENT NAME CHANGE FROM ALLIED SIGNAL TO HONEYWELL. MJS SENT DISPOSAL RECIEPT LETTER TO RP. 01/07/00: MJS RECEIVED MAILED COPY OF SAME REPORT AS ABOVE. 01/31/00: MJS RECEIVED COPY OF HAZ-WASTE MANIFEST FOR DISPOSAL DOCUMENTATION. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE.

Remark: employee was filling drum and overfilled - product spilled on land and did enter sewer which flows to water treatment plant - ethyl ether other product involved 53 - 185 lbs spilled

Region of Spill: 9
Spill Number: 9602139
Investigator: SAC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/08/1996 12:00
Reported to Dept Date/Time: 05/14/96 14:02
SWIS: 14
Spiller Name: ALLIED SIGNAL
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: 20 PEABODY STREET
Spiller City,St,Zip: BUFFALO, NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Spill Cause: Equipment Failure
Reported to Dept: In Sewer
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Federal Government
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. No DEC
Response. No corrective action required.
Spill Closed Dt: 05/15/96
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/14/96
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/16/96
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DICHLOROMETHANE
Class Type: DICHLOROMETHANE
Times Material Entry In File: 0
CAS Number: 00075092
Last Date: Not reported
Material: METHYLENE CHLORIDE
Class Type: METHYLENE CHLORIDE
Times Material Entry In File: 68
CAS Number: 00075092
Last Date: Not reported
Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 2
Unkonwn Quantity Spilled: False
Units: Pounds
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: ANTIMONY PENTACHLORIDE
Class Type: ANTIMONY PENTACHLORIDE
Times Material Entry In File: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

CAS Number: 07647189
Last Date: Not reported
Material Class Type: Hazardous Material
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: REFRIGERANT
Class Type: REFRIGERANT
Times Material Entry In File: 1
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: 5/14/96: COPY OF REPORT GIVEN TO DIV. OF AIR, DIV. OF WATER, BUFF SEWER AUTHORITY, SAC
TELECON DENNIS YOUNG/BSA NOTIFYING HIM OF SPILL, SPILL WAS BELOW REPORTABLE
QUANTITY FOR ANTIMONY PENTACHLORIDE.
Remark: r31 and r32 - liquid ??? reactor accident caused release of antimony to sewer -
released on may 11th 1996 - also, notifier indicated reactor routinely releases
methyline chloride, r31 and r32 to the air

Region of Spill: 9
Spill Number: 9701074
Investigator: MJS
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 04/19/1997 12:00
Reported to Dept Date/Time: 04/23/97 16:15
SWIS: 14
Spiller Name: ALLIED SIGNAL
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City, St, Zip: Not reported
Spill Cause: Unknown
Reported to Dept: In Sewer
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Citizen
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: 04/25/97
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: No spill occured. No DEC Response. No corrective action required.
Spill Closed Dt: 04/25/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/24/97
Date Spill Entered In Computer Data File: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HONEYWELL INC. BUFFALO RESEARCH LABORATO (Continued)

1000248676

Update Date: 03/03/99

Is Updated: False

Tank:

PBS Number: Not reported

Tank Number: Not reported

Tank Size: Not reported

Test Method: Not reported

Leak Rate Failed Tank: Not reported

Gross Leak Rate: Not reported

Material:

Material Class Type: Nonpetroleum/Nonhazardous

Quantity Spilled: 200

Unkonwn Quantity Spilled: False

Units: Gallons

Quantity Recovered: 0

Unkonwn Quantity Recovered: False

Material: PROPANE, 1,2-DIBROMO-3-CHLORO-

Class Type: PROPANE, 1,2-DIBROMO-3-CHLORO-

Times Material Entry In File: 0

CAS Number: 00096128

Last Date: Not reported

DEC Remarks: 04/25/97: MJS SITE INSPECT. NO EVIDENCE FOUND TO CONFIRM REPORT. NO FURTHER ACTION POSSIBLE. MJS CLOSE FILE.

Remark: ANONYMOUS EMPLOYEE REPORTS ACCIDENTAL RELEASE.

CBS:

CBS Number: 9-000298

Program Type: CBS

Dec Region: 9

Expiration Date: N/A

Facility Status: Unregulated

UTMX: Not reported

UTMY: Not reported

CBS Number: 9-000351

Program Type: CBS

Dec Region: 9

Expiration Date: 2010/08/19

Facility Status: Active

UTMX: Not reported

UTMY: Not reported

AI140
SE
1/2-1
0.634 mi.
3350 ft.

**ALLIED CHEM R&D FACILITY
20 PEABODY STREET
BUFFALO, NY**

Site 2 of 2 in cluster AI

**HSWDS S108146599
N/A**

**Relative:
Higher**

HSWDS:

Facility ID: Not reported

Region: 9

Facility Status: Unknown

Owner Type: Puplic

Owner: Allied Chemical

Owner Address: Unknown

Owner Phone: Unknown

**Actual:
593 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEM R&D FACILITY (Continued)

S108146599

Operator Type: Puplic
Operator: Same
Operator: Same
Operator Phone: Same
EPA ID: Not reported
Registry: D
Registry Site ID: 915002
RCRA Permitted: Unknown
Site Code: Leaking tanks, drums, lagoons, other containers
Owner City State: Not reported
Operator City State: Not reported
Quadrangle: Unknown
Latitude: Unknown
Longitude: Unknown
Acres: 0.00
Operator Date: 1955
Close Date: 1985
Completed: Unknown
Active: Unknown
PCB's Disposed: Unknown
Pesticides Disposed: Unknown
Metals Disposed: Unknown
Asbestos Disposed: Unknown
Volatile Organic Compounds Disposed: Unknown
Semi Volatile Organic Compounds Disposed: Unknown
Analytical Info Exists for Air: Not reported
Analytical Info Exists for Ground: None
Analytical Info Exists for Surface: Not reported
Analytical Info Exists for Sediments: Not reported
Analytical Info Exists for Surface: Not reported
Analytical Info Exists for Substance: Not reported
Analytical Info Exists for Waste: Not reported
Analytical Info Exists for Leachate: Not reported
Analytical Info Exists for EP Toxicity: Not reported
Analytical Info Exists for TCLP: Not reported
Threat to Environment/Public Health: N
Surface Water Contamination: Unknown
Surface Water Body Class: Unknown
Groundwater Contamination: Unknown
Groundwater Classification: Unknown
Drinking Water Contamination: Unknown
Drinking Water Supply is Active: Unknown
Any Known Fish or Wildlife: Unknown
Hazardous Exposure: Unknown
Site Has Controlled Access: Unknown
Ambient Air Contamination: Unknown
Direct Contact: Unknown
EPA Hazardous Ranking System Score: Unknown
Inventory: F
Nefrap: Not reported
Mailing: Not reported
Tax Map No: Not reported
Qualify: 0
Next Action: Not reported
Agencies: Not reported
Air: Not reported
Building: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEM R&D FACILITY (Continued)

S108146599

Site Desc: Not reported
Drink: Not reported
Eptox: Not reported
Fish: Not reported
Ground: Not reported
Ground Desc: Not reported
Hazardous Threat: Not reported
Haz Threat Desc: Not reported
Leachate: Not reported
Preparer: Not reported
Sediment: Not reported
Soil: Not reported
Surface: Not reported
Status: Not reported
Surface Soil: Not reported
Surface: Not reported
TCLP: Not reported
Waste: Not reported

141
NE
1/2-1
0.645 mi.
3404 ft.

Relative:
Higher

Actual:
600 ft.

ATLAS ELECTROPLATING
345 FILLMORE AVE.
BUFFALO, NY 14201

CERC-NFRAP 1000156917
RCRA-NonGen NYD002106540
FINDS
MANIFEST
NY Spills
NY Hist Spills

CERC-NFRAP:
Site ID: 0202848
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

CERCLIS-NFRAP Assessment History:

Action: REMOVAL
Date Started: 06/17/1988
Date Completed: 05/03/1989
Priority Level: Cleaned up

Action: DD
Date Started: Not reported
Date Completed: 08/21/1992
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: Not reported
Date Completed: 01/23/1996
Priority Level: Not reported

Action: ADMINISTRATIVE RECORDS
Date Started: 06/13/1996
Date Completed: Not reported
Priority Level: Admin Record Compiled for a Removal Event

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: ATLAS EO PG CP
Facility address: 345 FILLMORE AVE

ATLAS ELECTROPLATING (Continued)

1000156917

EPA ID:	NYD002106540
Mailing address:	FILLMORE AVE BUFFALO, NY 14206
Contact:	Not reported
Contact address:	FILLMORE AVE BUFFALO, NY 14206
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: LAWICKI RAYMOND
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 82001
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LAWICKI RAYMOND
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Unknown
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ATLAS ELECTROPLATING (Continued)

1000156917

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: ATLAS EO PG CP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: ATLAS EO PG CP
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Facility name: ATLAS EO PG CP
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 11/01/1986
Date achieved compliance: 11/01/1986
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 11/14/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/01/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 11/01/1986
Evaluation lead agency: State

Evaluation date: 11/12/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004338510

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ATLAS ELECTROPLATING (Continued)

1000156917

program staff to track the notification, permit, compliance, and
corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD002106540
Country: USA
Mailing Name: ATLAS ELECTRO PLATING CORPORATION
Mailing Contact: ATLAS ELECTRO PLATING CORPORATION
Mailing Address: 345 FILMORE AVENUE
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14206
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-854-0132

Document ID: WIA1707000
Manifest Status: Completed after the designated time period for a TSDf to get a copy to the DEC
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 850205
Trans1 Recv Date: 850205
Trans2 Recv Date: Not reported
TSD Site Recv Date: 850208
Part A Recv Date: 850412
Part B Recv Date: 850813
Generator EPA ID: NYD002106540
Trans1 EPA ID: GAD042097261
Trans2 EPA ID: Not reported
TSDf ID: WID006435887
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 19110
Units: P - Pounds
Number of Containers: 026
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 85
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

NY Spills:

Site ID: 108925

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ATLAS ELECTROPLATING (Continued)

1000156917

Facility Addr2: Not reported
Facility ID: 8802052
Spill Number: 8802052
Facility Type: ER
SWIS: 1502
Investigator: ROSS
Referred To: Not reported
Spill Date: 6/3/1988
Reported to Dept: 6/3/1988
CID: 30
Spill Cause: Abandoned Drums
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 7/7/1988
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Not reported
Spill Closed Dt: 7/7/1988
Remediation Phase: 0
Date Entered In Computer: 6/6/1988
Spill Record Last Update: 7/18/1988
Spiller Name: Not reported
Spiller Company: ATLAS ELECTROPLATING
Spiller Address: 345 FILLMORE AVENUE
Spiller City,St,Zip: BUFFALO, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 95710
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"LQR" 06/03/88: RNL NOTIFIED SW/HW B.MITREY TO INVESTIGATE SITE.
07/07/88: LQR MET W/ SW/HW AND EE SITE TURNED OVER TO EPA,NO FURTHER
ACTION REQUIRED BY SPILL UNIT.
Remarks: ABANDONED DRUMS, NOTIFIED BY FORMER EMPLOYEE
Material:
Site ID: 108925
Operable Unit ID: 919383
Operable Unit: 01
Material ID: 461184
Material Code: 0059A
Material Name: SOLVENTS
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False
Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ATLAS ELECTROPLATING (Continued)

1000156917

Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 8802052
Investigator: LQR
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 06/03/1988 12:00
Reported to Dept Date/Time: 06/03/88 12:00
SWIS: 14
Spiller Name: ATLAS ELECTROPLATING
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: 345 FILLMORE AVENUE
Spiller City,St,Zip: BUFFALO, NY
Spill Cause: Abandoned Drums
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: 07/07/88
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 07/07/88
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/06/88
Date Spill Entered In Computer Data File: Not reported
Update Date: 07/18/88
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ATLAS ELECTROPLATING (Continued)

1000156917

Gross Leak Rate: Not reported

Material:

Material Class Type: Hazardous Material

Quantity Spilled: 0

Unkonwn Quantity Spilled: False

Units: Gallons

Quantity Recovered: 0

Unkonwn Quantity Recovered: False

Material: SOLVENTS

Class Type: SOLVENTS

Times Material Entry In File: 424

CAS Number: Not reported

Last Date: 19940928

DEC Remarks: 06/03/88: RNL NOTIFIED SW/HW B.MITREY TO INVESTIGATE SITE. 07/07/88: LQR MET W/ SW/HW AND EE SITE TURNED OVER TO EPA,NO FURTHER ACTION REQUIRED BY SPILL UNIT.

Remark: ABANDONED DRUMS, NOTIFIED BY FORMER EMPLOYEE

142
ENE
1/2-1
0.654 mi.
3450 ft.

ENVIROX FILTER INC
60 MEDCALFE STREET
BUFFALO, NY

LTANKS S100118253
HIST LTANKS N/A

Relative:
Higher

Actual:
596 ft.

LTANKS:

Site ID: 314923
Spill No: 8910285
Spill Date: 1/26/1990
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 11/7/1990
Facility Addr2: Not reported
Cleanup Ceased: 11/7/1990
Cleanup Meets Standard: True
SWIS: 1502
Investigator: MXFRANKS
Referred To: Not reported
Reported to Dept: 1/26/1990
CID: 30
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 5/9/1990
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/26/1990
Spill Record Last Update: 11/21/1990
Spiller Name: Not reported
Spiller Company: ENVIROX FILTER INC
Spiller Address: 60 MEDCALFE STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 9

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENVIROX FILTER INC (Continued)

S100118253

DER Facility ID: 253900
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MF" 01/26/90: MF SITE VISIT WITH THE BSA & SPILLER. SLIGHT SPILLAGE NOTICED, THE SEWER IS PLUGGED. SPILLER PUT PADS IN PLACE. TANKS TO BE PUMPED, SOIL & TANKS TO BE DISPOSED OF. NO SPILLAGE GOT INTO THE SEWER. 02/01/90: MF SITE VISIT WITH PAT & PAUL, SAND IS BEING REMOVED FROM AROUND THE TANKS 2-1K. I CHECKED THIS SAND FOR SHEEH, IT CHECKED GOOD. I WILL REINSPECT WHEN THEY GET TO THE BOTTOM SAND. 03/27/90: MF SITE VISIT WITH PAUL, TANKS ALL PUMPED OUT. THEY ARE TAKING BIDS FOR TANK CLEANING. 05/09/90: MF SITE VISIT, THE 2-1K TANKS HAVE BEEN REMOVED. THE SOIL UNDER THE TANKS IS CONTAMINATED, APPX 3 BARRELS. TOLD ENVIROX WHAT MUST BE DONE. 06/27/90: MF 1ST DISPOSAL LETTER SENT GIVING UNTIL 7/31/90. 10/12/90: MF 2ND DISPOSAL LETTER SENT GIVING UNTIL 11/15/90. 11/07/90: MF RECEIVED DISPOSAL RECEIPT, NO FUTHER ACTION NECESSARY.
Remarks: BASEMENT TANKS IN BERMED AREA LEAKING. TANKS ARE OUT OF SERVICE.

Material:

Site ID: 314923
Operable Unit ID: 937308
Operable Unit: 01
Material ID: 443393
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30
Units: Gallons
Recovered: 28
Resource Affected: Soil
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:

Region of Spill: 9
Spill Number: 8910285
Spill Date: 01/26/1990
Spill Time: 11:00
Spill Cause: Tank Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 11/07/90

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENVIROX FILTER INC (Continued)

S100118253

Cleanup Ceased: 11/07/90
Cleanup Meets Standard: True
Investigator: MF
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 01/26/90
Reported to Department Time: 11:15
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
Spiller Name: ENVIROX FILTER INC
Spiller Address: 60 MEDCALFE STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (716) 856-7279
Facility Extension: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: 05/09/90
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 01/26/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 11/21/90
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 30
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 28
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENVIROX FILTER INC (Continued)

S100118253

Last Date: 19941207

DEC Remarks: 01/26/90: MF SITE VISIT WITH THE BSA SPILLER. SLIGHT SPILLAGE NOTICED, THE SEWER IS PLUGGED. SPILLER PUT PADS IN PLACE. TANKS TO BE PUMPED, SOIL TANKS TO BE DISPOSED OF. NO SPILLAGE GOT INTO THE SEWER. 02/01/90: MF SITE VISIT WITH PAT PAUL, SAND IS BEING REMOVED FROM AROUND THE TANKS 2-1K. I CHECKED THIS SAND FOR SHEEH, IT CHECKED GOOD. I WILL REINSPECT WHEN THEY GET TO THE BOTTOM SAND. 03/27/90: MF SITE VISIT WITH PAUL, TANKS ALL PUMPED OUT. THEY ARE TAKING BIDS FOR TANK CLEANING. 05/09/90: MF SITE VISIT, THE 2-1K TANKS HAVE BEEN REMOVED. THE SOIL UNDER THE TANKS IS CONTAMINATED, APPX 3 BARRELS. TOLD ENVIROX WHAT MUST BE DONE. 06/27/90: MF 1ST DISPOSAL LETTER SENT GIVING UNTIL 7/31/90. 10/12/90: MF 2ND DISPOSAL LETTER SENT GIVING UNTIL 11/15/90. 11/07/90: MF RECEIVED DISPOSAL RECEIPT, NO FURTHER ACTION NECESSARY.

Spill Cause: BASEMENT TANKS IN BERMED AREA LEAKING. TANKS ARE OUT OF SERVICE.

143
WNW
1/2-1
0.666 mi.
3518 ft.

CITY OF BUFFALO HOUSING
444 SENECA STREET
BUFFALO, NY

LTANKS S104516087
HIST LTANKS N/A

Relative:
Lower

Actual:
586 ft.

LTANKS:

Site ID: 216705
Spill No: 9975514
Spill Date: 11/12/1999
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 1/14/2000
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 1502
Investigator: SORGI
Referred To: Not reported
Reported to Dept: 11/12/1999
CID: 30
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 11/17/1999
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 11/12/1999
Spill Record Last Update: 1/26/2000
Spiller Name: FRED HEINLE
Spiller Company: CITY OF BFLO, COMM DEVPMT
Spiller Address: CITY HALL - ROOM 313
Spiller City, St, Zip: BUFFALO, NY 14202-
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 9
DER Facility ID: 179427
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"MJS" 11/12/99: MJS TELECON WITH MIKE MUGAS AND TOOK INFORMATION. THE SITE OF THE NEW HOUSING IS FORMER INDUSTRIAL PROPERTY. CITY OF

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CITY OF BUFFALO HOUSING (Continued)

S104516087

Remarks:

BUFFALO NOW BUILDING NEW HOUSES AND FOUND A 1500 GALLON TANK. CONTAMINATED SOIL REMOVED AND SAMPLES TAKEN. SAMPLES INDICATE CONTAMINATION REMAINS. THEY WILL EXCAVATE ADDITIONAL SOILS NEXT WEEK. 11/12/99: MJS RECEIVED FAX OF SAMPLE RESULTS, HIGHEST IS 3080 PPB 1,2,4-TRIMETHYLBENZENE. APPROX 14 PPM TOTAL VOC'S (DIRECT METHOD). 11/17/99: MJS SITE INSPECTION, MET WITH MIKE MUGAS AND MIKE STEFFAN. THEY HAVE REMOVED THREE ADDITIONAL TRUCKLOADS OF SOIL AND WILL NEED TO REMOVE ONE ADDITIONAL LOAD OF SOIL FROM WALL CLOSEST TO SENECA STREET. MJS ADVISED THEM TO OBTAIN SEPARATE COMPOSITE SAMPLES FROM BOTTOM AND FROM SIDEWALLS AND ANALYZE VIA TCLP. 11/17/99: MJS SECOND SITE INSPECTION, MET WITH MIKE MUGAS. ADDITIONAL LOAD REMOVED FROM WALL BY SENECA ST AND HE HAS OBTAINED CONFIRMATORY SAMPLES. RESULTS WILL BE DUE ON MONDAY 11/22. 11/ /99: MJS TELECON WITH MIKE STEFFAN. SECOND ROUND OF SAMPLES STILL INDICATE LOW-LEVEL CONTAMINATION. THEY WILL REMOVE ADDITIONAL SOIL AGAIN AND SAMPLE FOR THIRD TIME. CITY OF BUFFALO NEEDS CLEAN CLOSURE (HOUSING DEVELOPMENT). 11/22/99: MJS RECEIVED FAX OF SECOND ROUND OF SAMPLING. BOTTOM SAMPLE HAS LOW-LEVEL HITS - HIGHEST IS 5.6 PPB (TCLP) N-BUTYLBENZENE. SIDEWALLS - ONLY HIT IS 7.3 PPB (TCLP) 1,2,4-TRIMETHYLBENZENE 12/01/99: MJS TELECON FROM MIKE STEFFAN. ADDITIONAL SOIL REMOVED AND HE HAS RECEIVED RESULTS FROM THIRD ROUND SAMPLE AND THEY MEET STARS #1 STANDARDS. MJS ADVISED HIM WE NEED FINAL RESULTS AND DISPOSAL DOCUMENTATION TO ISSUE CLOSURE LETTER. 12/01/99: MJS RECEIVED FAX OF SAMPLE RESULTS AND CONFIRMED THAT TCLP RESULTS ARE BELOW GROUNDWATER STANDARDS. 12/21/99: MJS TELECON WITH MIKE STEFFAN. HE IS PREPARING REPORT AND WILL FORWARD WHEN COMPLETE. 01/03/00: MJS TELECON WITH MIKE STEFFAN. REPORT FORTHCOMING. 01/14/00: MJS RECEIVED CLOSURE REPORT FROM ECOLOGY & ENVIRONMENT ON 1/13. MJS REVIEWED REPORT, THIRD ROUND OF CONFIRMATORY SAMPLES ARE BELOW STARS #1 GUIDELINES, "CLEAN" CLOSURE. TOTAL OF 165.89 TONS SOIL DISPOSED AT MODERN LANDFILL, MODEL CITY. 700 GALLONS WATER DISPOSED BY BISON WASTE OIL. REPORT COMPLETE. MJS DRAFTED CLEAN CLOSURE LETTER TO CITY OF BUFFALO (RP). TANK REMOVAL. CONTAMINATED SOIL FOUND.

Material:

Site ID: 216705
Operable Unit ID: 1093876
Operable Unit: 01
Material ID: 292079
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Groundwater
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CITY OF BUFFALO HOUSING (Continued)

S104516087

Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:

Region of Spill: 9
Spill Number: 9975514
Spill Date: 11/12/1999
Spill Time: 09:00
Spill Cause: Tank Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 01/14/00
Cleanup Ceased: / /
Cleanup Meets Standard: True
Investigator: MJS
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 11/12/99
Reported to Department Time: 10:00
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
Spiller Name: CITY OF BFLO, COMM DEVPMT
Spiller Address: CITY HALL - ROOM 313
Spiller City,St,Zip: BUFFALO, NY 14202-
Spiller Cleanup Date: / /
Facility Contact: FRED HEINLE
Facility Phone: (716) 851-5306
Facility Extension: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: 11/17/99
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 11/12/99
Time Spill Entered In Computer Data File: 09:57
Spill Record Last Update: 01/26/00
Is Updated: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CITY OF BUFFALO HOUSING (Continued)

S104516087

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929

DEC Remarks: 11/12/99: MJS TELECON WITH MIKE MUGAS AND TOOK INFORMATION. THE SITE OF THE NEW HOUSING IS FORMER INDUSTRIAL PROPERTY. CITY OF BUFFALO NOW BUILDING NEW HOUSES AND FOUND A 1500 GALLON TANK. CONTAMINATED SOIL REMOVED AND SAMPLES TAKEN. SAMPLES INDICATE CONTAMINATION REMAINS. THEY WILL EXCAVATE ADDITIONAL SOILS NEXT WEEK. 11/12/99: MJS RECEIVED FAX OF SAMPLE RESULTS, HIGHEST IS 3080 PPB 1,2,4-TRIMETHYLBENZENE. APPROX 14 PPM TOTAL VOC S DIRECT METHOD). 11/17/99: MJS SITE INSPECTION, MET WITH MIKEMUGAS AND MIKE STEFFAN. THEY HAVE REMOVED THREE ADDITIONAL TRUCKLOADS OF SOIL AND WILL NEED TO REMOVE ONE ADDITIONAL LOAD OF SOIL FROM WALL CLOSEST TO SENECA STREET. MJS ADVISED THEM TO OBTAIN SEPARATE COMPOSITE SAMPLES FROM BOTTOM AND FROM SIDEWALLS AND ANALYZE VIA TCLP. 11/17/99: MJS SECOND SITE INSPECTION, MET WITH MIKE MUGAS. ADDITIONAL LOAD REMOVED FROM WALL BY SENECA ST AND HE HAS OBTAINED CONFIRMATORY SAMPLES. RESULTS WILL BE DUE ON MONDAY 11/22. 11/ /99: MJS TELECON WITH MIKE STEFFAN. SECOND ROUND OF SAMPLES STILL INDICATE LOW-LEVEL CONTAMINATION. THEY WILL REMOVE ADDITIONAL SOIL AGAIN AND SAMPLE FOR THIRD TIME. CITY OF BUFFALO NEEDS CLEAN CLOSURE HOUSING DEVELOPMENT). 11/22/99: MJS RECEIVED FAX OF SECOND ROUND OF SAMPLING. BOTTOM SAMPLE HAS LOW-LEVEL HITS - HIGHEST IS 5.6 PPB TCLP) N-BUTLYLBENZENE. SIDEWALLS - ONLY HIT IS 7.3 PPB TCLP) 1,2,4-TRIMETHYLBENZENE 12/01/99: MJS TELECON FROM MIKE STEFFAN. ADDITIONAL SOIL REMOVED AND HE HAS RECEIVED RESULTS FROM THIRD ROUND SAMPLE AND THEY MEET STARS 1 STANDARDS. MJS ADVISED HIM WE NEED FINAL RESULTS AND DISPOSAL DOCUMENTATION TO ISSUE CLOSURE LETTER. 12/01/99: MJS RECEIVED FAX OF SAMPLE RESULTS AND CONFIRMED THAT TCLP RESULTS ARE BELOW GROUNDWATER STANDARDS. 12/21/99: MJS TELECON WITH MIKE STEFFAN. HE IS PREPARING REPORT AND WILL FORWARD WHEN COMPLETE. 01/03/00: MJS TELECON WITH MIKE STEFFAN. REPORT FORTHCOMING. 01/14/00: MJS RECEIVED CLOSURE REPORT FROM ECOLOGY ENVIRONMENT ON 1/13. MJS REVIEWED REPORT, THIRD ROUND OF CONFIRMATORY SAMPLES ARE BELOW STARS 1 GUIDELINES, CLEAN CLOSURE. TOTAL OF 165.89 TONS SOIL DISPOSED AT MODERN LANDFILL, MODEL CITY. 700 GALLONS WATER DISPOSED BY BISON WASTE OIL. REPORT COMPLETE. MJS DRAFTED CLEAN CLOSURE LETTER TO CITY OFBUFFALO RP).

Spill Cause: TANK REMOVAL. CONTAMINATED SOIL FOUND.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AJ144 CLINTON AUTO WRECKING
ENE 1125 CLINTON STREET
1/2-1 BUFFALO, NY 14206
0.681 mi.
3596 ft. Site 1 of 2 in cluster AJ

SWF/LF S108468113
N/A

Relative:
Equal

Actual:
590 ft.

SWF/LF:
Flag: ACTIVE
Region Code: 9
Phone Number: 7168563016
Owner Name: Tony Mele
Owner Type: Private
Owner Address: 1125 Clinton Street
Owner Addr2: Not reported
Owner City,St,Zip: Buffalo, NY 14206
Owner Email: Not reported
Owner Phone: 7168563016
Contact Name: Tony Mele
Contact Address: Clinton Auto Wrecking Inc.
Contact Addr2: 1125 Clinton Street
Contact City,St,Zip: Buffalo, NY 14206
Contact Email: Not reported
Contact Phone: 7168563016
Activity Desc: Vehicle Dismantling
Activity Number: 15J22
Active: Yes
East Coordinate: 186832
North Coordinate: 4754313
Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
Regulatory Status: None
Waste Type: Not reported
Authorization #: None
Authorization Date: Not reported
Expiration Date: Not reported

AJ145 BENGART & MEMEL, INC.
ENE 1079 CLINTON STREET
1/2-1 BUFFALO, NY 14206
0.688 mi.
3634 ft. Site 2 of 2 in cluster AJ

SHWS S109059104
N/A

Relative:
Equal

Actual:
590 ft.

SHWS:
Program: HW
Site Code: 58011
Classification: SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region: 9
Acres: .410
HW Code: 915115
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 8/25/2009 2:21:00 PM
Updated By: MLDOSTER
Site Description: The Bengart and Memel (BM) site is located at 1079 Clinton St. in an urban commercial area on the south side of Clinton St. in the city of Buffalo and is approximately 0.41 acres in size. The surrounding land use is a mix of commercial and warehousing operations on the southern side of Clinton St. with residential and commercial on the north side of Clinton St. The former BM business operations consisted of three concrete block buildings with the balance of land previously used for employee parking and for non-ferrous scrap metal stockpiling and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BENGART & MEMEL, INC. (Continued)

S109059104

sorting. The former BM operations occupied approximately 2.91 acres of land prior to subdivision (1091 and 1079 Clinton St.). During operations, scrap metal and alloys were processed and sorted. BM periodically received transformers and capacitors containing PCB fluids. PCB-containing fluids were spilled on the site contaminating the soil and shallow groundwater. Fluid spills drained off the site reaching the Buffalo Sewer Authority (BSA) combined sanitary sewer system on Clinton St. Prior to a 1982 Order on Consent between the Department and BM, a 0.41 acre portion of the BM operations site containing the known PCB contamination was subdivided (1079 Clinton St.). This PCB-contaminated area currently contains one of the three former BM buildings, a dilapidated concrete block building formerly used as a garage, the asphalt capped area, and a groundwater collection and treatment system. As a special note, the groundwater treatment system is situated on a concrete containment pad that straddles the 0.41 acre site subject to the Order and the balance of the former BM operations site (1091 Clinton St.). The 1091 Clinton St. property has been sold several times since the subdivision and is currently used by an automobile wrecking operation. The 1982 Consent Order required remediation of the PCB spill area on the site. Remediation activities commenced in 1985. Contaminated soil in excess of 50 ppm PCBs was excavated and placed in drums for subsequent chemical treatment. Treatment of the PCB-contaminated soils was reportedly completed in 1986. Some of the treated soils were placed back onto the site and used as fill or were disposed off-site in a secure landfill. A shallow groundwater collection system was installed to intercept PCB-impacted groundwater in the shallow groundwater horizon. Collected water was batch processed by a carbon adsorption system prior to discharge to the BSA sanitary sewer system. The PCB-contaminated area was covered with an asphalt cap to minimize contact with residual level PCB-contaminated soil and reduce the generation of PCB-impacted shallow groundwater. Based on available information, the site was reclassified from a Class 2 site to a Class 4 site in 1987. The existing groundwater treatment system at 1079 Clinton St. has been inoperable for several years and the responsible party is no longer able to maintain the site. In response to assess the need for continued operation and upgrade of the collection and treatment system, the DEC performed a limited Site Characterization Study in 2006 to assess existing site conditions for residual PCBs. This investigation indicates elevated PCB concentrations are present in surface and below surfaces at the site. Groundwater was also determined to be above water quality standards for PCBs. An Interim Remedial Action is planned to remove PCB waste material.

Env Problem:

The 1982 Order on Consent required the reduction of total PCB levels below 50 ppm, elimination of PCB exposure by the management of shallow groundwater and maintenance of the asphalt cap area at the northeast section of the site. Upon meeting these requirements, the site was reclassified from a Class 2 site to a Class 4 site in 1987. The site was previously remediated using a PCB dechlorination process to reduce the PCB soil contamination levels to levels below 50 ppm. The data provided at the time of the previous remediation suggested that the remediation achieved the goal of reducing PCB levels below 50 ppm. The responsible party has not maintained the asphalt cap, ceased operating the groundwater remediation system, and has abandoned the site. The current treatment system has significant operational flaws and has been inoperable since the late 1990's.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BENGART & MEMEL, INC. (Continued)

S109059104

Several attempts were made by the NYSDEC to have the responsible party repair the groundwater remediation system and place it back in operation. Potential contaminant release points include groundwater bypassing the collection sump, broken pipes in treatment system, and overflow from potentially contaminated media in the treatment system containment area. A limited focused investigation was conducted by the NYSDEC in 2006 to assess existing site conditions for residual PCBs and continued need for maintaining the operation of the groundwater collection and treatment system. The site investigation revealed elevated levels of PCBs found throughout the site in surface and below surface soil samples above Part 375 cleanup standards for commercial facilities of 1 ppm PCB and above TSCA listed hazardous waste level of 50 ppm PCB. Subsurface PCB levels varied from levels above 1 ppm to 221 ppm total PCBs. Surface PCB levels varied from 14 ppm to 334 ppm total PCBs. PCB levels at the edge of the lot subject to public exposure varied from 74 ppm to 94 ppm total PCBs. Additionally, sediments/sludge in on-site sumps and catch basins that are connected to off-site sewer manholes also contained PCBs at levels that varied from 32 ppm to 91 ppm total PCBs. The investigation also revealed several volatile organic compound (VOCs) semi-volatile compounds (SVOCs) found in subsurface soil samples. Any intrusive work at the site could expose workers to hazardous waste levels of PCBs at the site. Shallow groundwater results revealed elevated levels of PCBs above the groundwater quality standard of 0.09 ppb (ug/l) PCB. PCB levels in shallow groundwater and several collection sumps revealed levels that varied from 18.2 to 130 ppb total PCBs. Because of the non-functioning ground remediation system and elevated fill at the site, there is the potential for off-site migration of PCB contamination from potential groundwater seeps that could occur along the fill embankment at the site. More information regarding the site can be found in the documents placed in the Site Document Repository.

Health Problem: People frequenting the site may come in contact with contaminated soil or inhale contaminated dust. Drinking contaminated water is not expected since public water serves the area.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1950
Disp Term: 1978
Lat/Long: 42:52:40:0 / 78:50:08:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 7/17/2009 11:31:00 AM
Updated By: ewmelnky
Own Op: Disp. Owner
Sub Type: T01
Owner Name: HOWARD POPKIN
Owner Company: BENGART AND MEMEL, INC
Owner Address: 95 CIMMARAND DRIVE
Owner Addr2: Not reported
Owner City,St,Zip: WILLIAMSVILLE, NY 14211
Owner Country: United States of America
Own Op: Owner
Sub Type: E

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BENGART & MEMEL, INC. (Continued)

S109059104

Owner Name: LLC OWNER: BRIAN SCHECTMAN OF IRF
Owner Company: 1091 CLINTON, INC. LLC
Owner Address: PO BOX 1011
Owner Addr2: Not reported
Owner City,St,Zip: BUFFALO, NY 14240
Owner Country: United States of America
HW Code: 915115
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915115
Waste Type: CARBON TETRACHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915115
Waste Type: 1,2,4-TRICHLORO BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915115
Waste Type: 1,4-DICHLORO BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD013703319
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS
Crossref ID: 91-7T01-06-82
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 3/10/2009 11:03:00 AM
Record Updated: 3/10/2009 11:03:00 AM
Updated By: DMMOULOG

146
ENE
1/2-1
0.700 mi.
3695 ft.

**80 METCALFE ARTRCRAFT
80 METCALFE STREET
BUFFALO, NY**

**LTANKS S101341700
HIST LTANKS N/A**

**Relative:
Higher**

**Actual:
597 ft.**

LTANKS:
Site ID: 206931
Spill No: 9412966
Spill Date: 12/28/1994
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 4/19/1995
Facility Addr2: Not reported
Cleanup Ceased: 4/19/1995
Cleanup Meets Standard: True
SWIS: 1502
Investigator: RMCROSSE
Referred To: Not reported
Reported to Dept: 12/28/1994
CID: 30

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

80 METCALFE ARTRCRAFT (Continued)

S101341700

Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 1/5/1995
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1/3/1995
Spill Record Last Update: 4/19/1995
Spiller Name: Not reported
Spiller Company: ARTCRAFT-BUROW PRINTERS
Spiller Address: 80 METCALFE STREET
Spiller City,St,Zip: BUFFALO, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 171760
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"RMC" 01/05/95: RMC/SHANAHAN/SITE EXCAVATION TO TOP OF TANK BEGUN,
CONTAMINATION FOUND, HOLE FILLED W/ WATER TO TOP OF TANKS, BISON ON
SITE, TO REINSPECT. 01/10/95: RMC/SHANAHAN/PHONE COULLLD NOT DIG TO
VISUAL CLEAN RP TO INSTALL PIT WELL,TEST RESULTS DUE 2/28/95.
03/01/95: RMC/RECEIVED EXCAVATION RESULTS, NO EXCEEDANCES, DISPOSAL
DUE 3/30/95. 04/04/95: RMC/RECEIVED EXCAVATION RESULTS, NO
EXCEEDANCES, DISPOSAL DUE 3/30/95REVISED TO 4/15/95. 04/19/95:
RMC/SHANAHAN/PHONE SOIL DISPOSED OF, DOCUMENTS TO FOLLOW, DUE
4/30/95. 04/19/95: RMC/RECEIVED DIESPOSAL DOCUMENTATION, OK, SPILL
COMPLETEE, CLOSE LETTER, CLOSE OUT.
Remarks: CLOSURE NOTICE SHOWS WATER IN TANKS, 1K+2K TANKS

Material:
Site ID: 206931
Operable Unit ID: 1010534
Operable Unit: 01
Material ID: 375250
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Soil
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

80 METCALFE ARTRCRAFT (Continued)

S101341700

Test Method: Not reported

HIST LTANKS:

Region of Spill: 9
Spill Number: 9412966
Spill Date: 12/28/1994
Spill Time: 12:00
Spill Cause: Tank Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 04/19/95
Cleanup Ceased: 04/19/95
Cleanup Meets Standard: True
Investigator: RMC
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 12/28/94
Reported to Department Time: 12:00
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
Spiller Name: ARTCRAFT-BUROW PRINTERS
Spiller Address: 80 METCALFE STREET
Spiller City,St,Zip: BUFFALO
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (716) -
Facility Extension: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: 01/05/95
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 01/03/95
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 04/19/95
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

80 METCALFE ARTRCRAFT (Continued)

S101341700

Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0

Unkonwn Quantity Recovered: False

Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929

DEC Remarks: 01/05/95: RMC/SHANAHAN/SITE EXCAVATION TO TOP OF TANK BEGUN, CONTAMINATION FOUND, HOLE FILLED W/ WATER TO TOP OF TANKS, BISON ON SITE, TO REINSPECT.
01/10/95: RMC/SHANAHAN/PHONE COULLLD NOT DIG TO VISUAL CLEAN RP TO INSTALL PIT WELL, TEST RESULTS DUE 2/28/95. 03/01/95: RMC/RECEIVED EXCAVATION RESULTS, NO EXCEEDANCES, DISPOSAL DUE 3/30/95. 04/04/95: RMC/RECEIVED EXCAVATION RESULTS, NO EXCEEDANCES, DISPOSAL DUE 3/30/95REVISED TO 4/15/95. 04/19/95: RMC/SHANAHAN/PHONE SOIL DISPOSED OF, DOCUMENTS TO FOLLOW, DUE 4/30/95.
04/19/95: RMC/RECEIVED DIESPOSAL DOCUMENTATION, OK, SPILL COMPLETEE, CLOSE LETTER, CLOSE OUT.

Spill Cause: CLOSURE NOTICE SHOWS WATER IN TANKS, 1K+2K TANKS

AK147
NE
1/2-1
0.715 mi.
3776 ft.

KAR KARE STATION
389 FILLMORE AVENUE
BUFFALO, NY

LTANKS **S100119591**
HIST LTANKS **N/A**

Site 1 of 2 in cluster AK

Relative:
Higher

LTANKS:

Actual:
599 ft.

Site ID: 151378
Spill No: 8710242
Spill Date: 3/7/1988
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 5/13/1988
Facility Addr2: Not reported
Cleanup Ceased: 5/13/1988
Cleanup Meets Standard: True
SWIS: 1502
Investigator: MXFRANKS
Referred To: Not reported
Reported to Dept: 3/7/1988
CID: 30
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 3/7/1988
Spill Record Last Update: 3/18/2002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KAR KARE STATION (Continued)

S100119591

Spiller Name: Not reported
Spiller Company: PAUL SPRADA
Spiller Address: 389 FILLMORE AVENUE
Spiller City,St,Zip: BUFFALO, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 9
DER Facility ID: 128648
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MF" 03/07/88: MF TELECON PAUL SPRADA, I GAVE HIM UNTIL NEXT WEEK TO
GET THE TANK RETESTED. 04/05/88: MF TELECON PAUL SPRADA, HE WILL SEND
ME A COPY OF THE RETEST RESULTS. 04/22/88: MF JIM BEECH TELECON (TANK
TESTER) 6K TANK FAILED TEST. TANK TO BE EXPOSED & RETESTED. TELECON
PAUL, GAVE HIM UNTIL NEXT WEEK TO HAVE TANK RETESTED OR EMPTIED.
05/02/88: MF JIM BEESCH TELECON, ALL TANKS PASSED TESTS OR RETESTS.
05/11/88: MF TELECON PAUL FOR RETEST RESULTS, NOT IN, LEFT MESSAGE TO
RETURN CALL. 05/13/88: MF RECEIVED RETEST RESULTS FROM PETROLEUM TANK
TESTING INC. BOTH TANKS PASSED RETEST.
Remarks: 4K UNLEADED TANK COULDN'T BE TESTED (INCONCLUSIVE). TO BE UNCOVERED &
RETESTED.

Material:
Site ID: 151378
Operable Unit ID: 915172
Operable Unit: 01
Material ID: 462018
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Groundwater
Oxygenate: False

Tank Test:
Site ID: 151378
Spill Tank Test: 1533389
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 9
Spill Number: 8710242
Spill Date: 03/07/1988
Spill Time: 13:30

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KAR KARE STATION (Continued)

S100119591

Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 05/13/88
Cleanup Ceased: 05/13/88
Cleanup Meets Standard: True
Investigator: MF
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 03/07/88
Reported to Department Time: 13:35
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: PAUL SPRADA
Spiller Address: 389 FILLMORE AVENUE
Spiller City,St,Zip: BUFFALO, NY
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (716) 849-0627
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: -
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 03/07/88
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/01/96
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KAR KARE STATION (Continued)

S100119591

Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 03/07/88: MF TELECON PAUL SPRADA, I GAVE HIM UNTIL NEXT WEEK TO GET THE TANK RETESTED. 04/05/88: MF TELECON PAUL SPRADA, HE WILL SEND ME A COPY OF THE RETEST RESULTS. 04/22/88: MF JIM BEECH TELECON TANK TESTER) 6K TANK FAILED TEST. TANK TO BE EXPOSED RETESTED. TELECON PAUL, GAVE HIM UNTIL NEXT WEEK TO HAVE TANK RETESTED OR EMPTIED. 05/02/88: MF JIM BEESCH TELECON, ALL TANKS PASSED TESTS OR RETESTS. 05/11/88: MF TELECON PAUL FOR RETEST RESULTS, NOT IN, LEFT MESSAGE TO RETURN CALL. 05/13/88: MFRECEIVED RETEST RESULTS FROM PETROLEUM TANK TESTING INC. BOTH TANKS PASSED RETEST.
Spill Cause: 4K UNLEADED TANK COULDN T BE TESTED INCONCLUSIVE). TO BE UNCOVERED RETESTED.

148
NNE
1/2-1
0.720 mi.
3799 ft.

**RICH LEE SERVICE
741 WILLIAM AT SMITH
BUFFALO, NY**

**LTANKS S100120508
HIST LTANKS N/A**

**Relative:
Higher**

**Actual:
597 ft.**

LTANKS:
Site ID: 83962
Spill No: 9008247
Spill Date: 10/29/1990
Spill Cause: Tank Failure
Spill Source: Gasoline Station
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/15/1992
Facility Addr2: Not reported
Cleanup Ceased: 12/15/1992
Cleanup Meets Standard: True
SWIS: 1502
Investigator: LEARY
Referred To: Not reported
Reported to Dept: 10/29/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 12/15/1992
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/30/1990
Spill Record Last Update: 3/19/2002
Spiller Name: Not reported
Spiller Company: RICH LEE SERVICE
Spiller Address: 741 WILLIAM STREET
Spiller City,St,Zip: BUFFALO, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 77243

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RICH LEE SERVICE (Continued)

S100120508

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "RNL" 10/29/90: RNL SITE INSP. 10/29/90, MINOR CONTAMINATION FOUND IN LOCALIZED AREA OF SOIL AROUND FILL, VERY SLIGHT SHEEN ON WATER, TWO TANKS EXPOSED. 10/30/90: RNL SITE INSP. 10/30/90, CONTAMINATED SOIL STOCKPILED, VERY SLIGHT SHEEN ON WATER, TWO TANKS REMOVED, ONE TANK TO BE REMOVED. 11/02/90: RNL SITE INSP. 11/02/90, ALL TANKS REMOVED, EXCAVATION SATISFACTORY, SOIL STOCKPILED, HOLD FOR SOIL RECEIPT. 12/06/90: RNL CHECK 12/06/90, SOIL STILL ON SITE, COVERED WITH PLASTIC, HOLD FOR DISPOSAL RECEIPT. 12/06/90: RNL CHECK 02/08/91, NO CHANGE, SOIL STILL ON SITE, COVERED WITH PLASTIC, HOLD FOR DISPOSAL RECEIPT. 03/15/91: RNL CHECK 03/15/91, NO CHANGE, SOIL STILL ON SITE, COVERED WITH PLASTIC, HOLD FOR DISPOSAL RECEIPT. 03/15/91: RNL TELECON TO MAJEWSKI 04/10/91 ABOUT SOIL DISPOSAL, HE WILL CHECK WITH HIS CONTRACTOR, HE WILL SEND RECEIPT WHEN AVAILABLE. 05/15/91: RNL SECOND TELECON TO MAJEWSKI 05/15/91 ABOUT SOIL DISPOSAL, HE WILL SEND RECEIPT WHEN AVAILABLE. 06/24/91: RNL INSP. 06/24/91, MET MAJEWSKI, HE SAID SOIL HAD BEEN REMOVED BY DOBLEE, HE WILL CHECK FOR RECEIPT. 08/26/91: RNL LETTER 08/26/91 TO MAJEWSKI, REQUESTED SOIL DISPOSAL RECEIPT. 09/24/91: RNL REC. LETTER FROM MAJEWSKI 09/24/91, BFI HANDLING DISPOSAL, WILL SEND RECEIPT, NOW SAMPLING. 02/25/92: RNL DISPOSAL LETTER TO MAJEWSKI 02/19/92, REQUESTED RECEIPT BY 03/20/92; RNL INSPECTION 02/25/92, SOIL STILL ON SITE, STATION NO LONGER PUMPING GAS. 07/10/92: RNL INSP. 07/09/92, STATION CLOSED, SOIL STILL ON SITE; RNL TELECON 07/10/92, NO ANSWER, SEND LETTER. 12/15/92: RNL INSP. 12/15/92, STATION CLOSED, NEW HOUSE BUILT WHERE SOIL WAS STAGED, SOIL PROBABLY SPREAD OUT, DECIDE TO CLOSEOUT, NOT WARRANTED TO PURSUE, SOIL HAD NO ODOR OR VISIBLE CONTAMINATION.

Remarks: NOTIFIED BY CONTRACTOR, OLD TANKS BEING REMOVED, NEW TANKS BEING INSTALLED

Material:

Site ID: 83962
Operable Unit ID: 948892
Operable Unit: 01
Material ID: 432081
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Groundwater
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RICH LEE SERVICE (Continued)

S100120508

HIST LTANKS:

Region of Spill: 9
Spill Number: 9008247
Spill Date: 10/29/1990
Spill Time: 14:00
Spill Cause: Tank Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Gas Station
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/15/92
Cleanup Ceased: 12/15/92
Cleanup Meets Standard: True
Investigator: RNL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 10/29/90
Reported to Department Time: 14:30
SWIS: 14
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: RICH LEE SERVICE
Spiller Address: 741 WILLIAM STREET
Spiller City,St,Zip: BUFFALO, NY
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (716) 852-3226
Facility Extention: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: 12/15/92
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/30/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 12/30/92
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RICH LEE SERVICE (Continued)

S100120508

Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum

Quantity Spilled: 0

Unkonwn Quantity Spilled: False

Units: Gallons

Quantity Recovered: 0

Unkonwn Quantity Recovered: False

Material: GASOLINE

Class Type: GASOLINE

Times Material Entry In File: 21329

CAS Number: Not reported

Last Date: 19940929

DEC Remarks: 10/29/90: RNL SITE INSP. 10/29/90, MINOR CONTAMINATION FOUND IN LOCALIZED AREA OF SOIL AROUND FILL, VERY SLIGHT SHEEN ON WATER, TWO TANKS EXPOSED. 10/30/90: RNL SITE INSP. 10/30/90, CONTAMINATED SOIL STOCKPILED, VERY SLIGHT SHEEN ON WATER, TWO TANKS REMOVED, ONE TANK TO BE REMOVED. 11/02/90: RNL SITE INSP. 11/02/90, ALL TANKS REMOVED, EXCAVATION SATISFACTORY, SOIL STOCKPILED, HOLD FOR SOIL RECEIPT. 12/06/90: RNL CHECK 12/06/90, SOIL STILL ON SITE, COVERED WITH PLASTIC, HOLD FOR DISPOSAL RECEIPT. 12/06/90: RNL CHECK 02/08/91, NO CHANGE, SOIL STILL ON SITE, COVERED WITH PLASTIC, HOLD FOR DISPOSAL RECEIPT. 03/15/91: RNL CHECK 03/15/91, NO CHANGE, SOIL STILL ON SITE, COVERED WITH PLASTIC, HOLD FOR DISPOSAL RECEIPT. 03/15/91: RNL TELECON TO MAJEWSKI 04/10/91 ABOUT SOIL DISPOSAL, HE WILL CHECK WITH HIS CONTRACTOR, HE WILL SEND RECEIPT WHEN AVAILABLE. 05/15/91: RNL SECOND TELECON TO MAJEWSKI 05/15/91 ABOUT SOIL DISPOSAL, HE WILL SEND RECEIPT WHEN AVAILABLE. 06/24/91: RNL INSP. 06/24/91, MET MAJEWSKI, HE SAID SOIL HAD BEEN REMOVED BY DOBLEE, HE WILL CHECK FOR RECEIPT. 08/26/91: RNL LETTER 08/26/91 TO MAJEWSKI, REQUESTED SOIL DISPOSAL RECEIPT. 09/24/91: RNL REC. LETTER FROM MAJEWSKI 09/24/91, BFI HANDLING DISPOSAL, WILL SENDRECEIPT, NOW SAMPLING. 02/25/92: RNL DISPOSAL LETTER TO MAJEWSKI 02/19/92, REQUESTED RECEIPT BY 03/20/92; RNL INSPECTION 02/25/92, SOIL STILL ON SITE, STATION NO LONGER PUMPING GAS. 07/10/92: RNL INSP. 07/09/92, STATION CLOSED, SOIL STILL ON SITE;RNL TELECON 07/10/92, NO ANSWER, SEND LETTER. 12/15/92: RNL INSP. 12/15/92, STATION CLOSED, NEW HOUSE BUILT WHERE SOIL WAS STAGED, SOIL PROBABLY SPREAD OUT, DECIDE TO CLOSEOUT, NOT WARRANTED TO PURSUE, SOIL HAD NO ODOR OR VISIBLE CONTAMINATION.

Spill Cause: NOTIFIED BY CONTRACTOR, OLD TANKS BEING REMOVED, NEW TANKS BEING INSTALLED

AK149
NE
1/2-1
0.722 mi.
3814 ft.

FILLMORE TRAILER SITE
393 FILLMORE AVENUE
BUFFALO, NY 14207

Site 2 of 2 in cluster AK

CERCLIS **1006931953**
NYN000204493

Relative:
Higher

CERCLIS:

Site ID: 0204493

Federal Facility: Not a Federal Facility

Actual:
600 ft.

NPL Status: Not on the NPL

Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

CERCLIS Site Contact Name(s):

Contact Name: Not reported

Contact Tel: Not reported

Contact Title: 22720

Contact Name: Not reported

Contact Tel: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FILLMORE TRAILER SITE (Continued)

1006931953

Contact Title: 22720

Site Description: Abandoned trailer damaged by arson fire. The trailer contained about 100 drums, with some bulging and was open to the public. The site is near a senior citizen housing facility, gasoline/food store and residences. An emergency removal will be performed.

CERCLIS Assessment History:

Action: REMOVAL

Date Started: 8/27/2003 0:00:00

Date Completed: 10/9/2003 0:00:00

Priority Level: Cleaned up

Action: REMOVAL ASSESSMENT

Date Started: 8/27/2003 0:00:00

Date Completed: 12/15/2003 0:00:00

Priority Level: Not reported

Action: NON-NPL PRP SEARCH

Date Started: 8/27/2003 0:00:00

Date Completed: 9/22/2006 0:00:00

Priority Level: Search Complete, No Viable PRPs

150
East
1/2-1
0.727 mi.
3840 ft.

BENGART-MEMEL
1091 CLINTON ST
BUFFALO, NY 14206

CERC-NFRAP 1006426325
NYD013703319

Relative:
Equal

CERC-NFRAP:

Site ID: 0201510

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

Non NPL Status: NFRAP

Actual:
590 ft.

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: BENGART-MEMEL INC (NYD049830094)

Alias Address: Not reported
ERIE, NY

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY

Date Started: Not reported

Date Completed: 04/01/1980

Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT

Date Started: Not reported

Date Completed: 12/22/1987

Priority Level: NFRAP: No further Remedial Action planned

Action: ARCHIVE SITE

Date Started: Not reported

Date Completed: 04/22/1998

Priority Level: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AL151 **BUFFALO COLOR CORPORATION**
SSE 100 LEE STREET
1/2-1 **BUFFALO, NY 14210**
0.729 mi.
3849 ft. **Site 1 of 3 in cluster AL**

Relative:
Lower

CBS AST 1001010979
HIST AST N/A
MOSF AST
MANIFEST
NY Spills
NY Hist Spills
MOSF
CBS

Actual:
587 ft.

CBS AST:
CBS Number: 9-000130
Region: STATE
ICS Number: 9-178382
PBS Number: 9-514144
MOSF Number: -
Telephone: (716) 827-4605
Facility Town: BUFFALO (C)
Operator: SECURITY
Emrgncy Contact: MICHAEL W. LINDAMAN
Emrgncy Phone: (716) 827-4605
Expiration Date: 06/20/2003
Owner Name: BUFFALO COLOR CORPORATION
Owner Address: PO BOX 7027
Owner City,St,Zip: BUFFALO, NY 14240
Owner Telephone: (716) 827-4500
Owner type: Corporate/Commercial
Facility Type: MANUFACTURING
Mail Name: BUFFALO COLOR CORPORATION
Mail Contact Addr: PO BOX 7027
Mail Contact Addr2: 100 LEE ST.
Mail Contact Contact: LANA DOLE
Mail Contact City,St,Zip: BUFFALO, NY 14240
Mail Phone: (716) 827-4525
SPDES Number: 0-002470
Facility Status: ACTIVE FACILITY
Owner Sub Type: Not reported

Tank Id: 93053
Date Entered: 11/08/1999
Capacity (Gal): 12032
Chemical: Aniline
Tank Closed: 08/01
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 12/99
Certified Date: 12/07/2001
CAS Number: 62533
Substance: More than one Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 5
Pipe Containment: None
Tank Containment: Diking
Leak Detection: Other
Overfill Protection: High Level Alarm,Fiberglass

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Haz Percent: 100
Total Tanks: 28
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I51I57 / 78I50I38
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: 07/20/93
Is it There: F
Deliquent: F
Date Expired: 06/20/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/14/2001
Total Capacity of All Active Tanks(gal): 397597

Tank Id: 08201
Date Entered: 06/20/1989
Capacity (Gal): 7138
Chemical: Sodium
Tank Closed: 12/99
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 12/77
Certified Date: 12/07/2001
CAS Number: 7440235
Substance: Single Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: Other
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 6
Pipe Containment: None
Tank Containment: Other
Leak Detection: None
Overfill Protection: Automatic Shut-Off
Haz Percent: 100
Total Tanks: 28
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I51I57 / 78I50I38
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: 07/20/93

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Is it There: F
Delinquent: F
Date Expired: 06/20/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/14/2001
Total Capacity of All Active Tanks(gal): 397597

Tank Id: 94810
Date Entered: 06/20/1989
Capacity (Gal): 23029
Chemical: Sodium hydroxide
Tank Closed: 00/00
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 12/77
Certified Date: 12/07/2001
CAS Number: 1310732
Substance: More than one Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: Jacketed
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 6
Pipe Containment: None
Tank Containment: Diking,Painted/Asphalt Coating
Leak Detection: None
Overfill Protection: Catch Basin
Haz Percent: 9
Total Tanks: 28
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42!51!57 / 78!50!38
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: 07/20/93
Is it There: F
Delinquent: F
Date Expired: 06/20/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/14/2001
Total Capacity of All Active Tanks(gal): 397597

Tank Id: 94811

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Date Entered: 06/20/1989
Capacity (Gal): 13056
Chemical: Sodium hydroxide
Tank Closed: 00/00
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 12/72
Certified Date: 12/07/2001
CAS Number: 1310732
Substance: More than one Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: Jacketed
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 6
Pipe Containment: None
Tank Containment: Diking
Leak Detection: None
Overfill Protection: Catch Basin
Haz Percent: 9
Total Tanks: 28
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I51I57 / 78I50I38
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: 07/20/93
Is it There: F
Deliquent: F
Date Expired: 06/20/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/14/2001
Total Capacity of All Active Tanks(gal): 397597

Tank Id: 94821
Date Entered: 06/20/1989
Capacity (Gal): 23029
Chemical: Sodium hydroxide
Tank Closed: 00/00
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 12/72
Certified Date: 12/07/2001
CAS Number: 1310732
Substance: More than one Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: Fiberglass Liner (FRP)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Extrnl Protection: Jacketed,None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 6
Pipe Containment: None
Tank Containment: Remote Impounding Area,Painted/Asphalt Coating
Leak Detection: None
Overfill Protection: Catch Basin
Haz Percent: 9
Total Tanks: 28
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I51I57 / 78I50I38
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: 07/20/93
Is it There: F
Deliquent: F
Date Expired: 06/20/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/14/2001
Total Capacity of All Active Tanks(gal): 397597

[Click this hyperlink](#) while viewing on your computer to access
51 additional NY_AST_CBS: record(s) in the EDR Site Report.

HIST AST:

PBS Number: 9-514144
SWIS Code: 1402
Operator: BUFFALO COLOR CORP
Facility Phone: (716) 827-4500
Facility Addr2: Not reported
Facility Type: MANUFACTURING
Emergency: GORDON G. BOLLES JR.
Emergency Tel: (716) 827-4525
Old PBSNO: Not reported
Date Inspected: 19930306
Inspector: JES
Result of Inspection: 9
Owner Name: LANESBOROUGH
Owner Address: 100 LEE ST.
Owner City,St,Zip: BUFFALO, NY 14210
Federal ID: Not reported
Owner Tel: (716) 827-4500
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: GORDON BOLLES JR.
Mailing Name: BUFFALO COLOR CORPORATION
Mailing Address: P.O. BOX 7027

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Mailing Address 2: Not reported
Mailing City,St,Zip: BUFFALO, NY 14240
Mailing Telephone: (716) 827-4525
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 09/29/2000
Expiration: 12/17/2005
Renew Flag: False
Renew Date: Not reported
Total Capacity: 385900
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: 9-000130
Town or City: BUFFALO (C)
County Code: 14
Town or City Code: 02
Region: 9

Tank ID: HT1 AREA A
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19960101
Capacity (Gal): 275
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 01
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Tank Containment: 08
Leak Detection: 00
Overfill Protection: 00
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: HT1 AREA B
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19810101
Capacity (Gal): 275

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: 8
Leak Detection: 0
Overfill Protection: 0
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: HT1 AREA C
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19940101
Capacity (Gal): 275
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 04
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: 8
Leak Detection: 0
Overfill Protection: 00
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: HT2 AREA C
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19940101
Capacity (Gal): 275
Product Stored: DIESEL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 00
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 01
Tank Containment: 08
Leak Detection: 00
Overfill Protection: 00
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: PT2 AREA C
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19760101
Capacity (Gal): 1000
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 0
Tank Containment: Synthetic Liner
Leak Detection: 0
Overfill Protection: 0
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: VT3 AREA C
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: 19700101
Capacity (Gal): 383800
Product Stored: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 6
Tank Containment: 8
Leak Detection: 0
Overfill Protection: 40
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

MOSF AST:

MOSF Number: 9-1480
SWIS Code: 14
Facility Town: BUFFALO
Facility Phone: (716) 827-4525
Emergency Contact Name: Not reported
Emergency Contact Phone: Not reported
Total Tanks: 1
Total Capacity: 383800
Daily Throughput: 15603
License Status: MOSF AST
Facility Type: OTHER RETAIL SALES
Product Transfer Operation: Tank Truck
Facility Status: NO LONGER A MAJOR FACILITY
Operator Name: D. SAUER
Owner Name: BUFFALO COLOR CORPORATION
Owner Address: P.O. BOX 7027
Owner City,St,Zip: BUFFALO, NY 14240-
Owner Phone: (716) 827-4500
Owner Type: Corporate/Commercial
Owner Status: 1
Owner Mark: First Owner
Mailing Name: BUFFALO COLOR CORPORATION
Mailing Address: P.O. BOX 7027
Mailing Address 2: Not reported
Mailing City,St,Zip: BUFFALO, NY 14240-
Mailing Contact: D. SAUER
Mailing Phone: (716) 827-4525
Legal Agent Name: MOOT, SPRAGUS, MARCY, FORNBACH & SMYTHE
Legal Agent Address: 2300 ERIE SAVINGS BANK-2 MAIN
Legal Agent City,St,Zip: BUFFALO, NY 14202-
LIC Expires: 03/31/1991

Tank ID: VT-2
Tank Location: ABOVEGROUND
Install Date: 12/48
Product: NOS 1,2, OR 4 FUEL OIL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 9
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Other
Second Contain: 8
Leak Detection: None
Overfill Protection: None
Dispensing Mthd: Suction
Test Date: Not reported
Date Closed: UNKWN
Status of Data: Complete
Capacity (gal): 30600
Lat/Long: 42I51I57 / 78I50I30
Federal ID: Not reported
Inspected Date: / /
Inspector: Not reported
Renew Date: / /
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Status of Data: In Service
COI Date: / /
Date License Issued: 04/01/1990
Date License Application Received: / /
Chemical Bulk Storage Number: 9-000130
Pollution Discharge Elimination System Num: Not reported
Date Legal Agent Filed with Secretary of State: 02/77

Tank ID: VT-3
Tank Location: ABOVEGROUND
Install Date: 12/70
Product: NOS 5 OR 6 FUEL OIL
Tank Status: In Service
Tank Type: Fiberglass coated steel
Tank Internal: None
Tank External: 9
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Other
Second Contain: 8
Leak Detection: None
Overfill Protection: Product Level Gauge
Dispensing Mthd: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Capacity (gal): 383800
Lat/Long: 42I51I57 / 78I50I30
Federal ID: Not reported
Inspected Date: / /

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Inspector: Not reported
Renew Date: / /
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Status of Data: In Service
COI Date: / /
Date License Issued: 04/01/1990
Date License Application Received: / /
Chemical Bulk Storage Number: 9-000130
Pollution Discharge Elimination System Num: Not reported
Date Legal Agent Filed with Secretary of State: 02/77

Tank ID: VT-15
Tank Location: ABOVEGROUND
Install Date: 12/74
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 9
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Other
Second Contain: 8
Leak Detection: None
Overfill Protection: Product Level Gauge
Dispensing Mthd: Suction
Test Date: Not reported
Date Closed: 12/90
Status of Data: Complete
Capacity (gal): 13500
Lat/Long: 42|51|57 / 78|50|30
Federal ID: Not reported
Inspected Date: / /
Inspector: Not reported
Renew Date: / /
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Status of Data: In Service
COI Date: / /
Date License Issued: 04/01/1990
Date License Application Received: / /
Chemical Bulk Storage Number: 9-000130
Pollution Discharge Elimination System Num: Not reported
Date Legal Agent Filed with Secretary of State: 02/77

NY MANIFEST:

EPA ID: NYR000002147
Country: USA
Mailing Name: HONEYWELL INC - BUFFALO COLOR
Mailing Contact: EMIL WALERKO

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Mailing Address: 101 COLUMBIA RD
Mailing Address 2: Not reported
Mailing City: MORRISTOWN
Mailing State: NJ
Mailing Zip: 07962
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 201-455-2281

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: OHK000107847
Trans2 State ID: Not reported
Generator Ship Date: 2009-01-29
Trans1 Recv Date: 2009-01-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-01-30
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000002147
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: PAD987270725
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TP - Tanks, portable
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 005116116JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H039

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: PAD980707442
Trans2 State ID: Not reported
Generator Ship Date: 2009-01-21
Trans1 Recv Date: 2009-01-21
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-01-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000002147

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: PAD987270725
Waste Code: Not reported
Quantity: 2427.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TP - Tanks, portable
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 005116015JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H039

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: OHR000107847
Trans2 State ID: Not reported
Generator Ship Date: 2009-06-24
Trans1 Recv Date: 2009-06-24
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-06-25
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000002147
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: PAD987270725
Waste Code: Not reported
Quantity: 2190.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TP - Tanks, portable
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 005116118JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H039

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: OHK000107847
Trans2 State ID: Not reported
Generator Ship Date: 2009-01-29
Trans1 Recv Date: 2009-01-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-01-30
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000002147
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: PAD987270725
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TP - Tanks, portable
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 005116116JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H039

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: PAD980707442
Trans2 State ID: Not reported
Generator Ship Date: 2009-01-21
Trans1 Recv Date: 2009-01-21
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-01-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000002147
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: PAD987270725
Waste Code: Not reported
Quantity: 2427.0
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Number of Containers: 1.0
Container Type: TP - Tanks, portable
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 005116015JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H039

NY Spills:

Site ID: 285073
Facility Addr2: Not reported
Facility ID: 0175010
Spill Number: 0175010
Facility Type: ER
SWIS: 1502
Investigator: lcross
Referred To: Not reported
Spill Date: 3/22/2001
Reported to Dept: 3/22/2001
CID: 30
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not Closed
Remediation Phase: 1
Date Entered In Computer: 4/3/2001
Spill Record Last Update: 3/22/2006
Spiller Name: LANA DOLE
Spiller Company: BUFFALO COLOR CORPORATION
Spiller Address: 100 LEE STREET
Spiller City,St,Zip: BUFFALO, NY 14240-
Spiller Company: 001
Contact Name: LANA DOLE
Contact Phone: (716) 278-7686
DEC Region: 9
DER Facility ID: 231175
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TED" 03/22/01: TED RECEIVED MESSAGE FROM STAN RADON THAT HE HAD BEEN
INFORMED BY LANA DOLE AT BUFFALO COLOR CORP. THAT PETROLEUM PRODUCT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

HAD BEEN FOUND IN ONE OF BUFFALO COLOR'S MONITORING WELLS (MW's) DURING A ROUTINE INSPECTION. LANA SAID MW LOCATED NEAR EXXON MOBIL TERMINAL. SHE THINKS PRODUCT MIGHT BE DIESEL. 03/23/01: TED TELECON W/ LANA DOLE, SHE WILL FAX OVER PORTION OF SITE MAP SHOWING LOCATION OF MW IN WHICH PRODUCT HAD BEEN FOUND. LANA SAID WELL WILL BE SAMPLED TODAY FOR INHOUSE ANALYSIS OF PRODUCT. SHE SAID OIL HAD BEEN FOUND IN SAME MW (R-14) IN 1996. A SAMPLE HAD BEEN TAKEN AT THAT TIME AND ANALYSED BY BUFFALO COLOR (METHOD UNKNOWN) INDICATING PETROLEUM. 03/30/01: TED RECEIVED CLOSED MOSF FILE FOR BUFFALO COLOR. 1990 SPCC PLAN LISTED DIESEL FUEL STORAGE TANKS AND PORTABLE TANKS (CONTENTS NOT LISTED) IN AREA OF WELL R-14 (AREA E). ALSO NOTED LOCATION OF FORMER ABOVEGROUND TANK V-1 (CONTENTS UNKNOWN) IN AREA E. SENT MEMO TO PJB RECOMMENDING RCRA FOLLOWUP GIVEN POTENTIAL ON-SITE SOURCE AND RCRA'S PRIOR INVOLVEMENT AT SITE. SPOKE W/ LANA DOLE, SHE SAID SHE HAD RECEIVED SAMPLE RESULTS FOR R-14 WHICH INDICATED PETROLEUM. TOLD LANA ABOUT POTENTIAL ON-SITE SOURCE, BASED ON REVIEW OF MOSF FILE, AND HAVE RECOMMENDED FURTHER INVESTIGATION. UNSURE WHO AT DEC WILL TAKE LEAD AT THIS TIME. FAXED LANA COVER PAGE OF 1990 SPCC PLAN AND PAGE 13 OF PLAN LISTING PETROLEUM STORAGE IN AREA E. 04/02/01: TED TELECON W/ LANA DOLE, SHE SAID DIESEL STORAGE WAS BY BLDG. #312. SHE ALSO HAD DISCUSSION W/ LONG TIME EMPLOYEES WHO SAID THERE HADN'T BEEN ANY DIESEL STORAGE NEAR R-14 THEREFORE THEY THINK PETRO NOT FROM BUFFALO COLOR. 04/03/01: MEMO FROM FRANK SHATTUCK, RCRA PROGRAM WILL TAKE LEAD ON SPILL, STAN RADON WILL FOLLOWUP. 04/04/01: TED GAVE COPY OF BUFFALO COLOR SPILL REPORT # 0175010 WITH HISTORY NOTES TO STAN. 03/22/06: Spill transferred to Linda Ross for followup under Superfund Program.

Remarks: PETROLEUM WAS FOUND IN ONE OF BUFFALO COLOR'S MONITORING WELLS DURING A ROUTINE SITE INSPECTION. NOTIFIER THINKS IT IS DIESEL.

Material:

Site ID: 285073
Operable Unit ID: 852653
Operable Unit: 01
Material ID: 524336
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Groundwater
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

NY Hist Spills:

Region of Spill: 9
Spill Number: 0175010
Investigator: TED
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 03/22/2001 12:00
Reported to Dept Date/Time: 03/22/01 12:00
SWIS: 14
Spiller Name: BUFFALO COLOR CORPORATION
Spiller Contact: LANA DOLE
Spiller Phone: (716) 827-4525
Spiller Contact: LANA DOLE
Spiller Phone: (716) 278-7686
Spiller Address: 100 LEE STREET
Spiller City,St,Zip: BUFFALO, NY 14240-
Spill Cause: Unknown
Reported to Dept: Groundwater
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/03/01
Date Spill Entered In Computer Data File: 15:26
Update Date: 04/04/01
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR CORPORATION (Continued)

1001010979

Unkonwn Quantity Recovered: False

Material: UNKNOWN PETROLEUM

Class Type: UNKNOWN PETROLEUM

Times Material Entry In File: 16414

CAS Number: Not reported

Last Date: 19940929

DEC Remarks: 03/22/01: TED RECEIVED MESSAGE FROM STAN RADON THAT HE HAD BEEN INFORMED BY LANA DOLE AT BUFFALO COLOR CORP. THAT PETROLEUM PRODUCT HAD BEEN FOUND IN ONE OF BUFFALO COLOR S MONITORING WELLS MW s) DURING A ROUTINE INSPECTION. LANA SAID MW LOCATED NEAR EXXON MOBIL TERMINAL. SHE THINKS PRODUCT MIGHT BE DIESEL. 03/23/01: TED TELECON W/ LANA DOLE, SHE WILL FAX OVER PORTION OF SITE MAP SHOWING LOCATION OF MW IN WHICH PRODUCT HAD BEEN FOUND. LANA SAID WELL WILL BE SAMPLED TODAY FOR INHOUSE ANALYSIS OF PRODUCT. SHE SAID OIL HAD BEEN FOUND IN SAME MW R-14) IN 1996. A SAMPLE HAD BEEN TAKEN AT THAT TIME AND ANALYSED BY BUFFALO COLOR METHOD UNKNOWN) INDICATING PETROLEUM. 03/30/01: TED RECEIVED CLOSED MOSF FILE FOR BUFFALO COLOR. 1990 SPCC PLAN LISTED DIESEL FUEL STORAGE TANKS AND PORTABLE TANKS CONTENTS NOT LISTED) IN AREA OF WELL R-14 AREA E). ALSO NOTED LOCATION OF FORMER ABOVEGROUND TANK V-1 CONTENTS UNKNOWN) IN AREA E. SENT MEMO TO PJB RECOMMENDING RCRA FOLLOWUP GIVEN POTENTIAL ON-SITE SOURCE AND RCRA S PRIOR INVOLVEMENT AT SITE. SPOKE W/ LANA DOLE, SHE SAID SHE HAD RECEIVED SAMPLE RESULTS FOR R-14 WHICH INDICATED PETROLEUM. TOLD LANA ABOUT POTENTIAL ON-SITE SOURCE, BASED ON REVIEW OF MOSF FILE, AND HAVE RECOMMENDED FURTHER INVESTIGATION. UNSURE WHO AT DEC WILL TAKE LEAD AT THIS TIME. FAXED LANA COVER PAGE OF 1990 SPCC PLAN AND PAGE 13 OF PLAN LISTING PETROLEUM STORAGE IN AREA E. 04/02/01: TED TELECON W/ LANA DOLE, SHE SAID DIESEL STORAGE WAS BY BLDG. 312. SHE ALSO HAD DISCUSSION W/ LONG TIME EMPLOYEES WHO SAID THERE HADN T BEEN ANY DIESEL STORAGE NEAR R-14 THEREFORE THEY THINK PETRO NOT FROM BUFFALO COLOR. 04/03/01: MEMO FROM FRANK SHATTUCK, RCRA PROGRAM WILL TAKE LEAD ON SPILL, STAN RADON WILL FOLLOWUP. 04/04/01: TED GAVE COPY OF BUFFALO COLOR SPILL REPORT 0175010 WITH HISTORY NOTES TO STAN. PETROLEUM WAS FOUND IN ONE OF BUFFALO COLOR S MONITORING WELLS DURING A ROUTINE SITE INSPECTION. NOTIFIER THINKS IT IS DIESEL.

Remark:

MOSF:

Facility ID: 9-1480

Program Type: MOSF

Dec Region: 9

Expiration Date: N/A

Tank Status: No Longer MOSF

UTMX: Not reported

UTMY: Not reported

CBS:

CBS Number: 9-000130

Program Type: CBS

Dec Region: 9

Expiration Date: 2005/06/20

Facility Status: Active

UTMX: 186002.24455999

UTMY: 4752971.2967999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AL152 BUFFALO COLOR
SSE 340 ELK ST
1/2-1 BUFFALO, NY 14210
0.729 mi.
3849 ft. Site 2 of 3 in cluster AL

Relative:
Lower

Actual:
587 ft.

RCRA-TSDF 1000227743
CORRACTS NYD080335052
RCRA-LQG
US ENG CONTROLS
US INST CONTROL
FINDS
RAATS
SHWS
MANIFEST
MANIFEST

RCRA-TSDF:

Date form received by agency: 01/01/2007
Facility name: BUFFALO COLOR CORPORATION
Facility address: LEE ST
 BUFFALO, NY 14210
EPA ID: NYD080335052
Contact: GORDON G BOLLES
Contact address: LEE ST
 BUFFALO, NY 14210
Contact country: US
Contact telephone: (716) 827-4525
Contact email: GBOLLES@BUFFALOCOLOR.COM
EPA Region: 02
Land type: Private
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste

TSD commencement date: Not reported
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: BUFFALO COLOR CORP
Owner/operator address: 1 GARRET MOUNTAIN PLZ
 OPERCITY, NJ 99999

Owner/operator country: US
Owner/operator telephone: (201) 881-1700
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BUFFALO COLOR CORPORATION
Owner/operator address: LEE ST
 BUFFALO, NY 14210

Owner/operator country: US
Owner/operator telephone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/01/1977
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: BUFFALO COLOR CORPORATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/06/2004
Facility name: BUFFALO COLOR CORPORATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/28/2002
Facility name: BUFFALO COLOR CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Facility name: BUFFALO COLOR CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 02/20/1998
Facility name: BUFFALO COLOR CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 02/27/1996
Facility name: BUFFALO COLOR CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 02/18/1994
Facility name: BUFFALO COLOR CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 04/24/1992
Facility name: BUFFALO COLOR CORPORATION
Site name: BUFFALO COLOR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Classification: Large Quantity Generator

Date form received by agency: 02/28/1992

Facility name: BUFFALO COLOR CORPORATION

Classification: Large Quantity Generator

Date form received by agency: 11/19/1980

Facility name: BUFFALO COLOR CORPORATION

Site name: BUFFALO COLOR

Classification: Not a generator, verified

Date form received by agency: 08/05/1980

Facility name: BUFFALO COLOR CORPORATION

Site name: BUFFALO COLOR

Classification: Large Quantity Generator

Date form received by agency: 12/31/1979

Facility name: BUFFALO COLOR CORPORATION

Site name: BUFFALO COLOR

Classification: Large Quantity Generator

Corrective Action Summary:

Event date: 06/01/1980

Event: CA772ID

Event date: 09/30/1983

Event: CA770GW

Event date: 09/30/1983

Event: CA770NG

Event date: 04/04/1986

Event: RFA Completed

Event date: 02/15/1987

Event: RFI Imposition

Event date: 09/30/1988

Event: CA772ID

Event date: 03/16/1992

Event: Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations.

Event date: 03/16/1992

Event: Stabilization Measures Evaluation

Event date: 03/27/1992

Event: CA Prioritization, Facility or area was assigned a high corrective action priority.

Event date: 05/20/1992

Event: RFA Determination Of Need For An RFI, RFI is Necessary;

Event date: 06/28/1993

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Event:	RFI Imposition
Event date:	02/10/1995
Event:	CA772EP
Event date:	07/05/1995
Event:	RFI Workplan Received
Event date:	09/15/1995
Event:	RFI Workplan Approved
Event date:	09/15/1995
Event:	RFI Workplan Approved
Event date:	02/08/1996
Event:	CA145
Event date:	03/21/1996
Event:	RFI Supplemental Implementation Begun
Event date:	11/27/1996
Event:	RFI Supplemental Information Received
Event date:	12/16/1996
Event:	RFI Supplemental Information Deemed Satisfactory
Event date:	01/21/1997
Event:	RFI Supplemental Information Received
Event date:	03/06/1997
Event:	RFI Supplemental Information Deemed Satisfactory
Event date:	11/13/1997
Event:	RFI Report Received
Event date:	03/04/1998
Event:	RFI Supplemental Information Requested By Agency
Event date:	06/30/1998
Event:	RFI Supplemental Information Received
Event date:	07/07/1998
Event:	RFI Supplemental Information Deemed Satisfactory
Event date:	12/24/1998
Event:	RFI Report Received
Event date:	12/24/1998
Event:	RFI Report Received
Event date:	12/24/1998
Event:	RFI Report Received
Event date:	03/19/1999
Event:	Stabilization Measures Implemented, Groundwater extraction and treatment (e.g., to achieve groundwater containment, to achieve MCL).

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Event date:	03/19/1999
Event:	RFI Approved
Event date:	03/19/1999
Event:	CMS Imposition
Event date:	05/17/1999
Event:	CMS Workplan Received
Event date:	07/06/1999
Event:	CMS Workplan Approved
Event date:	01/31/2000
Event:	CMS Report Received
Event date:	07/10/2000
Event:	CMS Approved
Event date:	09/30/2004
Event:	Current Human Exposures under Control, Yes, Current Human Exposures Under Control has been verified. Based on a review of information contained in the EI determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.
Event date:	03/25/2005
Event:	Date For Remedy Selection (CM Imposed)
Event date:	03/25/2005
Event:	CA770GW
Event date:	03/25/2005
Event:	Date For Public Notice On Proposed Remedy
Event date:	03/25/2005
Event:	Corrective Measures Design Approved
Event date:	05/10/2005
Event:	Date To Submit Remedy Design
Event date:	09/15/2005
Event:	Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

Facility Has Received Notices of Violations:

Regulation violated:	SR - 372.2(b)(3)
Area of violation:	Generators - Manifest

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Date violation determined: 12/05/2003
Date achieved compliance: 01/05/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/18/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.2(g)
Area of violation: Generators - General
Date violation determined: 12/30/2002
Date achieved compliance: 02/03/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/03/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 01/31/1995
Date achieved compliance: 06/26/1995
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 04/28/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 2700
Paid penalty amount: 2700

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 01/31/1995
Date achieved compliance: 06/26/1995
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 01/31/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 4500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 12/30/1991

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Date achieved compliance: 02/11/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/30/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 03/12/1991
Date achieved compliance: 03/12/1991
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 03/12/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 03/24/1987
Date achieved compliance: 11/20/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/26/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 08/20/1986
Date achieved compliance: 11/20/1987
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 08/20/1986
Date achieved compliance: 10/31/1986

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 08/20/1986
Date achieved compliance: 02/11/1992
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 07/08/1986
Date achieved compliance: 11/20/1987
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 02/18/1986
Date achieved compliance: 04/30/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/14/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 12/16/1985
Date achieved compliance: 10/31/1986
Violation lead agency: EPA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 12/16/1985
Date achieved compliance: 10/31/1986
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 12/16/1985
Date achieved compliance: 04/30/1986
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 10/21/1985
Date achieved compliance: 12/04/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/21/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 09/01/1985
Date achieved compliance: 03/12/1991
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Enforcement action date: 09/30/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 6000
Final penalty amount: 6000
Paid penalty amount: 6000

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 03/11/1985
Date achieved compliance: 07/30/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/27/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Application
Date violation determined: 01/16/1985
Date achieved compliance: 07/28/1986
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 06/27/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 6500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 12/18/1984
Date achieved compliance: 11/12/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 10/19/1984
Date achieved compliance: 12/04/1985
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 09/18/1984
Date achieved compliance: 11/19/1984
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/18/1984
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 07/18/1984
Date achieved compliance: 03/15/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/11/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 05/30/1984
Date achieved compliance: 03/13/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/16/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 11/17/1983
Date achieved compliance: 03/15/1985
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 09/08/1983
Date achieved compliance: 03/12/1991
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 02/07/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 3000
Paid penalty amount: 3000

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 09/08/1983
Date achieved compliance: 03/12/1991
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/30/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 6000
Paid penalty amount: 6000

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 09/08/1983
Date achieved compliance: 03/12/1991
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 03/07/1984
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 16000
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 09/08/1983
Date achieved compliance: 03/12/1991
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 02/07/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 3000
Paid penalty amount: 3000

Evaluation Action Summary:

Evaluation date: 12/15/2003
Evaluation: OPERATION AND MAINTENANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/05/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 01/05/2004
Evaluation lead agency: State

Evaluation date: 12/30/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 02/03/2003
Evaluation lead agency: State

Evaluation date: 12/13/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/30/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/26/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/06/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/04/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/27/1997
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/21/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 06/26/1995
Evaluation lead agency: State

Evaluation date: 11/21/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 06/26/1995
Evaluation lead agency: State

Evaluation date: 09/28/1993
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/09/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/19/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 02/11/1992
Evaluation lead agency: State

Evaluation date: 03/12/1991
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 03/12/1991
Evaluation lead agency: EPA

Evaluation date: 12/06/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/20/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/16/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Evaluation date: 03/25/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/22/1988
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/20/1988
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/10/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/25/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/24/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 11/20/1987
Evaluation lead agency: State

Evaluation date: 01/20/1987
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/15/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/31/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/20/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Date achieved compliance: 02/11/1992
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 08/20/1986
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 11/20/1987
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 08/20/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 10/31/1986
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 08/20/1986
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: TSD - General
Date achieved compliance: 02/11/1992
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 07/08/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 11/20/1987
Evaluation lead agency: State

Evaluation date: 05/09/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/18/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 04/30/1986
Evaluation lead agency: State

Evaluation date: 01/14/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/16/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Closure/Post-Closure
Date achieved compliance: 10/31/1986
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 12/16/1985
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 04/30/1986
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Evaluation date: 12/16/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Financial Requirements
Date achieved compliance: 10/31/1986
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 12/06/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/02/1985
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/21/1985
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD - Closure/Post-Closure
Date achieved compliance: 12/04/1985
Evaluation lead agency: State

Evaluation date: 09/01/1985
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 03/12/1991
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 06/26/1985
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 06/26/1985
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/20/1985
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/11/1985
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 07/30/1986
Evaluation lead agency: State

Evaluation date: 01/16/1985
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Permits - Application

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Date achieved compliance: 07/28/1986
Evaluation lead agency: EPA

Evaluation date: 12/18/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 11/12/1985
Evaluation lead agency: State

Evaluation date: 10/19/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD - Closure/Post-Closure
Date achieved compliance: 12/04/1985
Evaluation lead agency: State

Evaluation date: 09/18/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 11/19/1984
Evaluation lead agency: State

Evaluation date: 09/13/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 07/18/1984
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 03/15/1985
Evaluation lead agency: State

Evaluation date: 07/18/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/18/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/30/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 03/13/1985
Evaluation lead agency: State

Evaluation date: 05/21/1984
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Evaluation date: 12/27/1983
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 11/17/1983
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 03/15/1985
Evaluation lead agency: State

Evaluation date: 09/08/1983
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 03/12/1991
Evaluation lead agency: EPA Contractor/Grantee

Evaluation date: 09/08/1983
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 03/12/1991
Evaluation lead agency: EPA Contractor/Grantee

CORRACTS:

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 1/21/1997
Action: CA160 - RFI Supplemental Information Received
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 1/31/2000
Action: CA340 - CMS Report Received
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 2/10/1995
Action: CA772EP
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 2/15/1987
Action: CA100 - RFI Imposition
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/4/1998
Action: CA155 - RFI Supplemental Information Requested By Agency
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/6/1997
Action: CA170 - RFI Supplemental Information Deemed Satisfactory
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/16/1992
Action: CA225YE - Stabilization Measures Evaluation, This facility ,is amenable to stabilization activity based on the, status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/16/1992
Action: CA225 - Stabilization Measures Evaluation
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/19/1999
Action: CA200 - RFI Approved
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/19/1999
Action: CA600GW - Stabilization Measures Implemented, Groundwater extraction
and treatment
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/19/1999
Action: CA250 - CMS Imposition
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/21/1996
Action: CA180 - RFI Supplemental Implementation Begun
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/25/2005
Action: CA770GW
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/25/2005
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/25/2005
Action: CA380 - Date For Public Notice On Proposed Remedy
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/25/2005
Action: CA450 - Corrective Measures Design Approved
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 3/27/1992
Action: CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 4/4/1986
Action: CA050 - RFA Completed
NAICS Code(s): 325132 32511 325192

Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 5/10/2005
Action: CA410 - Date To Submit Remedy Design
NAICS Code(s): 325132 32511 325192

Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 5/17/1999
Action: CA260 - CMS Workplan Received
NAICS Code(s): 325132 32511 325192

Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 5/20/1992
Action: CA070YE - RFA Determination Of Need For An RFI, RFI is Necessary
NAICS Code(s): 325132 32511 325192

Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Area Name: SITEWIDE
Actual Date: 6/1/1980
Action: CA772ID
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 6/28/1993
Action: CA100 - RFI Imposition
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 6/30/1998
Action: CA160 - RFI Supplemental Information Received
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 7/5/1995
Action: CA110 - RFI Workplan Received
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 7/6/1999
Action: CA300 - CMS Workplan Approved
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 7/7/1998
Action: CA170 - RFI Supplemental Information Deemed Satisfactory
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 7/10/2000
Action: CA350 - CMS Approved
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/15/1995
Action: CA150 - RFI Workplan Approved
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/15/2005
Action: CA750YE - Migration of Contaminated Groundwater under Control, Yes,
Migration of Contaminated Groundwater Under Control has been verified
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/30/1983
Action: CA770NG
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/30/1983
Action: CA770GW
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: LAGOONS (1, 2, AND 3)
Actual Date: 9/30/1988
Action: CA772ID
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/30/2004
Action: CA725YE - Current Human Exposures Under Control, Yes, Current Human
Exposures Under Control has been verified
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 11/13/1997
Action: CA190 - RFI Report Received
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing

Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 11/27/1996

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Action: CA160 - RFI Supplemental Information Received
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 12/16/1996
Action: CA170 - RFI Supplemental Information Deemed Satisfactory
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD080335052
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 12/24/1998
Action: CA190 - RFI Report Received
NAICS Code(s): 325132 32511 325192
Synthetic Organic Dye and Pigment Manufacturing
Petrochemical Manufacturing
Cyclic Crude and Intermediate Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

US ENG CONTROLS:

EPA ID: NYD080335052
Site ID: Not reported
Name: BUFFALO COLOR CORPORATION
Address: LEE ST
BUFFALO, NY 14210

EPA Region: 2
County: ERIE
Event Code: CA770GW
Actual Date: 03/25/05

Action ID: Not reported
Action Name: Not reported
Action Completion date: Not reported
Planned Complet. date: Not reported
Operable Unit: Not reported
Contaminated Media : Not reported
Engineering Control: Not reported

Action ID: Not reported
Action Name: Not reported
Action Completion date: Not reported
Planned Complet. date: Not reported
Operable Unit: Not reported
Contaminated Media : Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Engineering Control: Not reported

US INST CONTROL:

EPA ID: NYD080335052
Site ID: Not reported
Name: BUFFALO COLOR CORPORATION
Action Name: Not reported
Address: LEE ST
BUFFALO, NY 14210
EPA Region: 2
County: ERIE
Event Code: CA772EP
Inst. Control: Not reported
Actual Date: 02/10/95
Comple. Date: Not reported
Operable Unit: Not reported
Contaminated Media : Not reported

EPA ID: NYD080335052
Site ID: Not reported
Name: BUFFALO COLOR CORPORATION
Action Name: Not reported
Address: LEE ST
BUFFALO, NY 14210
EPA Region: 2
County: ERIE
Event Code: CA772ID
Inst. Control: Not reported
Actual Date: 09/30/88
Comple. Date: Not reported
Operable Unit: Not reported
Contaminated Media : Not reported

FINDS:

Registry ID: 110000748610

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and at Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

SHWS:

Program: HW
Site Code: 56547
Classification: SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region: 9
Acres: 19.000
HW Code: 915012
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 10/23/2009 2:49:00 PM
Updated By: MLDOSTER
Site Description:

The site consists of a 19 acre parcel of land in Buffalo on a peninsula of the Buffalo River known as the "D" area. The "D" area is bounded by the Buffalo River, an active rail line, an abandoned Railroad Right-Of-Way and the Buffalo Color Plant site on the fourth side. The area was operated by Allied Chemical and is currently inactive. Contaminants on the site were from iron oxide lagoons which were used to dispose of iron oxide sludge wastes and a metal sludge weathering area which was used for the disposal of triphenylmethane dyes. Several other areas were contaminated with petroleum products and process chemicals from past operations. The area was originally owned and operated by Allied Chemical for the production of petroleum based detergents, dye intermediates, picric acid, and various other chemicals until 1974. The facility was sold to Buffalo Color in 1977. A Consent Agreement was signed in 1982. Buffalo Color razed all buildings on the site in 1984. A field investigation was completed which determined that the site posed a significant threat to the environment based on waste disposal and groundwater contamination. A Remedial Investigation/Feasibility Study (RI/FS) began in 1988. The FS was finalized in 1991. The Record of Decision (ROD), signed in 1991 selected a remedy consisting of containment of waste by a slurry wall and cap, extraction and treatment of groundwater, removal of contaminated sediments from the Buffalo River, and protection of its shoreline from erosion. Allied Signal signed a Remedial Design/Remedial Action (RD/RA) agreement in 1993. Remedial Design was completed in 1996. Remedial work began in 1996 and was completed in 1998. Final shore line planting was done in 1999. Long term monitoring is underway, and a study of river sediments is under review.

Env Problem: Contamination of groundwater and Buffalo River sediments by organic chemicals and metals had occurred. Surface and subsurface soils are also contaminated. Remedial efforts have partially isolated the contaminated materials from the river ecosystem.

Health Problem: Although access to the site is restricted, there is the potential for exposure through inhalation of contaminated dust and direct contact with contaminated surface water, sediments, and soil. The site is in an industrial/commercial area of Buffalo that is served by public water. Exposures via drinking water are not expected because public water serves the area. The remedial actions which include a cap, a slurry wall, and a groundwater collection and treatment system should eliminate the potential for human exposures.

Dump: False
Structure: False
Lagoon: True
Landfill: True
Pond: False
Disp Start: 1960

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Disp Term: 1975
Lat/Long: 42:51:37:0 / 78:50:49:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 11/18/1999 12:00:00 PM
Updated By: DJFARRAR
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: Allied Chemical
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: ALLIED CHEMICAL
Owner Address: P.O. BOX 7027, 100 LEE ST.
Owner Addr2: Not reported
Owner City,St,Zip: BUFFALO, NY 14210
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: Buffalo Color Corporation
Owner Address: 100 Lee Street / PO Box 7027
Owner Addr2: Not reported
Owner City,St,Zip: Buffalo, NY 14210
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: Not reported
Owner Company: Allied Chemical
Owner Address: 35 Lee Street
Owner Addr2: Not reported
Owner City,St,Zip: Buffalo, NY 14210
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: ALLIED CHEMICAL
Owner Address: 35 LEE ST.
Owner Addr2: Not reported
Owner City,St,Zip: BUFFALO, NY 14210
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: JOHN YENSAN
Owner Company: OSC ON BEHALF OF SOUTH BUFFALO DEVELOPMENT, LLC
Owner Address: 333 GANSON STREET
Owner Addr2: Not reported
Owner City,St,Zip: BUFFALO, NY 14203
Owner Country: United States of America
HW Code: 915012
Waste Type: METAL SLUDGES CONTAINING ORGANICS
Waste Quantity: UNKNOWN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Waste Code: Not reported
Crossref ID: NYD980507792
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 5/10/2001 4:31:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: REGTRANS
Crossref ID: C915230
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 5/8/2009 3:51:00 PM
Record Updated: 5/8/2009 3:51:00 PM
Updated By: DSSZYMAN

NY MANIFEST:

EPA ID: NYD080335052
Country: USA
Mailing Name: BUFFALO COLOR CORP
Mailing Contact: JAMES A GOUCK
Mailing Address: 100 LEE ST
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14210
Mailing Zip4: 2100
Mailing Country: USA
Mailing Phone: 716-827-4527

Document ID: NYA7583958
Manifest Status: Completed copy
Trans1 State ID: LZ5979NY
Trans2 State ID: Not reported
Generator Ship Date: 890327
Trans1 Recv Date: 890327
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890327
Part A Recv Date: 890330
Part B Recv Date: 890405
Generator EPA ID: NYD080335052
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: OHD981960123
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 03040
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 146
Waste Code: Not reported
Quantity: 00065
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA6139971
Manifest Status: Completed copy
Trans1 State ID: 10212P(NY
Trans2 State ID: Not reported
Generator Ship Date: 890922
Trans1 Recv Date: 890922
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890922
Part A Recv Date: 890928
Part B Recv Date: 890927
Generator EPA ID: NYD080335052
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: NYD043815703
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 02900
Units: P - Pounds
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00350
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00040
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA6139962
Manifest Status: Completed copy
Trans1 State ID: 10213D(NY
Trans2 State ID: Not reported
Generator Ship Date: 890801
Trans1 Recv Date: 890801
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890801
Part A Recv Date: 890807
Part B Recv Date: 890807
Generator EPA ID: NYD080335052
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: NYD000632372
Waste Code: D003 - NON-LISTED REACTIVE WASTES
Quantity: 00369
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MNA1532840
Manifest Status: Completed copy
Trans1 State ID: 6519
Trans2 State ID: Not reported
Generator Ship Date: 931209
Trans1 Recv Date: 931209
Trans2 Recv Date: Not reported
TSD Site Recv Date: 931216
Part A Recv Date: 931220
Part B Recv Date: 931228
Generator EPA ID: NYD080335052
Trans1 EPA ID: MND980791321
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

TSD ID: MND981190242
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 02052
Units: K - Kilograms (2.2 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 93
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAH5377560
Manifest Status: Completed copy
Trans1 State ID: 25816MASS
Trans2 State ID: Not reported
Generator Ship Date: 940316
Trans1 Recv Date: 940316
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940317
Part A Recv Date: 940401
Part B Recv Date: 940330
Generator EPA ID: NYD080335052
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSD ID: MAD000604447
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00700
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Document ID: NYB6742629
Manifest Status: Completed copy
Trans1 State ID: NY11206P
Trans2 State ID: Not reported
Generator Ship Date: 941026
Trans1 Recv Date: 941026
Trans2 Recv Date: Not reported
TSD Site Recv Date: 941027
Part A Recv Date: 941107
Part B Recv Date: 941114
Generator EPA ID: NYD080335052
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSD ID: OHD981093420
Waste Code: B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB
Quantity: 08176
Units: K - Kilograms (2.2 pounds)
Number of Containers: 002
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 04853
Units: K - Kilograms (2.2 pounds)
Number of Containers: 017
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00024
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAH5377570
Manifest Status: Completed copy
Trans1 State ID: 25816MASS
Trans2 State ID: Not reported
Generator Ship Date: 940316
Trans1 Recv Date: 940316
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

TSD Site Recv Date: 940317
Part A Recv Date: 940401
Part B Recv Date: 940330
Generator EPA ID: NYD080335052
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSDF ID: MAD000604447
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00450
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYG0822114
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: MOD095038998
Generator Ship Date: 03/12/1998
Trans1 Recv Date: 03/12/1998
Trans2 Recv Date: 03/19/1998
TSD Site Recv Date: 03/23/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: NCD000648451
Trans2 EPA ID: Not reported
TSDF ID: MA25818
Waste Code: D022 - CHLOROFORM 6.0 MG/L TCLP
Quantity: 00010
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYG3509775
Manifest Status: Not reported
Trans1 State ID: NYD049253719
Trans2 State ID: Not reported
Generator Ship Date: 11/11/2002
Trans1 Recv Date: 11/11/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/12/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: NYD049253719
Trans2 EPA ID: Not reported
TSDF ID: 8604B6NY
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00015
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 02
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8506377
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: Not reported
Generator Ship Date: 06/09/2003
Trans1 Recv Date: 06/09/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/10/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: KYD005009923
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

TSD ID: 1319B7NY
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 03400
Units: P - Pounds
Number of Containers: 002
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA8138961
Manifest Status: Completed copy
Trans1 State ID: OH50M981
Trans2 State ID: TT-42320(
Generator Ship Date: 890714
Trans1 Recv Date: 890714
Trans2 Recv Date: 890727
TSD Site Recv Date: 890728
Part A Recv Date: 890718
Part B Recv Date: 890807
Generator EPA ID: NYD080335052
Trans1 EPA ID: OHD981960123
Trans2 EPA ID: NYD980769947
TSD ID: OHD981960123
Waste Code: B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Quantity: 02310
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 150
Waste Code: Not reported
Quantity: 00075
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 060
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA8139357
Manifest Status: Completed copy
Trans1 State ID: 10250PNY
Trans2 State ID: Not reported
Generator Ship Date: 890829
Trans1 Recv Date: 890829
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890830
Part A Recv Date: 890908
Part B Recv Date: 890912
Generator EPA ID: NYD080335052
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: OHD981093420
Waste Code: B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB
Quantity: 04000
Units: P - Pounds
Number of Containers: 001
Container Type: TP - Tanks, portable
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 000
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA6139944
Manifest Status: Completed copy
Trans1 State ID: X74489B
Trans2 State ID: Not reported
Generator Ship Date: 890509
Trans1 Recv Date: 890509
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890509
Part A Recv Date: 890516
Part B Recv Date: 890512
Generator EPA ID: NYD080335052
Trans1 EPA ID: NYD980769947

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Trans2 EPA ID: Not reported
TSDF ID: NYD000632372
Waste Code: D003 - NON-LISTED REACTIVE WASTES
Quantity: 00510
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00001
Units: P - Pounds
Number of Containers: 001
Container Type: CY - Cylinders
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00001
Units: P - Pounds
Number of Containers: 001
Container Type: CY - Cylinders
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00001
Units: P - Pounds
Number of Containers: 001
Container Type: CY - Cylinders
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: PAE7159261
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: Not reported
Generator Ship Date: 03/02/1998
Trans1 Recv Date: 03/02/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/02/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: PAD000736942

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Trans2 EPA ID: Not reported
TSDF ID: PAAH0315
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 01500
Units: P - Pounds
Number of Containers: 001
Container Type: TP - Tanks, portable
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: PAE7159305
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: Not reported
Generator Ship Date: 06/15/1998
Trans1 Recv Date: 06/15/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/15/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: PAD000736942
Trans2 EPA ID: Not reported
TSDF ID: PAAH0315
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 01500
Units: P - Pounds
Number of Containers: 001
Container Type: TP - Tanks, portable
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Mgmt Method Type Code: Not reported

Document ID: MAK4949750
Manifest Status: Not reported
Trans1 State ID: MOD095038998
Trans2 State ID: SCD987574647
Generator Ship Date: 01/13/1999
Trans1 Recv Date: 01/01/1900
Trans2 Recv Date: 01/13/1999
TSD Site Recv Date: 01/22/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSDF ID: HQ80775OR
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAK4949760
Manifest Status: Not reported
Trans1 State ID: MOD095038998
Trans2 State ID: SCD987574647
Generator Ship Date: 01/13/1999
Trans1 Recv Date: 01/01/1900
Trans2 Recv Date: 01/13/1999
TSD Site Recv Date: 01/22/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSDF ID: HQ80775OR
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAM2710350
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: MOD095038998
Generator Ship Date: 09/20/1999
Trans1 Recv Date: 09/20/1999
Trans2 Recv Date: 09/22/1999
TSD Site Recv Date: 09/23/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSDF ID: MA38315
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00600
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00150
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAM2710360
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: MOD095038998
Generator Ship Date: 09/20/1999
Trans1 Recv Date: 09/20/1999
Trans2 Recv Date: 09/22/1999
TSD Site Recv Date: 09/23/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSD ID: MA38315
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 01200
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAM2764140
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: Not reported
Generator Ship Date: 05/20/1999
Trans1 Recv Date: 05/20/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/25/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080335052
Trans1 EPA ID: MAD000604447
Trans2 EPA ID: Not reported
TSD ID: MA38315
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00100
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00500
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

[Click this hyperlink](#) while viewing on your computer to access
431 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

Manifest Code: 000239799VES
EPA ID: NYD080335052
Date Shipped: 9/10/2008
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NYD980769947
Transporter 3 EPA ID: NJD054126164
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 9/10/2008
Date Trans2 Transported Waste: 9/19/2008
Date Trans3 Transported Waste: 9/24/2008
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 9/30/2008
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D004
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 8800
Unit: P
Hand Code: H141

Manifest Code: NJA5289692
EPA ID: NYD080335052
Date Shipped: 20060206
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060206
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060209
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04100621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5289771
EPA ID: NYD080335052
Date Shipped: 20060322
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060322
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060323
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04110621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5289769
EPA ID: NYD080335052
Date Shipped: 20060322
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060322
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060323
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04110621
Reference Manifest Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5226188
EPA ID: NYD080335052
Date Shipped: 20060206
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060206
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060209
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04040621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5289770
EPA ID: NYD080335052
Date Shipped: 20060322
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060322
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060323
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04110621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5289689
EPA ID: NYD080335052
Date Shipped: 20060206
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060206
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060209
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 03200621
Reference Manifest Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5289772
EPA ID: NYD080335052
Date Shipped: 20060322
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060322
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060323
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04110621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5289691
EPA ID: NYD080335052
Date Shipped: 20060206
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060206
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060209
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 03200621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5289768
EPA ID: NYD080335052
Date Shipped: 20060322
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060322
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060323
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: 04110621
Reference Manifest Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 000022629VES
EPA ID: NYD080335052
Date Shipped: 5/17/2007
TSDF EPA ID: NJD002385730
Transporter EPA ID: NYD980769947
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 5/17/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 5/18/2007
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D002
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 4314
Unit: G
Hand Code: H08

Manifest Code: 000022630VES
EPA ID: NYD080335052
Date Shipped: 5/17/2007
TSDF EPA ID: NJD002385730
Transporter EPA ID: NYD980769947
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 5/17/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 5/19/2007
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D002
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 3471
Unit: G
Hand Code: H08

Manifest Code: 000022327VES
EPA ID: NYD080335052
Date Shipped: 10/3/2007
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/3/2007
Date Trans2 Transported Waste: 10/12/2007
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 10/15/2007
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUFFALO COLOR (Continued)

1000227743

Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 000021734VES
EPA ID: NYD080335052
Date Shipped: 1/9/2007
TSDf EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: NJD054126164
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 1/9/2007
Date Trans2 Transported Waste: 1/15/2007
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 1/17/2007
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D002
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 800
Unit: P
Hand Code: H14

Waste Code: U012
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 300
Unit: P
Hand Code: H14

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AL153 **BUFFALO COLOR CORPORATION AREA E SITE**
SSE **85 LEE STREET**
1/2-1 **BUFFALO, NY 14210**
0.730 mi.
3855 ft. **Site 3 of 3 in cluster AL**

BROWNFIELDS **S109059139**
N/A

Relative:
Lower

BROWNFIELDS:

Program: BCP
Site Code: 394155

Actual:
587 ft.

Site Description: There had been continuous production of dyestuffs and organic chemicals at the facility for over 100 years. On July, 1, 1977 Buffalo Color Corporation (BCC) purchased certain assets from Allied Chemical (Honeywell), including the plant and the right to produce certain chemicals. In 1995, NYSDEC issued a Part 373 Post-Closure Permit to BCC. The permit required BCC to conduct a RCRA Facility Investigation for the site. Various remedial alternatives were examined in more detail in a Corrective Measures Study Report for BCC, dated January 2000. BCC filed for bankruptcy in 2003. In 2005 Honeywell entered into an Order on Consent to address various groundwater and other issues on the site. Honeywell completed a bulk chemical removal at the Site in 2007. Honeywell entered into an Order on Consent to perform an RI/FS in 2006. The RIFS was completed in 2008 and is the basis for a remedial work plan presented to the public in September 2008. This BCP application pertains to Buffalo Color Corporation Area E Site located at 85 Lee Street, Buffalo, Erie County. This site is approximately 16.4 acres in size. The land has been used for the production of dyestuff and organic chemicals for more than one hundred years. Dyestuff production began in the late 1800s and continued until 2003, when operations ceased. The future use for this site is for commercial and industrial. The known contaminants at this site are petroleum, chlorinated solvents, other VOCs, SVOCs and metals which are impacting the soil and groundwater. The Brownfield Cleanup Plan application has been approved as of April 27, 2009. The Remedial Work Plan was approved in May 2009. Design activities will continue into 2010.

Env Problem: Site indicator compound is chlorobenzene in both soil and groundwater. Very few other volatile organic compounds (VOCs) are found on site. However, metals such as mercury, lead and arsenic are found in the surface and subsurface soil. Semi-volatiles are found throughout Area E. The fill and upper portion of the native silt and clay soils is often stained. The shallow groundwater contains concentrations of chlorobenzene and aniline. Various metals, semi-volatiles and inorganic compounds are found in the groundwater. Separate phase LNAPL has been encountered floating on the groundwater, containing petroleum and other constituents. The deep groundwater is only slightly impacted.

Health Problem: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AM154 PVS CHEMICALS
SSE 55 LEE STREET
1/2-1 BUFFALO, NY 14210
0.755 mi.
3987 ft. Site 1 of 2 in cluster AM

Relative:
Lower

Actual:
587 ft.

RCRA-TSDF 1000106511
CORRACTS 14210PVSCH55
RCRA-LQG
TRIS
FINDS
RAATS
AST
HIST AST
NY Spills
NY Hist Spills

RCRA-TSDF:

Date form received by agency: 01/01/2007
Facility name: PVS CHEMICAL SOLUTIONS, INC.
Facility address: LEE STREET
BUFFALO, NY 14210
EPA ID: NYD980534390
Contact: ANNE M SCHILLACI
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: (716) 825-5762
Telephone ext.: 6231
Contact email: AMSCHILLACIL@VSCHEMICAS.CC
EPA Region: 02
Land type: Private
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste
TSD commencement date: Not reported
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: PVS CHEMICALS, INC.
Owner/operator address: HARPER AVE.
DETROIT, NY 48213
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1981
Owner/Op end date: Not reported
Owner/operator name: PVS CHEMICALS, SOLUTIONS
Owner/operator address: Not reported
Not reported
Owner/operator country: US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1981
Owner/Op end date: Not reported

Owner/operator name: PVS CHEMICALS INC
Owner/operator address: 11001 HARPER AVE
DETROIT, MI 48213

Owner/operator country: US
Owner/operator telephone: (313) 921-1200
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1981
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Waste type: Thermostats
Accumulated waste on-site: No
Generated waste on-site: No

Historical Generators:

Date form received by agency: 04/07/2006
Facility name: PVS CHEMICAL SOLUTIONS, INC.
Classification: Large Quantity Generator

Date form received by agency: 04/06/2006
Facility name: PVS CHEMICAL SOLUTIONS, INC.
Classification: Large Quantity Generator

Date form received by agency: 04/06/1996
Facility name: PVS CHEMICAL SOLUTIONS, INC.
Site name: P V S CHEMICAL INC NEW YORK
Classification: Not a generator, verified

Date form received by agency: 02/27/1992
Facility name: PVS CHEMICAL SOLUTIONS, INC.
Site name: PVS CHEMICALS INC (NY)
Classification: Small Quantity Generator

Date form received by agency: 03/01/1990
Facility name: PVS CHEMICAL SOLUTIONS, INC.
Site name: PVS CHEMICALS INC. (NY)
Classification: Large Quantity Generator

Date form received by agency: 09/19/1983
Facility name: PVS CHEMICAL SOLUTIONS, INC.
Site name: P V S CHEMICAL INC NEW YORK
Classification: Not a generator, verified

Date form received by agency: 01/14/1982
Facility name: PVS CHEMICAL SOLUTIONS, INC.
Site name: P V S CHEMICAL INC NEW YORK
Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2007

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSLEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

	WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs):	1000
Waste code:	D007
Waste name:	CHROMIUM
Amount (Lbs):	55940
Waste code:	D008
Waste name:	LEAD
Amount (Lbs):	600
Waste code:	D035
Waste name:	METHYL ETHYL KETONE
Amount (Lbs):	1000
Waste code:	F005
Waste name:	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs):	1000
Waste code:	U159
Waste name:	2-BUTANONE (I,T)
Amount (Lbs):	1000

Corrective Action Summary:

Event date:	09/30/1987
Event:	RFA Completed
Event date:	11/01/1991
Event:	CA Prioritization, Facility or area was assigned a high corrective action priority.
Event date:	01/13/2004
Event:	CA Prioritization, Facility or area was assigned a medium corrective action priority.

Facility Has Received Notices of Violations:

Regulation violated:	Not reported
Area of violation:	TSD - General
Date violation determined:	03/16/1998
Date achieved compliance:	05/06/1998
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	03/16/1998
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 04/16/1992
Date achieved compliance: 04/18/2002
Violation lead agency: State
Enforcement action: REFERRAL TO ATTORNEY GENERAL
Enforcement action date: 06/01/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 01/02/1992
Date achieved compliance: 04/18/2002
Violation lead agency: State
Enforcement action: REFERRAL TO ATTORNEY GENERAL
Enforcement action date: 06/01/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 10/17/1991
Date achieved compliance: 11/26/1991
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 11/30/1990
Date achieved compliance: 11/26/1991
Violation lead agency: State
Enforcement action: STATE TO EPA ADMINISTRATIVE REFERRAL
Enforcement action date: 11/30/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 10/15/1987
Date achieved compliance: 11/26/1991
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 07/03/1986
Date achieved compliance: 10/21/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/03/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Ground-Water Monitoring
Date violation determined: 07/03/1986
Date achieved compliance: 10/21/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/03/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 06/10/1986
Date achieved compliance: 10/21/1986
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 01/15/2008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/02/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/21/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/08/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/28/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/10/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/11/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 05/06/1998
Evaluation lead agency: State

Evaluation date: 10/08/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/15/1995
Evaluation: OPERATION AND MAINTENANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/17/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Evaluation lead agency: State

Evaluation date: 09/25/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/16/1992
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 04/18/2002
Evaluation lead agency: State

Evaluation date: 12/31/1991
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 04/18/2002
Evaluation lead agency: State

Evaluation date: 12/05/1991
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 04/18/2002
Evaluation lead agency: State

Evaluation date: 10/17/1991
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 11/26/1991
Evaluation lead agency: State

Evaluation date: 09/19/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/30/1990
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 11/26/1991
Evaluation lead agency: State

Evaluation date: 09/21/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/15/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/16/1988

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/15/1987
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 11/26/1991
Evaluation lead agency: State

Evaluation date: 09/17/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/23/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/03/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD - General
Date achieved compliance: 10/21/1986
Evaluation lead agency: State

Evaluation date: 07/03/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: TSD IS-Ground-Water Monitoring
Date achieved compliance: 10/21/1986
Evaluation lead agency: State

Evaluation date: 06/11/1986
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/10/1986
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: TSD - General
Date achieved compliance: 10/21/1986
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 06/10/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 10/21/1986
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 06/10/1986
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: TSD - General
Date achieved compliance: 10/21/1986

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 12/06/1985

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported

Date achieved compliance: Not reported

Evaluation lead agency: EPA

Evaluation date: 08/26/1985

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported

Date achieved compliance: Not reported

Evaluation lead agency: State

Evaluation date: 09/21/1984

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported

Date achieved compliance: Not reported

Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 08/15/1984

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported

Date achieved compliance: Not reported

Evaluation lead agency: State

Evaluation date: 05/11/1984

Evaluation: FINANCIAL RECORD REVIEW

Area of violation: Not reported

Date achieved compliance: Not reported

Evaluation lead agency: EPA

Evaluation date: 01/19/1984

Evaluation: FINANCIAL RECORD REVIEW

Area of violation: Not reported

Date achieved compliance: Not reported

Evaluation lead agency: EPA

Evaluation date: 11/17/1983

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported

Date achieved compliance: Not reported

Evaluation lead agency: EPA

Evaluation date: 05/16/1982

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported

Date achieved compliance: Not reported

Evaluation lead agency: EPA

CORRACTS:

EPA ID: NYD980534390

EPA Region: 02

Area Name: SITEWIDE

Actual Date: 1/13/2004

Action: CA075ME - CA Prioritization, Facility or area was assigned a medium

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

corrective action priority
NAICS Code(s): 325188
All Other Basic Inorganic Chemical Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD980534390
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/30/1987
Action: CA050 - RFA Completed
NAICS Code(s): 325188
All Other Basic Inorganic Chemical Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD980534390
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 11/1/1991
Action: CA075HI - CA Prioritization, Facility or area was assigned a high
corrective action priority
NAICS Code(s): 325188
All Other Basic Inorganic Chemical Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

FINDS:

Registry ID: 110000326996

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

transported off-site.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and at Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

US EPA Risk Management Plan (RMP) database stores the risk management plans reported by companies that handle, manufacture, use, or store certain flammable or toxic substances, as required under section 112(r) of the Clean Air Act (CAA).

AST:

Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-439924
Program Type:	PBS
UTM X:	186051.92939999999
UTM Y:	4752973.52996999996
Expiration Date:	2013/06/28

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Tank Number: 1
Tank Id: 167638
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 1/1/1973
Capacity Gallons: 50000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Trade Sec: False
Modified By: LDGOMEZ
Last Modified: 4/11/2008

UST_PBS_BSAFFIL:

Site Id: 54315
Program Number: 9-439924
Facility Type: Owner
Affiliation Type: 01
Affiliation Subtype: E
Company Name: PVS CHEMICALS, INC. (NY)
Contact Type: PLANT MANAGER
Contact Name: CHRIS CANCELLA
Address1: 55 LEE STREET
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14210
Country Code: 001
Phone: (716) 825-5762
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 4/11/2008

Site Id: 54315
Program Number: 9-439924
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: PVS CHEMICALS, INC. (NY)
Contact Type: Not reported
Contact Name: CHRIS CANCELLA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 825-5762
Phone Ext: Not reported
Email: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 54315
Program Number: 9-439924
Facility Type: Mail Contact
Affiliation Type: 07
Affiliation Subtype: NNN
Company Name: PVS CHEMICALS, INC. (NY)
Contact Type: PLANT MANAGER
Contact Name: CHRIS CANCELLA
Address1: 55 LEE STREET
Address2: Not reported
City: BUFFALO
State: NY
Zip Code: 14210
Country Code: 001
Phone: (716) 825-5762
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 4/11/2008

Site Id: 54315
Program Number: 9-439924
Facility Type: On-Site Operator
Affiliation Type: 04
Affiliation Subtype: NNN
Company Name: PVS CHEMICALS, INC. (NY)
Contact Type: Not reported
Contact Name: PVS CHEMICALS, INC. (NY)
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 825-5762
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: LDGOMEZ
Date Last Modified: 4/11/2008

UST_AST_PBS_BSEQUIP:

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Equipment: G05
Code Name: Synthetic Liner
Type: Tank Secondary Containment

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: H00
Code Name: None
Type: Tank Leak Detection

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: J02
Code Name: Suction
Type: Dispenser

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: B01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: E04
Code Name: Double-Walled (Underground)
Type: Piping Secondary Containment

Site Id: 54315
Tank Id Number: 167638
Tank Number: 1
Equipment: F05
Code Name: Jacketed
Type: Pipe External Protection

HIST AST:

PBS Number: 9-439924
SWIS Code: 1402
Operator: PVS CHEMICALS,INC. (NY)
Facility Phone: (716) 825-5762
Facility Addr2: Not reported
Facility Type: MANUFACTURING
Emergency: CHRIS CANCELLA
Emergency Tel: (716) 825-5762
Old PBSNO: Not reported
Date Inspected: 19900706
Inspector: JES
Result of Inspection: Not reported
Owner Name: PVS CHEMICALS, INC. (NY)
Owner Address: 55 LEE STREET
Owner City,St,Zip: BUFFALO, NY 14210
Federal ID: Not reported
Owner Tel: (716) 825-5762
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: CHRIS CANCELLA
Mailing Name: PVS CHEMICALS, INC. (NY)
Mailing Address: 55 LEE STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: BUFFALO, NY 14210
Mailing Telephone: (716) 825-5762

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 04/14/1998
Expiration: 06/28/2003
Renew Flag: False
Renew Date: 19930301
Total Capacity: 50000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: 9-000143
Town or City: BUFFALO (C)
County Code: 14
Town or City Code: 02
Region: 9
Tank ID: 1
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19730101
Capacity (Gal): 50000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 01
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 05
Tank Containment: 6A
Leak Detection: 00
Overfill Protection: 24
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

NY Spills:

Site ID: 100786
Facility Addr2: Not reported
Facility ID: 0007116
Spill Number: 0007116
Facility Type: ER
SWIS: 1502
Investigator: JFOTTO
Referred To: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Spill Date: 9/16/2000
Reported to Dept: 9/16/2000
CID: 30
Spill Cause: Equipment Failure
Water Affected: BUFFALO RIVER
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. No DEC Response. No corrective action required.
Spill Closed Dt: 9/18/2000
Remediation Phase: 0
Date Entered In Computer: 9/16/2000
Spill Record Last Update: 11/1/2000
Spiller Name: ANNE SCHILLACI
Spiller Company: PVS CHEMICAL
Spiller Address: 55 LEE STREET
Spiller City,St,Zip: BUFFALO, NY 14210-
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 89448
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JFO" 09/18/00: JFO NOTE TO FILE, THIS SPILL WAS REFERRED TO THE DIV. OF WATER BY THE DUTY OFFICER JERRY PALUMBO. SPILLS WAS NOT NOTIFIED OF THE INCIDENT, NO RESPONSE, NO ACTION NOW POSSIBLE BY SPILLS. CLOSED
Not reported
Remarks: equipment failure caused a release of acid into a non contact cooling water, which will eventually spill into the river
Material:
Site ID: 100786
Operable Unit ID: 829899
Operable Unit: 01
Material ID: 548217
Material Code: 0039A
Material Name: SULFURIC ACID
Case No.: 07664939
Material FA: Hazardous Material
Quantity: 88
Units: Pounds
Recovered: No
Resource Affected: Surface Water
Oxygenate: False
Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 371188
Facility Addr2: Not reported
Facility ID: 0651196
Spill Number: 0651196
Facility Type: ER
SWIS: 1502
Investigator: RMCROSSE
Referred To: Not reported
Spill Date: 9/1/2006
Reported to Dept: 9/29/2006
CID: 30
Spill Cause: Deliberate
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 9/29/2006
Remediation Phase: 0
Date Entered In Computer: 9/29/2006
Spill Record Last Update: 9/29/2006
Spiller Name: Not reported
Spiller Company: PVS CHEMICAL
Spiller Address: 55 LEE STREET
Spiller City,St,Zip: BUFFALO, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 89448
DEC Memo: 09/29/06 RMC/FILE. FAXED TO BUFFALO SEWER, FORWARDED TO RECRA, DOW, AND LE FOR FOLLOW UP. CLOSE OUT AS A SPILLS ISSUE.
Remarks: anonymous tip that chemical company has been and is currently dumping sulfuric acid directly to the sanitary sewers. claims ph is less than 1 and sewer smokes when dumping.

Material:
Site ID: 371188
Operable Unit ID: 1128959
Operable Unit: 01
Material ID: 2118609
Material Code: 2685A
Material Name: Sulfuric acid
Case No.: 08014957
Material FA: Hazardous Material
Quantity: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Units: Gallons
Recovered: Not reported
Resource Affected: Sewer
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

[Click this hyperlink](#) while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill: 9
Spill Number: 9109272
Investigator: MF
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/30/1991 18:00
Reported to Dept Date/Time: 11/30/91 20:22
SWIS: 14
Spiller Name: PVS CHEMICAL
Spiller Contact: Not reported
Spiller Phone: (716) 824-0499
Spiller Address: 55 LEE STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spill Cause: Equipment Failure
Reported to Dept: Air
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: 12/02/91
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 12/02/91
Corrective Action Plan Submitted: / /

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/02/91
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/19/91
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Not reported
Quantity Spilled: Not reported
Unkonwn Quantity Spilled: Not reported
Units: Not reported
Quantity Recovered: Not reported
Unkonwn Quantity Recovered: Not reported
Material: Not reported
Class Type: Not reported
Times Material Entry In File: Not reported
CAS Number: Not reported
Last Date: Not reported

DEC Remarks: 12/02/91: MF 12/02/91 RECEIVED SPILL FROM DUTY OFFICER. REFERED SPILL TO AIR
DIVISION. NO FURTHER ACTION NECESSARY. 09/29/95: This is additional
information about material spilled from the translation of the old spill file:
AIR VIOLATION.

Remark: OPACITY READING EXCEEDED DUE TO POWER FAILURE. SHOULD RETURN TO NORMAL.

Region of Spill: 9
Spill Number: 8806982
Investigator: CAF
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/21/1988 11:00
Reported to Dept Date/Time: 11/21/88 11:10
SWIS: 14
Spiller Name: PVS
Spiller Contact: Not reported
Spiller Phone: (716) 825-5762
Spiller Address: 55LEE STREET
Spiller City,St,Zip: BUFFALO, NY 14210
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: 11/29/88
Cleanup Meets Std: True
Last Inspection: 11/22/88

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 11/29/88
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/22/88
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/13/88
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 50
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: SULFURIC ACID
Class Type: SULFURIC ACID
Times Material Entry In File: 0
CAS Number: 07664939
Last Date: Not reported

DEC Remarks: 11/21/88: CAF SITE VISIT WAS SHOWN CONTAINMENT EFFORTS,CLEAN UP TO FOLLOW.
11/22/88: CAF SITE VISIT REASONABLE CLEAN UP EFFORT MADE,NO FUTHER ACTION
CONTEMPLATED.

Remark: OLEUM SPILLED OUT OF TANK DUE TO POWER OUTAGE,SODA ASH USED TO NEUTRALIZE
SPILLED ACID.

Region of Spill: 9
Spill Number: 9510124
Investigator: KAH
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/13/1995 22:00
Reported to Dept Date/Time: 11/13/95 23:52
SWIS: 14
Spiller Name: PRAXAIR
Spiller Contact: KEN HALGASH
Spiller Phone: (716) 879-7173
Spiller Contact: KEN HALGASH
Spiller Phone: (716) 879-7173
Spiller Address: PO BOX 44

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Spiller City,St,Zip: TONAWANDA, NY 14151-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Possible release with minimal potential for fire or hazard or Known
release with no damage. DEC Response. Willing Responsible Party.
Corrective action taken.
Spill Closed Dt: 11/14/95
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/13/95
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/14/95
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 1
Unkonwn Quantity Recovered: False
Material: HYDRAULIC OIL
Class Type: HYDRAULIC OIL
Times Material Entry In File: 1846
CAS Number: Not reported
Last Date: 19940728

DEC Remarks: 11/14/95 - KAH RECEIVED AFTER HOURS REPORT FROM RICH SUINICH, DUTY OFFICER.
MINOR SPILLAGE OF APPROXIMATELY 1 GAL. OF HYDRAULIC OIL. SPILL CLEANED UP BY
RP. R.S. GAVE COPY OF REPORT TO TO BRUCE WAGER, DIVISION OF WATER SPDES
PERMITTED FACILITY) FOR FOLLOW-UP. NO FURTHER ACTION BY SPILLS NECESSARY.

Remark: HYDRALIC SYSTEM ON TANKER LEAKED ABOUT 1 GALLON ON ASPHALT AREA WAS CLEANED UP
USING A SPILL KIT NO NEED FOR DEC TO FOLLOW UP UNLESS THEY WOULD LIKE THEY CAN
CALL IN AM

Region of Spill: 9
Spill Number: 9410426
Investigator: FG
Caller Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/04/1994 16:00
Reported to Dept Date/Time: 11/04/94 16:58
SWIS: 14
Spiller Name: PVS CHEMICAL
Spiller Contact: Not reported
Spiller Phone: (716) 825-5762
Spiller Address: 55 LEE STREET
Spiller City,St,Zip: BUFFALO, NY
Spill Cause: Equipment Failure
Reported to Dept: Surface Water
Water Affected: BUFFALO RIVER
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: 11/07/94
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt: 11/07/94
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/07/94
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/08/99
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 10
Unkonwn Quantity Spilled: False
Units: Pounds
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: SULFURIC ACID
Class Type: SULFURIC ACID
Times Material Entry In File: 0
CAS Number: 07664939
Last Date: Not reported

DEC Remarks: 11/07/94: COPY OF SPILL REPORT TO DOW 11/7/94-RNL. NO RESPONSE NEC. SITE CAN BE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Remark: CLOSED.
LEAK IN PIPELINE, PH@3.1 ENTERING RIVER. AIR FLUE LEAK ALLOWED ACID TO LEAK OUT.

Region of Spill: 9
Spill Number: 0007116
Investigator: JFO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 09/16/2000 02:30
Reported to Dept Date/Time: 09/16/00 09:38
SWIS: 14
Spiller Name: PVS CHEMICAL
Spiller Contact: ANNE SCHILLACI
Spiller Phone: (716) 825-5762
Spiller Phone: () -
Spiller Address: 55 LEE STREET
Spiller City,St,Zip: BUFFALO, NY 14210-
Spill Cause: Equipment Failure
Reported to Dept: Surface Water
Water Affected: BUFFALO RIVER
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. No DEC
Response. No corrective action required.
Spill Closed Dt: 09/18/00
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 09/16/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/01/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 88
Unkonwn Quantity Spilled: False
Units: Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PVS CHEMICALS (Continued)

1000106511

Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: SULFURIC ACID
Class Type: SULFURIC ACID
Times Material Entry In File: 0
CAS Number: 07664939
Last Date: Not reported
DEC Remarks: 09/18/00: JFO NOTE TO FILE, THIS SPILL WAS REFERRED TO THE DIV. OF WATER BY THE DUTY OFFICER JERRY PALUMBO. SPILLS WAS NOT NOTIFIED OF THE INCIDENT, NO RESPONSE, NO ACTION NOW POSSIBLE BY SPILLS. CLOSED
Remark: equipment failure caused a release of acid into a non contact cooling water, which will eventually spill into the river

AM155
SSE
1/2-1
0.776 mi.
4100 ft.

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV
55 LEE STREET
BUFFALO, NY 14210

Site 2 of 2 in cluster AM

CERC-NFRAP 1000248674
CORRACTS NYD001863372
RCRA-NonGen
FINDS
RAATS
MANIFEST

Relative:
Lower

CERC-NFRAP:
Site ID: 0201327
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP

Actual:
588 ft.

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV
Alias Address: Not reported
ERIE, NY

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY
Date Started: Not reported
Date Completed: 06/01/1981
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: 09/19/1986
Date Completed: 09/29/1986
Priority Level: NFRAP: No further Remedial Action planned

Action: ARCHIVE SITE
Date Started: Not reported
Date Completed: 11/07/1989
Priority Level: Not reported

Action: SITE INSPECTION
Date Started: Not reported
Date Completed: 11/07/1989
Priority Level: NFRAP: No further Remedial Action planned

CORRACTS:

EPA ID: NYD001863372
EPA Region: 02

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Area Name: SITEWIDE
Actual Date: 9/29/1996
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 325192 325188 32511
Cyclic Crude and Intermediate Manufacturing
All Other Basic Inorganic Chemical Manufacturing
Petrochemical Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-NonGen:

Date form received by agency: 01/01/2007
Facility name: ALLIED CHEMICAL CORP-BUFFALO CHEM
Facility address: 35 LEE ST
BUFFALO, NY 142102109
EPA ID: NYD001863372
Mailing address: PHILADELPHIA PIKE
MARCUS HOOK, NY 19061
Contact: Not reported
Contact address: PHILADELPHIA PIKE
MARCUS HOOK, NY 19061
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ALLIED CHEMICAL CORP
Owner/operator address: 35 LEE ST
BUFFALO, NY 14210
Owner/operator country: US
Owner/operator telephone: (716) 824-8424
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ALLIED CHEMICAL CORP
Owner/operator address: 35 LEE STREET
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: (716) 824-8424
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: ALLIED CHEMICAL CORP-BUFFALO CHEM
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: ALLIED CHEMICAL CORP-BUFFALO CHEM
Classification: Not a generator, verified

Date form received by agency: 11/19/1980
Facility name: ALLIED CHEMICAL CORP-BUFFALO CHEM
Classification: Not a generator, verified

Date form received by agency: 08/11/1980
Facility name: ALLIED CHEMICAL CORP-BUFFALO CHEM
Classification: Large Quantity Generator

Corrective Action Summary:

Event date: 09/29/1996
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 07/23/1986
Date achieved compliance: 12/21/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/23/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/06/1982
Date achieved compliance: 07/23/1987
Violation lead agency: EPA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 04/30/1984
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 8000
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/06/1982
Date achieved compliance: 07/23/1987
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 04/27/1984
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 8000
Final penalty amount: 6000
Paid penalty amount: 6000

Evaluation Action Summary:

Evaluation date: 07/23/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/23/1986
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 12/21/1986
Evaluation lead agency: State

Evaluation date: 10/16/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/01/1983
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/06/1982
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/23/1987
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

FINDS:

Registry ID: 110004336184

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD001863372
Country: USA
Mailing Name: ALLIED CHEMICAL CORP
Mailing Contact: TAYLOR JAMES PLANT MANAGE
Mailing Address: 35 LEE ST
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14210
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-824-8424

Document ID: NYO1460232
Manifest Status: Completed copy
Trans1 State ID: 9A-090
Trans2 State ID: Not reported
Generator Ship Date: 820715
Trans1 Recv Date: 820715
Trans2 Recv Date: Not reported
TSD Site Recv Date: 820715
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001863372
Trans1 EPA ID: NYD080336241
Trans2 EPA ID: Not reported
TSD ID: NYD080336241
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00330
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 82
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Mgmt Method Type Code: Not reported

Document ID: NYO1460286
Manifest Status: Completed copy
Trans1 State ID: 9A-045
Trans2 State ID: Not reported
Generator Ship Date: 820923
Trans1 Recv Date: 820923
Trans2 Recv Date: Not reported
TSD Site Recv Date: 820923
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001863372
Trans1 EPA ID: NYT370012403
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 04000
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 82
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYO2172051
Manifest Status: Completed copy
Trans1 State ID: 9A-090
Trans2 State ID: Not reported
Generator Ship Date: 830303
Trans1 Recv Date: 830303
Trans2 Recv Date: Not reported
TSD Site Recv Date: 830303
Part A Recv Date: 030308
Part B Recv Date: 030308
Generator EPA ID: NYD001863372
Trans1 EPA ID: NYD080336241
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: P120 - VANADIUM PENTOXIDE
Quantity: 00400
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00002
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 003
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 100
Year: 83
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYO2172042
Manifest Status: Completed copy
Trans1 State ID: 9A-045
Trans2 State ID: Not reported
Generator Ship Date: 830125
Trans1 Recv Date: 830125
Trans2 Recv Date: Not reported
TSD Site Recv Date: 830128
Part A Recv Date: 030218
Part B Recv Date: 030218
Generator EPA ID: NYD001863372
Trans1 EPA ID: NYD074045055
Trans2 EPA ID: Not reported
TSD ID: ALD000772301
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 83
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYO2172024
Manifest Status: Completed copy
Trans1 State ID: 9A-045
Trans2 State ID: Not reported
Generator Ship Date: 821122
Trans1 Recv Date: 821122
Trans2 Recv Date: Not reported
TSD Site Recv Date: 821122
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001863372
Trans1 EPA ID: NYT370012403
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D006 - CADMIUM 1.0 MG/L TCLP
Quantity: 01000
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 82
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYO2172159
Manifest Status: Completed copy
Trans1 State ID: 9A-045

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Trans2 State ID: Not reported
Generator Ship Date: 821117
Trans1 Recv Date: 821117
Trans2 Recv Date: Not reported
TSD Site Recv Date: 821117
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001863372
Trans1 EPA ID: NYT370012403
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 04000
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 82
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYO3225726
Manifest Status: Completed copy
Trans1 State ID: 7A002
Trans2 State ID: Not reported
Generator Ship Date: 840409
Trans1 Recv Date: 840409
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840411
Part A Recv Date: 840412
Part B Recv Date: 840418
Generator EPA ID: NYD001863372
Trans1 EPA ID: NYD088658646
Trans2 EPA ID: Not reported
TSDF ID: OHD000816629
Waste Code: B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Quantity: 00680
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100
Year: 84
Manifest Tracking Num: Not reported
Import Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ALLIED CHEMICAL, INDUSTRIAL CHEMICAL DIV (Continued)

1000248674

Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYO3225735
Manifest Status: Completed copy
Trans1 State ID: NY9A091
Trans2 State ID: Not reported
Generator Ship Date: 840328
Trans1 Recv Date: 840328
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840328
Part A Recv Date: 840405
Part B Recv Date: 840404
Generator EPA ID: NYD001863372
Trans1 EPA ID: NYD012955134
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: B010 - PCB CONT TRANS CONT 50PPM OR>PCB,<500PPM
Quantity: 00016
Units: T - Tons
Number of Containers: 004
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 84
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

AN156 BEHRINGER PROPERTY (IMSON STREET)
ESE 181 IMSON STREET
1/2-1 BUFFALO, NY 14210

0.821 mi.
4336 ft.

Site 1 of 2 in cluster AN

Relative:
Higher

SHWS:
Program: HW
Site Code: 58342
Classification: C
Region: 9

Actual:
597 ft.

SHWS S108061186
N/A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BEHRINGER PROPERTY (IMSON STREET) (Continued)

S108061186

Acres: .200

HW Code: 915155

Record Add: 11/18/1999 12:00:00 PM

Record Upd: 6/27/2007 12:51:00 PM

Updated By: GPSUTTON

Site Description: The Behringer Property Site is located at 181 Imson Street in the City of Buffalo. The site consists of a small yard (0.2 acres) surrounding a single story wood framed storage building adjacent to the former Behringer Brothers Inc. facility. The Seneca-Babcock neighborhood is generally residential. However, the site itself is located at the end of Imson Street, adjacent to the former Houdaille-Manzel Industrial Plant and a Pennsylvania railroad corridor. The available history of the site is limited; however, local residents have indicated that the site was used as a railroad siding yard as well as a storage yard for a former scrap metal business. The soil on the site is generally higher than the surrounding area due to the filling of the site during former and current uses. The fill consists of miscellaneous fill materials, such as slag, stone of various sizes, soil, construction and demolition debris and topsoil. This layer is approximately 18 inches to 30 inches in depth. Natural soil is found below this layer. In 1991, as part of the investigation of the Houdaille-Manzel Industrial Plant (Site # 915037) surface soil samples were collected from the yard near the corner of a shed located in the yard behind the building. The results showed characteristic hazardous waste levels of lead from 5.57 ppm to 250 ppm (limit 5 ppm). A follow-up site inspection was performed in June 1995 in preparation for conducting a remedial investigation of the property and to investigate a report that the property owner had disposed construction debris on the site. At that time, it was determined that excavation activities had been performed at the site which exposed additional contaminated soils. Furthermore, it was noted during the inspection that neighborhood children were actively playing on the pile of contaminated soil. The New York State Department of Health (NYSDOH) was notified of the excavations and of the exposure of area children to the contaminated soil. The NYSDOH subsequently sent a letter to the owners advising them to restrict access to the site however the owner refused to address the issue citing insufficient financial capability. The NYSDEC prepared an Interim Remedial Measure (IRM) work plan to remove the contaminated soils. This work plan was presented at a public meeting on August 30, 1995 to inform the neighborhood of the necessary work. The objective of the IRM was to reduce lead contamination to a level which is protective of public health and the environment. This was achieved by the excavation and removal of contaminated soils from the site under an Emergency Removal Contract. A No further Action Record of Decision (ROD) was signed in April 1996.

Env Problem: High levels of lead that were found in site soils have been removed. No further action is required. Groundwater was not impacted.

Health Problem: A completed interim remedial measure which included the excavation and off-site disposal of approximately 1,000 cubic yards of lead contaminated soil and the backfilling and covering of the excavation with at least two feet of "clean" earth cover material should prevent exposures from occurring. Public water serves the area which eliminates potential exposures via drinking water.

Dump: True
Structure: False
Lagoon: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BEHRINGER PROPERTY (IMSON STREET) (Continued)

S108061186

Landfill: False
Pond: False
Disp Start: unknown
Disp Term: Not reported
Lat/Long: 42:52:22:0 / 78:49:54:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 11/18/1999 12:00:00 PM
Updated By: INITIAL
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: BEHRINGER BROTHERS, INC.
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: Not reported
Owner Company: Behringer Brothers, Inc.
Owner Address: 181 Imson Street
Owner Addr2: Not reported
Owner City,St,Zip: Buffalo, NY 14210
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: BEHRINGER BROTHERS, INC.
Owner Address: 181 IMSON ST.
Owner Addr2: Not reported
Owner City,St,Zip: BUFFALO, NY 14210
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: Samuel Delmonte
Owner Address: 1115 Seneca Street
Owner Addr2: Not reported
Owner City,St,Zip: Buffalo, NY 14210
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: BEHRINGER BROTHERS, INC.
Owner Address: 1115 SENECA ST.
Owner Addr2: Not reported
Owner City,St,Zip: BUFFALO, NY 14210
Owner Country: United States of America
HW Code: 915155
Waste Type: EP TOX LEAD (250 PPM)
Waste Quantity: APPROX. 50 CU/YD
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BEHRINGER PROPERTY (IMSON STREET) (Continued)

S108061186

Record Updated: Not reported
Updated By: Not reported

AN157 BEHRINGER PROPERTY (IMSON STREET)

DEL SHWS S105973173
N/A

ESE

1/2-1

BUFFALO, NY 14210

0.821 mi.

4336 ft. Site 2 of 2 in cluster AN

Relative:
Higher

Actual:
597 ft.

DEL SHWS:

Year: 1996
Site Code Id: 915155
Site Classification: Not reported
Region: Not reported
Epa Id Number: Not reported
Site Type - Dump: Yes
Site Type - Structure: No
Site Type - Lagoon: No
Site Type - Landfill: No
Site Type - Treat Pond: No
Site Size (Acres): Not reported
Site Size Comment: Not reported
Period Assoc/HW Start: unknown
Period Assoc/HW End: Not reported
Lat/Long: Not reported
Lat/Long Decimal: Not reported
Lat/Long (dms): 42 52 215.0 / 78 49 540.0
Hazardous Waste Code: Not reported
Hazard Waste Disposed: EP Tox Lead (250 ppm)
Quantity: approx. 50 cu/yd
Air Data Available: No
SW Std Contravention: No
GW Std Contravention: No
Soil Type: X
Sediment Data Available: No
GW Std Contravention: No
DW Std Contravention: No
SW Std Contravention: No
Air Stand Contraventions: No
Legal Action Type: Not reported
State Legal Action: Yes
Federal Legal Action: No
Enforce Status Code: OS
Remedial Act Proposed: No
Rem Act Under Design: No
Rem Act In Progress: No
Rem Act Completed: No
Remedial Action Type: Not reported
Soil Type: Mixed permeable fill
Depth To Groundwater: 2 feet
Owner Name: Not reported
Owner Address: Not reported
Owner City, St, Zip: Not reported
Owner Phone: Not reported
Owner Contact Name: Not reported
Owner During Disposal: Not reported
Owner During Use: Behringer Brothers, Inc.
Operator Name: Behringer Brothers, Inc.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BEHRINGER PROPERTY (IMSON STREET) (Continued)

S105973173

Operator Address: Not reported
Operator City,St,Zip: Not reported
Operator Phone: Not reported
Operator Contact Name: Not reported
Oper During Disposal: Not reported
Site Type: Not reported
HW Disposal Period: Not reported
Analytical Data Available: Not reported
Applicable Std Exceeded: Not reported
Geotech Info: Not reported
Depth To Groundwater: Not reported
Status: Not reported
Nature Of Action: Not reported
Env Prob Assessment: High levels of lead were found in site soils. Soils do not support vegetative growth and is mostly uncovered. There is potential for direct contact with contaminated soil and potential for dust generation.
Site Description: Not reported
Confirmed HW: Not reported
Environment Assessment: Not reported
Health Assessment: Not reported
Disposal Start Date: Not reported
Disposal Term Date: Not reported
Air Violation: Not reported
Groundwater Violation: Not reported
Drink Water Violation: Not reported
Surface Water Violation: Not reported
Legal New York State: Not reported
Legal Federal: Not reported
Legal State: Not reported
Remedial Action Active: Not reported
Remedial Action Done: Not reported
NPL Status: Not reported
Count Operator: Not reported
Count Owner: Not reported
NYTM X: Not reported
NYTM Y: Not reported
Co Name: Not reported
Co Addr: Not reported
Operator Addr: Not reported
Operator Addr 2: Not reported
Operator Addr 3: Not reported
Operator Addr 4: Not reported
HWDP From: Not reported
From To: Not reported
Assessment Of Health: Not reported
Env Assessment: Not reported
HW Disposed/Quantity: Not reported
Description: Not reported
Assess/Env Prog: Not reported
Assess/Health Prob: Not reported
Site Description: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

158
East
1/2-1
0.996 mi.
5261 ft.

C & D POWER SYSTEMS - BUFFALO SALES
45 SCOVILLE AVENUE
BUFFALO, NY 14201

CERC-NFRAP 1000109840
RCRA-NonGen NYD085686426
FINDS
SHWS
MANIFEST

Relative:
Higher

CERC-NFRAP:
Site ID: 0201637
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP

Actual:
592 ft.

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY
Date Started: Not reported
Date Completed: 07/09/1985
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: 12/04/1987
Date Completed: 12/30/1987
Priority Level: Low priority for further assessment

Action: SITE INSPECTION
Date Started: Not reported
Date Completed: 12/01/1989
Priority Level: Higher priority for further assessment

Action: SH
Date Started: Not reported
Date Completed: 07/24/1997
Priority Level: NFRAP: No further Remedial Action planned

Action: ARCHIVE SITE
Date Started: Not reported
Date Completed: 09/30/1997
Priority Level: Not reported

RCRA-NonGen:

Date form received by agency: 01/01/2007
Facility name: C & D BATTERIES DIV
Facility address: 45 SCOVILLE AVE
BUFFALO, NY 142062932
EPA ID: NYD085686426
Mailing address: SCOVILLE AVE
BUFFALO, NY 14206
Contact: Not reported
Contact address: SCOVILLE AVE
BUFFALO, NY 14206
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Owner/Operator Summary:

Owner/operator name: ELTRA CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ELTRA CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: C & D BATTERIES DIV
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: C & D BATTERIES DIV
Classification: Not a generator, verified

Date form received by agency: 03/01/1990
Facility name: C & D BATTERIES DIV
Site name: C & D CHARTER POWER SYSTEMS
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980
Facility name: C & D BATTERIES DIV

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 05/21/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/23/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/03/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/25/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004372866

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SHWS:

Program: HW
Site Code: 56627
Classification: C
Region: 9
Acres: .250
HW Code: 915134
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/5/2008 12:11:00 PM
Updated By: AJWHITE

Site Description: The site was used for storage and refurbishing of industrial batteries. Past plant operating practices included washing of batteries on an out- door and unbermed concrete pad at the rear of the facility. During 1985 , C&D Power in vestigated the site for lead contamination. Surface soil samples collected between the pad and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

adjacent properties are also affected. Soil samples from these properties indicated presence of lead over 5000 parts per million. Additional studies were done in 1987-88 to further determine the extent of contamination. Groundwater samples were found not contaminated. The DEC approved the interim remediation plan submitted by the PRP which required the removal of all contaminated soil and its replacement by clean soil. An order on consent was issued. The contaminated soil has been removed and replaced by clean soil. A groundwater investigation was completed in 1989, no significant contamination was found. Remediation of this site is complete.

Env Problem: Removal of contaminated soil has addressed the environmental problems at this site. No further action is necessary.

Health Problem: Surface soil samples collected next to the concrete pad used for washing the batteries contained lead at levels of 1400 to 15,100 ppm. Surface soil samples in residential backyards ranged from 610 to 5070 ppm. The site is and was unrestricted. A concern existed for exposure through increased uptake of lead by area residents through inhalation of wind blown soil or indoor dust, ingestion of soil or dust, and through the food chain from garden vegetables grown in contaminated adjacent residential backyards. Groundwater was found not to be impacted, and area residents are provided with public water. Remediation of the site has been completed including removal of contaminated soils. Post remediation groundwater monitoring is in progress to ensure contamination is not impacting shallow groundwater in the area. The site has been delisted.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1969
Disp Term: 1985
Lat/Long: 00:00:00.0 / 00:00:00.0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 11/18/1999 12:00:00 PM
Updated By: INITIAL
Own Op: Disp. Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: ALLIED SIGNAL CORP. , MORRISTOWN, NJ
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: ALLIED SIGNAL CORP. , MORRISTOWN, NJ
Owner Address: COLUMBIA RD. AND PARK AVE.
Owner Addr2: Not reported
Owner City,St,Zip: MORRISTOWN, NJ 07960
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: ALLIED SIGNAL CORP. , MORRISTOWN, NJ

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Owner Address: 3043 WALTON RD.
Owner Addr2: Not reported
Owner City,St,Zip: PLYMOUTH MEETING, PA 19462
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: C&D Power Systems
Owner Address: 3043 WALTON ROAD
Owner Addr2: Not reported
Owner City,St,Zip: PLYMOUTH MEETING, PA
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: C & D Power Systems
Owner Address: 3043 Walton Road
Owner Addr2: Not reported
Owner City,St,Zip: Plymouth Meeting, PA 19462
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: Allied Signal Corporation
Owner Address: Columbia Road and Park Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Morristown, NJ 07960
Owner Country: United States of America
HW Code: 915134
Waste Type: LEAD AND POSSIBLY OTHER METALS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915134
Waste Type: WASHINGS FROM INDUSTRIAL BATTERIES, MAINLY
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD085686426
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS

NY MANIFEST:

EPA ID: NYD085686426
Country: USA
Mailing Name: C & D CHARTER POWER SYSTEMS
Mailing Contact: C & D CHARTER POWER SYSTEMS
Mailing Address: 3043 WALTER RD-ATTN: P REICH
Mailing Address 2: Not reported
Mailing City: PLYMOUTH MEETING
Mailing State: PA
Mailing Zip: 19462
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 215-828-9000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Document ID: NYA6056163
Manifest Status: Completed copy
Trans1 State ID: 60210CNY
Trans2 State ID: Not reported
Generator Ship Date: 890117
Trans1 Recv Date: 890117
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890117
Part A Recv Date: 890201
Part B Recv Date: 890124
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 45640
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA5983461
Manifest Status: Completed copy
Trans1 State ID: E69850MAI
Trans2 State ID: Not reported
Generator Ship Date: 890117
Trans1 Recv Date: 890117
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890117
Part A Recv Date: 890201
Part B Recv Date: 890123
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 36840
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA5983452
Manifest Status: Completed copy
Trans1 State ID: MAINE3744
Trans2 State ID: Not reported
Generator Ship Date: 890117
Trans1 Recv Date: 890117
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890117
Part A Recv Date: 890131
Part B Recv Date: 890123
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 37280
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA6056181
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 890117
Trans1 Recv Date: 890117

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Trans2 Recv Date: Not reported
TSD Site Recv Date: 890118
Part A Recv Date: 890131
Part B Recv Date: 890123
Generator EPA ID: NYD085686426
Trans1 EPA ID: OHD038093688
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 37500
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA5983479
Manifest Status: Completed copy
Trans1 State ID: 79615Z(NY
Trans2 State ID: Not reported
Generator Ship Date: 890117
Trans1 Recv Date: 890117
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890117
Part A Recv Date: 890131
Part B Recv Date: 890123
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 39560
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA6056172
Manifest Status: Completed copy
Trans1 State ID: 55345DNY
Trans2 State ID: Not reported
Generator Ship Date: 890117
Trans1 Recv Date: 890117
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890117
Part A Recv Date: 890131
Part B Recv Date: 890123
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 41400
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA5982048
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 39477B(NY
Trans2 State ID: Not reported
Generator Ship Date: 881207
Trans1 Recv Date: 881207
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881207
Part A Recv Date: 890126
Part B Recv Date: 881213
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD051809952

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00016
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA6329394
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 86549Z(NY)
Trans2 State ID: Not reported
Generator Ship Date: 881206
Trans1 Recv Date: 881206
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881206
Part A Recv Date: 890126
Part B Recv Date: 881213
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00020
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Mgmt Method Type Code: Not reported

Document ID: NYA5982039
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: E69849(MA
Trans2 State ID: Not reported
Generator Ship Date: 881209
Trans1 Recv Date: 881209
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881213
Part A Recv Date: 890105
Part B Recv Date: 890105
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00020
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA5980086
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 54795D(NY
Trans2 State ID: Not reported
Generator Ship Date: 881208
Trans1 Recv Date: 881208
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881208
Part A Recv Date: 890201
Part B Recv Date: 881213
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00018
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA6329376
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 86549Z(NY
Trans2 State ID: Not reported
Generator Ship Date: 881206
Trans1 Recv Date: 881206
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881206
Part A Recv Date: 890126
Part B Recv Date: 881213
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00020
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA5925762
Manifest Status: Completed copy
Trans1 State ID: 776197(NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Trans2 State ID: Not reported
Generator Ship Date: 881216
Trans1 Recv Date: 881216
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881219
Part A Recv Date: 890105
Part B Recv Date: 890105
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00018
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA6329403
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: 86558Z(NY)
Trans2 State ID: Not reported
Generator Ship Date: 881206
Trans1 Recv Date: 881206
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881206
Part A Recv Date: 890127
Part B Recv Date: 881213
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00020
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88
Manifest Tracking Num: Not reported
Import Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C & D POWER SYSTEMS - BUFFALO SALES (Continued)

1000109840

Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYA5982093
Manifest Status: Completed after the designated time period for a TSDf to get a copy to the DEC
Trans1 State ID: 38851B(NY)
Trans2 State ID: Not reported
Generator Ship Date: 881208
Trans1 Recv Date: 881208
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881208
Part A Recv Date: 890201
Part B Recv Date: 881213
Generator EPA ID: NYD085686426
Trans1 EPA ID: NYD051809952
Trans2 EPA ID: Not reported
TSDf ID: NYD080336241
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00018
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

159
WNW
> 1
1.027 mi.
5423 ft.

Relative:
Lower

Actual:
588 ft.

W & F MFG CO INC
251 SENECA ST
BUFFALO, NY 14204

CORRACTS:

EPA ID: NYD002100121
EPA Region: 02

CORRACTS 1000113745
RCRA-NonGen NYD002100121
FINDS
RAATS
MANIFEST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W & F MFG CO INC (Continued)

1000113745

Area Name: SITEWIDE
Actual Date: 1/12/1994
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 339999
All Other Miscellaneous Manufacturing
Original schedule date: 03/31/1994
Schedule end date: Not reported

EPA ID: NYD002100121
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 7/19/1994
Action: CA070YE - RFA Determination Of Need For An RFI, RFI is Necessary
NAICS Code(s): 339999
All Other Miscellaneous Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002100121
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/22/1992
Action: CA050 - RFA Completed
NAICS Code(s): 339999
All Other Miscellaneous Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002100121
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 10/28/1988
Action: CA050PA - RFA Completed, Assessment was a PA-Plus
NAICS Code(s): 339999
All Other Miscellaneous Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD002100121
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 12/16/1988
Action: CA070NO - RFA Determination Of Need For An RFI, RFI is Not Necessary
NAICS Code(s): 339999
All Other Miscellaneous Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-NonGen:

Date form received by agency: 01/01/2007
Facility name: W & F MFG CO INC
Facility address: 251 SENECA ST
BUFFALO, NY 142042013
EPA ID: NYD002100121
Mailing address: PO BOX 126
BUFFALO, NY 14240

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W & F MFG CO INC (Continued)

1000113745

Contact: Not reported
Contact address: PO BOX 126
BUFFALO, NY 14240
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: W & F MFG CO INC
Owner/operator address: 251 SENECA ST
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: (716) 856-3600
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: W & F MFG CO INC
Owner/operator address: 251 SENECA ST
BUFFALO, NY 14204
Owner/operator country: US
Owner/operator telephone: (716) 856-3600
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: W & F MFG CO INC
Classification: Not a generator, verified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W & F MFG CO INC (Continued)

1000113745

Date form received by agency: 07/08/1999
Facility name: W & F MFG CO INC
Classification: Not a generator, verified

Date form received by agency: 11/19/1980
Facility name: W & F MFG CO INC
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Facility name: W & F MFG CO INC
Classification: Large Quantity Generator

Corrective Action Summary:

Event date: 10/28/1988
Event: RFA Completed, Assessment was a PA-Plus.

Event date: 12/16/1988
Event: RFA Determination Of Need For An RFI, RFI is Not Necessary;

Event date: 09/22/1992
Event: RFA Completed

Event date: 01/12/1994
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 07/19/1994
Event: RFA Determination Of Need For An RFI, RFI is Necessary;

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/26/1984
Date achieved compliance: 12/08/1984
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 12/21/1983
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 7500
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/31/1983
Date achieved compliance: 12/08/1984
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 11/06/1984
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W & F MFG CO INC (Continued)

1000113745

Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/31/1983
Date achieved compliance: 12/08/1984
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 12/23/1983
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 7500
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 07/26/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/17/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/09/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/26/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 12/08/1984
Evaluation lead agency: EPA

Evaluation date: 01/31/1983
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 12/08/1984
Evaluation lead agency: EPA

FINDS:

Registry ID: 110009464800

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W & F MFG CO INC (Continued)

1000113745

corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD002100121
Country: USA
Mailing Name: W & F MANUFACTURING
Mailing Contact: UNKNOWN
Mailing Address: 2299 KENMORE AVE
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14207
Mailing Zip4: 1311
Mailing Country: USA
Mailing Phone: 000-000-0000

Document ID: NYO2759769
Manifest Status: Completed copy
Trans1 State ID: 9A090
Trans2 State ID: Not reported
Generator Ship Date: 831014
Trans1 Recv Date: 831014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 831014
Part A Recv Date: 031025
Part B Recv Date: 031025
Generator EPA ID: NYD002100121
Trans1 EPA ID: NYD080336241
Trans2 EPA ID: Not reported
TSDF ID: NYD080336241
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00025
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100
Year: 83
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W & F MFG CO INC (Continued)

1000113745

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

AO160 EXXONMOBIL OIL CORPORATION
SE 625 ELK STREET
> 1 BUFFALO, NY 14210

1.069 mi.
5643 ft.

Site 1 of 2 in cluster AO

Relative:
Higher

Actual:
593 ft.

SHWS:

Program: HW
Site Code: 56562
Classification: DOES NOT PRESENT A SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR THE ENVIRONMENT - ACTION MAY BE DEFERRED.

Region: 9
Acres: 3.000
HW Code: 915040
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 5/8/2008 9:03:00 AM
Updated By: MLDOSTER

Site Description:

The site is located along the Buffalo River and was used for the disposal of wastes such as demolition debris, tank sediments, sewer sediments, soils containing asphalt and general refuse. Prior to Mobil's ownership, the property was used by the City of Buffalo for the disposal of municipal wastes. The U.S.G.S. analysis of soil samples taken in August of 1982 indicated the presence of high levels of lead and various organic compounds. A State Superfund Phase I Investigation Report was completed in 1983. A Phase II Report by Mobil Oil was completed in 1987. Data from this report showed the presence of lead in soil samples at levels of up to 3,160 ppm. The Industrial Waste Survey of 1979 indicates that sludge containing tetraethyl-lead was disposed at this site. Further site investigation was conducted under the DEC's Multi-Media Pollution Prevention (M2P2) Program. The site is part of a 77 acre petroleum storage and distribution terminal which was historically an oil refinery. Currently two remedial systems are in place to contain and recover spilled oil in soils and groundwater. This system has operated since 1971. In 2004 Exxon/Mobil submitted plans to upgrade the containment system. As part of this effort buried abandoned pipes were removed from the northern portion of the terminal. It is in an urban area, generally surrounded by a mixture of industrial and commercial property. There are a few isolated residential parcels located immediately to the north. Southside Bowling Alley LLC is located to the northeast and the Buffalo River bounds the south side of the site. The property adjacent to the south side of the Buffalo River is a mixture of commercial and industrial land use, including a former greenhouse operation, which is currently vacant. To the west is a business for the storage and distribution of construction materials. Former refinery, lube plant and terminal activities may have impacted this site. Contaminants which are known or suspected to affect soil, groundwater, surface water, sediment or soil gas are petroleum, other VOC's, SVOC's and or metals. Remedial design and remedial actions are being conducted under the State's Brownfield Cleanup Program (refer to C915201). Remediation of OU-1 (former residential property) was completed in 2007. Pipeline removal on OU-2 (plant property) was

SHWS S101341711
LTANKS N/A
HIST LTANKS
CBS AST
NY Spills
NY Hist Spills
AIRS
CBS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

completed in 2007. A groundwater pumping system continues to operate to prevent migration of oil to the river.

Env Problem: Soil is contaminated with lead and petroleum. Oily seeps are visible along the Buffalo River. Adsorbents are placed in the seeps areas.

Health Problem: Direct contact with contaminated on-site soils is unlikely because site access is restricted by a locked fence. Exposures through drinking water ingestion are not expected because the area is served by public water.

Dump: True

Structure: False

Lagoon: False

Landfill: False

Pond: False

Disp Start: 1951

Disp Term: 1976

Lat/Long: 42:51:42:0 / 78:49:43:0

Dell: False

Record Add: 11/18/1999 12:00:00 PM

Record Upd: 11/18/1999 12:00:00 PM

Updated By: INITIAL

Own Op: Owner

Sub Type: E

Owner Name: Not reported

Owner Company: MOBIL OIL CORPORATION

Owner Address: 635 ELK ST.

Owner Addr2: Not reported

Owner City,St,Zip: BUFFALO, NY 14204

Owner Country: United States of America

Own Op: Disp. Owner

Sub Type: NNN

Owner Name: Not reported

Owner Company: MOBIL OIL CORPORATION

Owner Address: Not reported

Owner Addr2: Not reported

Owner City,St,Zip: ZZ

Owner Country: United States of America

Own Op: On-Site Operator

Sub Type: NNN

Owner Name: Not reported

Owner Company: Mobil Oil Corporation

Owner Address: 635 Elk Street

Owner Addr2: Not reported

Owner City,St,Zip: Buffalo, NY 14204

Owner Country: United States of America

Own Op: On-Site Operator

Sub Type: E

Owner Name: Not reported

Owner Company: MOBIL OIL CORPORATION

Owner Address: 635 ELK ST.

Owner Addr2: Not reported

Owner City,St,Zip: BUFFALO, NY 14204

Owner Country: United States of America

Own Op: Owner

Sub Type: NNN

Owner Name: Not reported

Owner Company: Mobil Oil Corporation

Owner Address: 635 Elk Street

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Owner Addr2: Not reported
Owner City,St,Zip: Buffalo, NY 14204
Owner Country: United States of America
HW Code: 915040
Waste Type: TETRAETHYL LEAD AND LUBE SLUDGES
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915040
Waste Type: SPENT CATALYSTS
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915201
Cross Ref Type Code: 03
Cross Ref Type: BF Site ID
Record Added Date: 12/7/2005 9:09:00 AM
Record Updated: 12/7/2005 9:09:00 AM
Updated By: brwolose
Crossref ID: NYD002107019
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS
Crossref ID: 15-S-53
Cross Ref Type Code: 07
Cross Ref Type: Muni. Waste ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: INITIAL
Crossref ID: C915201
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 12/7/2005 9:09:00 AM
Record Updated: 12/7/2005 9:09:00 AM
Updated By: brwolose

LTANKS:

Site ID: 165321
Spill No: 9805432
Spill Date: 7/31/1998
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 8/3/1998
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 1502
Investigator: TEDIEFFE
Referred To: Not reported
Reported to Dept: 7/31/1998
CID: 30
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 7/31/1998
Spill Record Last Update: 8/3/1998
Spiller Name: SARAH
Spiller Company: GRAND ISLAND SALES AND
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: DALE KIVETT
Spiller Phone: (716) 827-5114
Spiller Extension: Not reported
DEC Region: 9
DER Facility ID: 139345
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TED" 08/03/98: SPILL AT TRUCK LOADING RACK CONTAINED, PRODUCT
DRAINED TO CONTAINMENT UST. NO RESPONSE REQUIRED. SPILL CLOSED
8/31/98.
Remarks: driver overfilled compartment on truck - spill occ at terminal rack
and contained in containment system

Material:
Site ID: 165321
Operable Unit ID: 1063215
Operable Unit: 01
Material ID: 556170
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: 20
Resource Affected: Soil
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 165310
Spill No: 0208556
Spill Date: 11/18/2002
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Possible release with minimal potential for fire or hazard or Known
release with no damage. DEC Response. Willing Responsible Party.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Corrective action taken.
Spill Closed Dt: 11/22/2002
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 1502
Investigator: MXFRANKS
Referred To: Not reported
Reported to Dept: 11/18/2002
CID: 30
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: 11/18/2002
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/18/2002
Spill Record Last Update: 11/22/2002
Spiller Name: MIKE STANTON
Spiller Company: US FLEET SERVICE
Spiller Address: 1875 HARLEM ROAD
Spiller City,St,Zip: CHEEKTOWAGA, NY 14212-
Spiller County: 001
Spiller Contact: ARTHUR POWERS
Spiller Phone: (716) 827-5127
Spiller Extention: Not reported
DEC Region: 9
DER Facility ID: 139345
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MF" 11/18/02: MF S/I/ART POWERS, MOBIL OIL & MIKE STANTON, US FLEET
SERVICES. US FLEET TANKER WAS OVERFILLED, #2 FO CAME OUT OF VAPOR
RECOVERY PIPE WHEN IT LEFT FUELING AREA. SPILLED APPX 5 GALLONS OVER
CONCRETE & BLACKTOP AREA. NO SPILLAGE REACHED DRAINS. MOBIL APPLIED
SPEEDY DRY & SWEEPED INTO 55 GALLONS DRUM. MOBIL WILL HANDLE DISPOSAL,
APPX 1/2 DRUM OF DEBRIS. SMALL SPILL, ALL CLEAN, NO FURTHER ACTION
NECESSARY.*****COMPUTER FILE ONLY*****
Remarks: driver overfilled truck. clean up inprogress at this time.

Material:
Site ID: 165310
Operable Unit ID: 859977
Operable Unit: 01
Material ID: 515557
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 2
Resource Affected: Soil
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:

Region of Spill: 9
Spill Number: 9805432
Spill Date: 07/31/1998
Spill Time: 11:00
Spill Cause: Tank Overfill
Resource Affected: On Land
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/03/98
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: TED
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 07/31/98
Reported to Department Time: 11:30
SWIS: 14
Spiller Contact: DALE KIVETT
Spiller Phone: (716) 827-5114
Spiller Extension: Not reported
Spiller Name: GRAND ISLAND SALES AND
Spiller Address: Not reported
Spiller City, St, Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: SARAH
Facility Phone: (716) 773-3527
Facility Extension: Not reported
Spill Notifier: Affected Persons
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 07/31/98
Time Spill Entered In Computer Data File: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Spill Record Last Update: 08/03/98
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 20
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 20
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929

DEC Remarks: 08/03/98: SPILL AT TRUCK LOADING RACK CONTAINED, PRODUCT DRAINED TO CONTIANMENT UST. NO RESPONSE REQUIRED. SPILL CLOSED 8/31/98.

Spill Cause: driver overfilled compartment on truck - spill occ at terminal rack and contained in containment system

CBS AST:

CBS Number: 9-000326
Region: STATE
ICS Number: Not reported
PBS Number: Not reported
MOSF Number: 9-1200
Telephone: (716) 827-5127
Facility Town: BUFFALO (C)
Operator: D.N. SHELDON
Emrgncy Contact: D.N. SHELDON
Emrgncy Phone: (716) 827-5127
Expiration Date: 06/10/2002
Owner Name: EXXONMOBIL OIL CORPORATION
Owner Address: 3225 GALLOWES ROAD
Owner City,St,Zip: FAIRFAX, VA 22037
Owner Telephone: (703) 849-6000
Owner type: Corporate/Commercial
Facility Type: RETAIL GASOLINE SALES
Mail Name: EXXONMOBIL OIL CORPORATION
Mail Contact Addr: 625 ELK STREET
Mail Contact Addr2: Not reported
Mail Contact Contact: D.N. SHELDON
Mail Contact City,St,Zip: BUFFALO, NY 14210
Mail Phone: (716) 827-5127
SPDES Number: 0-204480
Facility Status: ACTIVE FACILITY
Owner Sub Type: Not reported

Tank Id: 2A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Date Entered: 06/09/1992
Capacity (Gal): 8000
Chemical: Xylene (mixed)
Tank Closed: 05/93
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 10/88
Certified Date: 04/26/2000
CAS Number: 1330207
Substance: Single Hazardous Substance on DEC List
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Intrnl Protection: None
Extrnl Protection: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 11
Pipe Containment: None
Tank Containment: Diking
Leak Detection: None
Overfill Protection: None
Haz Percent: 50
Total Tanks: 3
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42151145 / 78150100
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: / /
Is it There: F
Deliquent: F
Date Expired: 06/10/94
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/01/2000
Total Capacity of All Active Tanks(gal): 22300

Tank Id: A-2
Date Entered: 09/17/1996
Capacity (Gal): 10000
Chemical: Xylene (mixed)
Tank Closed: Not reported
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 09/96
Certified Date: 04/26/2000
CAS Number: 1330207
Substance: More than one Hazardous Substance on DEC List
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Intrnl Protection: None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Extrnl Protection: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Pipe Containment: Diking
Tank Containment: Diking
Leak Detection: Other
Overfill Protection: High Level Alarm
Haz Percent: 38
Total Tanks: 3
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I51I45 / 78I50I00
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: / /
Is it There: F
Deliquent: F
Date Expired: 06/10/94
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/01/2000
Total Capacity of All Active Tanks(gal): 22300

Tank Id: 1A
Date Entered: 06/09/1992
Capacity (Gal): 12000
Chemical: Xylene (mixed)
Tank Closed: Not reported
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 06/92
Certified Date: 04/26/2000
CAS Number: 1330207
Substance: Single Hazardous Substance on DEC List
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Intrnl Protection: None
Extrnl Protection: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Pipe Containment: None
Tank Containment: Diking
Leak Detection: None
Overfill Protection: High Level Alarm
Haz Percent: 50
Total Tanks: 3
Tank Secret: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I51I45 / 78I50I00
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: / /
Is it There: F
Deliquent: F
Date Expired: 06/10/94
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/01/2000
Total Capacity of All Active Tanks(gal): 22300

Tank Id: F-1
Date Entered: 12/14/1999
Capacity (Gal): 300
Chemical: Ethylene glycol
Tank Closed: Not reported
Tank Status: In Service
Tank Type: Steel/carbon steel
Install Date: 01/91
Certified Date: 04/26/2000
CAS Number: 107211
Substance: Single Hazardous Substance on DEC List
Tank Location: ABOVEGROUND
Intrnl Protection: None
Extrnl Protection: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Pipe Containment: None
Tank Containment: Double-Walled
Leak Detection: Other
Overfill Protection: Product Level Gauge
Haz Percent: 10
Total Tanks: 3
Tank Secret: False
Last Test: Not reported
Due Date: Not reported
Tank Error Status: No Missing Data
SWIS Code: 1402
Lat/Long: 42I51I45 / 78I50I00
Pipe Flag: False
Federal ID: Not reported
Is Updated: F
Renew Date: / /
Is it There: F
Deliquent: F
Date Expired: 06/10/94

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 03/01/2000
Total Capacity of All Active Tanks(gal): 22300

NY Spills:

Site ID: 158592
Facility Addr2: Not reported
Facility ID: 9907444
Spill Number: 9907444
Facility Type: ER
SWIS: 1502
Investigator: BRENNAN
Referred To: Not reported
Spill Date: 9/21/1999
Reported to Dept: 9/21/1999
CID: 30
Spill Cause: Equipment Failure
Water Affected: BUFFALO
Spill Source: Vessel
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: No spill occured. No DEC Response. No corrective action required.
Spill Closed Dt: 9/22/1999
Remediation Phase: 0
Date Entered In Computer: 9/21/1999
Spill Record Last Update: 9/27/1999
Spiller Name: Not reported
Spiller Company: NONE - DRILL
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: DON SHELDON
Contact Phone: (716) 827-5127
DEC Region: 9
DER Facility ID: 134000
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks: "KAB" 09/22/99: KAB RECEIVED REPORT. THIS WAS A DRILL; THERE WAS NO ACTUAL SPILL. NO ACTION NECESSARY. CLOSE OUT.
*****DRILL*****DRILL*****DRILL***** VESSEL NAME
"DOUG FLUTIE." OFF-LOADING LINE BROKE. CALLER BELIEVES THAT ALL 20000 GALLONS WENT INTO THE RIVER. NRC CONTACTED. FURTHER INFORMATION TO FOLLOW.

Material:

Site ID: 158592
Operable Unit ID: 1081735
Operable Unit: 01
Material ID: 300149
Material Code: 0001
Material Name: #2 Fuel Oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Surface Water
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 165316
Facility Addr2: Not reported
Facility ID: 0406417
Spill Number: 0406417
Facility Type: ER
SWIS: 1500
Investigator: MXFRANKS
Referred To: Not reported
Spill Date: 9/11/2004
Reported to Dept: 9/11/2004
CID: 30
Spill Cause: Unknown
Water Affected: BUFFULO RIVER
Spill Source: Major Facility > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: 9/11/2004
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 9/16/2004
Remediation Phase: 0
Date Entered In Computer: 9/11/2004
Spill Record Last Update: 9/16/2004
Spiller Name: KIVETT, DALE
Spiller Company: EXXON MOBIL
Spiller Address: 625 ELK ST
Spiller City,St,Zip: BUFFALO, NY 14210
Spiller Company: 001
Contact Name: KIVETT, DALE
Contact Phone: (716) 827-5104
DEC Region: 9
DER Facility ID: 280480
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

"MF" 09/11/04: MF S/I/DALE KIVETT & CREW, EXXON MOBIL/MARK FALZONE, GES. BOOMING UP APPX 200' OF WALL AT THE BUFFALO RIVER. THE MEN IN THE BOAT TOLD ME THAT THERE IS A SLIGHT AMOUNT OF PRODUCT COMING OUT OF THE WALL. WE HAD OVER 4" OF RAIN PREVIOUSLY. THE OVERFLOW IF DOWNSTREAM OF THIS SHEEN. THERE IS NO FLOW IN THE RIVER & THE WIND IS BLOWING EVERYTHING UPSTREAM. THERE IS MORE SHIT THEN SHEEN. THE COAST GUARD HAS BEEN NOTIFIED. 09/16/04: MF COPY OF REPORT TO JASPAL. NO FURTHER ACTION NECESSARY. *****COMPUTER FILE ONLY*****

Remarks: unknown petroleum sheen on buffulo river in front of Exxon Mobile Dock. Exxon Mobil in the process of putting out booms at this time. Possibly from Heavy rain on Thursday , from well point system along dock.

Material:

Site ID: 165316
Operable Unit ID: 889009
Operable Unit: 01
Material ID: 487484
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Surface Water
Oxygenate: False
Site ID: 165316
Operable Unit ID: 889009
Operable Unit: 01
Material ID: 487485
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Surface Water
Oxygenate: False

Tank Test:

Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

[Click this hyperlink](#) while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

NY Hist Spills:

Region of Spill: 9
Spill Number: 0010756
Investigator: TED
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 12/28/2000 09:00
Reported to Dept Date/Time: 12/28/00 09:57
SWIS: 14
Spiller Name: MOBIL OIL
Spiller Contact: DALE KIVETT
Spiller Phone: (716) 827-5114
Spiller Contact: DALE KIVETT
Spiller Phone: (716) 827-5114
Spiller Address: 625 ELK STREET
Spiller City,St,Zip: BUFFALO, NY -
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 03
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/28/00
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/28/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/01/01
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 130
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 130

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Unkonwn Quantity Recovered:False

Material: #2 FUEL OIL

Class Type: #2 FUEL OIL

Times Material Entry In File: 24464

CAS Number: Not reported

Last Date: 19941207

DEC Remarks: 12/28/00: TED/DALE KIVETT/TELECON, SPILL OCCURRED INSIDE TRUCK LOADING RACK. ALL PRODUCT RECOVERED VIA DRAINS TO UST. NO FURTHER WORK REQUIRED. CLOSE OUT.
01/30/01: TED/DON SHELDON TELECON, REGARDING DISPOSAL OF WATER AND PETROLEUM PRODUCT COLLECTED AT TRUCK LOADING RACK UST RESULTING FROM OCCASIONAL TANKER TRUCK OVERFILLS. UST IS PERIODICALLY GUAGED, WHEN IT ACCUMULATES 6000 GALLONS, ENVIRONMENTAL PRODUCTS SERVICES EP S) IS CALLED OUT TO PUMP OUT PRODUCT AND WATER AND TRANSPORT SAME TO EXXON MOBIL S ALBANY TERMINAL WHERE THE PRODUCT IS RECYCLED. TRANSPORT AND DISPOSAL RECORDS KEPT AT BUFFALO TERMINAL. HENCEFORTH, RECORDS FOR THESE DISPOSAL EVENTS WILL BE REVIEWED DURING THE ANNUAL MOSF INSPECTIONS AND COPIES OF DISPOSAL DOCUMENTATION ATTACHED TO ANNUAL MOSF INSPECTION REPORT.

Remark: ELECTRIC GAUGE FAILED TO STOP THE DELIVERY TO THE FUEL TRUCK; CLEANED UP AT THE PUMPS.

Region of Spill:

9

Spill Number: 0175441

Investigator: TED

Caller Name: Not reported

Caller Agency: Not reported

Caller Phone: Not reported

Notifier Name: Not reported

Notifier Agency: Not reported

Notifier Phone: Not reported

Spill Date/Time: 12/04/2001 09:00

Reported to Dept Date/Time: 12/04/01 10:30

SWIS: 14

Spiller Name: Not reported

Spiller Contact: Not reported

Spiller Phone: Not reported

Spiller Contact: CALLER

Spiller Phone: () -

Spiller Address: Not reported

Spiller City,St,Zip: Not reported

Spill Cause: Equipment Failure

Reported to Dept: On Land

Water Affected: Not reported

Spill Source: 03

Spill Notifier: Responsible Party

PBS Number: Not reported

Cleanup Ceased: / /

Cleanup Meets Std: False

Last Inspection: / /

Recommended Penalty: Penalty Not Recommended

Spiller Cleanup Dt: / /

Enforcement Date: / /

Invstgn Complete: / /

UST Involvement: False

Spill Class: Not reported

Spill Closed Dt: / /

Corrective Action Plan Submitted: / /

Date Region Sent Summary to Central Office: / /

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Date Spill Entered In Computer Data File: 12/04/01
Date Spill Entered In Computer Data File: 10:38
Update Date: 12/10/01
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 10
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 10
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207

DEC Remarks: Not reported

Remark: DURING LOADING TANKER TRUCK, LOADER ARM FITTING LEAKED OR BROKE - SPILLING
APPROX 10 GAL OF FUEL OIL INTO CONTAINMENT AREA. ALL OF SPILL WAS CLEANED.

Region of Spill: 9
Spill Number: 9907444
Investigator: KAB
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 09/21/1999 08:25
Reported to Dept Date/Time: 09/21/99 08:47
SWIS: 14
Spiller Name: NONE - DRILL
Spiller Contact: Not reported
Spiller Phone: () -
Spiller Contact: DON SHELDON
Spiller Phone: (716) 827-5127
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Equipment Failure
Reported to Dept: Surface Water
Water Affected: BUFFALO
Spill Source: 10
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: No spill occured. No DEC Response. No corrective action required.
Spill Closed Dt: 09/22/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 09/21/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 09/27/99
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207

DEC Remarks: 09/22/99: KAB RECEIVED REPORT. THIS WAS A DRILL; THERE WAS NO ACTUAL SPILL. NO ACTION NECESSARY. CLOSE OUT.

Remark: *****DRILL*****DRILL*****DRILL***** VESSEL NAME DOUG FLUTIE. OFF-LOADING LINE BROKE. CALLER BELIEVES THAT ALL 20000 GALLONS WENT INTO THE RIVER. NRC CONTACTED. FURTHER INFORMATION TO FOLLOW.

AIRS:

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: 100414
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 6
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: 108383
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: 108883
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 32
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 28
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: 71432
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 6
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: 91203
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 1
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: 95487
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: 98828

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 4
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RDSFP
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.2775
Unit: TON

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: 100414
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 4
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: 108383
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: 108883
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 48
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: 110543
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 59
Unit: LB

County Fips: 36029
DEC Id: 9140200600

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 19
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: 1634044
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 36
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: 540841
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 30
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: 71432
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 33
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: RGSFP
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 1.8555
Unit: TON

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: 100414
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 13
Unit: LB

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: 108383
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: 108883
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 170
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: 110543
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 210
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 65
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: 1634044
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 126
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: 540841
Epa Control Code: Not reported
Contol Eff: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Emissions: 105
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: 71432
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 118
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1RACK1
Process Id: TTVFP
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 6.55
Unit: TON

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 100414
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 6
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 108383
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 108883
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 22
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Contaminant Name/cas: 110543
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 14
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 25
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 1634044
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 6
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 540841
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 34
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 71432
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 9
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 91203
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 1
Unit: LB

County Fips: 36029

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: 92524
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: FG1FP
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.408
Unit: TON

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: 100414
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 72
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: 108383
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: 108883
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 936
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: 110543
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 1153

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Control Eff: Not reported
Emissions: 359
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: 1634044
Epa Control Code: Not reported
Control Eff: Not reported
Emissions: 690
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: 540841
Epa Control Code: Not reported
Control Eff: Not reported
Emissions: 575
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: 71432
Epa Control Code: Not reported
Control Eff: Not reported
Emissions: 648
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: 1TANKS
Process Id: GASFP
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Control Eff: Not reported
Emissions: 36
Unit: TON

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 100414

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 13
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 108383
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 108883
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 63
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 108952
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 55
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 71432
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 11
Unit: LB

County Fips: 36029
DEC Id: 9140200600

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 91203
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 1
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 95487
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: 98828
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 7
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E04EI
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.5495
Unit: TON

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E05EI
Contaminant Name/cas: 108883
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E05EI
Contaminant Name/cas: 110543
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E05EI
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E05EI
Contaminant Name/cas: 71432
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E05EI
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0005
Unit: TON

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E06EI
Contaminant Name/cas: 100414
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 14
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E06EI
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 38
Unit: LB

County Fips: 36029
DEC Id: 9140200600
Emission Unit Id: EI0001
Process Id: E06EI
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXXONMOBIL OIL CORPORATION (Continued)

S101341711

Emissions: 0.0255
Unit: TON

County Fips: Not reported
DEC Id: 9140200600
Emission Unit Id: Not reported
Process Id: Not reported
Contaminant Name/cas: Not reported
Epa Control Code: Not reported
Control Eff: Not reported
Emissions: Not reported
Unit: Not reported

CBS:

CBS Number: 9-000326
Program Type: CBS
Dec Region: 9
Expiration Date: 2011/04/28
Facility Status: Active
UTMX: 186966.70295000
UTMY: 4752840.4527599

AO161 MOBIL OIL CORP
SE 635 ELK ST
> 1 BUFFALO, NY 14240
1.086 mi.
5732 ft. Site 2 of 2 in cluster AO

Relative:
Higher

Actual:
592 ft.

CERC-NFRAP:
Site ID: 0201389
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: Deferred to RCRA

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: MOBIL OIL CORP BUFFALO
Alias Address: Not reported
ERIE, NY

Program Priority:

Description: RCRA Deferral Audit

Description: RCRA Deferral - Lead Confirmed

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY
Date Started: Not reported
Date Completed: 06/01/1981
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: Not reported
Date Completed: 09/01/1984

CERC-NFRAP 1000253436
CORRACTS NYD002107019
RCRA-SQG
FINDS
MANIFEST
MANIFEST
NY Spills
NY Hist Spills

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Priority Level: Low priority for further assessment

Action: SITE INSPECTION

Date Started: 05/01/1985

Date Completed: 05/31/1985

Priority Level: Deferred to RCRA (Subtitle C)

Action: ARCHIVE SITE

Date Started: Not reported

Date Completed: 01/31/1997

Priority Level: Not reported

CORRACTS:

EPA ID: NYD002107019

EPA Region: 02

Area Name: SITEWIDE

Actual Date: 1/10/1994

Action: CA050 - RFA Completed

NAICS Code(s): 42471

Petroleum Bulk Stations and Terminals

Original schedule date: Not reported

Schedule end date: Not reported

EPA ID: NYD002107019

EPA Region: 02

Area Name: SITEWIDE

Actual Date: 1/19/1994

Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority

NAICS Code(s): 42471

Petroleum Bulk Stations and Terminals

Original schedule date: 03/31/1994

Schedule end date: Not reported

EPA ID: NYD002107019

EPA Region: 02

Area Name: SITEWIDE

Actual Date: 10/1/1993

Action: CA225YE - Stabilization Measures Evaluation, This facility ,is amenable to stabilization activity based on the, status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations

NAICS Code(s): 42471

Petroleum Bulk Stations and Terminals

Original schedule date: 12/31/1993

Schedule end date: Not reported

RCRA-SQG:

Date form received by agency: 01/01/2007

Facility name: EXXONMOBIL OIL CORP 3140

Facility address: 625 ELK ST

BUFFALO, NY 142102236

EPA ID: NYD002107019

Mailing address: NORTHCHASE DR - ROOM 911

HOUSTON, TX 77060

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Contact: DALE VIATOR
Contact address: NORTHCHASE DR - ROOM 911
HOUSTON, TX 77060
Contact country: US
Contact telephone: (281) 671-8470
Contact email: DALE.VIATOR@EXXONMOBIL.COM
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: EXXON MOBIL OIL CORP
Owner/operator address: LAS COLINAS BLVD
IRVING, TX 73039
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/31/1979
Owner/Op end date: Not reported

Owner/operator name: MOBIL OIL CORPORATION BUFFALO REFINERY
Owner/operator address: PO BOX 367
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: (716) 827-5111
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: EXXONMOBIL OIL CORP
Owner/operator address: ELK ST
BUFFALO, NY 14210
Owner/operator country: Not reported
Owner/operator telephone: (716) 827-5127
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1936
Owner/Op end date: Not reported

Owner/operator name: EXXONMOBIL OIL CORP
Owner/operator address: ELK ST
BUFFALO, NY 14210
Owner/operator country: Not reported
Owner/operator telephone: (716) 827-5127
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1936
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: EXXONMOBIL OIL CORP 3140
Classification: Small Quantity Generator

Date form received by agency: 07/21/2005

Facility name: EXXONMOBIL OIL CORP 3140
Classification: Small Quantity Generator

Date form received by agency: 02/17/2004

Facility name: EXXONMOBIL OIL CORP 3140
Site name: EXXON MOBIL BUFFALO TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 09/26/2003

Facility name: EXXONMOBIL OIL CORP 3140
Site name: EXXONMOBIL BUFFALO TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/28/2002

Facility name: EXXONMOBIL OIL CORP 3140
Site name: EXXON MOBIL OIL CORP
Classification: Large Quantity Generator

Date form received by agency: 05/04/2001

Facility name: EXXONMOBIL OIL CORP 3140
Site name: MOBIL OIL CORP BUFFALO TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/27/1998

Facility name: EXXONMOBIL OIL CORP 3140
Site name: MOBIL/31010 BUFFALO TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/14/1992

Facility name: EXXONMOBIL OIL CORP 3140
Site name: MOBIL OIL
Classification: Large Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Date form received by agency: 03/01/1990

Facility name: EXXONMOBIL OIL CORP 3140

Site name: MOBIL OIL CORPORATION

Classification: Large Quantity Generator

Date form received by agency: 11/19/1980

Facility name: EXXONMOBIL OIL CORP 3140

Site name: MOBIL OIL CORP BUFFALO TERMINAL

Classification: Not a generator, verified

Date form received by agency: 08/18/1980

Facility name: EXXONMOBIL OIL CORP 3140

Site name: MOBIL OIL CORP BUFFALO TERMINAL

Classification: Large Quantity Generator

Date form received by agency: 12/31/1979

Facility name: EXXONMOBIL OIL CORP 3140

Site name: MOBIL OIL CORP BUFFALO TERMINAL

Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSLEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D008

Waste name: LEAD

Waste code: D009

Waste name: MERCURY

Waste code: D018

Waste name: BENZENE

Waste code: U061

Waste name: BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS(4-CHLORO-

Biennial Reports:

Last Biennial Reporting Year: 2007

Annual Waste Handled:

Waste code: D001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 2400

Waste code: D005
Waste name: BARIUM
Amount (Lbs): 13661

Waste code: D008
Waste name: LEAD
Amount (Lbs): 13661

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 2400

Corrective Action Summary:

Event date: 10/01/1993
Event: Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations.

Event date: 01/10/1994
Event: RFA Completed

Event date: 01/19/1994
Event: CA Prioritization, Facility or area was assigned a medium corrective action priority.

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 02/09/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/11/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 08/09/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Evaluation date: 06/17/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/11/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/13/1984
Evaluation: GROUNDWATER MONITORING EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

FINDS:

Registry ID: 110000326978

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

US Facility Response Plan (FRP) contains plans for responding, to the maximum extent practical, to worst case discharges of oil.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

NY MANIFEST:

EPA ID: NYD002107019
Country: USA
Mailing Name: EXXON MOBIL CORPORATION
Mailing Contact: ART POWERS
Mailing Address: 16825 NORTH CHASE DRIVE
Mailing Address 2: ROOM 911
Mailing City: HOUSTON
Mailing State: TX
Mailing Zip: 77060
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-827-5111

Document ID: NJA1855234
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 940125
Trans1 Recv Date: 940125
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940126
Part A Recv Date: 940202
Part B Recv Date: 940211
Generator EPA ID: NYD002107019
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: NJD053288239
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00450
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC2779244
Manifest Status: Completed copy
Trans1 State ID: NYRW9920
Trans2 State ID: Not reported
Generator Ship Date: 940125
Trans1 Recv Date: 940125

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Trans2 Recv Date: Not reported
TSD Site Recv Date: 940202
Part A Recv Date: 940202
Part B Recv Date: 940211
Generator EPA ID: NYD002107019
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00500
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: TXA0273198
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: MOD095038998
Generator Ship Date: 04/03/1998
Trans1 Recv Date: 04/03/1998
Trans2 Recv Date: 04/15/1998
TSD Site Recv Date: 04/20/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: TXD077603371
Trans2 EPA ID: Not reported
TSDF ID: 88888
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00800
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: CTF1144705
Manifest Status: Not reported
Trans1 State ID: CTD021816889
Trans2 State ID: Not reported
Generator Ship Date: 02/11/2003
Trans1 Recv Date: 02/11/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/17/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: CTD021816889
Trans2 EPA ID: Not reported
TSDF ID: V40376CT
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAQ0143677
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: OHD009865825
Generator Ship Date: 05/19/2003
Trans1 Recv Date: 05/19/2003
Trans2 Recv Date: 05/23/2003
TSD Site Recv Date: 05/24/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: MAD053452637

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Trans2 EPA ID: Not reported
TSDF ID: PWR38426
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00800
Units: P - Pounds
Number of Containers: 002
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: CTF0533235
Manifest Status: Not reported
Trans1 State ID: VTR000500090
Trans2 State ID: VTR000500090
Generator Ship Date: 12/23/2003
Trans1 Recv Date: 12/23/2003
Trans2 Recv Date: 12/29/2003
TSD Site Recv Date: 12/29/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: CTD021816889
Trans2 EPA ID: Not reported
TSDF ID: VI78C50
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 00500
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Mgmt Method Type Code: Not reported

Document ID: NYG3513015
Manifest Status: Not reported
Trans1 State ID: CTD021816889
Trans2 State ID: Not reported
Generator Ship Date: 11/14/2002
Trans1 Recv Date: 11/14/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/14/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: NYD080469935
Trans2 EPA ID: Not reported
TSDF ID: CTV56728
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 28880
Units: P - Pounds
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 02
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYG3513042
Manifest Status: Not reported
Trans1 State ID: CTD021816889
Trans2 State ID: Not reported
Generator Ship Date: 11/18/2002
Trans1 Recv Date: 11/18/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/18/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: NYD080469935
Trans2 EPA ID: Not reported
TSDF ID: AR6997NH
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 12720
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 02
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: ILA0019773
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: MAD039322250
Generator Ship Date: 09/09/2003
Trans1 Recv Date: 09/09/2003
Trans2 Recv Date: 09/13/2003
TSD Site Recv Date: 09/29/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: ILD000608471
Trans2 EPA ID: Not reported
TSD ID: UPW081074
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: U061 - DDT
Quantity: 00015
Units: P - Pounds
Number of Containers: 001
Container Type: CY - Cylinders
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00010
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: ILA0446638
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: MAD039322250
Generator Ship Date: 08/22/2003
Trans1 Recv Date: 08/22/2003
Trans2 Recv Date: 08/23/2003
TSD Site Recv Date: 09/11/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: ILD000608471
Trans2 EPA ID: Not reported
TSDF ID: 55855PANY
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 01500
Units: P - Pounds
Number of Containers: 005
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MDC1068642
Manifest Status: Not reported
Trans1 State ID: MAD039322250

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Trans2 State ID: Not reported
Generator Ship Date: 09/29/2003
Trans1 Recv Date: 09/29/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/30/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: MDD980555189
Trans2 EPA ID: Not reported
TSDF ID: HWH16000A
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 03128
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC7138168
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 07/22/2003
Trans1 Recv Date: 07/22/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/22/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002107019
Trans1 EPA ID: NYD981556541
Trans2 EPA ID: Not reported
TSDF ID: NY92865AT
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00040
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAC6985650
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 29852MA
Trans2 State ID: Not reported
Generator Ship Date: 900410
Trans1 Recv Date: 900410
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900411
Part A Recv Date: 900510
Part B Recv Date: 900529
Generator EPA ID: NYD002107019
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: Not reported
TSDF ID: MAD053452637
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 01630
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 028
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 90
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAC4457820
Manifest Status: Completed copy
Trans1 State ID: MA29603
Trans2 State ID: Not reported
Generator Ship Date: 891117
Trans1 Recv Date: 891117
Trans2 Recv Date: Not reported
TSD Site Recv Date: 891118
Part A Recv Date: 891127

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Part B Recv Date: 891130
Generator EPA ID: NYD002107019
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: Not reported
TSD ID: MAD053452637
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC2896143
Manifest Status: Completed copy
Trans1 State ID: NYRW9920
Trans2 State ID: Not reported
Generator Ship Date: 940405
Trans1 Recv Date: 940405
Trans2 Recv Date: 940411
TSD Site Recv Date: 940412
Part A Recv Date: 940420
Part B Recv Date: 940427
Generator EPA ID: NYD002107019
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ARD981908551
TSD ID: KYD053348108
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MAC4457810
Manifest Status: Completed copy
Trans1 State ID: MA-006T15
Trans2 State ID: MAD039322
Generator Ship Date: 890831
Trans1 Recv Date: 890831
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890901
Part A Recv Date: 890907
Part B Recv Date: 890911
Generator EPA ID: NYD002107019
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: Not reported
TSDF ID: MAD053452637
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00225
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: ARA4227120
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PCM064801
Trans2 State ID: PC711H11
Generator Ship Date: 891212
Trans1 Recv Date: 891212
Trans2 Recv Date: 891221
TSD Site Recv Date: 891227
Part A Recv Date: 891218
Part B Recv Date: 900112
Generator EPA ID: NYD002107019
Trans1 EPA ID: MOD095038998
Trans2 EPA ID: Not reported
TSDF ID: ARD069748192
Waste Code: F005 - UNKNOWN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Quantity: 04095
Units: P - Pounds
Number of Containers: 013
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: MDC0203646
Manifest Status: Completed copy
Trans1 State ID: HWH16089A
Trans2 State ID: Not reported
Generator Ship Date: 891122
Trans1 Recv Date: 891122
Trans2 Recv Date: Not reported
TSD Site Recv Date: 891122
Part A Recv Date: 891128
Part B Recv Date: 891215
Generator EPA ID: NYD002107019
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: Not reported
TSDF ID: MDD980555189
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 04400
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 080
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 89
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Document ID:	MDC0203647
Manifest Status:	Completed copy
Trans1 State ID:	16089A221
Trans2 State ID:	Not reported
Generator Ship Date:	891127
Trans1 Recv Date:	891127
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891128
Part A Recv Date:	891205
Part B Recv Date:	891215
Generator EPA ID:	NYD002107019
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	Not reported
TSDF ID:	MDD980555189
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	01045
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	019
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	12600
Units:	P - Pounds
Number of Containers:	021
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported
Document ID:	NYA5836113
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	MA670402
Trans2 State ID:	Not reported
Generator Ship Date:	900410
Trans1 Recv Date:	900410
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900411
Part A Recv Date:	900511
Part B Recv Date:	900622
Generator EPA ID:	NYD002107019
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	Not reported
TSDF ID:	OHD004178612

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 02218
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 90
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

[Click this hyperlink](#) while viewing on your computer to access
345 additional NY_MANIFEST: record(s) in the EDR Site Report.

PA MANIFEST:

Manifest Number: 000240200JJK
Manifest Type: T
Generator Epa Id: NYD002107019
Generator Date: 4/30/2008
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD Epa Id: MID980991566
TSD Date: Not reported
TSD Facility Name: EQ DETROIT INC
TSD Facility Address: 1923 FREDERICK STREET
TSD Facility City: DETROIT
TSD Facility State: MI
Facility Telephone: 716-827-5127
Page Number: 1
Line Number: 1
Waste Number: D009
Container Number: 1
Container Type: DF
Waste Quantity: 6
Unit: P
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

NY Spills:

Site ID: 201212
Facility Addr2: Not reported
Facility ID: 8703102
Spill Number: 8703102

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Facility Type: ER
SWIS: 1502
Investigator: MJHINTON
Referred To: Not reported
Spill Date: 7/17/1987
Reported to Dept: 7/17/1987
CID: 30
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Major Facility > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: 8/4/1987
Cleanup Meets Std: True
Last Inspection: 8/4/1987
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Not reported
Spill Closed Dt: 8/4/1987
Remediation Phase: 0
Date Entered In Computer: 7/20/1987
Spill Record Last Update: 8/5/1987
Spiller Name: Not reported
Spiller Company: MOBIL OIL CORP.
Spiller Address: 1 BABCOCK STREET
Spiller City,St,Zip: BUFFALO, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 9
DER Facility ID: 167404
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MJH" // : MJH TELECON 07/17/87, PRODUCT FOUND IN TRENCH EXCAVATION,
MOBIL CLEANED UP ONE GALLON. // : 7/31/87 TELECON W/ECO KUCZKA,
GASOLINE IN DITCH;8/4/87 MJH INSP. CLEANUP BY MOBIL SATISFACTORY, NO
FURTHER ACTION NEEDED. // : MJH SITE VISIT 8/4/87 NO PROBLEMS
REPORTED BY NFG EMPLOYEES NOTHING OBSERVED IN TRENCH NO FURTHER
ACTION BY SPILL GROUP.
Remarks: GASOLINE FOUND IN TRENCH
Material:
Site ID: 201212
Operable Unit ID: 907130
Operable Unit: 01
Material ID: 469364
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Groundwater
Oxygenate: False
Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:

Region of Spill: 9
Spill Number: 8703102
Investigator: MJH
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 07/17/1987 11:30
Reported to Dept Date/Time: 07/17/87 11:45
SWIS: 14
Spiller Name: MOBIL
Spiller Contact: Not reported
Spiller Phone: (716) 827-5127
Spiller Address: 1 BABCOCK STREET
Spiller City,St,Zip: BUFFALO, NY
Spill Cause: Unknown
Reported to Dept: Groundwater
Water Affected: Not reported
Spill Source: 03
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: 08/04/87
Cleanup Meets Std: True
Last Inspection: 08/04/87
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 08/04/87
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/20/87
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/05/87
Is Updated: False

Tank:

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP (Continued)

1000253436

Gross Leak Rate: Not reported

Material:

Material Class Type: Petroleum

Quantity Spilled: 1

Unkonwn Quantity Spilled: False

Units: Gallons

Quantity Recovered: 1

Unkonwn Quantity Recovered: False

Material: GASOLINE

Class Type: GASOLINE

Times Material Entry In File: 21329

CAS Number: Not reported

Last Date: 19940929

DEC Remarks: / / : MJH TELECON 07/17/87, PRODUCT FOUND IN TRENCH EXCAVATION, MOBIL
CLEANED UP ONE GALLON. / / : 7/31/87 TELECON W/ECO KUCZKA, GASOLINE IN
DITCH;8/4/87 MJH INSP. CLEANUP BY MOBIL SATISFACTORY, NO FURTHER ACTION NEEDED.
/ / : MJH SITEVISIT 8/4/87 NO PROBLEMS REPORTED BY NFG EMPLOYEES NOTHING
OBSERVED IN TRENCH NO FURTHER ACTION BY SPILL GROUP.

Remark: GASOLINE FOUND IN TRENCH

162
WNW
> 1
1.199 mi.
6330 ft.

NIKE BU 09

FUDS 1007372646
N/A

BUFFALO, NY

Relative:
Higher

Actual:
604 ft.

FUDS:

Federal Facility ID: NY9799F1084

FUDS #: C02NY0091

INST ID: 59097

Facility Name: NIKE BU 09

City: Buffalo

State: NY

EPA Region: 2

County: ERIE

Congressional District: 27

US Army District: New England District (NAE)

Fiscal Year: 2008

Telephone: 978-318-8238

NPL Status: Not Listed

RAB: Not reported

CTC: Not reported

Current Owner: CITY; PRIVATE

FUDS Description Details:

THE SITE IS NOW UNDER BENEFICIAL OCCUPATION BY SEVERAL OWNERS

FUDS History Details:

Consists of 128.13 acres , acquired by Gov. for a Nike missile program
in Nlagara Falls, Buffalo. 4 Jun 1962 16.73 acres fee and 4.24 acres
in easements reassigned to ARCtr. 2 Nov 1972 16.73 acres f ee and 4.24
acres in easement conveyed to Amherst,
current owner. 33.29 acres fee and 73.87n acres in easements interests
excessed to GSA on 6 Jul 1965.

FUDS Current Program Details:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NIKE BU 09 (Continued)

1007372646

FUDS Future Program Details:

163
SSW
> 1
1.211 mi.
6394 ft.

SAFETY-KLEEN CORP
FOOT OF KATHERINE ST
BUFFALO, NY 14205

CORRACTS 1000406321
RCRA-SQG NYD980593842
PADS
FINDS
MANIFEST

Relative:
Lower

CORRACTS:

Actual:
585 ft.

EPA ID: NYD980593842
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 9/18/1995
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 324191
Petroleum Lubricating Oil and Grease Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-SQG:

Date form received by agency: 01/01/2007
Facility name: SAFETY-KLEEN SYSTEMS INC BUFFALO
Facility address: 60 KATHERINE ST
BUFFALO, NY 14210
EPA ID: NYD980593842
Mailing address: KATHERINE ST
BUFFALO, NY 14210
Contact: DANIEL HOLDNACK
Contact address: KATHERINE ST
BUFFALO, NY 14210
Contact country: US
Contact telephone: (212) 555-1212
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: BOOTH OIL CO INC
Owner/operator address: PO BOX 18
BUFFALO, NY 14205
Owner/operator country: US
Owner/operator telephone: (716) 855-2212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported
Owner/operator name: SAFETY KLEEN SYSTEMS INC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Owner/operator address: 301 GERVAIS ST SUITE 300
COLUMBIA, SC 29201
Owner/operator country: US
Owner/operator telephone: (803) 933-4200
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibility indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: Yes
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: Yes
Used oil transfer facility: No
Used oil transporter: Yes
Off-site waste receiver: Accepts waste from (any) off-site source(s)

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: SAFETY-KLEEN SYSTEMS INC BUFFALO
Classification: Small Quantity Generator

Date form received by agency: 01/01/2001
Facility name: SAFETY-KLEEN SYSTEMS INC BUFFALO
Site name: SAFETY KLEEN SYSTEMS INC
Classification: Large Quantity Generator

Date form received by agency: 01/11/1999
Facility name: SAFETY-KLEEN SYSTEMS INC BUFFALO
Classification: Small Quantity Generator

Date form received by agency: 03/30/1995
Facility name: SAFETY-KLEEN SYSTEMS INC BUFFALO
Classification: Unverified

Date form received by agency: 09/25/1990
Facility name: SAFETY-KLEEN SYSTEMS INC BUFFALO
Classification: Not a generator, verified

Corrective Action Summary:

Event date: 09/18/1995
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 11/29/1990
Date achieved compliance: 08/23/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 07/27/1987
Date achieved compliance: 12/13/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 02/11/1987
Date achieved compliance: 04/29/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/25/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 02/11/1987
Date achieved compliance: 12/13/1988
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 07/24/1986
Date achieved compliance: 09/10/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/29/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 04/02/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 03/23/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/15/2006
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/21/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 01/31/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/27/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/26/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA Contractor/Grantee

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Evaluation date: 11/14/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 08/23/1993
Evaluation lead agency: State

Evaluation date: 11/15/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/13/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/14/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 12/18/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/27/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 12/13/1988
Evaluation lead agency: State

Evaluation date: 02/11/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 04/29/1987
Evaluation lead agency: State

Evaluation date: 02/11/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 12/13/1988
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 07/24/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 09/10/1986
Evaluation lead agency: State

Evaluation date: 07/24/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 11/26/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110000616619

Environmental Interest/Information System

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD980593842
Country: USA
Mailing Name: SAFETY-KLEEN SYSTEMS
Mailing Contact: DAN HOLDNACK
Mailing Address: 60 KATHERINE ST
Mailing Address 2: Not reported
Mailing City: BUFFALO
Mailing State: NY
Mailing Zip: 14210
Mailing Zip4: 2006
Mailing Country: USA
Mailing Phone: 716-855-2212

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 4/20/2007
Trans1 Recv Date: 4/20/2007
Trans2 Recv Date: 5/2/2007
TSD Site Recv Date: 5/3/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000023341SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 4/20/2007
Trans1 Recv Date: 4/20/2007
Trans2 Recv Date: 5/2/2007
TSD Site Recv Date: 5/3/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 900
Units: P - Pounds
Number of Containers: 3
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000023356SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 1/26/2007
Trans1 Recv Date: 1/26/2007
Trans2 Recv Date: 2/1/2007
TSD Site Recv Date: 2/2/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 1200
Units: P - Pounds
Number of Containers: 3
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000106685CEX
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 8/9/2007
Trans1 Recv Date: 8/9/2007
Trans2 Recv Date: 8/17/2007
TSD Site Recv Date: 8/19/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 350
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000256091SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 10/5/2007
Trans1 Recv Date: 10/5/2007
Trans2 Recv Date: 10/19/2007
TSD Site Recv Date: 10/23/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 700
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000260554SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Trans1 State ID: TXR000050930
Trans2 State ID: NJD986607380
Generator Ship Date: 6/15/2007
Trans1 Recv Date: 6/15/2007
Trans2 Recv Date: 6/25/2007
TSD Site Recv Date: 6/27/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: KYD053348108
Waste Code: Not reported
Quantity: 700
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000541715SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 11/16/2007
Trans1 Recv Date: 11/16/2007
Trans2 Recv Date: 11/30/2007
TSD Site Recv Date: 12/1/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: KYD053348108
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 000541956SKS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: PAE7621526
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: Not reported
Generator Ship Date: 08/27/1998
Trans1 Recv Date: 08/27/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/11/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: PAD987367216
Trans2 EPA ID: Not reported
TSD ID: PAAH0172
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: PAE7621784
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: SCD987574647
Generator Ship Date: 12/15/1998
Trans1 Recv Date: 12/15/1998
Trans2 Recv Date: 12/18/1998
TSD Site Recv Date: 12/30/1998

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: PAD981113749
Trans2 EPA ID: Not reported
TSD ID: PAAH0172
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 00015
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: PAG1668020
Manifest Status: Not reported
Trans1 State ID: OHD038093688
Trans2 State ID: Not reported
Generator Ship Date: 05/07/2002
Trans1 Recv Date: 05/07/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/08/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: PAD987270725
Trans2 EPA ID: Not reported
TSD ID: PAAH0267
Waste Code: U188 - PHENOL
Quantity: 06518
Units: P - Pounds
Number of Containers: 018
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 02
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC6933262
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 09/05/2003
Trans1 Recv Date: 09/05/2003
Trans2 Recv Date: 09/12/2003
TSD Site Recv Date: 09/16/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: KYD053348108
Trans2 EPA ID: Not reported
TSDF ID: NYC10826J
Waste Code: F005 - UNKNOWN
Quantity: 00500
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 03
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC7140060
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 05/07/2003
Trans1 Recv Date: 05/07/2003
Trans2 Recv Date: 05/09/2003
TSD Site Recv Date: 05/12/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: KYD053348108
Trans2 EPA ID: Not reported
TSDF ID: NYC10826J

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Waste Code:	F005 - UNKNOWN
Quantity:	01000
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F003 - UNKNOWN
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	03
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported
Document ID:	NYB4229721
Manifest Status:	Completed copy
Trans1 State ID:	NYHA1800
Trans2 State ID:	Not reported
Generator Ship Date:	941011
Trans1 Recv Date:	941011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	941011
Part A Recv Date:	Not reported
Part B Recv Date:	941025
Generator EPA ID:	NYD980593842
Trans1 EPA ID:	NYD006994040
Trans2 EPA ID:	Not reported
TSD ID:	NYD000818781
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00036
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC4097081
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: Not reported
Generator Ship Date: 03/16/1999
Trans1 Recv Date: 03/16/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/16/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: KYD053348108
Trans2 EPA ID: Not reported
TSD ID: 11590DNY
Waste Code: F005 - UNKNOWN
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC4097136
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: Not reported
Generator Ship Date: 05/20/1999
Trans1 Recv Date: 05/20/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/27/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: KYD053348108
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

TSD ID:	ILT104414
Waste Code:	F005 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F005 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported
Document ID:	NYC4097171
Manifest Status:	Not reported
Trans1 State ID:	NYD980769947
Trans2 State ID:	Not reported
Generator Ship Date:	08/16/1999
Trans1 Recv Date:	08/16/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/16/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980593842
Trans1 EPA ID:	OHD986975399
Trans2 EPA ID:	Not reported
TSD ID:	10239PNY
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	18159
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC4097182
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: Not reported
Generator Ship Date: 08/17/1999
Trans1 Recv Date: 08/17/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/17/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: OHD986975399
Trans2 EPA ID: Not reported
TSDF ID: 10239PNY
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 09273
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC4097237
Manifest Status: Not reported
Trans1 State ID: NYD980769947
Trans2 State ID: Not reported
Generator Ship Date: 07/16/1999
Trans1 Recv Date: 07/16/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/18/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: KYD053348108

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Trans2 EPA ID: Not reported
TSDF ID: 12610P
Waste Code: F005 - UNKNOWN
Quantity: 00400
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB8514936
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: Not reported
Generator Ship Date: 10/21/1999
Trans1 Recv Date: 10/21/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/29/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: KYD053348108
Trans2 EPA ID: Not reported
TSDF ID: NJT913LY
Waste Code: F005 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F005 - UNKNOWN
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SAFETY-KLEEN CORP (Continued)

1000406321

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2009-05-22
Trans1 Recv Date: 2009-05-22
Trans2 Recv Date: 2009-06-03
TSD Site Recv Date: 2009-06-04
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980593842
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 150.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000542422SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

[Click this hyperlink](#) while viewing on your computer to access
93 additional NY_MANIFEST: record(s) in the EDR Site Report.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BUFFALO	100553260	NEW YORK STATE THRUWAY AUTHORITY	SELKIRK STREET BIN 5512239	14210	FINDS,RCRA-NLR,MANIFEST
BUFFALO	1008178854	DOLLAR TREE	153 RT 78	14210	FTTS,HIST FTTS INSP
BUFFALO	1008182050	HOME DEPOT	4139 RT 78	14210	FTTS,HIST FTTS INSP
BUFFALO	1009231905	CONSOLIDATED RAIL CORP	SENECA YARD	14210	MANIFEST
BUFFALO	1009244576	NIAGARA TRANSFORMER CORP	1600 SENECA ST NYT370011223	14210	MANIFEST
BUFFALO	S100493920	UNKNOWN TRUCK	ROUTE 198 EAST		LTANKS,HIST LTANKS
BUFFALO	S102174044	BOAT SUNK BUFFALO HARBOR	ROUTE 198 EAST		SPILLS,HIST SPILLS
BUFFALO	S102174058	CARGILL DRUMS	BUFFALO HARBOR - ROUTE 5		SPILLS,HIST SPILLS
BUFFALO	S102175440	NSYDOT PUMPHOUSE RT. 33	ROUTE 5		SPILLS,HIST SPILLS
BUFFALO	S102175597	BRENTON - BLUE LIQUID	ROUTE 33		SPILLS,HIST SPILLS
BUFFALO	S102175659	SCAJAQUADA EXPRY. OIL	ROUTE 198		SPILLS,HIST SPILLS
BUFFALO	S102177197	MOTOR OIL ON KENSINGTON	ROUTE 98		SPILLS,HIST SPILLS
BUFFALO	S102178402	FICEL TRUCKING	ROUTE 33		SPILLS,HIST SPILLS
BUFFALO	S102178515	TAR ON ROAD	ROUTE 5		SPILLS,HIST SPILLS
BUFFALO	S102178777	OIL ON ROUTE 33 WESTBOUND	ROUTE 198		SPILLS,HIST SPILLS
BUFFALO	S103562349	KIELSA TANKER	ROUTE 33 WEST		SPILLS,HIST SPILLS
BUFFALO	S106011350	FATHER BAKER BRIDGE	ROUTE 5 - BUFFALO HARBOR		SPILLS,HIST SPILLS
BUFFALO	S106018618	WWTP SLUDGE	ROUTE 5 / TIFFT ST		SPILLS
LACKAWANNA (C)	S108667393	LACKAWANNA BUSINESS PARK	ROUTE 5 AT TIFFT		SPILLS
BUFFALO	S109581915	OIL ON ROAD	ROUTE 5 / SMOKES CREEK ON 'A'	14218	ERP
			ROUTE 33 AT HUMBOLDT		SPILLS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/01/2009	Source: EPA
Date Data Arrived at EDR: 10/14/2009	Telephone: N/A
Date Made Active in Reports: 11/09/2009	Last EDR Contact: 11/13/2009
Number of Days to Update: 26	Next Scheduled EDR Contact: 01/25/2010
	Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/01/2009	Source: EPA
Date Data Arrived at EDR: 10/14/2009	Telephone: N/A
Date Made Active in Reports: 11/09/2009	Last EDR Contact: 11/13/2009
Number of Days to Update: 26	Next Scheduled EDR Contact: 01/25/2010
	Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991	Source: EPA
Date Data Arrived at EDR: 02/02/1994	Telephone: 202-564-4267
Date Made Active in Reports: 03/30/1994	Last EDR Contact: 08/17/2009
Number of Days to Update: 56	Next Scheduled EDR Contact: 11/16/2009
	Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/01/2009	Source: EPA
Date Data Arrived at EDR: 10/14/2009	Telephone: N/A
Date Made Active in Reports: 11/09/2009	Last EDR Contact: 11/13/2009
Number of Days to Update: 26	Next Scheduled EDR Contact: 01/25/2010
	Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/30/2009	Source: EPA
Date Data Arrived at EDR: 08/11/2009	Telephone: 703-412-9810
Date Made Active in Reports: 09/21/2009	Last EDR Contact: 11/23/2009
Number of Days to Update: 41	Next Scheduled EDR Contact: 01/11/2010
	Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 06/23/2009	Source: EPA
Date Data Arrived at EDR: 09/02/2009	Telephone: 703-412-9810
Date Made Active in Reports: 09/21/2009	Last EDR Contact: 11/24/2009
Number of Days to Update: 19	Next Scheduled EDR Contact: 03/15/2010
	Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 09/15/2009	Source: EPA
Date Data Arrived at EDR: 09/22/2009	Telephone: 800-424-9346
Date Made Active in Reports: 11/09/2009	Last EDR Contact: 11/16/2009
Number of Days to Update: 48	Next Scheduled EDR Contact: 03/01/2010
	Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Transporters, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 11/12/2008
Date Data Arrived at EDR: 11/18/2008
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 118

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 11/18/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/12/2008
Date Data Arrived at EDR: 11/18/2008
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 118

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 11/18/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 11/12/2008
Date Data Arrived at EDR: 11/18/2008
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 118

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 11/18/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/12/2008
Date Data Arrived at EDR: 11/18/2008
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 118

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 11/18/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/01/2009
Date Data Arrived at EDR: 10/09/2009
Date Made Active in Reports: 11/09/2009
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 12/10/2009
Next Scheduled EDR Contact: 03/29/2010
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/01/2009	Source: Environmental Protection Agency
Date Data Arrived at EDR: 10/09/2009	Telephone: 703-603-0695
Date Made Active in Reports: 11/09/2009	Last EDR Contact: 12/10/2009
Number of Days to Update: 31	Next Scheduled EDR Contact: 03/29/2010
	Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 08/31/2009	Source: National Response Center, United States Coast Guard
Date Data Arrived at EDR: 09/17/2009	Telephone: 202-267-2180
Date Made Active in Reports: 11/09/2009	Last EDR Contact: 10/06/2009
Number of Days to Update: 53	Next Scheduled EDR Contact: 01/18/2010
	Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 11/23/2009	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 11/24/2009	Telephone: 518-402-9622
Date Made Active in Reports: 12/09/2009	Last EDR Contact: 11/24/2009
Number of Days to Update: 15	Next Scheduled EDR Contact: 03/08/2010
	Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrusion Legacy Site List

"Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil. Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for exposures from the soil vapor intrusion pathway. Based on this additional information, New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 07/14/2009	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 09/09/2009	Telephone: 518-402-9814
Date Made Active in Reports: 09/21/2009	Last EDR Contact: 12/04/2009
Number of Days to Update: 12	Next Scheduled EDR Contact: 03/08/2010
	Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/14/2009
Date Data Arrived at EDR: 10/15/2009
Date Made Active in Reports: 11/06/2009
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 10/13/2009
Next Scheduled EDR Contact: 01/25/2010
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 11/23/2009
Date Data Arrived at EDR: 11/24/2009
Date Made Active in Reports: 12/09/2009
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/24/2009
Date Data Arrived at EDR: 09/10/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 42

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 10/30/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 03/24/2009
Date Data Arrived at EDR: 05/20/2009
Date Made Active in Reports: 06/17/2009
Number of Days to Update: 28

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 11/04/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 08/24/2009
Date Data Arrived at EDR: 08/26/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 26

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 10/30/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/19/2009	Source: EPA Region 1
Date Data Arrived at EDR: 02/19/2009	Telephone: 617-918-1313
Date Made Active in Reports: 03/16/2009	Last EDR Contact: 10/30/2009
Number of Days to Update: 25	Next Scheduled EDR Contact: 02/15/2010
	Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 08/20/2009	Source: EPA Region 10
Date Data Arrived at EDR: 08/21/2009	Telephone: 206-553-2857
Date Made Active in Reports: 09/21/2009	Last EDR Contact: 10/30/2009
Number of Days to Update: 31	Next Scheduled EDR Contact: 02/15/2010
	Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 08/21/2009	Source: Environmental Protection Agency
Date Data Arrived at EDR: 10/06/2009	Telephone: 415-972-3372
Date Made Active in Reports: 10/22/2009	Last EDR Contact: 10/30/2009
Number of Days to Update: 16	Next Scheduled EDR Contact: 02/15/2010
	Data Release Frequency: Quarterly

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 08/20/2009	Source: EPA Region 4
Date Data Arrived at EDR: 08/26/2009	Telephone: 404-562-8677
Date Made Active in Reports: 10/22/2009	Last EDR Contact: 10/30/2009
Number of Days to Update: 57	Next Scheduled EDR Contact: 02/15/2010
	Data Release Frequency: Semi-Annually

State and tribal registered storage tank lists

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 10/06/2009	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 10/07/2009	Telephone: 518-402-9549
Date Made Active in Reports: 11/03/2009	Last EDR Contact: 10/07/2009
Number of Days to Update: 27	Next Scheduled EDR Contact: 01/18/2010
	Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002	Source: NYSDEC
Date Data Arrived at EDR: 02/20/2002	Telephone: 518-402-9549
Date Made Active in Reports: 03/22/2002	Last EDR Contact: 10/24/2005
Number of Days to Update: 30	Next Scheduled EDR Contact: 01/23/2006
	Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: Varies

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 10/06/2009
Date Data Arrived at EDR: 10/07/2009
Date Made Active in Reports: 11/03/2009
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/07/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 10/06/2009
Date Data Arrived at EDR: 10/07/2009
Date Made Active in Reports: 11/06/2009
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/07/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 10/06/2009
Date Data Arrived at EDR: 10/07/2009
Date Made Active in Reports: 11/06/2009
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/07/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 04/01/2008
Date Data Arrived at EDR: 12/30/2008
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 76

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 11/04/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 08/21/2009
Date Data Arrived at EDR: 08/26/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 57

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 10/30/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 08/24/2009
Date Data Arrived at EDR: 09/10/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 42

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 10/30/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Quarterly

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 08/20/2009
Date Data Arrived at EDR: 08/26/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 57

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 10/30/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Semi-Annually

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 08/20/2009
Date Data Arrived at EDR: 08/21/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 31

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/30/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Quarterly

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 02/19/2009
Date Data Arrived at EDR: 02/19/2009
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 25

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/30/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 08/24/2009
Date Data Arrived at EDR: 08/26/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 26

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 10/30/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 09/08/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 10/16/2008
Number of Days to Update: 27

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 10/22/2009
Next Scheduled EDR Contact: 11/16/2009
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 11/23/2009
Date Data Arrived at EDR: 11/24/2009
Date Made Active in Reports: 12/09/2009
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 11/23/2009
Date Data Arrived at EDR: 11/24/2009
Date Made Active in Reports: 12/09/2009
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Quarterly

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 12/31/1992
Date Data Arrived at EDR: 01/31/2007
Date Made Active in Reports: 04/19/2007
Number of Days to Update: 78

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 09/30/2009
Next Scheduled EDR Contact: 01/11/2010
Data Release Frequency: No Update Planned

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 04/02/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 10/05/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 11/23/2009
Date Data Arrived at EDR: 11/24/2009
Date Made Active in Reports: 12/09/2009
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a \$200 million Environmental Restoration or Brownfields Fund as part of the \$1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 11/23/2009
Date Data Arrived at EDR: 11/24/2009
Date Made Active in Reports: 12/09/2009
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 11/23/2009
Date Data Arrived at EDR: 11/24/2009
Date Made Active in Reports: 12/09/2009
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 07/01/2009
Date Data Arrived at EDR: 09/11/2009
Date Made Active in Reports: 11/09/2009
Number of Days to Update: 59

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 11/04/2009
Next Scheduled EDR Contact: 01/11/2010
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-972-3336
Last EDR Contact: 12/08/2009
Next Scheduled EDR Contact: 03/22/2010
Data Release Frequency: Varies

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 10/14/2009
Date Data Arrived at EDR: 10/15/2009
Date Made Active in Reports: 11/06/2009
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 10/13/2009
Next Scheduled EDR Contact: 01/25/2010
Data Release Frequency: Semi-Annually

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 11/04/2009
Next Scheduled EDR Contact: 02/08/2010
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 11/09/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 03/01/2009
Date Data Arrived at EDR: 06/22/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 91

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 12/14/2009
Next Scheduled EDR Contact: 03/22/2010
Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 06/09/2009
Date Data Arrived at EDR: 06/11/2009
Date Made Active in Reports: 07/01/2009
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 08/18/2009
Date Data Arrived at EDR: 08/21/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 11/02/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005
Date Data Arrived at EDR: 12/11/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 31

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/20/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 10/05/2009
Date Data Arrived at EDR: 10/05/2009
Date Made Active in Reports: 11/09/2009
Number of Days to Update: 35

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 10/05/2009
Next Scheduled EDR Contact: 01/11/2010
Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 11/23/2009
Date Data Arrived at EDR: 11/24/2009
Date Made Active in Reports: 12/09/2009
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA-NonGen: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 11/12/2008
Date Data Arrived at EDR: 11/18/2008
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 118

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 11/18/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transportation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 08/12/2009
Date Data Arrived at EDR: 08/27/2009
Date Made Active in Reports: 12/01/2009
Number of Days to Update: 96

Source: Department of Transportation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 11/10/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 703-692-8801
Last EDR Contact: 10/23/2009
Next Scheduled EDR Contact: 02/01/2010
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 09/30/2009
Date Made Active in Reports: 12/01/2009
Number of Days to Update: 62

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 09/30/2009
Next Scheduled EDR Contact: 12/28/2009
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 08/03/2009
Date Data Arrived at EDR: 10/27/2009
Date Made Active in Reports: 11/09/2009
Number of Days to Update: 13

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 10/06/2009
Next Scheduled EDR Contact: 01/18/2010
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 09/01/2009
Date Data Arrived at EDR: 09/22/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 30

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/22/2009
Next Scheduled EDR Contact: 12/28/2009
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 01/05/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 05/08/2009
Number of Days to Update: 1

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/30/2009
Next Scheduled EDR Contact: 03/15/2010
Data Release Frequency: Varies

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/07/2009
Date Data Arrived at EDR: 09/18/2009
Date Made Active in Reports: 11/09/2009
Number of Days to Update: 52

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 12/08/2009
Next Scheduled EDR Contact: 03/22/2010
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2007
Date Data Arrived at EDR: 04/09/2009
Date Made Active in Reports: 06/17/2009
Number of Days to Update: 69

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 12/01/2009
Next Scheduled EDR Contact: 03/15/2010
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2002
Date Data Arrived at EDR: 04/14/2006
Date Made Active in Reports: 05/30/2006
Number of Days to Update: 46

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 10/07/2009
Next Scheduled EDR Contact: 01/11/2010
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 12/14/2009
Next Scheduled EDR Contact: 03/15/2010
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009	Source: EPA
Date Data Arrived at EDR: 04/16/2009	Telephone: 202-566-1667
Date Made Active in Reports: 05/11/2009	Last EDR Contact: 12/14/2009
Number of Days to Update: 25	Next Scheduled EDR Contact: 03/15/2010
	Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/01/2007	Telephone: 202-564-2501
Date Made Active in Reports: 04/10/2007	Last EDR Contact: 12/17/2007
Number of Days to Update: 40	Next Scheduled EDR Contact: 03/17/2008
	Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/01/2007	Telephone: 202-564-2501
Date Made Active in Reports: 04/10/2007	Last EDR Contact: 12/17/2008
Number of Days to Update: 40	Next Scheduled EDR Contact: 03/17/2008
	Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2007	Source: EPA
Date Data Arrived at EDR: 05/19/2009	Telephone: 202-564-4203
Date Made Active in Reports: 09/21/2009	Last EDR Contact: 11/02/2009
Number of Days to Update: 125	Next Scheduled EDR Contact: 02/15/2010
	Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 08/21/2009	Source: Environmental Protection Agency
Date Data Arrived at EDR: 08/27/2009	Telephone: 202-564-5088
Date Made Active in Reports: 10/22/2009	Last EDR Contact: 09/28/2009
Number of Days to Update: 56	Next Scheduled EDR Contact: 01/11/2010
	Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

PADS: PCB Activity Database System

PCB Activity Database. PADS identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/01/2009	Source: EPA
Date Data Arrived at EDR: 10/21/2009	Telephone: 202-566-0500
Date Made Active in Reports: 12/01/2009	Last EDR Contact: 10/21/2009
Number of Days to Update: 41	Next Scheduled EDR Contact: 02/01/2010
	Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/06/2009	Source: Nuclear Regulatory Commission
Date Data Arrived at EDR: 07/13/2009	Telephone: 301-415-7169
Date Made Active in Reports: 09/21/2009	Last EDR Contact: 12/14/2009
Number of Days to Update: 70	Next Scheduled EDR Contact: 03/29/2010
	Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 10/15/2009	Source: Environmental Protection Agency
Date Data Arrived at EDR: 10/16/2009	Telephone: 202-343-9775
Date Made Active in Reports: 12/01/2009	Last EDR Contact: 10/16/2009
Number of Days to Update: 46	Next Scheduled EDR Contact: 01/25/2010
	Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 10/19/2009	Source: EPA
Date Data Arrived at EDR: 10/22/2009	Telephone: (212) 637-3000
Date Made Active in Reports: 12/01/2009	Last EDR Contact: 12/10/2009
Number of Days to Update: 40	Next Scheduled EDR Contact: 03/29/2010
	Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995	Source: EPA
Date Data Arrived at EDR: 07/03/1995	Telephone: 202-564-4104
Date Made Active in Reports: 08/07/1995	Last EDR Contact: 06/02/2008
Number of Days to Update: 35	Next Scheduled EDR Contact: 09/01/2008
	Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/2007
Date Data Arrived at EDR: 02/19/2009
Date Made Active in Reports: 05/22/2009
Number of Days to Update: 92

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 11/20/2009
Next Scheduled EDR Contact: 03/05/2010
Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 10/27/2009
Date Data Arrived at EDR: 11/10/2009
Date Made Active in Reports: 12/09/2009
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 11/10/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 10/01/2009
Date Data Arrived at EDR: 10/02/2009
Date Made Active in Reports: 11/06/2009
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 09/23/2009
Next Scheduled EDR Contact: 01/04/2010
Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 10/21/2009
Date Data Arrived at EDR: 10/22/2009
Date Made Active in Reports: 11/06/2009
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 10/19/2009
Next Scheduled EDR Contact: 02/01/2010
Data Release Frequency: No Update Planned

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 09/05/2007
Date Made Active in Reports: 10/17/2007
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 11/02/2009
Next Scheduled EDR Contact: 02/15/2010
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 07/29/2009	Source: New York City Department of City Planning
Date Data Arrived at EDR: 10/05/2009	Telephone: 718-595-6658
Date Made Active in Reports: 11/06/2009	Last EDR Contact: 09/30/2009
Number of Days to Update: 32	Next Scheduled EDR Contact: 01/11/2010
	Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005	Source: USGS
Date Data Arrived at EDR: 12/08/2006	Telephone: 202-208-3710
Date Made Active in Reports: 01/11/2007	Last EDR Contact: 10/23/2009
Number of Days to Update: 34	Next Scheduled EDR Contact: 02/01/2010
	Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 09/09/2009	Source: Environmental Protection Agency
Date Data Arrived at EDR: 09/09/2009	Telephone: 615-532-8599
Date Made Active in Reports: 10/22/2009	Last EDR Contact: 11/09/2009
Number of Days to Update: 43	Next Scheduled EDR Contact: 02/08/2010
	Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 10/14/2009	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 10/15/2009	Telephone: 518-402-8660
Date Made Active in Reports: 11/06/2009	Last EDR Contact: 10/13/2009
Number of Days to Update: 22	Next Scheduled EDR Contact: 01/25/2010
	Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 01/01/2008	Source: Environmental Protection Agency
Date Data Arrived at EDR: 02/18/2009	Telephone: 202-566-0517
Date Made Active in Reports: 05/29/2009	Last EDR Contact: 11/13/2009
Number of Days to Update: 100	Next Scheduled EDR Contact: 02/15/2010
	Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/23/2009
Next Scheduled EDR Contact: 02/01/2010
Data Release Frequency: N/A

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 02/20/2009
Date Data Arrived at EDR: 02/25/2009
Date Made Active in Reports: 03/09/2009
Number of Days to Update: 12

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 11/23/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 02/20/2009
Date Data Arrived at EDR: 02/25/2009
Date Made Active in Reports: 03/09/2009
Number of Days to Update: 12

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 11/23/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/13/2009
Next Scheduled EDR Contact: 01/25/2010
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 08/20/2007
Date Data Arrived at EDR: 10/10/2007
Date Made Active in Reports: 11/19/2007
Number of Days to Update: 40

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/20/2009
Next Scheduled EDR Contact: 02/01/2010
Data Release Frequency: Varies

Registered Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/13/2009
Next Scheduled EDR Contact: 01/25/2010
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 08/20/2007
Date Data Arrived at EDR: 10/10/2007
Date Made Active in Reports: 11/19/2007
Number of Days to Update: 40

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/20/2009
Next Scheduled EDR Contact: 02/01/2010
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database

A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 09/30/2009
Date Data Arrived at EDR: 10/01/2009
Date Made Active in Reports: 11/03/2009
Number of Days to Update: 33

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 12/14/2009
Next Scheduled EDR Contact: 03/29/2010
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database

A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 09/30/2009
Date Data Arrived at EDR: 10/01/2009
Date Made Active in Reports: 11/03/2009
Number of Days to Update: 33

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 12/14/2009
Next Scheduled EDR Contact: 03/29/2010
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database

A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006
Date Data Arrived at EDR: 01/11/2007
Date Made Active in Reports: 02/07/2007
Number of Days to Update: 27

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 11/09/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006
Date Data Arrived at EDR: 01/11/2007
Date Made Active in Reports: 02/07/2007
Number of Days to Update: 27

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 11/09/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Annually

WESTCHESTER COUNTY:

Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 05/05/2005
Date Data Arrived at EDR: 05/31/2005
Date Made Active in Reports: 06/30/2005
Number of Days to Update: 30

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 11/09/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Varies

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 05/05/2005
Date Data Arrived at EDR: 05/31/2005
Date Made Active in Reports: 06/30/2005
Number of Days to Update: 30

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 11/09/2009
Next Scheduled EDR Contact: 02/22/2010
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2007
Date Data Arrived at EDR: 08/26/2009
Date Made Active in Reports: 09/11/2009
Number of Days to Update: 16

Source: Department of Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/24/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 05/05/2009
Date Made Active in Reports: 05/22/2009
Number of Days to Update: 17

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 10/20/2009
Next Scheduled EDR Contact: 02/01/2010
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 12/01/2009
Date Made Active in Reports: 12/14/2009
Number of Days to Update: 13

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 11/23/2009
Next Scheduled EDR Contact: 03/08/2010
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 06/01/2009
Date Data Arrived at EDR: 06/12/2009
Date Made Active in Reports: 06/29/2009
Number of Days to Update: 17

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 11/30/2009
Next Scheduled EDR Contact: 03/15/2010
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 03/31/2009
Date Data Arrived at EDR: 04/09/2009
Date Made Active in Reports: 05/20/2009
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 10/23/2009
Next Scheduled EDR Contact: 02/08/2010
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 07/17/2009
Date Made Active in Reports: 08/10/2009
Number of Days to Update: 24

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 09/24/2009
Next Scheduled EDR Contact: 01/04/2010
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: PennWell Corporation
Telephone: (800) 823-6277

This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.
Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health
Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers

Source: Department of Health

Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands

Source: Department of Environmental Conservation

Telephone: 518-402-8961

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2009 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.