

# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>
1	4/17/2013

## HARBORcenter Brownfield Cleanup

### Description:

Former Webster Block (75 Main Street) Brownfield cleanup site.



<b>Exhibit:</b>	<b>Date:</b>
2	4/22/2013

## HARBORcenter Brownfield Cleanup

### Description:

Excavation of test pit at grid location F3.



# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>
3	4/22/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
Groundwater and oily sludge from F3 test pit.



<b>Exhibit:</b>	<b>Date:</b>
4	5/6/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
Excavation of contaminated fill from northeast corner.



# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>
5	5/7/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
Excavation of contaminated fill.  
Native silty clay material underneath fill.



<b>Exhibit:</b>	<b>Date:</b>
6	5/8/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
Profile of subsurface.  
Fill material overlaying native soil.



# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>
7	5/9/2013

## HARBORcenter Brownfield Cleanup

**Description:**

Excavation of fill material from grid locations F2 and F3.



<b>Exhibit:</b>	<b>Date:</b>
8	5/9/2013

## HARBORcenter Brownfield Cleanup

**Description:**

Offset earth retention shoring (BCP Boundary) due to location of active water line.



# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>	<b>HARBORcenter Brownfield Cleanup</b>
9	5/14/2013	

**Description:**  
Finish grading  
excavation bottom.



<b>Exhibit:</b>	<b>Date:</b>	<b>HARBORcenter Brownfield Cleanup</b>
10	5/17/2013	

**Description:**  
View of finished  
excavation bottom at  
grid location H5.



# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>
11	5/20/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
View of finished excavation bottom at grid location G5.



<b>Exhibit:</b>	<b>Date:</b>
12	5/21/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
Removal of wood frame pit in grids E3.



# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>
13	5/21/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
Finished excavation bottom at grid location E3.



<b>Exhibit:</b>	<b>Date:</b>
14	5/23/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
Contractor performing dust control and sediment cleanup.



# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>
15	6/1/2013

## HARBORcenter Brownfield Cleanup


**Description:**  
View of finished excavation bottom at grid location C3.



<b>Exhibit:</b>	<b>Date:</b>
16	6/5/2013

## HARBORcenter Brownfield Cleanup

**Description:**  
View of site.



# PHOTOGRAPHIC LOG

<b>Exhibit:</b>	<b>Date:</b>
17	6/7/2013

## HARBORcenter Brownfield Cleanup

**Description:**

Backfilling pit from casion removal with flowable fill.



<b>Exhibit:</b>	<b>Date:</b>
18	6/10/2013

## HARBORcenter Brownfield Cleanup

**Description:**

Excavation of fill material along wailer section to 13 - 14 ft below ground surface.

