# SITE INSPECTION REPORT

**Site Name:** 73-79 W. Huron Street **Site Number:** C915282

**Location:** 73-79 W. Huron Street, Buffalo, New York, 14202

**Inspection Date:** 8/28/2026

**NYSDEC Project Manager:** Bradley Demo

**Weather Conditions:** Sunny, warm

**Personnel Onsite:** Tom B. **(Roux)**, Chris **(Buffalo School of Culinary Arts and Hospitality)**

**Description of Work Performed:** Institutional and Engineering Controls Inspection

Details:

- Observed sump pumps in basement and 2 SSDS units operating properly. Piping was secured, no cracks in floor observed, pressure readings showing a negative vacuum.

- Roux is completing groundwater gauging and sampling via low flow purge to compare to previous use of passive diffusion bag methods. All wells were accessible and appeared in good condition.

**Inspector:** Bradley Demo

**Signature:** 

**Photolog:**




GSW-1




SSDS leg.