



August 21, 2012

Linda Owen
R&P Pool
574 Main Street
Tonawanda, New York 14150

RE: Contaminated Soil Cleanup- Niagara Street - Property

Dear Linda,

Enclosed is a sketch of the site showing the limits of excavation. The site was excavated and 132 tons of contaminated soils were removed. The excavation was mainly fill materials from a previous building demolition. The site was excavated between 8-12 feet below the ground surface, the site was excavated until clay material was located. The site included the removal of a concrete secondary containment and old sump and clay pipe that was not in use. The excavation was confined to the interior of the building are were limited by the structure, the exaction to the south and west were to the exterior foundations.


No accumulation of oil was noted in the bottom of the excavation, suspect soils and staining remained on the foundation walls. Exterior monitoring wells should be installed to monitor any remaining contamination.

Thank you for the opportunity to provide you with these services. Should you have any questions, please call me

Sincerely,


A handwritten signature in black ink, appearing to read "Raj Chopra", is written over a horizontal line.

Raj Chopra



BUILDING -
FOOTERS -
LIMIT OF EXCAVATION 40'

INSET



INSET LEGEND:



APPROXIMATE LOCATION AND
DESIGNATION OF SOIL PROBE




APPROXIMATE LOCATION AND
DESIGNATION OF SOIL PROBE WITH
MICRO WELL INSTALLED

UNLESS SPECIFICALLY STATED BY WRITTEN AGREEMENT, THIS DRAWING IS THE SOLE PROPERTY OF GZA GEOENVIRONMENTAL, INC. (GZA). THE INFORMATION SHOWN ON THE DRAWING IS SOLELY FOR USE BY GZA'S CLIENT OR THE CLIENT'S DESIGNATED REPRESENTATIVE FOR THE SPECIFIC PROJECT AND LOCATION IDENTIFIED ON THE DRAWING. THE DRAWING SHALL NOT BE TRANSFERRED, REUSED, COPIED, OR ALTERED IN ANY MANNER FOR USE AT ANY OTHER LOCATION OR FOR ANY OTHER PURPOSE WITHOUT THE PRIOR WRITTEN CONSENT OF GZA. ANY TRANSFER, REUSE, OR MODIFICATION TO THE DRAWING BY THE CLIENT OR OTHERS, WITHOUT THE PRIOR WRITTEN EXPRESS CONSENT OF GZA, WILL BE AT THE USER'S SOLE RISK AND WITHOUT ANY RISK OR LIABILITY TO GZA.

NO.		ISSUE/DESCRIPTION		BY	DATE
LEISURE LIVING 1130 NIAGARA STREET BUFFALO, NEW YORK					
SITE PLAN					
PREPARED BY: GZA GeoEnvironmental of N.Y. Engineers and Scientists 635 WASHINGTON STREET 11th FLOOR BUFFALO, NEW YORK 14203 (716) 685-2300			PREPARED FOR: LEISURE LIVING		
PROJECT NO:	JLB	REVIEWED BY:	CHECKED BY:	FIGURE	
DESIGNED BY:	DEW	DRAWN BY:	SCALE: AS SHOWN	2	
DATE	OCTOBER 2010	PROJECT NO.	21 0056547.10	REVISION NO.	

NIAGARA EXPRESSWAY (NYS I-190)



- ALLEY -

APPROXIMATE
SITE LIMITS

SB-13E/MW-2

WAREHOUSE

SEE INSET
THIS FIGURE

LOADING
DOCK

BASEMENT

OFFICE

WAREHOUSE

46'

25'

SB-12E/MW-1

SB-12C


SB-12A

SB-12B

SB-12D

NIAGARA STREET

SITE PLAN



SCALE IN FEET

NOTES:

1. BASE MAP ADAPTED FROM AN AERIAL PHOTO AND PROPERTY LINE DOWNLOADED FROM <http://www.bing.com/maps/> AND FIELD OBSERVATIONS.

2. BORING LOCATIONS SHOWN, TAKEN FROM FIGURE 1 OF A PHASE II ENVIRONMENTAL SITE ASSESSMENT REPORT PREPARED BY CONESTOGA-ROVERS & ASSOCIATES, DATED JULY 2009, PROVIDED TO GZA BY DAMON MORLEY, LLP.

3. THE SIZE AND LOCATION OF EXISTING SITE FEATURES SHOULD BE CONSIDERED APPROXIMATE.

AREA of Excavation
132 TONS SOIL Disposal
8'-12' -BGS Excavation
Square footage of Area 1000 sq

SITE PLAN LEGEND:

SB-12E/MW-1

APPROXIMATE LOCATION AND DESIGNATION
MONITORING WELL INSTALLED PREVIOUSLY
CONESTOGA-ROVERS & ASSOCIATES

SB-12B

APPROXIMATE LOCATION AND DESIGNATION
SOIL BORING DONE PREVIOUSLY BY
CONESTOGA-ROVERS & ASSOCIATES