

**New York State Department of Environmental Conservation**  
**Division of Environmental Remediation, Region 9**  
270 Michigan Avenue, Buffalo, New York 14203-2915  
**Phone:** (716) 851-7220 • **Fax:** (716) 851-7226  
**Website:** [www.dec.ny.gov](http://www.dec.ny.gov)

## **INSPECTION REPORT**

**Site Number:** C915303 **Date:** August 29, 2017  
**Site Name:** 19 North St  
**Location:** 19-23 North St  
**Project Manager:** Dan Riker  
**Project Engineer:** C&S Engineer  
**Job Phone:** NA

**HEALTH & SAFETY:** Level D  
**DESCRIPTION OF WORK PERFORMED:**

MJH on site at 1400 hrs

No one on site.

Excavation and backfill complete with the exception of the poles in Grids A2 and A4.  
Telcon with Ben Oblitz, Nation Grid may be on site on 9/1 to secure and or move poles to complete excavation

No evidence of any off site issues with erosion or dust.

Pile of stone mixed with soil on site. Need explanation on the fate of this material.

**Attachments:** photos,  
**Inspector's Name (Print):** Michael Hinton  
**Inspector's Signature:**

**Date:** August 30, 2017





