



SITE INSPECTION REPORT

Site Name: 293 Grote Street

Site Number: C915368

Location: 293 Grote Street, Buffalo NY

Inspection Date: 9/12/2025

Site Inspectors: Bradley Demo

Weather Conditions: Sunny, cool

Description of Work Performed: Institutional and Engineering Controls Inspection

Details:

Site cover in good condition. Adequate soil and vegetative cover was observed in landscaped areas. Adequate stone coverage observed behind tenant building, some vegetation growing but none observed that would penetrate cover system. Asphalt intact, no cracks or signs of excavation. Inside building floor in acceptable condition. No institutional control violations observed.

Inspector: Bradley Demo

Signature: *Bradley W. Demo*

Attachments: Photolog

Photolog:



Western asphalt/landscaped area.



Central entrance/courtyard concrete and gravel cover.



Partial loading dock crawlspace cover.



Behind building stone cover.



Stone cover behind building continued.



Inside of building floor conditions facing south.



Inside of building floor conditions facing west.

Site Inspection Report
293 Grote Street (C915368)
September 12, 2025
Page 9



Inside of building floor conditions facing east.