

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: www.dec.ny.gov



Joe Martens
Acting
Commissioner

INSPECTION REPORT

Site Number: C932164

Date: February 24, 2015

Site Name: 401, 402 & 430 Buffalo Ave

Location: Buffalo Ave Niagara Falls, Niagara
County

Project Manager: Nate Munley - Benchmark

Project Engineer: Benchmark/Turnkey

Job Phone: (c) 289-1072, (o) 716-85-0599

HEALTH & SAFETY: Level D

DESCRIPTION OF WORK PERFORMED:

MJH on site at 1000 hrs w/ Ken Martin

Weather – T~15⁰F WC -2⁰F, overcast, blowing snow Wind SW @ 15 gusts to 30 mph

Benchmark on site with geo-probe conducting RI work

Elevated Rad found in parking lot of 402 Buffalo Ave >50,000 cpm through asphalt and snow

Demolition proceeding. No water mist applied to asbestos debris. Variance obtained from DOL to eliminate water mist in very cold weather.

Attachments:

Inspector's Name (Print): Michael J Hinton

Inspector's Signature:

Date: March 9, 2015