



**Division of Environmental Remediation  
Remedial Bureau C, Central Office**

**Field Log**

<b>Site Code #:</b> E360077	<b>Date:</b> 11/20/2025
-----------------------------	-------------------------

**Site Name:** Davids Island  
**Location:** Davids Island, New Rochelle, NY 10801  
**DEC Project Manager:** Matthew Hubicki

	<b>AM</b>	<b>PM</b>
<b>Weather</b>	Partly Cloudy	Mostly Sunny
<b>Temperature</b>	43 Deg F	48 Deg F
<b>Wind Direction</b>	0-3 mph NE	7 mph NE

**Objective:** Inspection of site cover, beach areas, incinerator area, and meet with consultant, HRP, and site owner (Rep of New Rochelle) for development of the ISMP.

**Description of Inspection Activities and Discussions:**

Meet with City of New Rochelle and HRP inspect the beach areas near the incinerator area on the south shore. Appears there are trespassing on-site. No access to the site only by water. We noticed no signage with HRP. The beach areas seem to be eroded from seasonal storms since last visit with debris and other stuff that's either left behind or washing up. Interior is overgrown and hard to see the original roads and paths, and staging area. Some pavement under leaves and debris.

Mark Wright from HRP Associates, Rita Arzeylant, Todd Castaldado, and Jessica Paladino from City of New Rochelle, plus City of New Rochelle Harbor Patrol were present and provided transportation to the island.

**Health & Safety:**

Level of protection: Level D, with safety vests.

**Site Representative:** Matt Hubicki


**Date:** 11/20/2025

*Watt Hurl*

**Representative's Signature:**



**Southern Shore Docking Area – Looking West towards New Rochelle**



**Southern Shore – Looking East towards Long Island Sound**



**Southern Shore Wall – Looking South**



**Eastern Shore Wall – Looking West**



Interior Island near the Fenced Staging Area – Looking North



