CC: "Joe Biondolillo" <biondj@cityofrochester.gov>, "Dennis Peck (City)" <de...

Date: 11/15/2010 3:47 PM

Subject: NYSDEC Site #E828144 - Andrews St 11/12/10 through 11/15/10 demolition progress **Attachments:** Figure 3, Andrews St NYSDEC Site # E828144, Demolition Progress 11-11-10 thorugh 11-15-10.pdf; 11-12-10 P 008.jpg; 11-12-10 P 001.jpg; 11-12-10 P 004.jpg; 11-15-10 P 010.jpg; 11-15-10 P 005.jpg

Charlotte.

The above grade demolition continued on 11/12/10 and 11/13/10 at the 300, 304-308 and 320 Andrews Street and 25 Evans Street Site. Actives completed included site cleanup measures and the construction of the decon pad. Refer to the attached photos Figure 3.

At-grade and below grade demolition work was not conducted on 11/15/10 due to a leaking 6-inch diameter water main within the southern basement wall of the 304-308 Andrews Street building. In addition, a 3/4-inch service line within the southern basement wall of the 300 Andrews Street building is also leaking but at a much lower rate than the 6-inch water main. The water observed leaking into both 300 and 304-308 Andrews Street parcels is water from the municipal water system located in Andrews Street. Refer to the attached photos and Figure 3 for approximate locations of the 6-inch water main, the 3/4-inch service line and accumulated water within the basement of the 304-308 Andrews Street building. Following a discussion with Sean Keenan (753-7658) with the Monroe County Division of Pure Waters, it was determined that the accumulated water could be pumped from the basement to the combined sewer system without analytical laboratory testing results. Once the water lines have been addressed and are no longer leaking into the basements, the accumulated water will be discharged to the combined sewer system and the at-grade and below grade demolition work will begin at the 300 Andrews Street building. It is currently anticipated that the water main will be decommissioned on 11/16/10 and the at-grade and sub-grade demolition will begin on 11/16/10.

Accessible portions of the restricted area boundaries continue to be established in the field using spray paint. Please refer to the attached photos and Figure 3 for locations of the restricted area boundaries.

Nate Simon, P.E. Day Environmental, Inc. 40 Commercial Street Rochester, New York 14614-1008 Phone: (585) 454-0210 ext:109

Fax: (585) 454-0825

<<Figure 3, Andrews St NYSDEC Site # E828144, Demolition Progress 11-11-10 thorugh
11-15-10.pdf>> <<11-12-10 P 008.jpg>> <<11-12-10 P 001.jpg>> <<11-12-10 P 004.jpg>> <<11-15-10
P 010.jpg>> <<11-15-10 P 013.jpg>> <<11-12-10 P 005.jpg>>

This message may contain information that is privileged or confidential. If you are not the intended recipient or an employee or agent responsible for delivering this message to the intended recipient, you are not authorized to read, print, retain, copy or disseminate this message or any part of it. If you received this transmission in error, please notify the sender by reply e-mail and delete the message and any attachments.







CC: "Joe Biondolillo" <biondj@cityofrochester.gov>, "Dennis Peck (City)" <de...

Date: 11/17/2010 4:52 PM

Subject: NYSDEC Site #E828144 - Andrews St 11/16/10 demolition progress

Attachments: Figure 3, Andrews St NYSDEC Site # E828144, Demolition Progress 11-17-10.pdf; 11-

16-10 P 006.jpg; 11-16-10 P 009.jpg

Charlotte,

The at-grade and sub-grade demolition began on 11/16/10 at the 300, 304-308, 320 Andrews Street and 25 Evans Street Site. Initially, the water that accumulated in the basement of the 304-308 Andrews Street building from the municipal water system was discharged to the Monroe County Division of Pure Waters Sewer System. Subsequently, portions of the slab and foundation walls from the 300 and 304-308 basements were removed and screened in accordance with the "At-Grade and Sub-Grade Demolition Work Plan, 300, 304-308, 320 Andrews Street and 25 Evans Street, Rochester New York, NYSDEC Site # E828144" prepared by DAY dated October 2010. Underlying overburden soil was also screened in accordance with the Work Plan. Refer to attached photo and Figure 3 depicting the area demolished to date.

Nate Simon, P.E. Day Environmental, Inc. 40 Commercial Street Rochester, New York 14614-1008 Phone: (585) 454-0210 ext:109

Fax: (585) 454-0825

<<Figure 3, Andrews St NYSDEC Site # E828144, Demolition Progress 11-17-10.pdf>> <<11-16-10 P 006.jpg>> <<11-16-10 P 009.jpg>>

This message may contain information that is privileged or confidential. If you are not the intended recipient or an employee or agent responsible for delivering this message to the intended recipient, you are not authorized to read, print, retain, copy or disseminate this message or any part of it. If you received this transmission in error, please notify the sender by reply e-mail and delete the message and any attachments.



DAILY AIR MONITORING REPORT

DATE: IIII	PAGE: OF
NYSDEC SITE #: <u>E828144</u>	DAY PROJECT #: <u>4265S-09</u>
SITE: 300, 304-308, 320 Andrews Street, 25 Evans Street, Rochester, N	ew York
BY: KAC	
WEATHER CONDITIONS: partly Cloudy	
PREVAILING WIND DIRECTION: \(\int \mathcal{W} \)	
AIR MONITORING AND CORRECTIVE ACTION NOTES: 1010 ~	
SW comes of basement 300 anglesing- 1015 homestopped, in	ater broat slab.
1025-demo bignagan. wan ends 315	
<i>y</i> 8	

DESCRIPTION	TIME	LOCATION	PID (ppm)	PARTICULATES (mg/m3)
B6-	716		1 1D (ppin)	
			0.00	0.000
Carry	1630	2	0.00	0.000
1 ms	1045	(2)	0.00	0.000
bomb	1100		0.00	0.012
comb	1115		0.00	0.023
. BZ T	1120	(3)	0.00	0.008
Comun	1130	(2)	6.00	0.031
Comulo	1145		0.00	0.029
Comp	0800	73)	0.00	0.035
CAMI	17:15	2	3.0	0 031
CAMO	12:30	Ũ	1 2.1	0.017
CAMP	12:45	(3)	1.3	0.00
BE	1250	(3)	0.00	0.029
gamp	300	(3)	0-00	0.000
Obras	1315		0.00	0.000
Camp	1330		0.00	0.017
amb	1345	(2)	0.00	0-018
Camp	1400		0.00	0-018
làmb	1415		0.00	0.003
anyo	1430	(A)	0.00	0.002
Varmo	W45	(7)	0.00	0.004
021	1450	(3)	0.00	0.023



DAILY AIR MONITORING REPOR				
DATE: 11 16 10	PAGE:_	2	_OF_	5
NYSDEC SITE #: <u>E828144</u>	DAY PR	ROJEC"	Γ#: <u>42</u>	65S-09
SITE: 300, 304-308, 320 Andrews Street, 25 Evans Street, Rochester, N BY: 1900 WEATHER CONDITIONS: 0 Monthly 1900 1900	ew York			
PREVAILING WIND DIRECTION: (1)				
AIR MONITORING AND CORRECTIVE ACTION NOTES:				
		· · · · · · · · · · · · · · · · · · ·		

DESCRIPTION	TIME	LOCATION	PID (ppm)	PARTICULATES (mg/m3)
Comp	1500	(b)	0.00	0.002
almo	1515	<u>(D)</u>	0-00	0.004
	ena	work		•

DACE 7	OE	5
PAGE 5	OF	<u> </u>

DAY ENVIRONMENTAL, INC.DAILY SITE OBSERVATION REPORT

CLIENT: City of Rochester		DATE: 11/10/10
PROJECT: Andrews St At-Grade/Sub-Grade Demolition (DA	NYSDEC SITE #: E828144	
LOCATION: 300, 304-308, 320 Andrews Street, 25 Evans Street	rk	
ON-SITE AT: 700		
CONTRACTOR(S): GFrederico		

COMMENTS:


KAC Onsite - 700 G Frederica onsite a 700 - G Frederica Ogiste a 705 - needs to get hose KAC Calibatis particulate motes - ok Calibrates 2 Plps - 100 - 102 ppmos
6 Frederico Ogista 2 705 - noods to get hose
KAC Calibation particulate moter-ok Calibration 2 Plas - 900 - 102 momor
City of wochester water services are on south side of andrews
Street woming on watermain. 2740 there is about
If of well on bettom of last side of pasement (300 anders of)
745 - Grellico buell on site w/ 2nd mill and droken (brewlancing)
WILL began. AD OWND Almountage used a out of
basement (300 andreus). Drew Lancine of site. 6. Frederico Cleaned out Santary surer drain located arting
6. Frederico Cleaned out santary sure drain located adone
South wall of pumping water to flow out w/o pump.
JAD on Ste 815 - KAC, JAD, G. Freder to never HASP and CAMP.
V. Vech + C. Fex from City on site ~ 845. Jap. D. Rock, St. 20 200
C. Fox offsite 3 10:30 G. Frederico done pumping basement out 20 1000. NES onsite 1005. Begin to demo slab in su come of 300
a 1000. NES on set 1005. begin to demo slab in su come of 300
annus portung that up sunt 23 mones of water beneath Stab. 1123 calls
The b. D lity ok to continue work. KAZ Stans soil/water from busement floor
Concrete as demolition continues.
KAC Samples wall and ground surface in basement
fort print. Collect Samples - 45, 006, 007. S-2, S-3, S-4 1330 - encounter an approximate 2x2 bright morter square sub grade WORK FORCE AND FOURMENT:
1330 - encounter an apparamate 2x2 bright motor square subgrate
WORK FORCE AND EQUIPMENT: G Frederic - Excavator
J Francisco
DAY Representative (print): Kelly Cranda DAY Representative (signed): My Cranda DAY Representative (signed):

PAGE 4 OF 5

DAY ENVIRONMENTAL, INC.DAILY SITE OBSERVATION REPORT

CLIENT: City of Rochester		DATE:)1)(6 (10			
PROJECT: Andrews St At-Grade/Sub-Grade Demolition (D	NYSDEC SITE #: E828144				
LOCATION : 300, 304-308, 320 Andrews Street, 25 Evans S	ork				
ON-SITE AT: 700	330				
CONTRACTOR(S): 6. Fredlice					

COMMENTS: WORK FORCE AND EQUIPMENT: DAY Representative (print):_ DAY Representative (signed):_



CC: "Joe Biondolillo" <biondj@cityofrochester.gov>, "Dennis Peck (City)" <de...

Date: 11/17/2010 4:55 PM

Subject: Andrews Street, NYSDEC Site #E828144 11-16-10 Daily Site Report

Attachments: Andrews St, NYSDEC Site # E828144, DAY Env. Daily Site Report 11-16-10.pdf

Charlotte,

The attached pdf is DAY's daily site report for November 16, 2010. The daily site report includes the CAMP monitoring results, a daily observation report summarizing the demolition activities that were completed and a figure presenting CAMP station designations and sample locations/designations. The collected samples are anticipated to be shipped to Chemtech on 11/18/2010 and DAY or the City will be contacting the NYSDEC in the near future of its input regarding actual samples to be analyzed.

Nate Simon, P.E. Day Environmental, Inc. 40 Commercial Street Rochester, New York 14614-1008 Phone: (585) 454-0210 ext:109

Fax: (585) 454-0825

<<Andrews St, NYSDEC Site # E828144, DAY Env. Daily Site Report 11-16-10.pdf>> This message may contain information that is privileged or confidential. If you are not the intended recipient or an employee or agent responsible for delivering this message to the intended recipient, you are not authorized to read, print, retain, copy or disseminate this message or any part of it. If you received this transmission in error, please notify the sender by reply e-mail and delete the message and any attachments.







CC: "Joe Biondolillo" <biondj@cityofrochester.gov>, "Dennis Peck (City)" <de...

Date: 11/18/2010 4:43 PM

Subject: NYSDEC Site #E828144 - Andrews St 11/17/10 demolition progress

Attachments: Figure 3, Andrews St NYSDEC Site # E828144, Demolition Progress 11-17-10.pdf;

P1010006.JPG; 11-17-10 P 006.jpg; 11-17-10 P 013.jpg

Charlotte,


The at-grade and sub-grade demolition continued on 11/17/10, primarily removal of portions of the slab and foundation walls from the 300 and 304-308 basements. Refer to attached photo and Figure 3 and the attached photos depicting the area demolished to date.

At-grade and sub-grade demolition work will not be conducted on 11/19/2010. The contractor will be removing hard debris from the Site. At-grade and sub-grade demolition work is scheduled to resume on 11/29/10; however, this schedule is subject to change and the NYSDEC will be updated as the schedule is finalized.

Nate Simon, P.E. Day Environmental, Inc. 40 Commercial Street Rochester, New York 14614-1008 Phone: (585) 454-0210 ext:109 Fax: (585) 454-0825

<<Figure 3, Andrews St NYSDEC Site # E828144, Demolition Progress 11-17-10.pdf>>
<<P1010006.JPG>> <<11-17-10 P 006.jpg>> <<11-17-10 P 013.jpg>>

This message may contain information that is privileged or confidential. If you are not the intended recipient or an employee or agent responsible for delivering this message to the intended recipient, you are not authorized to read, print, retain, copy or disseminate this message or any part of it. If you received this transmission in error, please notify the sender by reply e-mail and delete the message and any attachments.





DAILY AIR MONITORING REPOR	T ,
DATE: 11/17/10	PAGE: OF
NYSDEC SITE #: E828144	DAY PROJECT #: <u>4265S-09</u>
SITE: 300, 304-308, 320 Andrews Street, 25 Evans Street, Rochester, No	ew York
BY: KAC	
WEATHER CONDITIONS: CLANDY M5°F YOUN	bleins ~ 1000
PREVAILING WIND DIRECTION: WIE	
AIR MONITORING AND CORRECTIVE ACTION NOTES:	
Begin demolition of subgrade material	1 200. No visible
dust emmissions - Pained last night so	materials are wet
Contolling dust.	
)	

DESCRIPTION	TIME	LOCATION	PID (ppm)	PARTICULATES (mg/m3)
B6~	ଟ00		0.00	0.000
amo	830	(\mathfrak{I})	0.190	0.000
annal	SU5		0.00	0.000
(amo)	7960	(F)	0.00	0.000
Campo	0915		0.00	0.000
Camp	0930		0.00	0.000
deno	0945	2)	0.00	0.000
62-1	<u> 1005</u>	(E)	000	0.003
Comp	1000	(2)	0.00	0.000
Ramo	1013		0.00	0 000
domos	1030		0.00	0.00.0
Compl	1175		0.00	0.020
	ME		8.00	0.000
ican	1100	(3)	0.00	0.00.6
(my)	1115		0.00	0-000
Comio	1136	3000.77	0.00	0 000
comp	1145		0.00	0.000
() 2 Y	1150		0.00	0.000
ann?	1200	(9)	0.00	0.000
Dany	1215		ට· O ()	0.000
Damb	1230	Δ	0.00	000
Compl	1245	(2)	0.00	0.000



DAILY AIR MONITORING REPORT

DATE: __i\| \(\frac{1}{7} \) \(\frac{1}{9} \) PAGE: ___ OF ___

NYSDEC SITE #: <u>E828144</u>

DAY PROJECT #: <u>4265S-09</u>

SITE: __300, 304-308, 320 Andrews Street, 25 Evans Street, Rochester, New York

BY: _____

WEATHER CONDITIONS: _______

WEATHER CONDITIONS: _______

AIR MONITORING AND CORRECTIVE ACTION NOTES: _______

DESCRIPTION	TIME	LOCATION	PID (ppm)	PARTICULATES (mg/m3)
Jamos	1300	W	0.00	0.000
Comb	1515		0.00	0.000
32	1320	(3)	0.00	0.004
Comp	1330	(2)	00.00	0.000
James	1345	(3)	0.00	0.000
Compl		(2)	D-00	0.000
Cando	1915		0.00	0.000
15t	1420	(30)	0.00	0.000
yamp	1930	(2)	0.00	0.000
yamp_	1995		0.00	0.000
<u>camp</u>	1200	(3)	10.00	0.000
	end Su	bsurface i	va/C	
		U		
DECOMPTION DO				


PAGE 3 OF 4

DAY ENVIRONMENTAL, INC.

DAILY SITE OBSI	ERVATION REPORT			
CLIENT: City of Rochester	DATE: 111710			
PROJECT: Andrews St At-Grade/Sub-Grade Demolition (Da	AY Project #4265S-09)	NYSDEC SITE #: E828144		
LOCATION : 300, 304-308, 320 Andrews Street, 25 Evans St	reet, Rochester, New Yor	rk		
ON-SITE AT: 0 YDO	OFF-SITE AT:			
CONTRACTOR(S): 6. Explesion				
comments: Dennilect and 6: Freileuro m sto.	7800, Apala	with roman has		
abouterade rame sto. D. Perk an sote	\mathcal{L}	n demolating		
	n site 830°	Msite 29000		
Begin to full word from subgrades t		sols from beneath		
	Jsol. PID O.O	·		
15 Sandy, brown. trues of ashard placed in void. Freduce somo	20 2	cont. 10 bucheto		
from orea ~915-1030 -	begins with	northern 1/2 basement		
of socrations. 3" metal per	è encout	hed on western		
portun, Pid in pipe = 0.00 ppin	D. Dock	inserts polo into		
pipe-light on end of polo. Clear, no colors. pid=0.00				
Ver Stons all removed	contrete i	ith My PiD		
	20-6". Se	The corlects		
at 1245 and 1250. 5-820	-6" at 1440	5. 6. Frederia		

WORK FORCE AND EQUIPMENT:

DAY Representative (print): Kally Crandall DAY Representative (signed): Kally Crandall



CC: "Joe Biondolillo" <biondj@cityofrochester.gov>, "Dennis Peck (City)" <de...

Date: 11/18/2010 4:27 PM

Subject: Andrews Street, NYSDEC Site #E828144 11-17-10 Daily Site Report

Attachments: Andrews St, NYSDEC Site # E828144, DAY Env. Daily Site Report 11-17-10.pdf

Charlotte,

The attached pdf is DAY's daily site report for November 17, 2010. The daily site report includes the CAMP monitoring results, a daily observation report summarizing the demolition activities that were completed and a figure presenting CAMP station designations and sample locations/designations. The collected samples are anticipated to be shipped to Chemtech on 11/18/2010. DAY or the City will be contacting the NYSDEC in the near future for its input regarding actual samples to be analyzed.

The decon pad currently staged on the 25 Evans Street parcel is accumulating rain water. Prior to it's initial use, the accumulated rain water will be pumped to the ground surface.

Nate Simon, P.E. Day Environmental, Inc. 40 Commercial Street Rochester, New York 14614-1008 Phone: (585) 454-0210 ext:109

Fax: (585) 454-0825

<<Andrews St, NYSDEC Site # E828144, DAY Env. Daily Site Report 11-17-10.pdf>>
This message may contain information that is privileged or confidential. If you are not the intended recipient or an employee or agent responsible for delivering this message to the intended recipient, you are not authorized to read, print, retain, copy or disseminate this message or any part of it. If you received this transmission in error, please notify the sender by reply e-mail and delete the message and any attachments.





