

**Daily Field Oversight Summary**

<b>Project No.:</b> EE1705007.0010	<b>Date:</b> 04/29/2025
<b>Project Name:</b> Greenpoint Oversight	<b>Project Location:</b> Brooklyn, NY

**Oversight Personnel:** Timothy Williams  
**Weather:** AM: Sunny, 57°F, wind 2-12 mph

**Internal Reviewer:** Brian Cervi  
PM: Sunny, 77°F, wind 3-22 mph

**Last 24 hours Temperature / Precipitation:** 56 – 76°F / 0.0 Inches

<b>Hourly Summary of Today's Activities</b>	
Tuesday, April 29, 2025	
08:45	E&E/WSP arrives at the ExxonMobil 400 Kingsland property and meets with Mauricio Hollis (Roux) and Jackie Carames (Roux) to observe ongoing spill cleanup activities.
11:00	E&E/WSP completes today's oversight activities and leaves the site for the day.

<b>Field Tests Performed/Samples Collected by Oversight Personnel</b>
None
<b>Problems Encountered And/Or Safety Issues</b>
None

Project No.: EE1705007.0010	Date: 04/29/2025
Project Name: Greenpoint Oversight	Project Location: Brooklyn, NY

[illegible]

**Daily Field Oversight Summary**

<b>Project No.:</b> EE1705007.0010	<b>Date:</b> 04/29/2025
<b>Project Name:</b> Greenpoint Oversight	<b>Project Location:</b> Brooklyn, NY

**Site:** Newtown Creek

<b>Observed Personnel</b>	<b>Affiliation</b>	<b>Task Performed</b>	<b>Level of PPE</b>
None			
<b>Description of Activities</b>			
NA			
<b>Planned Activities for Next Workday</b>			
NA			

## Daily Field Oversight Summary

Project No.: EE1705007.0010	Date: 04/29/2025
Project Name: Greenpoint Oversight	Project Location: Brooklyn, NY

## Photo log

[illegible]

Timothy Williams

04/29/2025


**Oversight Personnel Signature:**

**Date**

### Daily Field Oversight Summary

Project No.: EE1705007.0010	Date: 04/29/2025
Project Name: Greenpoint Oversight	Project Location: Brooklyn, NY

#### Daily Photo Log



Newtown Creek conditions at the ExxonMobil On-site effluent outfall facing north.  
042925 - IMG\_1881



Newtown Creek conditions at the ExxonMobil On-site effluent outfall facing south.  
042525 - IMG\_1882



CAMP Station on north side of ExxonMobil site.  
042925 - IMG\_1885



Stained soil on the ExxonMobil site.  
042925 - IMG\_1884



## Daily Field Oversight Summary

Project No.: EE1705007.0010	Date: 04/29/2025
Project Name: Greenpoint Oversight	Project Location: Brooklyn, NY



Contractor scraping up top 2" of stained soil.  
042925 - IMG\_1895



Contractor using shovels to assist in removal of stained soil.  
042925 - IMG\_1893



Stained soil to the north of the RCS treatment building on the ExxonMobil site.  
042925 - IMG\_1876



Soil being stockpiled on poly in dedicated impacted soil area. Additional poly was laid down after photo was taken.  
042925 - IMG\_1887