ROUX ENVIRONMENTAL ENGINEERING AND GEOLOGY, D.P.C.

DAILY FIELD ACTIVITY REPORT

Client:	ExxonMobil	Roux Field Representatives:	Asa Tuke
Location:	410 Kingsland Ave, Brooklyn. NY	Weather:	61-71°F, Cloudy
Project Number:	0172.0030Y123		H: 92%, P: 29.97 inHg
Job:	ExxonMobil Greenpoint Petroleum Remediation Project	Wind:	W @ 3-6 mph
		Date:	Tuesday, September 29, 2026

Personnel Onsite

Asa Tuke (Roux)

- Monitoring Well Installation Contractor (ADT)
  - German Torres — Laborer
  - Christian Crave — Laborer

Equipment Onsite

Hand Auger

Digger Bar

Description of Work Performed:

- ADT developed monitoring wells D-103, D-104, D-114, S-104, and S-105. Purgewater was stored in 55-gallon drums at the Site.
- ADT furnished and installed concrete pads and 12" manholes at monitoring wells D-103, D-104, D-105, and D-114.
- ADT furnished and installed a concrete pads and 8" manholes at monitoring well S-104 and S-105.
- ADT demobilized all equipment and monitoring well installation material offsite.

Description of Upcoming Work Activities:

None.

Material Delivered To Site:

- None.

Material Removed From Site:

- None.

Sampling Performed:

- None.

CAMP Performed:

- The community air monitoring program (CAMP) was performed from approximately 8:00 AM - 4:00 PM during all subsurface activities. No exceedances were observed. Dust suppression measures were implemented as necessary throughout the duration.

DAILY FIELD ACTIVITY REPORT

Photographs of Work Performed: Date: Tuesday, September 29, 2026



Photo 1: Facing down, view of ADT developing monitoring well S-105.



Photo 2: Facing down, view of furnished concrete pad and 12" manhole at monitoring well D-114.

Roux Environmental Engineering and Geology, D.P.C.
Community Air Monitoring Program - DUST

Project: ExxonMobil Greenpoint Petroleum Remediation Project - Monitoring Well Installation
PM: Jacqueline Carames
Location: 410 Kingsland Ave, Brooklyn. NY
Date: 9/29/2026

Upwind Serial Number 8530172602
Downwind Serial Number 8530182512

Upwind		Downwind		Corrected Downwind	Comments
Time	Concentration [mg/m3]	Time	Concentration [mg/m3]	Concentration [mg/m3]	
8:26 AM	0.012	8:26 AM	0.010	-0.003	
8:41 AM	0.013	8:41 AM	0.010	-0.003	
8:56 AM	0.014	8:56 AM	0.010	-0.004	
9:26 AM	0.016	9:26 AM	0.013	-0.003	
9:41 AM	0.013	9:41 AM	0.010	-0.003	
9:56 AM	0.014	9:56 AM	0.010	-0.004	
10:11 AM	0.012	10:11 AM	0.009	-0.003	
10:26 AM	0.013	10:26 AM	0.011	-0.002	
10:41 AM	0.012	10:41 AM	0.010	-0.002	
10:56 AM	0.012	10:56 AM	0.012	0.000	
11:11 AM	0.011	11:11 AM	0.011	0.000	
11:26 AM	0.010	11:26 AM	0.010	0.001	
11:41 AM	0.010	11:41 AM	0.011	0.001	
11:56 AM	0.006	11:56 AM	0.008	0.002	
12:11 PM	0.006	12:11 PM	0.008	0.002	
12:26 PM	0.008	12:26 PM	0.009	0.001	
12:41 PM	0.005	12:41 PM	0.007	0.001	
12:56 PM	0.005	12:56 PM	0.006	0.001	
1:11 PM	0.005	1:11 PM	0.007	0.002	
1:26 PM	0.006	1:26 PM	0.008	0.002	
1:41 PM	0.008	1:41 PM	0.008	0.000	
1:56 PM	0.008	1:56 PM	0.008	0.000	
2:11 PM	0.007	2:11 PM	0.008	0.001	
2:26 PM	0.006	2:26 PM	0.007	0.001	
2:41 PM	0.008	2:41 PM	0.011	0.003	
2:56 PM	0.006	2:56 PM	0.014	0.009	
3:11 PM	0.007	3:11 PM	0.007	0.001	
3:26 PM	0.013	3:26 PM	0.013	0.000	
3:41 PM	0.016	3:41 PM	0.016	0.000	
3:56 PM	0.011	3:56 PM	0.011	0.000	

Notes:
1. NM - Not Measured

Roux Environmental Engineering and Geology, D.P.C.
Community Air Monitoring Program - VOC

Project: ExxonMobil Greenpoint Petroleum Remediation Project - Monitoring Well Installation
PM: Jacqueline Carames
Location: 410 Kingsland Ave, Brooklyn. NY
Date: 9/29/2026

Upwind Serial Number 592-600931
Downwind Serial Number 592-921005

Upwind		Downwind		Corrected Downwind	Comments
Time	VOC Average (ppm)	Time	VOC Average (ppm)	VOC Average (ppm)	
8:22 AM	0.0	8:22 AM	0.0	0.0	
8:37 AM	0.0	8:37 AM	0.0	0.0	
8:52 AM	0.0	8:52 AM	0.0	0.0	
9:07 AM	0.0	9:07 AM	0.0	0.0	
9:22 AM	0.0	9:22 AM	0.0	0.0	
9:37 AM	0.0	9:37 AM	0.0	0.0	
9:52 AM	0.0	9:52 AM	0.0	0.0	
10:07 AM	0.0	10:07 AM	0.0	0.0	
10:22 AM	0.0	10:22 AM	0.0	0.0	
10:37 AM	0.0	10:37 AM	0.0	0.0	
10:52 AM	0.0	10:52 AM	0.0	0.0	
11:07 AM	0.0	11:07 AM	0.0	0.0	
11:22 AM	0.0	11:22 AM	0.0	0.0	
11:37 AM	0.0	11:37 AM	0.0	0.0	
11:52 AM	0.0	11:52 AM	0.0	0.0	
12:07 PM	0.0	12:07 PM	0.0	0.0	
12:22 PM	0.0	12:22 PM	0.0	0.0	
12:37 PM	0.0	12:37 PM	0.0	0.0	
12:52 PM	0.0	12:52 PM	0.0	0.0	
1:07 PM	0.0	1:07 PM	0.0	0.0	
1:22 PM	0.0	1:22 PM	0.0	0.0	
1:37 PM	0.0	1:37 PM	0.0	0.0	
1:52 PM	0.0	1:52 PM	0.0	0.0	
2:07 PM	0.0	2:07 PM	0.0	0.0	
2:22 PM	0.0	2:22 PM	0.0	0.0	
2:37 PM	0.0	2:37 PM	0.0	0.0	
2:52 PM	0.0	2:52 PM	0.0	0.0	
3:07 PM	0.0	3:07 PM	0.0	0.0	
3:22 PM	0.0	3:22 PM	0.0	0.0	
3:37 PM	0.0	3:37 PM	0.0	0.0	
3:52 PM	0.0	3:52 PM	0.0	0.0	

Notes:
1. NM - Not Measured




Figure 1: 410 Kingsland Property Site Map - September 29, 2026