

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: <u>Taylor Instruments</u>		Class: <u>4</u>	Number: <u>8280289</u>
O&M Funding Source: <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input type="checkbox"/> Responsible Party			
O&M Information:    O&M Start: <u>None</u> End:    Annual Cost: \$ <input type="checkbox"/> Estimated			
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
<input checked="" type="checkbox"/> Cap/Cover	<input type="checkbox"/> Containment Structure	<input type="checkbox"/> Fence/Security	
<input type="checkbox"/> Groundwater Recovery/Treatment	<input type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment	
<input type="checkbox"/> Air Sparging/Stripper System	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input type="checkbox"/> Other:			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input type="checkbox"/> Other:			
O&M Review Information:			
Reports: <u>10/1/98</u>			
Inspection: <u>9/23/98 - site visit</u>			
Sampling:			
Other:			
Conclusions:			
Remedy Effective? <input type="checkbox"/> Yes <input type="checkbox"/> No: <u>Remedy not yet implemented</u>			
ROD Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: <u>N/A</u>			
Consent Order Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: <u>N/A</u>			
Other: <u>Voluntary Agreement in effect. Currently in compliance.</u>			
Recommendations: <u>VCA signed with responsible party 11/97. Remedial work plan is being finalized to include excavation of mercury-contaminated soil and dual phase extraction to treat VOC-contaminated soil.</u>			
<u>Recommend implementation of work plan when ready. If not implemented, then the site should be reclassified.</u>			
ROD/Consent Order Modifications? <input type="checkbox"/> No <input type="checkbox"/> Yes (per above)    Reclassify the Site? <input type="checkbox"/> No <input type="checkbox"/> Yes → Class:			
Comments: <u>Site currently fenced &amp; an asphalt parking lot covers entire site. At time of site visit, PRP was performing test pits to better define mercury contamination.</u>			
Project Manager:		Reviewer:	
<u>D. G. Pratt</u> 12/1/98		<u>Mary Jane Peachey</u> 12/9/98	
Signature    Date		Signature    Date	
DAVID G. PRATT    Reg. 8    716/226-2466		Mary Jane Peachey    Reg. 8    716-226-2466	
Name    Region or Bureau    Telephone		Name    Region or Bureau    Telephone	