

Jerry P. DERJ
Will W. WELING
DER

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: National Fuel Gas - Mineral Spring Maintenance Facility **Class:** NL **Number:** V00195-9

O&M Funding Source: State Superfund Federal Superfund Municipal Responsible Party

O&M Information: O&M Start: June 2001 End: Annual Cost: \$ Estimated

Interim Remedial Measures/Operable Units in O&M Phase:

Drum Removal Soil Removal Tank Removal
 Cap/Cover (Pavement & Clay) Containment Structure Fence/Security
 Groundwater Recovery/Treatment Leachate Collection/Treatment Vapor Extraction/Treatment
 Air Sparging/Stripper System Treatment/Filtration Plant/System Potable Water Supply/System
 Other: DNAPL Recovery System

Institutional Controls: Deed Restriction Discharge Permit Department of Health Sampling
 Other: Annual certification

O&M Review Information:
 Reports: OM&M Plan dated May 2002, Remedial Completion Report dated May 2002, Last GW Sampling Report dated October 9, 2003

Inspection: Performed 04/30/04 w/ Charlie Burke of NFG representing facility. No problems noted. Discussed NFG pursuing further investigation of why cyanide levels in site GW are not reducing since remedial measures have been put in place. Mr. Burke noted that NFG and RETEC have already been discussing issue and how to proceed. All clay capped areas well vegetated. All pavement capped areas in good condition. Pavement around one DI behind Building #3 (area B3SAC) is damage due to subsurface settling. NFG has placed on maintenance schedule for repair this spring. All swale areas are sound, no seeps noted.

Sampling: Facility conducts GW sampling 3 times per year, results sent to DEC. Annual report due November 2004, Annual Cert. Due May 2004. No sampling was conducted at the time of the inspection.

Other:

Conclusions:

Remedy Effective? Yes No: explain: _____

ROD Compliance? Yes No: explain: _____


Consent Order Compliance? Yes No: explain: _____


Other:

Recommendations: Further follow-up on cyanide levels required once next round of GW sampling data comes in for review.

ROD/Consent Order Modifications? No Yes (per above) Reclassify the Site? No Yes → Class:

Comments: _____

Project Manager:

 Signature: _____ Date: 5/03/04
 Name: Gregory Sutton Region or Bureau: R9 Telephone: 851-7220

Reviewer:

 Signature: _____ Date: 5/3/04
 Name: _____ Region or Bureau: _____ Telephone: _____